

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET  
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

**PLM Bulk Asbestos Report**Applied Technology Services, Inc.  
Attn: Steve Vanderwoude  
240 North Avenue  
New Rochelle, NY 10801

|                      |            |                       |           |
|----------------------|------------|-----------------------|-----------|
| <b>Date Received</b> | 05/06/2002 | <b>SciLab Job No.</b> | 202051557 |
| <b>Date Examined</b> | 05/06/2002 | <b>P.O. #</b>         | E02411    |
| <b>ELAP Number</b>   | 11480      | <b>Page 1 of 5</b>    |           |
| <b>RE:</b>           | E02411     |                       |           |

| <b>Client No. / HGA</b> | <b>Lab No.</b> | <b>Asbestos Present</b> | <b>Total % Asbestos</b> |
|-------------------------|----------------|-------------------------|-------------------------|
| 26-050602-01            | 202051557-01   | <i>No</i>               | NAD                     |

DUS-001      **Location:** Roof, 16th Floor, SE Corner Roof Drains**Description:** Brown, Heterogeneous, Dust / Debris**Asbestos Types:****Other Material:** Cellulose 5. %, Fibrous glass 2. %, Synthetic fibers Trace,  
Non-fibrous 93. %

|              |                                               |           |     |
|--------------|-----------------------------------------------|-----------|-----|
| 26-050602-02 | 202051557-02                                  | <i>No</i> | NAD |
| DUS-001      | <b>Location:</b> Roof, 16th Floor, 7th Column |           |     |

**Description:** OffWhite, Homogeneous, Dust / Debris**Asbestos Types:****Other Material:** Cellulose 30. %, Fibrous glass 5. %, Non-fibrous 65. %**Comment:** APPEARS TO BE INSULATION

|              |                                                 |           |     |
|--------------|-------------------------------------------------|-----------|-----|
| 26-050602-03 | 202051557-03                                    | <i>No</i> | NAD |
| DUS-001      | <b>Location:</b> Roof, 16th Floor, Door A Right |           |     |

**Description:** Grey, Heterogeneous, Dust / Debris**Asbestos Types:****Other Material:** Cellulose 10. %, Fibrous glass 10. %, Synthetic fibers Trace,  
Non-fibrous 80. %

|              |                                          |           |     |
|--------------|------------------------------------------|-----------|-----|
| 26-050602-04 | 202051557-04                             | <i>No</i> | NAD |
| DUS-001      | <b>Location:</b> Roof, 16th Floor, Drain |           |     |

**Description:** Brown, Heterogeneous, Dust / Debris**Asbestos Types:****Other Material:** Cellulose 8. %, Fibrous glass 5. %, Non-fibrous 87. %

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET  
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

**PLM Bulk Asbestos Report**

Applied Technology Services, Inc.  
Attn: Steve Vanderwoude  
240 North Avenue  
New Rochelle, NY 10801

**Date Received** 05/06/2002 **SciLab Job No.** 202051557  
**Date Examined** 05/06/2002 **P.O. #** E02411  
**ELAP Number** 11480 **Page 2 of 5**  
**RE:** E02411

| <b>Client No. / HGA</b> | <b>Lab No.</b>                                                                                                            | <b>Asbestos Present</b> | <b>Total % Asbestos</b> |
|-------------------------|---------------------------------------------------------------------------------------------------------------------------|-------------------------|-------------------------|
| 26-050602-05            | 202051557-05                                                                                                              | <i>No</i>               | NAD                     |
| DUS-001                 | <b>Location:</b> Roof, 16th Floor, Outer North Corner of Door A                                                           |                         |                         |
|                         | <b>Description:</b> OffWhite, Heterogeneous, Dust / Debris                                                                |                         |                         |
|                         | <b>Asbestos Types:</b>                                                                                                    |                         |                         |
|                         | <b>Other Material:</b> Cellulose Trace, Non-fibrous 100. %                                                                |                         |                         |
| 26-050602-06            | 202051557-06                                                                                                              | <i>Yes</i>              | <1. %                   |
| DUS-001                 | <b>Location:</b> Roof, 16th Floor, 3rd Drain North                                                                        |                         |                         |
|                         | <b>Description:</b> Brown, Heterogeneous, Dust / Debris                                                                   |                         |                         |
|                         | <b>Asbestos Types:</b> Chrysotile Trace                                                                                   |                         |                         |
|                         | <b>Other Material:</b> Animal hair Trace, Cellulose 12. %, Fibrous glass 8. %, Synthetic fibers Trace, Non-fibrous 80. %  |                         |                         |
| 26-050602-07            | 202051557-07                                                                                                              | <i>Yes</i>              | <1. %                   |
| DUS-001                 | <b>Location:</b> Roof, 16th Floor, Handrail 4th Column NS                                                                 |                         |                         |
|                         | <b>Description:</b> Grey, Heterogeneous, Dust / Debris                                                                    |                         |                         |
|                         | <b>Asbestos Types:</b> Chrysotile Trace                                                                                   |                         |                         |
|                         | <b>Other Material:</b> Cellulose 20. %, Fibrous glass 35. %, Synthetic fibers Trace, Non-fibrous 45. %                    |                         |                         |
| 26-050602-08            | 202051557-08                                                                                                              | <i>Yes</i>              | <1. %                   |
| DUS-001                 | <b>Location:</b> Roof, 16th Floor, West Side of North Drain                                                               |                         |                         |
|                         | <b>Description:</b> Brown, Heterogeneous, Dust / Debris                                                                   |                         |                         |
|                         | <b>Asbestos Types:</b> Chrysotile Trace                                                                                   |                         |                         |
|                         | <b>Other Material:</b> Animal hair Trace, Cellulose 20. %, Fibrous glass 30. %, Synthetic fibers Trace, Non-fibrous 50. % |                         |                         |

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET  
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

**PLM Bulk Asbestos Report**Applied Technology Services, Inc.  
Attn: Steve Vanderwoude  
240 North Avenue  
New Rochelle, NY 10801

|                      |            |                       |           |
|----------------------|------------|-----------------------|-----------|
| <b>Date Received</b> | 05/06/2002 | <b>SciLab Job No.</b> | 202051557 |
| <b>Date Examined</b> | 05/06/2002 | <b>P.O. #</b>         | E02411    |
| <b>ELAP Number</b>   | 11480      | <b>Page</b>           | 3 of 5    |
| <b>RE:</b>           | E02411     |                       |           |

| Client No. / HGA                                                                                | Lab No.                                                         | Asbestos Present | Total % Asbestos |
|-------------------------------------------------------------------------------------------------|-----------------------------------------------------------------|------------------|------------------|
| 26-050602-09                                                                                    | 202051557-09                                                    | Yes              | <1.%             |
| DUS-001                                                                                         | Location: Roof, 16th Floor, 2nd Handrail North                  |                  |                  |
| Description: Brown, Heterogeneous, Dust / Debris                                                |                                                                 |                  |                  |
| Asbestos Types: Chrysotile Trace                                                                |                                                                 |                  |                  |
| Other Material: Cellulose 15. %, Fibrous glass 20. %, Synthetic fibers Trace, Non-fibrous 65. % |                                                                 |                  |                  |
| 26-050602-10                                                                                    | 202051557-10                                                    | No               | NAD              |
| ASH-001                                                                                         | Location: 15th Floor, West Building Wall, Near Air Intake       |                  |                  |
| Description: OffWhite, Homogeneous, Dust / Debris                                               |                                                                 |                  |                  |
| Asbestos Types:                                                                                 |                                                                 |                  |                  |
| Other Material: Cellulose 35. %, Fibrous glass 5. %, Non-fibrous 60. %                          |                                                                 |                  |                  |
| Comment: APPEARS TO BE INSULATION                                                               |                                                                 |                  |                  |
| 26-050602-11                                                                                    | 202051557-11                                                    | No               | NAD              |
| DUS-001                                                                                         | Location: 15th Floor, West Parapet Wall, 8' From South Corner   |                  |                  |
| Description: Grey, Heterogeneous, Dust / Debris                                                 |                                                                 |                  |                  |
| Asbestos Types:                                                                                 |                                                                 |                  |                  |
| Other Material: Cellulose 10. %, Fibrous glass 8. %, Synthetic fibers Trace, Non-fibrous 82. %  |                                                                 |                  |                  |
| 26-050602-12                                                                                    | 202051557-12                                                    | No               | NAD              |
| WIP-001                                                                                         | Location: 15th Floor, West Side Air Intake, 6' From Roof Louver |                  |                  |
| Description: (Wipe), Heterogeneous, Dust / Debris                                               |                                                                 |                  |                  |
| Asbestos Types:                                                                                 |                                                                 |                  |                  |
| Other Material: NAD                                                                             |                                                                 |                  |                  |
| Comment: THIS IS A QUALITATIVE RESULT, SHOULD BE CONSIDERED NVA                                 |                                                                 |                  |                  |



**SCIENTIFIC LABORATORIES, INC.**

117 EAST 30TH STREET  
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

# **PLM Bulk Asbestos Report**

Applied Technology Services, Inc.  
Attn: Steve Vanderwoude  
240 North Avenue  
New Rochelle, NY 10801

**Date Received** 05/06/2002 **SciLab Job No.** 202051557  
**Date Examined** 05/06/2002 **P.O. #** E02411  
**ELAP Number** 11480 **Page 4 of 5**  
**RE:** E02411

| Client No. / HGA | Lab No.      | Asbestos Present | Total % Asbestos |
|------------------|--------------|------------------|------------------|
| 26-050602-13     | 202051557-13 | Yes              | <1.%             |

DEB-001 **Location:** 15th Floor, At North Side Drain

**Description:** Green/Gray, Heterogeneous, Dust / Debris  
**Asbestos Types:** Chrysotile Trace  
**Other Material:** Cellulose 5. %, Fibrous glass 60. %, Non-fibrous 35. %

|              |              |     |      |
|--------------|--------------|-----|------|
| 26-050602-14 | 202051557-14 | Yes | <1.% |
|--------------|--------------|-----|------|

DEB-002 **Location:** East Side Walk, 10' South of Corner

**Description:** Grey, Heterogeneous, Dust / Debris  
**Asbestos Types:** Chrysotile Trace  
**Other Material:** Cellulose 15. %, Fibrous glass 40. %, Synthetic fibers Trace, Non-fibrous 45. %

|              |              |     |      |
|--------------|--------------|-----|------|
| 26-050602-15 | 202051557-15 | Yes | <1.% |
|--------------|--------------|-----|------|

ASH-002 **Location:** 15th Floor, East Side Walk, Window Leadge @Kitchen

**Description:** Grey, Heterogeneous, Dust / Debris  
**Asbestos Types:** Chrysotile Trace  
**Other Material:** Cellulose 8. %, Fibrous glass 30. %, Non-fibrous 62. %

|              |              |     |      |
|--------------|--------------|-----|------|
| 26-050602-16 | 202051557-16 | Yes | <1.% |
|--------------|--------------|-----|------|

ASH-003 **Location:** 15th Floor, South Side Walk, SE Corner, 6' West

**Description:** Grey, Heterogeneous, Dust / Debris  
**Asbestos Types:** Chrysotile Trace  
**Other Material:** Cellulose 12. %, Fibrous glass 35. %, Synthetic fibers Trace, Non-fibrous 53. %



**SCIENTIFIC LABORATORIES, INC.**

117 EAST 30TH STREET  
NEW YORK, NY 10016  
TEL: (212) 679-8600 • FAX: (212) 679-9392

**PLM Bulk Asbestos Report**

Applied Technology Services, Inc.  
Attn: Steve Vanderwoude  
240 North Avenue  
New Rochelle, NY 10801

**Date Received** 05/06/2002 **SciLab Job No.** 202051557  
**Date Examined** 05/06/2002 **P.O. #** E02411  
**ELAP Number** 11480 **Page** 5 of 5  
**RE:** E02411

**Reporting Notes:**

Analyzed by: David Roderick

\*NAD/NSD = no asbestos detected; NA = not analyzed; NA/PS = not analyzed / positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #200546-0) and ELAP PLM Analysis Protocol 198.1 for New York samples (NYSDOH ELAP Lab # 11480); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). National Institute of Standards and Technology Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested. AIHA# 102843; VT Cert# AL016055

Reviewed By: