

**SCIENTIFIC LABORATORIES, INC.**

117 EAST 30TH STREET

NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

Applied Technology Services, Inc.
Attn: Steve Vanderwoude
240 North Avenue
New Rochelle, NY 10801

Date Received 05/10/2002 **SciLab Job No.** 202052099
Date Examined 05/10/2002 **P.O. #** E02411
ELAP Number 11480 **Page 1 of 4**
RE: E02411

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
26-051002-01 001	202052099-01	No	NAD ¹
Location: 12th Floor / Dust + Debris N/W Corner / 24' E x 20' S Top Of Act.			
Description: Grey, Heterogeneous, Dust			
Asbestos Types:			
Other Material: Cellulose Trace, Fibrous glass Trace, Non-fibrous 100. %			
26-051002-06 004	202052099-02	No	NAD ¹
Location: 12th Floor / Dust / Top Of F/G Ins. CUNY R. Office At Closet Door			
Description: Grey, Heterogeneous, Dust			
Asbestos Types:			
Other Material: Cellulose 5. %, Fibrous glass 15. %, Non-fibrous 80. %			
26-051002-08 007	202052099-03	No	NAD ¹
Location: 15th Floor / AHU #2 / Filter Element Door Inside Temp. Wall			
Description: Grey, Heterogeneous, Dust			
Asbestos Types:			
Other Material: Cellulose 2. %, Fibrous glass 90. %, Non-fibrous 8. %			
26-051002-09	202052099-04	No	NAD ¹
Location: 16.5 Floor / Debris / N/W Corner 16.5 30' E Cooling Tower Area Along Wall			
Description: Brown, Heterogeneous, Dust			
Asbestos Types:			
Other Material: Cellulose 20. %, Fibrous glass 8. %, Non-fibrous 72. %			



SCIENTIFIC LABORATORIES, INC.

117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

Applied Technology Services, Inc.
Attn: Steve Vanderwoude
240 North Avenue
New Rochelle, NY 10801

Date Received 05/10/2002 **SciLab Job No.** 202052099
Date Examined 05/10/2002 **P.O. #** E02411
ELAP Number 11480 **Page** 2 **of** 4
RE: E02411

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
26-051002-10	202052099-05	No	NAD ¹
Location: 16.5 Floor / Dust / Top Of Rectifier #1 Elevator Mech. Room Description: Grey, Heterogeneous, Dust Asbestos Types: Other Material: Cellulose 15. %, Fibrous glass 25. %, Synthetic fibers 2. %, Non-fibrous 58. %			
26-051002-11	202052099-06	No	NAD ¹
Location: 15th Floor / Hallway Outside Phone Room Above Insulation Description: Grey, Heterogeneous, Dust Asbestos Types: Other Material: Cellulose 2. %, Fibrous glass 85. %, Non-fibrous 13. %			
26-051002-12	202052099-07	No	NAD ¹
Location: 15th Floor / Hallway Outside Phone Room Above Steel Header Description: Grey, Heterogeneous, Dust Asbestos Types: Other Material: Cellulose 10. %, Fibrous glass 15. %, Synthetic fibers 5. %, Non-fibrous 70. %			
26-051002-14	202052099-08	No	NAD ¹
Location: 15th Floor / Dust On Top Of Cooling Tower 8' East Of Door ENG. Office W/Door To Roof Description: Grey, Heterogeneous, Dust Asbestos Types: Other Material: Cellulose 8. %, Fibrous glass 12. %, Synthetic fibers Trace, Non-fibrous 80. %			

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos ReportApplied Technology Services, Inc.
Attn: Steve Vanderwoude
240 North Avenue
New Rochelle, NY 10801

Date Received	05/10/2002	SciLab Job No.	202052099
Date Examined	05/10/2002	P.O. #	E02411
ELAP Number	11480	Page	3 of 4
RE:	E02411		

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
26-051002-15	202052099-09	No	NAD ¹
Location: B Floor / Debris / Exhaust Duct On Fire Protection CZZ On Furn. West Wall Description: Brown, Heterogeneous, Debris Asbestos Types: Other Material: Cellulose 10. %, Fibrous glass 15. %, Synthetic fibers Trace, Non-fibrous 75. %			
26-051002-16	202052099-10	No	NAD ¹
Location: B Floor / Dust / East Side Of Unit AC-7 Air Intake Description: Grey, Heterogeneous, Dust Asbestos Types: Other Material: Cellulose 2. %, Fibrous glass 10. %, Non-fibrous 88. %			
26-051002-17	202052099-11	No	NAD ¹
Location: 4th Floor / Dust + Debris / Mastic / 75' West Of F403 Hallway Description: Grey, Heterogeneous, Dust Asbestos Types: Other Material: Cellulose 25. %, Fibrous glass 5. %, Synthetic fibers Trace, Non-fibrous 70. %			
26-051002-18	202052099-12	No	NAD ¹
Location: 4th Floor / 25' W. Along Wall Of F-408 Hallway A Top Water Fountains Description: Grey, Heterogeneous, Dust Asbestos Types: Other Material: Cellulose 15. %, Fibrous glass 15. %, Synthetic fibers Trace, Non-fibrous 70. %			

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos ReportApplied Technology Services, Inc.
Attn: Steve Vanderwoude
240 North Avenue
New Rochelle, NY 10801

Date Received	05/10/2002	SciLab Job No.	202052099
Date Examined	05/10/2002	P.O. #	E02411
ELAP Number	11480	Page	4 of 4
RE:	E02411		

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
26-051002-19	202052099-13	No	NAD ¹

Location: 4th Floor /* Dust / E. Wall 12' S Of Room F-405 Hall**Description:** Grey, Heterogeneous, Dust**Asbestos Types:****Other Material:** Cellulose 13. %, Fibrous glass 10. %, Synthetic fibers 2. %, Non-fibrous 75. %

26-051002-20	202052099-14	No	NAD ¹
--------------	--------------	----	------------------

Location: 4th Floor / E. Wall In R. Room 400**Description:** Grey, Heterogeneous, Dust**Asbestos Types:****Other Material:** Cellulose 15. %, Fibrous glass 10. %, Synthetic fibers Trace, Non-fibrous 75. %**Reporting Notes:**

(1) Composite analysis results for heterogeneous debris samples may be highly variable due to inhomogenities in materials present

Analyzed by: Jonathan Teda

*NAD/NSD = no asbestos detected; NA = not analyzed; NA/PS = not analyzed / positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #200546-0) and ELAP PLM Analysis Protocol 198.1 for New York samples (NYSDOH ELAP Lab # 11480); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). National Institute of Standards and Technology Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested. AIHA# 102843; VT Cert# A1016055

Reviewed By: