

Asbestos Inspection Report

Premise No. 101 MAIDEN LANE					Inspection Date: AS NOTED	
Floor ROOF & FACADE	Zip 10038	Borough 1	Block 68	Lot 10	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken (Yes) No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: AS NOTED		
WEDNESDAY SEPTEMBER 4 2002						
HANGING SCAFFOLD IS ERECTED IN PREPARATION FOR THE FACADE CLEAN UP ON THE EAST (PEARL STREET) FACE OF THE BUILDING. THE FACADES OF THE BUILDING CONTAINING SEVERAL AREAS OF CRACKED AND LOOSE BRICK. DURING THE ERECTION OF THE HANGING SCAFFOLD FOUR LOOSE BRICKS BECAME DISLODGED. NO INJURIES OCCURRED AS A RESULT OF THE FALLING BRICK.						
FRIDAY SEPTEMBER 6 2002						
THE CLEAN UP OF THE ROOF WORK AREA BEGINS AFTER THE INSTALLATION OF CRITICALS.						
SATURDAY SEPTEMBER 7 2002						
THE CLEAN UP OF THE EAST (PEARL STREET) FACADE AND ONE HALF OF THE SOUTH (MAIDEN LANE) FACADE WAS CONDUCTED TODAY. DUE TO SEVERAL AREAS OF LOOSE AND CRACKED BRICK NO POWER WASHING OF THE FACADE SURFACES OCCURRED. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY LUIS SOTO (CERTIFICATE # AH 00 20894 EXP 03/03). CLEAN UP ACTIVITIES ON THE ROOF OCCURED SIMULTANEOUSLY. AIR MONITORING FOR THAT PORTION OF THE CLEAN UP WAS PERFORMED BY RONALD KING (CERTIFICATE # AH 98-20226 EXP 10/02).						
SUNDAY SEPTEMBER 8 2002						
THE CLEAN UP OF THE SECOND HALF OF THE SOUTH (MAIDEN LANE) FACADE WAS CONDUCTED TODAY. THE CLEAN UP OF THE ROOF WAS COMPLETED TODAY. AIR MONITORING FOR THE FACADE CLEAN UP WAS PERFORMED BY LUIS SOTO. AIR MONITORING FOR THE ROOF CLEAN UP WAS PERFORMED BY						

