

**BUREAU OF ENVIRONMENTAL PROTECTION
ASBESTOS AND LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368**

JOEL A. NIELE, SR., P.E.
COMMISSIONER

**BULK
ANALYSIS CHAIN OF CUSTODY**

Incident No.: WTC

Date Sampled: 2/27/02

Premise: 102 NORTH END AVE

Boro: MANHATTAN

Time: 3:30 am/pm

Inspector: R. RAMMOHAN
Print

N. M. K. K.
Signature

Turnaround Time: Immediate | ☒ | 24 Hours | | 48 Hours | | 1 Week | |

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20227/A78011	Mud	Roof N.W	
2. 20227/A78012	Mud	Roof N.W	
3. 20227/A78013	Mud	Roof N.W	
4. 20227/A078014	Mud	Roof N.W	
5. 20227/A78015	Mud	Roof N.W	
6.			
7.			
8.			
9.			
10.			

ANALYSIS REQUESTED: Asbestos PLM | ☒ |

Asbestos TEM | |

Lead | |

Date	Time	Accepted By	Comments
1.	am pm	Print	
		Sign	
2.	am pm	Print	
		Sign	
3.	am pm	Print	
		Sign	
4.	am pm	Print	
		Sign	
5.	am pm	Print	
		Sign	

DEP ACLP REV5/00

ASBESTOS CONTROL PROGRAM EMERGENCY RESPONSE D I A G R A M

NAME <u>R. RAMMOHAN</u>	BADGE # <u>A078</u>	DATE <u>02/27/02</u>
LOCATION <u>102 NORTH END AVENUE (EMBASSY SUITES)</u>		

ROOF

☒ No Visible Debris

☐ Entire Roof Covered with Debris

☐ Partial Roof Covered

☐ Local/Isolated Areas
☐ Gutters
☐ 25% of the roof
☐ 50% of the roof
☐ 75% of the roof

FACADE

☒ Clean ,

☐ Entire Facade req. Clean-up

☐ _____ Req. Clean-up

EAST ↑

NORTH ↑

MAIN ROOF

ELEVATED ROOF

PH.
MCH ROOM

COOLING TOWERS

G
L
A
S
S

P
A
N
E
L
S

G L A S S P A N E L S

012
013
014
015

SOUTH ↑


WEST ↑

SAMPLE LOCATIONS.

1. Roof was made of rubber
2. The glass panels contained very fine layer of dust
3. The roof was completely cleaned as per Engineers.
4. The Embassy Suites was completely cleaned.
5. The restaurants (Rear side (East)) were not cleaned & mild dust observed on facade ledges.

ASBESTOS CONTROL PROGRAM EMERGENCY RESPONSE DIAGRAM

NAME R. RAMMOHAN BADGE # A078 DATE 02/27/02
 LOCATION 102 NORTH END AVENUE (EMBASSY SUITES)




① SAMPLE LOCATIONS.

1. Roof was made of rubber
2. The glass panels contained very fine layer of dust
3. The roof was completely cleaned as per Engineers.
4. The Embassy suites was completely cleaned.
5. The restaurants (Rear side (East)) were not cleaned & mild dust observed on facade ledges.

ASBESTOS CONTROL PROGRAM EMERGENCY RESPONSE DIAGRAM

NAME R. RAMMOHAN BADGE # A078 DATE 02/27/02
 LOCATION 102 NORTH END AVENUE (EMBASSY SUITES)



① SAMPLE LOCATIONS.

1. Roof was made of rubber
2. The glass panels contained very fine layer of dust
3. The roof was completely cleaned as per Engineers.
4. The Embassy suites was completely cleaned.
5. The restaurants (Rear side (East)) were not cleaned & mild dust observed on facade ledges.