

**BUREAU OF ENVIRONMENTAL PROTECTION
ASBESTOS AND LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368**

JOEL A. MIELL SR., P.E.
COMMISSIONER

**BULK
ANALYSIS CHAIN OF CUSTODY**

Incident No.: WTC

Date Sampled: 2/27/02

Premise: 365 South End Ave Bldg # 400

Boro: MANHATTAN

Time: 11:30 am/pm

Inspector: R. RAMMOHAN
Print

R. Rammo
Signature

Turnaround Time: Immediate | ☒ | 24 Hours | | 48 Hours | | 1 Week | |

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20227/A078 001	Mud	Roof N.E	
2. 20227/A078 002	Mud	Roof S.E	
3. 20227/A078 003	Mud	Roof Mid North	
4. 20227/A078 004	Mud	Roof N.W	
5. 20227/A078 005	Mud	Roof S.W	
6.			
7.			
8.			
9.			
10.			

ANALYSIS REQUESTED: Asbestos PLM | ☒ |

Asbestos TEM | |

Lead | |

Date	Time	Accepted By	Comments
1.	am pm	Print	
		Sign	
2.	am pm	Print	
		Sign	
3.	am pm	Print	
		Sign	
4.	am pm	Print	
		Sign	
5.	am pm	Print	
		Sign	

DEP ACP RLS 5/00

ASBESTOS CONTROL PROGRAM EMERGENCY RESPONSE DIAGRAM


NAME R. RAMMOHAN BADGE # A078 DATE 2/27/02
 LOCATION 365 SOUTH END AVE BLDG. # 400

ROOF


- ☒ No Visible Debris
- ☐ Entire Roof Covered with Debris
- ☐ Partial Roof Covered
 - ☐ Local/Isolated Areas
 - ☐ Gutters
 - ☐ 25% of the roof
 - ☐ 50% of the roof
 - ☐ 75% of the roof

FACADE

- ☒ Clean
- ☐ Entire Facade req. Clean-up
- ☐ _____ Req. Clean-up




GRAVEL
 SAMPLE LOCATION



- * Gravel on roof has been replaced ^{after 9/11} as per the super
- * Mud like material observed below gravel.

ASBESTOS CONTROL PROGRAM EMERGENCY RESPONSE DIAGRAM

NAME R. RAMMOHAN BADGE # A078 DATE 2/27/02
LOCATION 365 SOUTH END AVE BLDG # 400



* Gravel on roof has been replaced ^{after 9/11} as per the super
* Mud like material observed below gravel.

ASBESTOS CONTROL PROGRAM EMERGENCY RESPONSE DIAGRAM

NAME R. RAMMOHAN BADGE # A078 DATE 2/27/02
LOCATION 365 SOUTH END AVE BLDG # 400

