

ASBESTOS INSPECTION REPORT

PAGE 1 OF

PREMISE NO. 92 CHAMBERS ST		STREET		INSPECTION DATE 6/8/02	
FLOOR Roof	ZIP 10007	BORO CODE 1	BLOCK 135	LOT 20	SQUAD # 1
INSPECTOR ALPHONSO PLUMPTRE		BLDG TYPE	BASIS OF INSPECT. TRW804MNO2		PHOTOS TAKEN YES / NO
CONTRACTORS NAME FIBER CONTROL			SAMPLE NO.		
ADDRESS 3010 BURNS AVE			CITY WANTAGH		
STATE N.Y.			ZIP 11793		
PHONE 516 781-3000			SAMPLE NO.		
LABORATORY NAME WARREN & PANZER ENGINEERS, PC			OWNERS NAME HAMBURGER GREEN X		
ADDRESS 228 E. 45TH ST			CITY N.Y.		
STATE N.Y.			ZIP 10017		
PHONE (212) 922-0077			STATE N.Y.		
CONTACT PERSON Tony Costas			TIME OF INSPECTION FROM: 8:00 am TO: 1:30 pm		
INSPECTION DISCLOSED: Checked the supervisor and handlers licenses and were in order including Air Technician Fernandez -					
Final inspection (visual) was done after the completion of cleanup.					
NO visible debris observed on the roof after cleanup.					

NOV #	INFRACTIONS	RESULT CODE
		5
NOV #		SUPERVISOR'S INITIALS
		U

BORO 1 - MANHATTAN 2 - BRONX 3 - BROOKLYN 4 - QUEENS 5 - RICHMOND
 BLDG TYPE A > 6 Stories B < 6 Stories C Single Family
 D School E Hospital F Public Owned Property
 RESULT CODES 1 - Violation Issued 2 - No Violations Issued 3 - No Access
 4 - Project not Started (No NOV) 5 - Project Completed (No NOV)

ACP 30/93

FILE

WTC Visual Survey Form

Premise Address: <u>92 chamber Street</u>		
Block: <u>135</u>	Residential ☒ Commercial ☐	Name of Building:
Lot: <u>20</u>	Mix Use ☒ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management: <u>Hamberger Green & Haver</u>		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact: <u>The Restaurant Manager</u>		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description:					
Roof					
Debris: ☒ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: <u>Debris (mudlike near drains and in gutters)</u>					
Setbacks N/A ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					
<u>need to contact the owner. No access. Roof inspected from</u>					
<u>the adjacent roof.</u>					

Date: 011-24/2002Inspection Team: Name: R. Fitzpatrick
Name: R. RAMMCHANAgency: USEPA
Agency: NYC DEP