

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE
ASBESTOS AND LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368
JOEL A. MIELE, SR., P.E.
COMMISSIONER**

**BULK
ANALYSIS CHAIN OF CUSTODY**

Incident No.: _____

Date Sampled: 2-23-02

Premise: 95 CHAMBER ST.

Boro: MANHATTAN

Time: 2:00 am/pm

Inspector: D. SHAH
Print

DeShah
Signature

Turnaround Time : Immediate ☒ 24 Hours | | 48 Hours | | 1 Week | |

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20223/A060001	Fibrous & Dust	Roof mid west	
2. 20223/A060002	" "	Roof mid East	
3. 20223/A060003	" "	Roof Drain	
4. 20223/A060004	" "	Roof SW. Gutter	
5. 20223/A060005	" "	Roof S.W. Gutter	
6. 20223/A060006	" "	Roof S.W. Gutter	
7. 20223/A060007	" "	Roof S.W. Gutter	
8. 20223/A060008	" "	Roof S.W. Gutter	
9. 20223/A060009	" "	Roof S.W. Gutter	
10.			

ANALYSIS REQUESTED: Asbestos PLM ☒

Asbestos TEM | |

Lead | |

Date	Time	Accepted By	Comments
1.	am pm	Print	
		Sign	
2.	am pm	Print	
		Sign	
3.	am pm	Print	
		Sign	
4.	am pm	Print	
		Sign	
5.	am pm	Print	
		Sign	

NEP ACLP REV 5/00

ENTERED

WTC Visual Survey Form

Premise Address: 95 Chambers St

Block: Residential ☐ Commercial ☒ **Name of Building:** Ralph's Farm St. Inc.

Lot: Mix Use ☐ Other ☐

of Stories: 5 **AKA's:**

Building Owner/Management: Name: RAEM Chambers St Corp Telephone Number: (212) 267-5567
FAX: ()

Address:

On Site Contact: Name: Daniel Ades Telephone Number: (212) 267-5567

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☒ No
Exterior Survey Performed ☐ Yes ☒ No
General Clean Up ☒ Yes ☐ No Locations: All floors w/ water damage, falling concrete
ACM Clean Up ☐ Yes ☒ No Locations: place mat come through roof
Air Monitoring ☐ Yes ☒ No Locations:

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

	Inspected	Debris
North ☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
South ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
East ☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
West ☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Facade Description: broken windows etc

Roof

Debris: ☐ No Visible /Fine Layer ^{light dust} ☒ 1/2 to 1" of dust ☐ > 1" of dust.

Description: 1 ft² of debris/dust in southwest corner of roof. Also some material from wall section 3" square

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Comments

edges OK.

Owner: Mandy Mizrahi 212-267-5567

All material on 1/25/02 - discuss getting material tested

1 story not west side (part of Ralph's) no access. However, to be cleaned up

Date: 1/24/2002

Inspection Team: Name: R Fitzpatrick

Agency: USEP

Name: JC Kaminberg

Agency: LAC/NEA

Spec from: 5th Floor at 95 Chambers.

3

2/23/02

Mon-Fri only as per store manager.

no access to roof

2/23/02

