

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE
ASBESTOS AND LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368**
JOEL A. MIELE, SR., P.E.
COMMISSIONER

DUPLICATE

**BULK
ANALYSIS CHAIN OF CUSTODY**

Incident No.: _____

Date Sampled: 2/23/02Premise: 96 CHAMBER STREETBoro: MANHATTANTime: 11:35 am/pmInspector: R. RAMMOHAN
PrintMMohay
SignatureTurnaround Time: Immediate ☒ 24 Hours ☐ 48 Hours ☐ 1 Week ☐

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20223/A078 019	Fibrous Dirt	Roof Southwest	120 (CHRY 2-4)
2. 20223/A078 020	Fibrous Dirt	Roof Midwest	121
3. 20223/A078 021	Fibrous Dirt	Roof Midwest North west	122
4. 20223/A078 022	Fibrous Dirt	Roof Southwest mid	123
5. 20223/A078 023	Fibrous Dirt	Roof South Midwest East	124 (-)
6. 20223/A078 024	Fibrous Dirt	Roof South Gutter	125
7. 20223/A078 025	Fibrous Dirt	Roof South Gutter	126
8. 20223/A078 026	Fibrous Dirt	Roof South Gutter	127
9. 20223/A078 027	Fibrous Dirt	Roof South Gutter.	128 (CHRY 1-4)
10.			

ANALYSIS REQUESTED: Asbestos PLM ☒Asbestos TEM ☐Lead ☐

Date	Time	Accepted By	Comments
1. 2/23/02	6:00 am	Print Greg Fruchman	Safe Cust 94 BEC Lab
	pm	Sign <u>NY</u>	
2.	am	Print	
	pm	Sign	
3.	am	Print	
	pm	Sign	
4.	am	Print	
	pm	Sign	
5.	am	Print	
	pm	Sign	

DEP ACLP REV 5/00

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE
ASBESTOS AND LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368
JOEL A. MIELE, SR., P.E.
COMMISSIONER**

**BULK
ANALYSIS CHAIN OF CUSTODY**

Incident No.: _____

Date Sampled: 2/23/02

Premise: 96 CHAMBER STREET

Boro: MANHATTAN

Time: 11:35 am/pm

Inspector: R. RAMMOHAN
Print

M. Mohay
Signature

Turnaround Time: Immediate ☒ 24 Hours ☐ 48 Hours ☐ 1 Week ☐

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20223/A078 019	Fibrous Dirt	Roof Southwest	
2. 20223/A078 020	Fibrous Dirt	Roof Midwest	
3. 20223/A078 021	Fibrous Dirt	Roof Roof section North West	
4. 20223/A078 022	Fibrous Dirt	Roof South East mid	
5. 20223/A078 023	Fibrous Dirt	Roof South East East	
6. 20223/A078 024	Fibrous Dirt	Roof South Gutter	
7. 20223/A078 025	Fibrous Dirt	Roof South Gutter	
8. 20223/A078 026	Fibrous Dirt	Roof South Gutter	
9. 20223/A078 027	Fibrous Dirt	Roof South Gutter.	
10.			

ANALYSIS REQUESTED: Asbestos PLM ☒

Asbestos TEM ☐

Lead ☐

Date	Time	Accepted By	Comments
1.	am pm	Print	
		Sign	
2.	am pm	Print	
		Sign	
3.	am pm	Print	
		Sign	
4.	am pm	Print	
		Sign	
5.	am pm	Print	
		Sign	

DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF AIR, NOISE & HAZARDOUS MATERIALS
ASBESTOS/LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368

JOEL A. MIELE, SR., P.E.
COMMISSIONER

ASBESTOS CONTROL PROGRAM
BULK ANALYSIS CHAIN OF CUSTODY

Incident No.: _____ Date Sampled: 02/23/02
Premise: 98 CHAMBER STREET Time: 12:00 ^{NSD} am/pm
Boro: MANHATTAN
Inspector: R-RAMMOHAN NWobay
Print Sign

TURNAROUND TIME: 24HRS [☒] 48HRS [] 1 WK [] 2 WKS [] 4 WKS []

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20223/A078 028	Fibrous Dirt	Roof Midsection	
2. 20223/A078 029	Fibrous Dirt	Roof Mid	
3. 20223/A078 030	Fibrous Dirt	Roof Mid	
4. 20223/A078 031	Fibrous Dirt	Roof Mid	
5. 20223/A078 032	Fibrous Dirt	Roof South Gutter	
6. 20223/A078 033	Fibrous Dirt	Roof South Gutter	
7. 20223/A078 034	Fibrous Dirt	Roof South Gutter	
8. 20223/A078 035	Fibrous Dirt	Roof South Gutter	
9. 20223/A078 036	Fibrous Dirt	Roof South Gutter	
10.			

ANALYSES REQUESTED: Asbestos PLM [☒] Asbestos TEM [] Lead []

DATE	TIME	ACCEPTED BY	COMMENTS
		PRINT	
		SIGN	
		P	
		S	
		P	
		S	
		P	
		S	
		P	
		S	

DEP ACP REV 5/96

DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF AIR, NOISE & HAZARDOUS MATERIALS
ASBESTOS/LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368

JOEL A. MIELE, SR., P.E.
COMMISSIONER

ASBESTOS CONTROL PROGRAM
BULK ANALYSIS CHAIN OF CUSTODY

Incident No.: _____ Date Sampled: 02/23/02
Premise: 100 Chamber Street Time: 1:35 am/pm
Boro: MANHATTAN
Inspector: R. RAMMOHAN N. Mohay
Print Sign

TURNAROUND TIME: 24HRS [☒] 48HRS [] 1 WK [] 2 WKS [] 4 WKS []

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20223/A078 037	Fibrous Dirt	Roof South	
2. 20223/A078 038	Fibrous Dirt	Roof South	
3. 20223/A078 039	Fibrous Dirt	Roof South	
4. 20223/A078 040	Fibrous Dirt	Roof South	
5. 20223/A078 041	Fibrous Dirt	Roof South	
6. 20223/A078 042	Fibrous Dirt	Roof South Gutter	
7. 20223/A078 043	Fibrous Dirt	Roof South Gutter	
8. 20223/A078 044	Fibrous Dirt	Roof South Gutter	
9. 20223/A078 045	Fibrous Dirt	Roof South Gutter.	
10.			

ANALYSES REQUESTED: Asbestos PLM [☒] Asbestos TEM [] Lead []

DATE	TIME	ACCEPTED BY	COMMENTS
		PRINT	
		SIGN	
		P	
		S	
		P	
		S	
		P	
		S	
		P	
		S	

DEF ACP REV 9/96

WTC Visual Survey Form

Premise Address: 96-78-100 Chambers St.
 Block: Residential ☐ Commercial ☐ Name of Building:
 Lot: Mix Use ☒ Other ☐
 # of Stories: AKA's:
 Building Owner/Management: Frederick Moskowitz Telephone Number: (212) 732-4040
 Name: Frederick Moskowitz FAX: (212) 212-234-1971
 Address: P11 212-234-1971
 On Site Contact: P11 Telephone Number: ()
 Name: P11
 Building Owner Management Activities
 Interior Survey Performed ☐ Yes ☐ No
 Exterior Survey Performed ☐ Yes ☐ No
 General Clean Up ☐ Yes ☐ No Locations: Some tenants cleaned up on their own
 ACM Clean Up ☐ Yes ☐ No Locations:
 Air Monitoring ☐ Yes ☐ No Locations:
 Copies of All Reports and Data Requested ☐ Yes


Visual Inspection Results:

Facade:
 North ☐ N/A Inspected ☒ Yes ☐ No Debris ☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 South ☒ N/A ☐ Yes ☐ No ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 East ☒ N/A ☐ Yes ☐ No ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 West ☐ N/A ☐ Yes ☐ No ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 Facade Description: Brick windows etc
 Roof
 Debris: ☐ No Visible /Fine Layer Light dust ☒ 1/2 to 1" of dust ☐ > 1" of dust.
 Description: Debris on roof and in gutters. Could not get in back
roofs to be inspected close up. Looks like what debris.
 Setbacks N/A ☐
 Floor: Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 Floor: Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 Floor: Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 Floor: Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 Floor: Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 Comments: Need to contact owner and have him sample gutters
and other debris on roof


Date: 1/24/2002Inspection Team: Name: R. Fitzpatrick
Name: R. RamachandranAgency: US EPA
Agency: NYC DEP

37

2/23/02 Roof debris appeared to be same as of Jan 24, 2002
96 Chamber Street



98 Chamber St : Roof debris still present as observed on 1/24/02



100 Chamber St. Gutters with some debris

