

WTC Visual Survey Form

Premise Address: <u>97 Chambers Street</u>		
Block: Lot:	Residential ☐ Commercial ☐ Mix Use ☒ Other ☐	Name of Building: <u>DEE & DEE</u>
# of Stories: <u>5</u>	AKA's:	
Building Owner/Management: Name: <u>DEE & DEE</u>		Telephone Number: (212) <u>243-5800</u>
Address: <u>24 W 14th St, Manhattan</u>		FAX: ()
On Site Contact: Name: <u>Gregory Lardica - Mgr</u>		Telephone Number: (212) <u>238-3850</u>
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☒ No		
Exterior Survey Performed ☐ Yes ☒ No		
General Clean Up ☒ Yes ☐ No	Locations: <u>Entrance Stairway</u>	
ACM Clean Up ☐ Yes ☒ No	Locations: _____	
Air Monitoring ☐ Yes ☒ No	Locations: _____	
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris
North	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"

Facade Description: Arch windows etc

Roof

Debris: ☐ No Visible /Fine Layer ^{light dust} ☒ ½ to 1" of dust ☐ > 1" of dust.

Description: South side brick head wall - Near roof dormer (Pineapple core)

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"

Comments Roof debris is needs to be tested.

Date: 7 / 24 / 2002

Inspection Team: Name: K. Fitzpatrick
Name: A. R. [illegible]

Agency: USIA
Agency: NSC DCP

39

2/23/22 ~~NO ACCESS~~, Bob Stone manager.

Mon-Friday only as per store manager

Accessed from 165 ~~clerk~~ church st.

ENTERED

2/23/02


DEE & DEE

Roof debris appeared to be same as of 1/24/02

also, N/79 Reade Street, Bldg permits for side walk

Scaffolding posted for

Jaya Consulting Inc. 97 Chambers
Kow Chang Chai
(212) 941-9936



97 Chambers St.

Appeared to be one big roof
But multiple roofs.

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE
ASBESTOS AND LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368
JOEL A. MIELE, SR., P.E.
COMMISSIONER**

**BULK
ANALYSIS CHAIN OF CUSTODY**

Incident No.: _____ Date Sampled: 2-23-02
Premise: 97 CHAMBER ST Boro: MANHATTAN
Time: 3:30 am/pm pm
Inspector: D. SHAH DBShah
Print Signature

Turnaround Time: Immediate | 4 24 Hours | | 48 Hours | | 1 Week | |

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20223/A060021	Fiberglass & Dist	Roof N. W. corner	
2. 20223/A060022	" "	Roof mid section	
3. 20223/A060023	" "	Roof S. W. corner	
4. 20223/A060024	" "	Roof mid section	
5. 20223/A060025	" "	Roof S. gutter	
6. 20223/A060026	" "	Roof mid section	
7. 20223/A060027	" "	Roof W. side	
8. 20223/A060028	" "	Roof E. side	
9. 20223/A060029	" "	Roof N. side	
10.			

ANALYSIS REQUESTED: Asbestos PLM | 4 Asbestos TEM | | Lead | |

Date	Time	Accepted By	Comments
1.	am pm	Print	
		Sign	
2.	am pm	Print	
		Sign	
3.	am pm	Print	
		Sign	
4.	am pm	Print	
		Sign	
5.	am pm	Print	
		Sign	

NEP ACLP REV 5/00

ENTERED