

**ASBESTOS CONTROL PROGRAM
EMERGENCY RESPONSE
DIAGRAM**

NAME <u>173 L. REYNA</u> BADGE # <u>A055</u> LOCATION <u>173 BROADWAY</u>	DATE <u>2/27/02</u> <u>2:30 pm</u>
--	---

ROOF

☐ No Visible Debris

☐ Entire Roof Covered with Debris

☒ Partial Roof Covered

☐ Local/Isolated Areas

☐ Gutters

☒ 25% of the roof

☐ 50% of the roof

☐ 75% of the roof

FACADE

☐ Clean

☐ Entire Facade req. Clean-up

☐ _____ Req. Clean-up


Size of Roof $\approx 100 \times 20$

20'

BROADWAY

**ASBESTOS CONTROL PROGRAM
EMERGENCY RESPONSE
DIAGRAM**

NAME 173 L. Reyna BADGE # A055 DATE 2/27/02
LOCATION 173 Broadway 2:30 pm



**ASBESTOS CONTROL PROGRAM
EMERGENCY RESPONSE
DIAGRAM**

NAME <u>173 L. Reyna</u> BADGE # <u>A055</u>	DATE <u>2/27/02</u>
LOCATION <u>173 Broadway</u>	<u>2:30 pm</u>

Size of Roof $\approx 100 \times 20$

20'

BROADWAY

005

006

004

003

001

CORTLAND

002

South Pier wall

EAST

West