

Letter first
to Maintenance
to inspect
sewer

After report on
Condition of
sewer do
a structural
analysis of
effect structure have
would on sewer
(cover)

INTERVIEW

Sewer may have
to be resouted anyway
later due to Westway
being set at a lower
elevation. But this

is in future
Requires check on adequacy of Foundation
Design & Rehabilitation of Existing Sewer to
entire extent
Design needed.

① If Foundation is correct & sewer
is OK there is no problem

② If Foundation Design is incorrect
Sewer will collapse ^{where sewer is reliable or not}

③ If Foundation is correct &
sewer not OK there may still be a
problem

231.020

May 7, 1982

TO: FRANK OLIVERI P.E., CHIEF, DIVISION OF SEWER MAINTENANCE
 FROM: JOHN L. DiMARTINO P.E., ASSISTANT COMMISSIONER
 DIRECTOR, BUREAU OF SEWERS
 SUBJECT: INTREPID MUSEUM - W46 St., Pier 86.
 Borough of Manhattan

We are in receipt of a report prepared by your division on April 17, 1982 concerning the 6'-6" x 8'-6" F.T.R.C. Double Barrel Overflow Sewer at the above referenced location.

The report recommended approximately 40 linear feet of the sewer in the vicinity of the above referenced project to be rehabilitated.

This memorandum is a formal request to proceed with the rehabilitation as outlined in the report

JOHN L. DiMARTINO P.E.
 Assistant Commissioner
 Director, Bureau of Sewers

Att.

cc: DiMartino
 Novotny
 Farag
 Lao
 UriHo
 Yee
 Lanzano
 Suspense

REL/ep

~~Relay~~
 Hold to this
 request now
 (as per T.M. instructions)
 MAY 5/11/82