

REPORT — STRUCTURAL FIRE

BF-24

TYPE REPORT				INCIDENT LOCATION				DATE AND TIME				INCIDENT DURATION				HOW REPORTED				BOX LOCATION				REPORT				COMPANIES RESPONDING				HAZ MAT				SPECIAL USE			
COMMUNITY BOARD	ADMIN COMPANY	MONTH	DAY	YEAR	HOUR	MINUTE	MINUTES	INITIAL ALARM	HIGHEST ALARM	BOROUGH	BOX NUMBER	INCIDENT NUMBER	REPORT NUMBER	FLIGHT BATTALION	ENG. SO. NUMBER	LADDER RES. H.M.	OTHERS	CLASS	AMOUNT	HEAT EQUIP. FUEL	1	2	3	REVISED REPORT															
1	01 5 010	05-25-87	2137	01:00	10	1	0	1	0	0084	0413	0454	01	113	03	02																							

AIDED AND CASUALTIES				EXTIN. GUISHMENT				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
EVACUATED	FIRST AID	INJURED	KILLED	UNINJURED	COPI	SPK. PERF.	COND. ON APPAR.	EQUIP. INVOL.	HEAT FORM	MATERIAL TYPE	FACTOR	JUVENILE	CONSTRUCT	USE	STATUS	COMPLEX	FLOOR CODE	OCCUPANCY	AREA OF ORIGIN	MANNER	NO. BLDGS.	% DAMAGED	FLAME	SMOKE	WATER	PRESENT	TYPE	POWER	PERFORMANCE	FOR INVESTIGATION	
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00

STREET NAME				TYPE				SUFFIX			
126				146				161			

BUILDING			
STORIES	WIDTH	LENGTH	AREA
47	0150	0400	161

DEFECTIVE DETECTOR	
BRAND	SERIAL NO.
162	177

NAME OF OCCUPANT	ROOM/APT.	YR.	MAKE
211	6 Floor		

(Security) Sean Merrit

EQUIPMENT INVOLVED IN IGNITION			
UNIT	PTS.	ITEM	POWER
266	272	278	284

W	R	I
5	010	05
5	007	05
5	006	05
7	010	05
7	001	05

OPERATIONS

Upon arrival to box 84 found the following conditions, fire was on the 6 floor in four separate areas. Companies operated via: L-1 raised tower ladder to gain entry and extinguish with cans. E-7 and E-6 stretchrd line via outside building to L-10 on the fire floor, L-10 completed extinguishment. L-10 assisted by L-1 in search checked the floors below then up. above

BC	BN	DC	PAGE
J. Spillane	2140		1 OF 1
TYPE FULL NAME		DIV.	
John J. Spillane		1	
TIME OF ARRIVAL		TIME OF ARRIVAL	
2140			
WHITE—FIRE RECORD		GOLD—ADMINISTRATIVE COMPANY	
YELLOW—BATTALION <td colspan="2">PINK—REFERRAL </td>		PINK—REFERRAL	

BF-24 (12/86)

REPORT - STRUCTURAL FIRE

TYPE REPORT				INCIDENT LOCATION				DATE AND TIME				INCIDENT DURATION				HOW REPORTED				BOX LOCATION				REPORT				COMPANIES RESPONDING				HAZ MAT				SPECIAL USE			
COMMUNITY BOARD	ADMIN COMPANY	MONTH	DAY	YEAR	HOUR	MINUTE	MINUTES	INITIAL ALARM	HIGHEST ALARM	BOROUGH	BOX NUMBER	REPORT NUMBER	INCIDENT NUMBER	FILE NUMBER	BATTALION	ENGINE	LADDER	RES. H.M.	OTHERS	CLASS	AMOUNT	HAZ MAT	SPECIAL USE	REVISOR	REVISOR	REVISOR	REVISOR	REVISOR	REVISOR										
1	01	5	010	06-25-87	2137	01:00	10	1	0	1	0084	0413	0454	01	113	03	02																						

AIDED AND CASUALTIES				EXTIN-GUISHMENT				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS							
EVACUATED	FIRST AID	INJURED	KILLED	UNINFORMED	INJURED	CODE	SPK. PER	COND. ON ARRIVAL	EQUIP INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL FORM	FACTOR	JUVENILE	CONSTRUCT	USE	STATUS	COMPLEX	FLOOR CODE	OCCUPANCY	AREA OF ORIGIN	MANNER	PANES	NO BLDG.	% DAMAGED	FLAME	SMOKE	WATER	PRESENT	TYPE	POWER	PERFORMANCE	FOR INVESTIGATION		
00	00	00	00	5	0	1	3	15	63	15	21	0	1	591	6	59	01	00	81	01	01	0	0	1	1	1	0	0	0	0	0	0	0	0	0

BF-24

ADDRESS				STREET NAME				TYPE				SUFX DIRECT			
BORO	NUMBER (INCL. HYPHEN)	SUFFIX	DIRECTION	STREET NAME	TYPE	SUFX	DIRECT	STREET NAME	TYPE	SUFX	DIRECT	STREET NAME	TYPE	SUFX	DIRECT
1	7														

OPERATIONS

EQUIPMENT INVOLVED IN IGNITION				LEFT IN CHARGE				SERIAL NUMBER				POWER			
NAME OF OCCUPANT	ROOM/APT.	YR.	MAKE	MODEL	SERIAL NUMBER	POWER	DEFECTIVE DETECTOR	BRAND	SERIAL NO.	BADGE NO.	DEFECTIVE DETECTOR	BRAND	SERIAL NO.	BADGE NO.	

UNIT	PTS.	ITEM	212	214	216	218	220	222	224	226	228	230	232	234	236	238	240	242	244	246	248	250	252	254	256	258	260	262	264	
W	5	010	05	5	007	05	5	006	05	7	010	05	7	001	05															

Upon arrival to box 84 found the following conditions, fire was on the 6 floor in four separate areas. Companies operated via:
 L-11 raised tower ladder to gain entry and extinguish with cans.
 L-7 and L-6 stretched line via outside building to L-10 on the first floor, L-10 completed extinguishment.
 L-10 assisted by L-1 in search checked the floors below then up. above

BC	BN	DC	TYPE FULL NAME	TIME OF ARRIVAL	WHITE-FIRE RECORD	YELLOW-BATTALION	PINK-REFERRAL	GOLD-ADMINISTRATIVE COMPANY	PAGE	OF
J. Spillane	2140								1	1

TYPE FULL NAME	TIME OF ARRIVAL	WHITE-FIRE RECORD	YELLOW-BATTALION	PINK-REFERRAL	GOLD-ADMINISTRATIVE COMPANY

REPORT - STRUCTURAL FIRE

TYPE REPORT	INCIDENT LOCATION		DATE AND TIME		ALARM RECEIVED		INCIDENT DURATION		BOX LOCATION		REPORT		COS. RESP.						
	ADMIN. COMPANY	BLOCK NUMBER	MONTH	DAY	YEAR	HOUR	MINUTE	MINUTES	HIGHEST ALARM	BOX NUMBER	REPORT NUMBER	FILE NUMBER	ENGINE NUMBER	LADDER					
1	01	010	0026	12	31	35	0643	01	10	2	1	0	1	0084	0401	01	075	02	2

AIDED AND CASUALTIES				EXTINGUISHMENT				IGNITION				STRUCTURE				AREA FIRE ORIGIN				FIRE EXTENSION				SPECIAL USE											
CIVILIANS				SPRINKLER				MATERIAL TYPE				STATUS				FLOOR CODE				MANNER OF				NO. BLOBS				SMOKE DETECTORS							
KILLED				EQUIP INVOLVED				HEAT FORM				CONSTRUCT				CONTS. DMG				OCCUPANCY				OCCUPANTS				WITHIN BLDG.							
INJURED				TERMS USED				MATERIAL FORM				USE				BUDG. DAMAGE				RM/AREA CODE				FIRE EXT. ORIGIN				SPECIAL USE							
FIRST AID				SPRINKLER				MATERIAL FORM				CONSTRUCT				BUDG. DAMAGE				FLOOR CODE				MANNER OF				OCCUPANTS				WITHIN BLDG.			
UNINJURED				SPRINKLER				MATERIAL FORM				CONSTRUCT				BUDG. DAMAGE				FLOOR CODE				MANNER OF				OCCUPANTS				WITHIN BLDG.			
CODE				SPRINKLER				MATERIAL FORM				CONSTRUCT				BUDG. DAMAGE				FLOOR CODE				MANNER OF				OCCUPANTS				WITHIN BLDG.			
INJURED				SPRINKLER				MATERIAL FORM				CONSTRUCT				BUDG. DAMAGE				FLOOR CODE				MANNER OF				OCCUPANTS				WITHIN BLDG.			
UNINJURED				SPRINKLER				MATERIAL FORM				CONSTRUCT				BUDG. DAMAGE				FLOOR CODE				MANNER OF				OCCUPANTS				WITHIN BLDG.			
CODE				SPRINKLER				MATERIAL FORM				CONSTRUCT				BUDG. DAMAGE				FLOOR CODE				MANNER OF				OCCUPANTS				WITHIN BLDG.			

ADDRESS		STREET NAME		TYPE		SUITE		DIRECT		BUILDING		AREA	
96		104		106		126		130		132		137	
10		10		10		10		10		10		10	

NAME OF OCCUPANT	ROOM, APT. NO.	YR.	MAKE	MODEL	S/N	POWER

EQUIPMENT INVOLVED IN IGNITION

UNIT	PTS.	ITEM	188	194	200	206	212	217
0	0	0	0	0	0	0	0	0

OPERATIONS

Received report of fire on 4th floor of building under construction. Upon arrival found fire on 2nd floor in construction equipment, workmen shanty, propane cylinders and various construction material. Heavy fire and smoke throughout. Fire cause by worker accidentally spilling a combustible adhesive next to a propane heater. Units operated VLM:
L. 10 stretched 1 1/2" line to fire via stair, extinguished fire and assisted in overhauling as necessary. Then up.
L. 1 made necessary search of fire floor forced entry to adjoining shanty, opened with saw the two workmen tool boxes on floor. Overhauled then up.
L. 7 assisted L. 10 then stretched 2 1/2" backing line stood fast, then up.
L. 10 made search of 4th floor. Found no extension. Then up.

B.C.	Ludol h. J. Quatrone		0645	TIME OF ARRIVAL		TYPE FULL NAME		TIME OF ARRIVAL		PAGE		OF	

REPORT — STRUCTURAL FIRE

INCIDENT LOCATION		DATE AND TIME		ALARM RECEIVED		INCIDENT DURATION		BOX LOCATION		REPORT		COS. RESP.	
ADMIN. COMPANY	BLOCK NUMBER	YEAR	MONTH	DAY	HOUR	MINUTE	MINUTES	HIGHEST ALARM	BOX NUMBER	REPORT NUMBER	BATTALION	ENGINE	RESP.
101	0026	12	31	35	06	43	01	2	1	0	1	0004	01 075 02 2

AIDED AND CASUALTIES				EXTINGUISHMENT				IGNITION				STRUCTURE				AREA FIRE ORIGIN				FIRE EXTENSION				SPECIAL USE			
EVAQUATED	FIRST AID	INJURED	KILLED	UNIFORMED	INJURED	CODE	SPRINKLER	STANDPIPE	NO. OPEN	TERMS USED	EQUIP INVOLVED	HEAT FORM	MATERIAL TYPE	CONSTRUCT	USE	STATUS	BLDG DAMAGE	FLOOR CODE	RM AREA CODE	OCCUPANCY	MANNER OF	OCCUPANTS	NO. BLDGS	SMOKE DETECTORS	SPECIAL USE		
46	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00		

STREET NAME		TYPE	
104	106	126	130
104	106	126	130

NAME OF OCCUPANT		ROOM, APT. NO.		YR.		MAKE		MODEL		S/N		POWER	
LEFT IN CHARGE		132		134		134		134		134		134	

UNIT	PTS.	ITEM
101	102	103
104	105	106
107	108	109
110	111	112
113	114	115
116	117	118
119	120	121
122	123	124
125	126	127
128	129	130
131	132	133
134	135	136
137	138	139
140	141	142
143	144	145
146	147	148
149	150	151
152	153	154
155	156	157
158	159	160
161	162	163
164	165	166
167	168	169
170	171	172
173	174	175
176	177	178
179	180	181
182	183	184
185	186	187
188	189	190
191	192	193
194	195	196
197	198	199
200	201	202
203	204	205
206	207	208
209	210	211
212	213	214
215	216	217
218	219	220
221	222	223
224	225	226
227	228	229
230	231	232
233	234	235
236	237	238
239	240	241
242	243	244
245	246	247
248	249	250
251	252	253
254	255	256
257	258	259
260	261	262
263	264	265
266	267	268
269	270	271
272	273	274
275	276	277
278	279	280
281	282	283
284	285	286
287	288	289
290	291	292
293	294	295
296	297	298
299	300	301
302	303	304
305	306	307
308	309	310
311	312	313
314	315	316
317	318	319
320	321	322
323	324	325
326	327	328
329	330	331
332	333	334
335	336	337
338	339	340
341	342	343
344	345	346
347	348	349
350	351	352
353	354	355
356	357	358
359	360	361
362	363	364
365	366	367
368	369	370
371	372	373
374	375	376
377	378	379
380	381	382
383	384	385
386	387	388
389	390	391
392	393	394
395	396	397
398	399	400

OPERATIONS

Received report of fire on 4th floor of building under construction. Upon arrival found fire on 3rd floor in construction equipment, workman shanty, propane cylinders and various construction material. Heavy fire and smoke throughout. Fire cause by worker accidentally spilling a combustible adhesive next to a propane heater. Units operated VLM:

1. 10 stretched 1 1/2" line to fire via stair, extinguished fire and assisted in overhauling as necessary. Then up.

1. 1 made necessary search of fire floor forced entry to adjoining shanty, opened with saw the two workmen tool boxes on floor. Overhauled then up.

1. 7 assisted 1. 10 then stretched 2 1/2" backup line stood fast, then up.

1. 10 made search of 4th floor. Found no extension. Then up.

TYPE FULL NAME		TIME OF ARRIVAL		PAGE	
101	102	103	104	105	106
107	108	109	110	111	112
113	114	115	116	117	118
119	120	121	122	123	124
125	126	127	128	129	130
131	132	133	134	135	136
137	138	139	140	141	142
143	144	145	146	147	148
149	150	151	152	153	154
155	156	157	158	159	160
161	162	163	164	165	166
167	168	169	170	171	172
173	174	175	176	177	178
179	180	181	182	183	184
185	186	187	188	189	190
191	192	193	194	195	196
197	198	199	200	201	202
203	204	205	206	207	208
209	210	211	212	213	214
215	216	217	218	219	220
221	222	223	224	225	226
227	228	229	230	231	232
233	234	235	236	237	238
239	240	241	242	243	244
245	246	247	248	249	250
251	252	253	254	255	256
257	258	259	260	261	262
263	264	265	266	267	268
269	270	271	272	273	274
275	276	277	278	279	280
281	282	283	284	285	286
287	288	289	290	291	292
293	294	295	296	297	298
299	300	301	302	303	304
305	306	307	308	309	310
311	312	313	314	315	316
317	318	319	320	321	322
323	324	325	326	327	328
329	330	331	332	333	334
335	336	337	338	339	340
341	342	343	344	345	346
347	348	349	350	351	352
353	354	355	356	357	358
359	360	361	362	363	364
365	366	367	368	369	370
371	372	373	374	375	376
377	378	379	380	381	382
383	384	385	386	387	388
389	390	391	392	393	394
395	396	397	398	399	400