

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 10/23/08	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # A062
Inspector M. Gagnidze		Building Type F		Basis of Inspection TRU0086MN08		Photos Taken yes
Contractor's Name LVI Environmental				Sample Number -----		
Address City				Sample Number -----		
State Zip Phone				Sample Number -----		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address City 1340 Broadway New York				Address City One Liberty Plaza New York		
State Zip Phone NY 10018				State Zip Phone NY 10006 (212) 962-2300		
Contact Person Arnel Javal, Sr. Proj. Mgr/TRC Environmental				Time of Inspection from: 8:30 am to 10:05 am		

I arrived at the premise at 8:30 am. LVI schedule informed that activities include clean work area – North vestibule on 19th floor, prep area, cut walker ducts, raceways, clean work areas – South Comp Bay on 15th floor, scrape areas 11-13, box debris, Eagle putting platform across shafts on 11th floor, clear off floor, move debris on 10th floor.

I used north hoist to go to the 16th floor, I proceeded to the decon, followed all precautions necessary and left decon; using stairs I went to 19th floor.

19th Floor – 5 workers were on scaffolds inside the work area, cleaning the ceiling, beams. I observed 3 holes on ceiling; supervisor was advised to cover the holes. Three micro trap machines were powered on.

I proceeded to the decon, followed all precautions necessary and using stairs went to 15th floor.

15th Floor – 5 workers were on 2 scaffolds cutting raceways, spraying with amended water, 5 asbestos waste bags were on the floor ready for load out. Three holes were observed on the ceiling; supervisor covered them with duct tape. 3 micro trap machines were powered on.

After following the decontamination procedure I signed the log book and used north hoist to go to 10th floor.

I went to the decon on 10th floor, signed log book, donned personal protection, left decon and using B stairs went to 11th floor.

11th Floor – 20 workers were in a process of scraping fireproofing in the areas 11-13, plasticizing, cleaning the platform, placing debris into the plastic asbestos waste bags, preparing boxes, replacing the filters of micro trap machines. Inspection was done on micro trap tents.

I used B stairs to get to the 10th floor.

10th Floor – 8 workers were present on the floor. Workers were covering the shaft area with poly. 20 micro trap machines were powered on and 5 on stand by.

After following the decontamination procedure I signed the log book and used north hoist to go back to the ground floor.

Inspection was done on ATC trailer.

NOV #	Infraction	Infraction	Infraction	Infraction
NOV #	Infraction	Infraction	Infraction	Result Code 2
NOV #	Infraction	Infraction	Infraction	Supervisor's Initial <i>ny</i>

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property