

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 10/22/08	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # A062
Inspector M.Gagnidze		Building Type F		Basis of Inspection TRU0086MN08		Photos Taken yes
Contractor's Name LVI Environmental				Sample Number -----		
Address City				Sample Number -----		
State Zip Phone				Sample Number -----		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address 1340 Broadway		City New York		Address One Liberty Plaza		City New York
State NY	Zip 10018	Phone		State NY	Zip 10006	Phone (212) 962-2300
Contact Person Arnel Javal, Sr. Proj. Mgr/TRC Environmental				Time of Inspection from: 8:30 am to 10:00 am		
<p>I arrived at the premise at 8:30 am. LVI schedule informed that activities include cut walker ducts and raceways in north vestibule on 19th floor, clean work areas in South Comp Bay on 17th and 16th floors, prep area, cut walker ducts on 15th floor.</p> <p>I used north hoist to go to the 16th floor. I proceeded to the decon, followed all precautions necessary and left decon; using stairs I went to the 19th floor.</p> <p>19th Floor – 8 workers were present on the floor outside the decon ready to begin the work – prepare the decon and work site for cutting the raceways and walker ducts. Entering the work area I observed that one micro trap machine was powered off. I advised the handlers' supervisor to inspect the machine.</p> <p>Using stairs I went to the 17th floor, proceeded to the decon and entered containment.</p> <p>17th Floor – 8 workers were working on the floor in South Comp Bay area. Workers on 1 scaffolds were cutting raceways, removing walker ducts and cleaning from debris, placing into the black asbestos waste bags, cleaning, vacuuming the floor; spraying around with amended water. I observed a numerous holes on the floor and ceiling, still not covered since last inspection.</p> <p>I advised Handler Supervisor to direct workers to cover the holes. 3 micro trap machines were powered on. After following the decontamination procedure I signed the log book and used stairs to go to 16th floor.</p> <p>16th Floor – 8 people were present on the floor in South Comp Bay area. Workers were cleaning the ceiling, beams, walker ducts with vacuum, 10 asbestos waste bags were in the work area ready for load out, cleaning the floor, spraying with amended water. I observed filters were dirty; worker was advised to he replace them with new filters, which was done immediately. Three micro trap machines were powered on.</p> <p>After following the decontamination procedure I signed the log book and used stairs to go to 15th floor.</p> <p>15th Floor – No activities or personnel observed on the floor.</p> <p>I used stairs to go to the 16th floor. Using north hoist I went back to the ground floor.</p> <p>Inspection was done on ATC trailer.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction	Infraction	
NOV #	Infraction	Infraction	Infraction	Infraction	Result Code 2	
NOV #	Infraction	Infraction	Infraction	Infraction	Supervisor's Initial <i>mg</i>	

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property