


Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 08/16/08	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # AO61
Inspector H. Guirguis		Building Type A		Basis of Inspection TRU0086MN08		Photos Taken Yes
Contractor's Name LVI Environmental				Sample Number _____		
Address _____ City _____				Sample Number _____		
State _____ Zip _____ Phone _____				Sample Number _____		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address _____ City _____ 1430 Broadway New York				Address _____ City _____ One Liberty Plaza New York		
State _____ Zip _____ Phone _____ NY 10018				State _____ Zip _____ Phone _____ NY 10006 (212) 962-2300		
Contact Person Arnel Javal, Sr. Proj. Mgr./TRC Environmental				Time of Inspection from: 10:00 am – 11:00 am		
<p>On arrival I met Victor, Supervisor for TRC Environmental, at the TRC field office. Who informed me that a total of 1 Handler Supervisor and 26 Asbestos Handlers were on the 10th floor today for the first shift</p> <p>The daily work schedule informed me of the following:</p> <ol style="list-style-type: none"> 1. 14th & 15th floors: 34 men (each) cutting walker duct & raceways, boxing debris. 2. 13th & 12th floors: 30 men (each) demo, boxing debris 3. 10th floor: 26 men – demo, boxing debris. 4. Various floors : 8 men loading out boxes to ATC trailer <p>I went to the decontamination enclosure system on the 10th floor and after signing the log book, donned personal protection and accessed the work areas.</p> <ol style="list-style-type: none"> 1. 10th floor: 26 workers were found in the process of demo, boxing debris; there was still a lot of wet debris on the floor, demolition was not completed in all areas, Inspection was done on the Micro trap Machines and the Micro trap tents and on all the work area, 16 workers removing debris from the floor, 3 workers fine spraying amended water in the work area, 2 workers were using power tools, HEPA vacuum attached with the power tools, 3 workers Preparing Gaylord boxes, 2 workers were inspecting the critical barriers and re-sealing with duct tape 18 Gaylord boxes and numerous poly wrapped beams were on the floor ready to be taken out 2. 11th floor: There was no activity or personnel observed on the floor. Inspection was done on the Micro trap Machines and the Micro trap tents and on all the work area <p>I exited the work area after decontaminating myself and signing the log book.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction	Infraction	
NOV #	Infraction	Infraction	Infraction	Infraction	Result Code 2	
NOV #	Infraction	Infraction	Infraction	Infraction	Supervisor's Initial 	

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property