

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 09/05/08	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # A062
Inspector M. Gagnidze		Building Type A		Basis of Inspection TRU0086MN08		Photos Taken no
Contractor's Name LVI Environmental				Sample Number -----		
Address City				Sample Number -----		
State Zip Phone				Sample Number -----		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address 1340 Broadway		City New York		Address One Liberty Plaza		City New York
State Zip Phone NY 10018		State Zip Phone NY 10006		Phone (212) 962-2300		
Contact Person Arnel Javal, Sr. Proj. Mgr/TRC Environmental				Time of Inspection from: 5:10 pm to 6:15 pm		
<p>I arrived at the premise at 5:10 pm. LVI informed that scheduled activities include fine cleaning on the 15th and 14th floors, and demolition, boxing debris, cut raceway on 13th floor.</p> <p>I entered the decon area, suit up, don respirator and entered containment on 15th floor. Two workers were present cleaning in decontamination enclosure system.</p> <p>15th Floor – 25 workers were observed on site. Three electricians were found working in electrical room, wrapping electrical wires with poly. Eight workers were on platform cleaning beams and columns in the shaft area, 4 workers were in the process of putting rails to construct the platform between the electrical room and shaft area. Three workers on the west side of the area were cleaning the floor. Five Gaylord boxes were ready for load out. Inspection was done on micro trap machines and micro trap tents – air monitoring pumps were on. 20 Micro trap machines were powered on and 5 were on stand by. I used B stairwell to proceed to the 14th Floor.</p> <p>14th Floor – Twenty five workers were present on the floor, cleaning beams and ceiling on the west side of working area. Eight workers on 4 scaffolds were observed cleaning and scraping beams around the shaft area. Additional workers were cleaning the floors around the work areas and vacuuming up the water from the ceiling cleaning. One worker was observed on ladder working with a hammer. Worker was fine spraying amended water in the work area. 2 other workers were found in the process of preparing the boxes. 7 Gaylord boxes were ready for load out. 20 micro trap machines were powered on and 5 were on stand by. Inspection was done on micro trap tents. I used B stairwell to proceed to the 15th Floor.</p> <p>13th Floor – Was no activity or personnel observed on the floor. I used B stairwell to go back to the 14th Floor, proceeded to the decon, Showered out and signed the log book. I returned to the ground floor using the north hoist. Inspection was done on ATC trailer.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction		
NOV #	Infraction	Infraction	Infraction	Infraction	Result Code 2	
NOV #	Infraction	Infraction	Infraction	Infraction	Supervisor's Initial <i>ny</i>	

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property