


Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 08/02/08	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # AO61
Inspector H. Guirguis		Building Type A		Basis of Inspection TRU0086MN08		Photos Taken Yes
Contractor's Name LVI Environmental				Sample Number -----		
Address City				Sample Number -----		
State Zip Phone				Sample Number -----		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address 1430 Broadway		City New York		Address One Liberty Plaza		City New York
State Zip NY 10018		Phone		State Zip NY 10006		Phone (212) 962-2300
Contact Person Arnel Javal, Sr. Proj. Mgr./TRC Environmental				Time of Inspection from: 10:30 am – 11:30 am		
<p>On arrival I met Victor, Supervisor for TRC Environmental at the TRC field office, who informed me that a total of 1 Handler Supervisor and 30 Asbestos Handlers were on the 16th floor for the first shift.</p> <p>The daily work schedule informed me of the following:</p> <ol style="list-style-type: none"> 1. 16th & 17th floors: 30 men (each) fine cleaning floors. 2. 14th & 15th floors: 22 men (each) scraping, boxing debris. 3. 13th & 12th floors: 22 men (each) demo, boxing debris 4. Various floors : 6 men loading out boxes to ATC trailer <p>I went to the decontamination enclosure system on the 16th floor and after signing the log book, donned personal protection and accessed the work areas.</p> <ol style="list-style-type: none"> 1. 16th floor: I met Hitler Giraldo the handler supervisor. 30 workers were found in the process of fine cleaning floors, 17 workers cleaning the floors with amended water and HEPA vacuuming the floor in preparation for final inspection, 4 workers fine spring amended water in the work area, 2 workers on ladders fine cleaning the beams and wet wiping the walls, 3 workers cleaning scaffold parts and preparing them to be taken out, 3 workers preparing Gaylord boxes, 21 Gaylord boxes on the floor ready to be taken out. Inspection was done on the Micro trap Machines and the Micro trap tents, 20 Micro trap Machines were powered on and 5 on stand by The negative pressure was 0.056 I used the stairs to get to the 17th floor 2. 17th floor: I met Jose Jimenes the handler supervisor. 30 workers were found in the process of fine cleaning floors, 15 workers cleaning the floors with amended water and HEPA vacuuming the floor in preparation for final inspection, 6 workers fine spring amended water in the work area, 4 workers wet wiping the walls, 3 workers cleaning scaffold parts and preparing them to be taken out, 2 workers preparing Gaylord boxes, 21 Gaylord boxes on the floor ready to be taken out. I observed open ends of the poly sheets covering the floors and the beams, the supervisor was advised and he told two workers to re-seal all the ends with duct tape Inspection was done on the Micro trap Machines and the Micro trap tents, 20 Micro trap Machines were powered on and 5 on stand by 3. I used the stairs to go back to the 16th floor. <p>I exited the work area after decontaminating and signing the log book.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction		
NOV #	Infraction	Infraction	Infraction	Infraction	Result Code 2	
NOV #	Infraction	Infraction	Infraction	Infraction	Supervisor's Initial 	

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property