

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 05/11/09	
Floor 1 st Fl	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # A062
Inspector M.Gagnidze		Building Type F		Basis of Inspection TRU2068MN08		Photos Taken yes
Contractor's Name LVI Environmental Services Inc.				Sample Number _____		
Address 462 Gerry Ave				City Clifton		
State NJ				Zip 07011		
Phone (973) 772-3660				Sample Number _____		
Third Party Air Monitor TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address 1340 Broadway				City New York		
State NY				Zip 10018		
Phone (212) 221-7822				State NY		
Zip 10006				Phone (212) 962-2300		
Contact Person Arnel Javal, Sr. Proj. Mgr/TRC Environmental				Time of Inspection from: 5:30 pm to 6:10 pm		
<p>I entered the premise at 5:30 pm. LVI schedule informed that activities include: Clear floor, demo & wrap metal, load out on 1st floor.</p> <p>I proceeded to the decon, signed the log book, don the appropriate level of personal protective equipment to enter the regulated area on 1st floor. Two workers were present for the decon maintenance, cleaning shower chambers and organizing the clean room. Negative air pressure was -0.031.</p> <p>1st Floor – 30 workers were found inside the work area. Two workers on mezzanine at the north/west side work area were cleaning off the floor, picking up debris, metal pieces, placing into the boxes and spraying with amended water.</p> <p>Two workers were cutting metal into small pieces using equipment equipped with HEPA filter at the north/east side, another worker was spraying with water around the area. A large amount of debris exists on the floor. Workers at the south side area were wrapping beams with poly. Others were replacing filters of micro trap machines, preparing, wrapping and loading out sealed and sprayed boxes through the north side waste decon. 18 Gaylord boxes were ready for load out. 35 micro trap machines were powered on and 5 on stand by. Inspection was done on micro trap tents.</p> <p>I observed that:</p> <ol style="list-style-type: none"> 1. Main layer of the exhaust duct, connected to one of the micro traps at the south side work area was broken and needed to be repaired; 2. HEPA vacuum was attached to the electrical tool, but was not powered on, while the worker was cutting metal into the pieces at the <u>south side work area</u>. Supervisor was informed, who then powered on the HEPA vacuum immediately. 3. First main layer of poly inside tent located at the north/east side area was detached from the ceiling of the tent and was hanging down. <p>I met Julio Valero Handler Supervisor inside the work area to advise him to:</p> <ol style="list-style-type: none"> 1. Conduct emergency repair of exhaust duct, which was repaired immediately; 2. Re-tape poly inside the tent – Supervisor directed two workers to repair the tent in concern; 3. Advise handlers to use equipment properly – Usage of HEPA vacuum during cutting operations. <p>Photos has been taken and attached to the Inspection Report.</p> <p>After following the decontamination procedure I signed the log book and left the decon. Inspection was done on ATC trailer.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction	Infraction	
NOV #	Infraction	Infraction	Infraction	Infraction	Result Code 2	
NOV #	Infraction	Infraction	Infraction	Infraction	Supervisor's Initial 	

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property