

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 04/01/09	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # A062
Inspector M.Gagnidze		Building Type F		Basis of Inspection TRU2068MN08		Photos Taken yes
Contractor's Name LVI Environmental				Sample Number _____		
Address City				Sample Number _____		
State Zip Phone				Sample Number _____		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address 1340 Broadway		City New York		Address One Liberty Plaza		City New York
State NY	Zip 10018	Phone		State NY	Zip 10006	Phone (212) 962-2300
Contact Person Arnel Javal, Sr. Proj. Mgr/TRC Environmental				Time of Inspection from: 10:30 pm to 11:30 pm		
<p>I entered the premise at 10:30 pm. LVI schedule informed that activities include: demo walls, ceilings, ducts on 1st floor.</p> <p>I proceeded to the decon, signed the log book, don the appropriate level of personal protective equipment to enter the regulated area on 1st floor. Four workers were present for the decon maintenance, cleaning shower chambers and organizing the clean room. Negative air pressure was -0.028.</p> <p>1st Floor – 78 workers were present inside the work area. Two damaged exhaust ducts, that I observed during my earlier inspection, were repaired. Demolition of the equipments and installations inside the former computer room was not completed, workers were cutting and removing conduit using equipment equipped with HEPA filters.</p> <p>Workers on mezzanines at the various locations were cutting and removing air ducts, spraying with amended water, placing debris into the boxes.</p> <p>Workers harnessed in scissor lifts were cutting metal fixtures from the ceiling, spraying with amended water.</p> <p>Other workers were: cutting metal into small pieces at the various locations, placing into the boxes and spraying; wrapping beams with poly, loading out sealed and sprayed boxes through the north side waste decon. A large amount of debris and poly wrapped beams still exists on the floor.</p> <p>Still 55 Gaylord boxes were on the floor ready for load out. 35 micro trap machines were powered on and 5 on stand by. Inspection was done on micro trap tents.</p> <p>After following the decontamination procedure I signed the log book and left the decon.</p> <p>Inspection was done on ATC trailer.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction	Infraction	
NOV #	Infraction	Infraction	Infraction	Infraction	Result Code 2	
NOV #	Infraction	Infraction	Infraction	Infraction	Supervisor's Initial <i>my</i>	

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property