

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 09/25/08	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # AO61
Inspector H. Guirguis		Building Type A		Basis of Inspection TRU0086MN08		Photos Taken
Contractor's Name LVI Environmental				Sample Number -----		
Address City				Sample Number -----		
State Zip Phone				Sample Number -----		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address City 1430 Broadway New York				Address City One Liberty Plaza New York		
State Zip Phone NY 10018				State Zip Phone NY 10006 (212) 962-2300		
Contact Person Arnel Javal, Sr. Proj. Mgr./TRC Environmental				Time of Inspection from: 05:00pm - 06:30pm		
<p>On arrival I met Nugent Gerald, Supervisor for LVI Environmental at the LVI field office, who informed me that a total of 1 Handler Supervisor and 36 Asbestos Handlers were on the 9th floor today for the second shift.</p> <p>The daily work schedule informed me of the following:</p> <ol style="list-style-type: none"> 1. 19th & 18th floors: 8 men (each) - prep decon & work area North vestibule 2. 15th & 14th floors: 12 men (each)- breakdown, encapsulate 3. 13th floor: 36 men- scraping, boxing debris, cut raceways. 4. 11th floor: 14 men- demo, boxing debris. 5. 09th & 8th floors: 20 men (each)- demo, boxing debris 6. Various floors : 14 men loading out boxes to ATC trailer <p>After signing the log book donned personal protection I entered the work areas.</p> <p>10th floor: No workers present, Gaylord boxes and numerous poly wrapped beams were at various locations on the floors ready to be taken out. Inspection was done on the Micro trap Machines and the Micro trap tents and on all the work area.</p> <ol style="list-style-type: none"> 1. 9th floor: 25 workers were found in the process of Demo, boxing debris; there was still a lot of wet debris on the floor, demolition was not completed, workers were cutting metals using power tools, HEPA vacuum attached with the power tools, fine spraying amended water in the work area, preparing Gaylord boxes and wrapping beams, windows and windows framing. Gaylord boxes and numerous poly wrapped beams were at various locations on the floor ready to be taken out Inspection was done on the Micro trap Machines and the Micro trap tents and on all the work area. 2. 8th floor: 17 workers were found in the process of Demo, boxing debris; there was still a lot of wet debris on the floor, demolition was not completed, workers were cutting metals using power tools, HEPA vacuum attached with the power tools, fine spraying amended water in the work area, preparing Gaylord boxes and wrapping beams and cabinets. Gaylord boxes and numerous poly wrapped beams were at various locations on the floor ready to be taken out Inspection was done on the Micro trap Machines and the Micro trap tents and on all the work area. 3. I used the stairs to go back to the 9th floor. <p>I exited the work area after decontaminating myself and signing the log book.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction		
NOV #	Infraction	Infraction	Infraction	Result Code 2		
NOV #	Infraction	Infraction	Infraction	Supervisor's Initial <i>ny</i>		

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property