

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 06/08/09	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # A062
Inspector M.Gagnidze		Building Type F		Basis of Inspection TRU2068MN08		Photos Taken yes
Contractor's Name LVI Environmental				Sample Number -----		
Address City				Sample Number -----		
State Zip Phone				Sample Number -----		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address City 1340 Broadway New York				Address City One Liberty Plaza New York		
State Zip Phone NY 10018				State Zip Phone NY 10006 (212) 962-2300		
Contact Person Amel Javal, Sr. Proj. Mgr/TRC Environmental				Time of Inspection from: 11:10 pm to 12:00 pm		

I arrived at the premise at 11:10 pm. LVI schedule informed that activities include: clear floor, scrape fireproofing, demo, load out on 1st floor.

I proceeded to the decon, signed the log book, don the appropriate level of personal protective equipment to enter the regulated area on 1st floor.
Two workers were present for the decon maintenance, cleaning shower chamber and organizing the clean room.
Negative air pressure on the floor was -0.031.

1st Floor – 53 Workers were inside the work area, cutting metal panels from the column using equipment equipped with HEPA vacuum; demolishing the wall of shaft located at the north/west side, spraying with amended water; still scraping the fireproofing at the area #5: cleaning the floor of mezzanine, picking up debris, placing into the boxes; workers on scaffolds at the extended area were scraping the ceilings, vertical and horizontal beams, column.
Others were cleaning the floor from debris, washing scaffolds and equipment, spraying the area with amended water, preparing and loading out boxes through the waste decon.
5 Gaylord boxes were on the floor ready for load out.
40 micro trap machines were on and 5 on stand by. Inspection was done on micro trap tents.

At the east side of the area I **observed that main layer of exhaust duct at the east side area were cut off**. I took photos, then Handler Supervisor Victor was advised, he immediately directed workers exhaust ducts were repaired in concern.

After following the decontamination procedure I exited the work area.
Inspection was done on ATC trailer.

NOV #	Infraction	Infraction	Infraction	Infraction
NOV #	Infraction	Infraction	Infraction	Result Code 2
NOV #	Infraction	Infraction	Infraction	Supervisor's Initial <i>VJA</i>

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property