

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 05/13/09	
Floor 1 st Fl	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # A062
Inspector M.Gagnidze		Building Type F		Basis of Inspection TRU2068MN08		Photos Taken yes
Contractor's Name LVI Environmental Services Inc.				Sample Number -----		
Address 462 Gerry Ave		City Clifton		Sample Number -----		
State NJ	Zip 07011	Phone (973) 772-3660		Sample Number -----		
Third Party Air Monitor TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address 1340 Broadway		City New York		Address One Liberty Plaza		City New York
State NY	Zip 10018	Phone (212) 221-7822		State NY	Zip 10006	Phone (212) 962-2300
Contact Person Arnel Javal, Sr. Proj. Mgr/TRC Environmental				Time of Inspection from: 10:30 pm to 11:30 pm		
<p>I entered the premise at 10:30 pm. LVI schedule informed that activities include: Clear floor, demo & wrap metal, load out on 1st floor.</p> <p>I proceeded to the decon, signed the log book, don the appropriate level of personal protective equipment to enter the regulated area on 1st floor. Two workers were present for the decon maintenance, organizing the clean room. Negative air pressure was -0.039.</p> <p>1st Floor – 30 Asbestos Handlers were inside the work area. Workers at the north/west side area were in the process of picking up debris from the floor, placing into the boxes, cleaning the floor using mops. At the north side near the decon workers were HEPA vacuuming excessive water accumulation, drying the floor at the north/east side area using cloths, mops and other cleaning aids. Workers were observed at the west side near former electrical room filling holes and ditches with concrete, filling up the holes from pipes to the basement with foam, plasticizing the edges at the east side beams, plasticizing the floor at the west side vestibule.</p> <p>Others were preparing, wrapping and loading out sealed and sprayed boxes through the north side waste decon. 30Gaylord boxes were ready for load out. 35 micro trap machines were powered on and 5 on stand by. Inspection was done on micro trap tents.</p> <p>I observed that Asbestos Handler, who identified himself as Sean, was not wearing hood while working – clearing the floor from debris. I took the photo and advised him to wear suit appropriately. Worker immediately covered head with hood.</p> <p>After following the decontamination procedure I signed the log book and left the decon. Inspection was done on ATC trailer.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction	Infraction	
NOV #	Infraction	Infraction	Infraction	Infraction	Result Code 2	
NOV #	Infraction	Infraction	Infraction	Infraction	Supervisor's Initial 	

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 S=Public Owned Property