

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 04/28/09	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # A062
Inspector M.Gagnidze		Building Type F		Basis of Inspection TRU2068MN08		Photos Taken yes
Contractor's Name LVI Environmental				Sample Number -----		
Address City				Sample Number -----		
State	Zip	Phone		Sample Number -----		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address 1340 Broadway		City New York		Address One Liberty Plaza		City New York
State	Zip	Phone		State	Zip	Phone
NY	10018			NY	10006	(212) 962-2300
Contact Person Arnel Javal, Sr. Proj. Mgr/TRC Environmental				Time of Inspection from: 8:50 am to 9:45 am		
<p>I entered the premise at 8:50 am. LVI schedule informed that activities include: Clear floor, cut ducts, demo walls, ceilings on 1st floor.</p> <p>I proceeded to the decon, signed the log book, don the appropriate level of personal protective equipment to enter the regulated area on 1st floor. Two workers were present for the decon maintenance, cleaning shower chambers and organizing the clean room. Negative air pressure was -0.023.</p> <p>1st Floor – 75 workers were present inside the work area. Two workers on the north/east side of the work area, harnessed in scissor lifts and other workers on mezzanine demolishing drop ceiling, cutting metal fixtures, spraying with amended water during demo. On mezzanines at the south side and south/west side locations workers were demolishing the brick wall and spraying with amended water, breaking down hard drop ceiling, spraying with amended water, placing debris into the boxes.</p> <p>Other workers were: cutting metal into small pieces at the various locations, placing into the boxes and spraying; wrapping beams with poly, loading out sealed and sprayed boxes through the north side waste decon. 30 Gaylord boxes were ready for load out. 35 micro trap machines were powered on and 5 on stand by. Inspection was done on micro trap tents.</p> <p>I observed that: 1. Main layer of the exhaust duct, connected to one of the micro traps on South side was broken and needed to be repaired; 2. Tree light bulbs inside the former computer storage room were used not properly: one was hanging without any protection and two others had broken cages. I met Jose - LVI Supervisor – inside the work area to advise him to: 1. conduct emergency repair of exhaust duct, which was repaired immediately; 2. Contact Platinum Electrician for immediate protection cages repair. Photos had been taken and attached to Inspection Report.</p> <p>After following the decontamination procedure I signed the log book and left the decon. Inspection was done on ATC trailer.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction	Infraction	
NOV #	Infraction	Infraction	Infraction	Infraction	Result Code 2	
NOV #	Infraction	Infraction	Infraction	Infraction	Supervisor's Initial <i>ry</i>	

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property