

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 04/28/09	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # A062
Inspector M.Gagnidze		Building Type F		Basis of Inspection TRU2068MN08		Photos Taken yes
Contractor's Name LVI Environmental				Sample Number _____		
Address _____ City _____				Sample Number _____		
State _____ Zip _____ Phone _____				Sample Number _____		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address _____ City _____ 1340 Broadway New York				Address _____ City _____ One Liberty Plaza New York		
State _____ Zip _____ Phone _____ NY 10018				State _____ Zip _____ Phone _____ NY 10006 (212) 962-2300		
Contact Person Arnel Javal, Sr. Proj. Mgr/TRC Environmental				Time of Inspection from: 1:30 pm to 2:25 pm		
<p>I entered the premise at 1:30 pm. LVI schedule informed that activities include: clear floor, cut ducts, demo walls, ceilings on 1st floor.</p> <p>I proceeded to the decon, signed the log book, don the appropriate level of personal protective equipment to enter the regulated area on 1st floor. Two workers were present for the decon maintenance, cleaning shower chambers and organizing the clean room. Negative air pressure was -0.021.</p> <p>1st Floor – 75 workers were working inside the work area. Workers were observed on mezzanine at the west side area, cutting and demolishing the drop ceilings, spraying with amended water, placing debris into the boxes; Two workers harnessed on scissor lift, were cutting metals from the wall.</p> <p>Worker was observed on ladder cutting wires and metal fixtures inside the shaft area. Workers on scissor lift were breaking down the brick wall in the hallway between two shafts, spraying with water and placing debris into the boxes.</p> <p>Other workers were: cutting metal into small pieces at the various locations, placing into the boxes and spraying; wrapping beams with poly, preparing and loading out sealed and sprayed boxes through the north side waste decon.</p> <p>Approximately 70 Gaylord boxes were ready for load out. 35 micro trap machines were powered on and 5 on stand by. Inspection was done on micro trap tents.</p> <p>I observed that: 1. Main layer of the exhaust duct, connected to the micro trap at the South side work area was damaged.</p> <p>LVI Supervisor was advised, and he immediately directed workers to him to repair exhaust duct.</p> <p>After following the decontamination procedure I signed the log book and left the decon. Inspection was done on ATC trailer.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction		
NOV #	Infraction	Infraction	Infraction	Result Code 2		
NOV #	Infraction	Infraction	Infraction	Supervisor's Initial	<i>Ref.</i>	

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property