

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 03/20/09	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # AO61
Inspector H. Guirguis		Building Type A		Basis of Inspection TRU2068MN08		Photos Taken Yes
Contractor's Name LVI Environmental				Sample Number -----		
Address City				Sample Number -----		
State Zip Phone				Sample Number -----		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address City 1430 Broadway New York				Address City One Liberty Plaza New York		
State Zip Phone NY 10018				State Zip Phone NY 10006 (212) 962-2300		
Contact Person Arnel Javal, Sr. Proj. Mgr./TRC Environmental				Time of Inspection from: 08:00am – 10:00am		
<p>On arrival I met Nugent Gerald, Supervisor for LVI Environmental at the LVI field office, who informed me that a total of 1 Handler Supervisor and 50 Asbestos Handlers were in the 3rd floor today.</p> <p>The daily work schedule informed me of the following.</p> <ol style="list-style-type: none"> 1. 3rd floor: 50 men-scrape fireproofing, clear off floor 2. 2nd floor: 54 men- seal critical, clear off floor. Eagle-14 men erect platforms various locations 3. 1st floor: 76 men-clear floor, cut ducts, demo walls, ceilings, etc. 4. Various floors : 14 men loading out boxes to ATC trailer <p>I went to the decontamination enclosure system in the first floor at the west side After signing the log book donned personal protection and accessed the work areas, I used stair B to go to from 1st floor to 3rd floor.</p> <p>1st & 2nd floor: workers were found in the process of removing and wrapping debris; there was still a lot of wet debris on the floor, demo walls, demolition was not completed, workers were cutting metal ducts and electrical conduits into small pieces using power tools, HEPA vacuum attached with the power tools, disconnecting Mechanical Equipment (HVAC), fine spraying amended water in the work area, preparing Gaylord boxes, wrapping beams and lighting fixtures, inspecting the critical barriers and re-sealing with duct tape, erecting scaffolds and platforms in various locations, numerous Gaylord boxes and poly wrapped beams were at various locations on each floor ready to be taken out</p> <p>Inspection was done on the Micro trap Machines and the Micro trap tents and on all the work area.</p> <p>3rd floor, workers were found in the process of scraping and boxing fireproofing, fine spraying amended water in the work area, preparing Gaylord boxes.</p> <p>Inspection was done on the Micro trap Machines and the Micro trap tents and on all the work area.</p> <p>I exited the work area after decontaminating and signing the log book.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction		
NOV #	Infraction	Infraction	Infraction	Result Code 2		
NOV #	Infraction	Infraction	Infraction	Supervisor's Initial <i>WJ</i>		

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property