

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 02/16/09	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # A062
Inspector M Gagnidze		Building Type F		Basis of Inspection TRU2068MN08		Photos Taken yes
Contractor's Name LVI Environmental				Sample Number _____		
Address _____ City _____				Sample Number _____		
State _____ Zip _____ Phone _____				Sample Number _____		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address _____ City _____ 1340 Broadway New York				Address _____ City _____ One Liberty Plaza New York		
State _____ Zip _____ Phone _____ NY 10018				State _____ Zip _____ Phone _____ NY 10006 (212) 962-2300		
Contact Person Arnel Javal, Sr. Proj. Mgr/TRC Environmental				Time of Inspection from: 2:25 pm to 3:25 pm		
<p>I arrived at the premise at 2:25 pm, proceeded to the decon, signed the log book, don the appropriate level of personal protective equipment to enter the regulated area on 4th floor. Negative air pressure on the floor was 0.038. One worker was present for the decon maintenance.</p> <p>4th Floor – 25 workers were present on the floor, wrapping and elevating the electrical cables, washing, sweeping and vacuuming the floor at the north/east side of the work area with equipment equipped with HEPA filters, fine cleaning horizontal and vertical surfaces at the spandular beams, clearing off the floor, preparing for visual inspection. 4 Gaylord boxes were ready to be taken out. Inspection was done on micro trap machines and tents.</p> <p>I used B stairs to proceed to the 3rd floor.</p> <p>3rd Floor – 28 workers were working on the floor, demolishing the sheetrock wall between two shafts; taking down drop ceiling to remove the insulation and cut and demolish the air duct at the east and north side of the area; workers on the scissor lift were in the process of removing air ducts, removing metals from the ceiling at the east side vestibule, wrapping beams with poly, cutting metal using the tools with HEPA vacuum attached, cutting pipes on the floor at the north/west side vestibule. Others were loading out boxes and poly wrapped beams, picking up debris, preparing boxes. 12 Gaylord boxes were ready to be taken out. Inspection was done on micro trap machines and tents.</p> <p>I used B stairwell to proceed to the 2nd floor.</p> <p>2nd Floor – 53 workers were found inside the work place, demolishing the air ducts and pipes inside the mezzanine, located between 2nd and 1st floors, plasticizing the platforms, built above the escalator shaft at the east side of the area; cutting pipes and metal fixtures from the ceiling at the shaft, demolishing stairs at the south/east side. Others cutting metal into the pieces, using power tool with HEPA vacuum attached, spraying the area with amended water, removing metal ceiling components; picking up debris from the floor, placing into the boxes and spraying with amended water, wrapping beams with poly, preparing boxes. 15 Gaylord boxes were on the floor sealed, sprayed and ready for load out. Filters of micro trap machines were dirty. Handler Supervisor was advised, and 2 workers replaced the filters. 35 micro trap machines were powered on and 5 on stand by. Inspection was done on micro trap tents.</p> <p>I used B stairwell to proceed to the 1st floor.</p> <p>1st Floor – 34 workers were clearing off the floor. Workers on ladders and scissor lifts were cutting air ducts, demolishing the wall at the north side, cutting debris and placing into the boxes, spraying the work areas with amended water, preparing, wrapping and loading out boxes through the waste decon, A large amount of debris and poly wrapped beams exists on the floor. 15 sealed and 10 open Gaylord boxes were on the floor.</p> <p>I used B stairwell to proceed to the 4th floor.</p> <p>After following the decontamination procedure I signed the log book and used south hoist to return to the ground floor.</p> <p>Inspection was done on ATC trailer.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction		
NOV #	Infraction	Infraction	Infraction	Infraction	Result Code 2	
NOV #	Infraction	Infraction	Infraction	Infraction	Supervisor's Initial <i>ref</i>	

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property