

Asbestos Inspection Report

Premises: 130 Liberty Street					Inspection Date: 02/09/09	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # A011
Inspector N. Patel		Building Type A		Basis of Inspection TRU2068MN08		Photos Taken Yes
Contractor's Name LVI Environmental				Sample Number -----		
Address 462 Getty Avenue				City Clifton		
State NJ				Zip 07011		
Phone (973) 772-3660				Sample Number -----		
Laboratory Name TRC Environmental corp.				Owner's Name The Lower Manhattan Development Corp.		
Address 1430 Broadway				City New York		
State NY				Zip 10018		
Phone (212) 962-2300				Sample Number -----		
Contact Person Arnel Javal, Sr. Proj. Mgr. / TRC Environmental				Time of Inspection from: 8:50 am – 9:50 am (3 rd , 4 th , 2 nd & 1 st floor) and 1:25 pm – 2:10 pm (5 th floor).		
<p>On the 3rd floor, I entered to the work area with PPE and met Mr. Geraldo and Mr. Jerry Kadzilla, supervisors. There were 31 people working on the floor. They were demolishing walls and shaft area, boxing debris, cutting pipes with HEPA vacuum attached to the power tool, clearing off floor, preparing Gaylord boxes spraying amended water on the debris in the boxes. Four (4) Gaylord boxes and numerous poly wrapped beams piled on the floor ready to be load out. Negative Air pressure was -0.07. I used stair B to go to 4th floor.</p> <p>On the 4th floor, I met Mr. Victor, foreman. There were 10 people working on the floor. They were clear off floor for demo and cleaning water from floor by vacuum. One micro trap machine was not running and without Air filter. I took photo and told foreman to fix the problem. An inspection was done on micro trap machines and micro trap tents – Air pumps were on. I used stair B to go to 2nd floor.</p> <p>On the 2nd and 1st floor, I met Mr. Jose Jimenez, supervisor. There were 22 people working on the both floors under Mr. Jimenez. They were demolishing walls and bathroom, cleaning out shaft, spraying amended water on the debris, boxing debris and preparing Gaylord boxes. Three (3) Gaylord boxes and numerous poly wrapped beams piled on the floor ready to be load out. I found no water near stair B to clean rubber shoes. I told supervisor to put water near stair and he did that. I used stair B to go back to 3rd floor, proceeds to the decontamination system and showers out.</p> <p>On the 5th floor, I enters to the decontamination system with ATC personal and Mr. Arnel Javal of TRC, suits up, dons respirator, enters to the containment and met Mr. Rocco paves, supervisor. There were 26 people working on the floor. They were cleaning work area by vacuuming, checking critical barriers and re-sealing with duct tapes, boxing debris and changing Air filters. Eight (8) Gaylord boxes and number of plastic bags were on the floor ready to be load out. Negative Air pressure was -0.020. Two Micro trap machines were not running and without Air filters. I took photos and told foreman Mr. Raul to fix it. Also, I found few holes in the plastic barrier. I show to Mr. Arnel Javal of TRC and also Mr. Paul, foreman and told Foreman to fix it and he did that. I proceeded to the decontamination system, decontaminated myself, signed the log book and exited out. My observations were discussed with TRC personal.</p>						
NOV#						RESULT 2
NOV#						
NOV#						SUPERVISOR 

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV) 5=Public Owned Property