

COMMERCIAL LAB ENTERPRISE

270 Swinton Avenue
Bronx, New York 10465

☎ (718) 792-2832

Fax (718) 904-9117

BULK (TEM) SAMPLE TABLE SUMMARY OF ASBESTOS SAMPLES SURVEY LOCATIONS

CLIENT: Duane Street Associates.
c/o Hudson River Management LLC.,

INSPECTOR NAME: V. Escalona.

SITE ADDRESS: 310 Greenwich Street
New York, NY.

SURVEY DATE: November 27, 2002.


FILE No.: 02227.

AREA INSPECTED: Entire hallways at the
23rd / 22nd / 31st / 20th Floors.

Location	Material sampled	Material condition	Quantity of material	Friable Yes No	Sample #	Comments
23rd floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	49.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	50.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	51.	N/C.
22nd floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	52.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	53.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	54.	N/C.
21st floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	55.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	56.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	57.	N/C.
20th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	58.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	59.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	60.	N/C.

N/C= no comments.

The asbestos samples were analyzed by EMSL Analytical Inc., NYS DOH ELAP #: 11506 and NVLAP ID#: 101041-8.


Project Manager

ENVIRONMENTAL CONSULTING SERVICES

CITY_21MC100_002848045

COMMERCIAL LAB ENTERPRISE

270 Swinton Avenue
Bronx, New York 10465

☎ (718) 792-2832

Fax (718) 904-9117

BULK (TEM) SAMPLE TABLE SUMMARY OF ASBESTOS SAMPLES SURVEY LOCATIONS

CLIENT: Duane Street Associates.
c/o Hudson River Management LLC.,

INSPECTOR NAME: V. Escalona.

SITE ADDRESS: 310 Greenwich Street
New York, NY.

SURVEY DATE: November 27, 2002.


FILE No.: 02227.

AREA INSPECTED: Entire hallways at the
19th / 18th / 17th / 16th Floors.

Location	Material sampled	Material condition	Quantity of material	Friable Yes No	Sample #	Comments
19th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	61.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	62.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	63.	N/C.
18th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	64.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	65.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	66.	N/C.
17th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	67.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	68.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	69.	N/C.
16th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	70.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	71.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	72.	N/C.

N/C= no comments.

The asbestos samples were analyzed by EMSL Analytical Inc., NYS DOH ELAP #: 11506 and NVLAP ID#: 101044-9.


Project Manager

ENVIRONMENTAL CONSULTING SERVICES

CITY_21MC100_002848046

COMMERCIAL LAB ENTERPRISE

270 Swinton Avenue
Bronx, New York 10465

☎ (718) 792-2832

Fax (718) 904-9117

BULK (TEM) SAMPLE TABLE SUMMARY OF ASBESTOS SAMPLES SURVEY LOCATIONS

CLIENT: Duane Street Associates.
c/o Hudson River Management LLC.,

INSPECTOR NAME: V. Escalona.

SITE ADDRESS: 310 Greenwich Street
New York, NY.

SURVEY DATE: November 27, 2002.


FILE No.: 02227.

AREA INSPECTED: Entire hallways at the
15th / 14th / 13th / 12th Floors.

Location	Material sampled	Material condition	Quantity of material	Friable Yes No	Sample #	Comments
15th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	73.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	74.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	75.	N/C.
14th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	76.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	77.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	78.	N/C.
13th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	79.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	80.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	81.	N/C.
12th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	82.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	83.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	84.	N/C.

N/C= no comments.

The asbestos samples were analyzed by EMSL Analytical Inc., NYS DOH ELAP #: 11506 and NVLAP ID#: 1010329.


Project Manager

ENVIRONMENTAL CONSULTING SERVICES

CITY_21MC100_002848047

COMMERCIAL LAB ENTERPRISE

270 Swinton Avenue
Bronx, New York 10465

(718) 792-2832

Fax (718) 904-9117

BULK (TEM) SAMPLE TABLE SUMMARY OF ASBESTOS SAMPLES SURVEY LOCATIONS

CLIENT: Duane Street Associates.
c/o Hudson River Management LLC.,

INSPECTOR NAME: V. Escalona.

SITE ADDRESS: 310 Greenwich Street
New York, NY.

SURVEY DATE: November 27, 2002.

FILE No.: 02227.

AREA INSPECTED: Entire hallways at the
11th / 10th / 9th / 8th Floors.

Location	Material sampled	Material condition	Quantity of material	Friable Yes No	Sample #	Comments
11th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	85.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	86.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	87.	N/C.
10th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	88.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	89.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	90.	N/C.
9th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	91.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	92.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	93.	N/C.
8th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	94.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	95.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	96.	N/C.

N/C= no comments.

The asbestos samples were analyzed by EMSL Analytical Inc., NYS DOH ELAP #: 11506 and NVLAP ID#: 1019419.

Project Manager

ENVIRONMENTAL CONSULTING SERVICES

CITY_21MC100_002848048

COMMERCIAL LAB ENTERPRISE

270 Swinton Avenue
Bronx, New York 10465

(718) 792-2832

Fax (718) 904-9117

BULK (TEM) SAMPLE TABLE SUMMARY OF ASBESTOS SAMPLES SURVEY LOCATIONS

CLIENT: Duane Street Associates.
c/o Hudson River Management LLC.,

INSPECTOR NAME: V. Escalona.

SITE ADDRESS: 310 Greenwich Street
New York, NY.

SURVEY DATE: November 27, 2002.

FILE No.: 02227.

AREA INSPECTED: Entire hallways at the
7th / 6th / 5th / 4th Floors.

Location	Material sampled	Material condition	Quantity of material	Friable Yes No	Sample #	Comments
7th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	97.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	98.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	99.	N/C.
6th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	100.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	101.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	102.	N/C.
5th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	103.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	104.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	105.	N/C.
4th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	106.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	107.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	108.	N/C.

N/C= no comments.

The asbestos samples were analyzed by EMSL Analytical Inc., NYS DOH ELAP #: 11506 and NVLAP ID#: 101048-9.

Project Manager

ENVIRONMENTAL CONSULTING SERVICES

CITY_21MC100_002848049

COMMERCIAL LAB ENTERPRISE

270 Swinton Avenue
Bronx, New York 10465

☎ (718) 792-2832

Fax (718) 904-9117

BULK (TEM) SAMPLE TABLE SUMMARY OF ASBESTOS SAMPLES SURVEY LOCATIONS

CLIENT: Duane Street Associates.
c/o Hudson River Management LLC.,

INSPECTOR NAME: V. Escalona.

SITE ADDRESS: 310 Greenwich Street
New York, NY.

SURVEY DATE: November 27, 2002.


FILE No.: 02227.

AREA INSPECTED: Entire hallways at the
3rd / 2nd Floors.

Location	Material sampled	Material condition	Quantity of material	Friable Yes No	Sample #	Comments
3rd floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	1,175 sq.ft.	No.	109.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	1,175 sq.ft.	No.	110.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	1,175 sq.ft.	No.	111.	N/C.
2nd floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	112.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	113.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	114.	N/C.

N/C= no comments.

The asbestos samples were analyzed by EMSL Analytical Inc., NYS DOH ELAP #: 11506 and NVLAP ID#: 1017414.


Project Manager

ENVIRONMENTAL CONSULTING SERVICES

CITY_21MC100_002848050