

COMMERCIAL LAB ENTERPRISE

270 Swinton Avenue
Bronx, New York 10465

☎ (718) 792-2832

Fax (718) 904-9117

BULK (TEM) SAMPLE TABLE SUMMARY OF ASBESTOS SAMPLES SURVEY LOCATIONS

CLIENT: Duane Street Associates.
c/o Hudson River Management LLC.,

INSPECTOR NAME: V. Escalona.

SITE ADDRESS: 40 Harrison Street
New York, NY.

SURVEY DATE: November 29, 2002.


FILE No.: 02227.

AREA INSPECTED: Entire hallways at the
39th / 38th / 37th / 36th Floors.

Location	Material sampled	Material condition	Quantity of material	Friable Yes No	Sample #	Comments
39th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	115.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	116.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	117.	N/C.
38th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	118.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	119.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	120.	N/C.
37th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	121.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	122.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	123.	N/C.
36th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	124.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	125.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	126.	N/C.

N/C= no comments.

The asbestos samples were analyzed by EMSL Analytical Inc., NYS DOH ELAP #: 11506 and NVLAP ID#: 104045-9


Project Manager

ENVIRONMENTAL CONSULTING SERVICES

CITY_21MC100_010172347

COMMERCIAL LAB ENTERPRISE

270 Swinton Avenue
Bronx, New York 10465

☎ (718) 792-2832

Fax (718) 904-9117

BULK (TEM) SAMPLE TABLE SUMMARY OF ASBESTOS SAMPLES SURVEY LOCATIONS

CLIENT: Duane Street Associates.
c/o Hudson River Management LLC.,

INSPECTOR NAME: V. Escalona.

SITE ADDRESS: 40 Harrison Street
New York, NY.

SURVEY DATE: November 29, 2002.


FILE No.: 02227.

AREA INSPECTED: Entire hallways at the
35th / 34th / 33rd / 32nd Floors.

Location	Material sampled	Material condition	Quantity of material	Friable Yes No	Sample #	Comments
35th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	127.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	128.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	129.	N/C.
34th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	130.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	131.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	132.	N/C.
33rd floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	133.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	134.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	135.	N/C.
32nd floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	136.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	137.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	138.	N/C.

N/C= no comments.

The asbestos samples were analyzed by EMSL Analytical Inc., NYS DOH ELAP #: 11506 and NVLAP ID#: 1010419


Project Manager

ENVIRONMENTAL CONSULTING SERVICES

CITY_21MC100_010172348

COMMERCIAL LAB ENTERPRISE

270 Swinton Avenue
Bronx, New York 10465

☎ (718) 792-2832

Fax (718) 904-9117

BULK (TEM) SAMPLE TABLE SUMMARY OF ASBESTOS SAMPLES SURVEY LOCATIONS

CLIENT: Duane Street Associates.
c/o Hudson River Management LLC.,

INSPECTOR NAME: V. Escalona.

SITE ADDRESS: 40 Harrison Street
New York, NY.

SURVEY DATE: November 29, 2002.


FILE No.: 02227.

AREA INSPECTED: Entire hallways at the
31st / 30th / 29th / 28th Floors.

Location	Material sampled	Material condition	Quantity of material	Friable Yes No	Sample #	Comments
31st floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	139.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	140.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	141.	N/C.
30th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	142.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	143.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	144.	N/C.
29th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	145.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	146.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	147.	N/C.
28th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	148.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	149.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	150.	N/C.

N/C= no comments.

The asbestos samples were analyzed by EMSL Analytical Inc., NYS DOH ELAP #: 11506 and NVLAP ID#: 1010159.


Project Manager

ENVIRONMENTAL CONSULTING SERVICES

CITY_21MC100_010172349

COMMERCIAL LAB ENTERPRISE

270 Swinton Avenue
Bronx, New York 10465

(718) 792-2832

Fax (718) 904-9117

BULK (TEM) SAMPLE TABLE SUMMARY OF ASBESTOS SAMPLES SURVEY LOCATIONS

CLIENT: Duane Street Associates.
c/o Hudson River Management LLC.,

INSPECTOR NAME: V. Escalona.

SITE ADDRESS: 40 Harrison Street
New York, NY.

SURVEY DATE: November 29, 2002.

FILE No.: 02227.

AREA INSPECTED: Entire hallways at the
27th / 26th / 25th / 24th Floors.

Location	Material sampled	Material condition	Quantity of material	Friable Yes No	Sample #	Comments
27th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	151.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	152.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	153.	N/C.
26th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	154.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	155.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	156.	N/C.
25th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	157.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	158.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	159.	N/C.
24th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	160.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	161.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	162.	N/C.

N/C= no comments.

The asbestos samples were analyzed by EMSL Analytical Inc., NYS DOH ELAP #: 11506 and NVLAP ID#: 101028-9.

Project Manager

ENVIRONMENTAL CONSULTING SERVICES

CITY_21MC100_010172350

COMMERCIAL LAB ENTERPRISE

270 Swinton Avenue
Bronx, New York 10465

☎ (718) 792-2832

Fax (718) 904-9117

BULK (TEM) SAMPLE TABLE SUMMARY OF ASBESTOS SAMPLES SURVEY LOCATIONS

CLIENT: Duane Street Associates.
c/o Hudson River Management LLC.,

INSPECTOR NAME: V. Escalona.

SITE ADDRESS: 40 Harrison Street
New York, NY.

SURVEY DATE: November 29, 2002.


FILE No.: 02227.

AREA INSPECTED: Entire hallways at the
23rd / 22nd / 31st / 20th Floors.

Location	Material sampled	Material condition	Quantity of material	Friable Yes No	Sample #	Comments
23rd floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	163.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	164.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	165.	N/C.
22nd floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	166.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	167.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	168.	N/C.
21st floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	169.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	170.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	171.	N/C.
20th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	172.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	173.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	174.	N/C.

N/C= no comments.

The asbestos samples were analyzed by EMSL Analytical Inc., NYS DOH ELAP #: 11506 and NVLAP ID#: 1010489.


Project Manager

ENVIRONMENTAL CONSULTING SERVICES

CITY_21MC100_010172351