

COMMERCIAL LAB ENTERPRISE

270 Swinton Avenue
Bronx, New York 10465

☎ (718) 792-2832

Fax (718) 904-9117

BULK (TEM) SAMPLE TABLE SUMMARY OF ASBESTOS SAMPLES SURVEY LOCATIONS

CLIENT: Duane Street Associates.
c/o Hudson River Management LLC.,

INSPECTOR NAME: V. Escalona.

SITE ADDRESS: 40 Harrison Street
New York, NY.

SURVEY DATE: December 4, 2002.


FILE No.: 02227.

AREA INSPECTED: Entire hallways at the
19th / 18th / 17th / 16th Floors.

Location	Material sampled	Material condition	Quantity of material	Friable Yes No	Sample #	Comments
19th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	175.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	176.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	177.	N/C.
18th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	178.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	179.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	180.	N/C.
17th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	181.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	182.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	183.	N/C.
16th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	184.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	185.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	186.	N/C.

N/C= no comments.

The asbestos samples were analyzed by EMSL Analytical Inc., NYS DOH ELAP #: 11506 and NVLAP ID#: 101045-9.


Project Manager

ENVIRONMENTAL CONSULTING SERVICES

CITY_21MC100_002848051

COMMERCIAL LAB ENTERPRISE

270 Swinton Avenue
Bronx, New York 10465

☎ (718) 792-2832

Fax (718) 904-9117

BULK (TEM) SAMPLE TABLE SUMMARY OF ASBESTOS SAMPLES SURVEY LOCATIONS

CLIENT: Duane Street Associates.
c/o Hudson River Management LLC.,

INSPECTOR NAME: V. Escalona.

SITE ADDRESS: 40 Harrison Street
New York, NY.

SURVEY DATE: December 4, 2002.

FILE No.: 02227.

AREA INSPECTED: Entire hallways at the
15th / 14th / 13th / 12th Floors.

Location	Material sampled	Material condition	Quantity of material	Friable Yes No	Sample #	Comments
15th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	187.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	188.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	189.	N/C.
14th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	190.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	191.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	192.	N/C.
13th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	193.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	194.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	195.	N/C.
12th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	196.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	197.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	198.	N/C.

N/C= no comments.

The asbestos samples were analyzed by EMSL Analytical Inc., NYS DOH ELAP #: 11506 and NVLAP ID#: 1010449.

Project Manager

ENVIRONMENTAL CONSULTING SERVICES

CITY_21MC100_002848052

COMMERCIAL LAB ENTERPRISE

270 Swinton Avenue
Bronx, New York 10465

☎ (718) 792-2832

Fax (718) 904-9117

BULK (TEM) SAMPLE TABLE SUMMARY OF ASBESTOS SAMPLES SURVEY LOCATIONS

CLIENT: Duane Street Associates.
c/o Hudson River Management LLC.,

INSPECTOR NAME: V. Escalona.

SITE ADDRESS: 40 Harrison Street
New York, NY.

SURVEY DATE: December 4, 2002.


FILE No.: 02227.

AREA INSPECTED: Entire hallways at the
11th / 10th / 9th / 8th Floors.

Location	Material sampled	Material condition	Quantity of material	Friable Yes No	Sample #	Comments
11th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	199.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	200.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	201.	N/C.
10th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	202.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	203.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	204.	N/C.
9th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	205.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	206.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	207.	N/C.
8th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	208.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	209.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	210.	N/C.

N/C= no comments.

The asbestos samples were analyzed by EMSL Analytical Inc., NYS DOH ELAP #: 11506 and NVLAP ID#: 1010419


Project Manager

ENVIRONMENTAL CONSULTING SERVICES

CITY_21MC100_002848053

COMMERCIAL LAB ENTERPRISE

270 Swinton Avenue
Bronx, New York 10465

(718) 792-2832

Fax (718) 904-9117

BULK (TEM) SAMPLE TABLE SUMMARY OF ASBESTOS SAMPLES SURVEY LOCATIONS

CLIENT: Duane Street Associates.
c/o Hudson River Management LLC.,

INSPECTOR NAME: V. Escalona.

SITE ADDRESS: 40 Harrison Street
New York, NY.

SURVEY DATE: December 4, 2002.

FILE No.: 02227.

AREA INSPECTED: Entire hallways at the
7th / 6th / 5th / 4th Floors.

Location	Material sampled	Material condition	Quantity of material	Friable Yes No	Sample #	Comments
7th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	211.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	212.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	213.	N/C.
6th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	214.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	215.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	216.	N/C.
5th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	217.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	218.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	219.	N/C.
4th floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	220.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	221.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	222.	N/C.

N/C= no comments.

The asbestos samples were analyzed by EMSL Analytical Inc., NYS DOH ELAP #: 11506 and NVLAP ID#: 101049-9

Project Manager

ENVIRONMENTAL CONSULTING SERVICES

CITY_21MC100_002848054

COMMERCIAL LAB ENTERPRISE

270 Swinton Avenue
Bronx, New York 10465

☎ (718) 792-2832

Fax (718) 904-9117

BULK (TEM) SAMPLE TABLE SUMMARY OF ASBESTOS SAMPLES SURVEY LOCATIONS

CLIENT: Duane Street Associates.
c/o Hudson River Management LLC.,

INSPECTOR NAME: V. Escalona.

SITE ADDRESS: 40 Harrison Street
New York, NY.

SURVEY DATE: December 4, 2002.


FILE No.: 02227.

AREA INSPECTED: Entire hallways at the
3rd / 2nd Floors.

Location	Material sampled	Material condition	Quantity of material	Friable Yes No	Sample #	Comments
3rd floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	1,175 sq.ft.	No.	223.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	1,175 sq.ft.	No.	224.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	1,175 sq.ft.	No.	225.	N/C.
2nd floor:						
East side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	226.	N/C.
Middle area of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	227.	N/C.
West side of hallway.	Carpet glue/mastic material.	Fair.	885 sq.ft.	No.	228.	N/C.

N/C= no comments.

The asbestos samples were analyzed by EMSL Analytical Inc., NYS DOH ELAP #: 11506 and NVLAP ID#: 1010489.


Project Manager

ENVIRONMENTAL CONSULTING SERVICES

CITY_21MC100_002848055