

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10018

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

Hillmann Environmental Company, Inc. Date Received 10/09/2001 SciLab Job No. 201101831
 Attn: Mike Nehlsen Date Examined 10/10/2001 P.O. # Y2-1040
 1600 Rt. 22 East Page 5 of 15
 Union, NJ 07083 RE: Y2-1040; GAB Robins N America Inc.; 22 Courtland Street

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
1-017	201101831-17	No	NAD ¹

Location: 29th Floor, Office, South West

Description: Grey, Heterogeneous, Debris

Asbestos Types:

Other Material: Cellulose 12. %, Fibrous glass 18. %, Non-fibrous 70. %

1-018	201101831-18	Yes	1.3 % ¹
-------	--------------	-----	--------------------

Location: 28th Floor, Office, South West (Broken Window)

Description: Grey, Heterogeneous, Debris

Asbestos Types: Chrysotile 1.3 %

Other Material: Cellulose 5. %, Fibrous glass 10. %, Non-fibrous 83.7 %

1-019	201101831-19	No	NAD
-------	--------------	----	-----

Location: 28th Floor, Office, North West

Description: Grey, Heterogeneous, Debris

Asbestos Types:

Other Material: Cellulose 3. %, Fibrous glass 2. %, Non-fibrous 95. %

1-020	201101831-20	No	NAD ¹
-------	--------------	----	------------------

Location: 28th Floor, Stairwell, South

Description: Grey, Heterogeneous, Debris

Asbestos Types:

Other Material: Animal hair Trace, Cellulose 2. %, Non-fibrous 98. %

1-021	201101831-21	Yes	10 % ¹
-------	--------------	-----	-------------------

Location: 25th, Office, North West (Broken Window)

Description: Grey, Heterogeneous, Debris

Asbestos Types: Chrysotile 10. %

Other Material: Cellulose 10. %, Fibrous glass 30. %, Non-fibrous 50. %

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9382

PLM Bulk Asbestos Report

Hillmann Environmental Company, Inc. Date Received 10/09/2001 SciLab Job No. 201101831
 Attn: Mike Nehlsen Date Examined 10/10/2001 P.O. # Y2-1040
 1600 Rt. 22 East Page 6 of 15
 Union, NJ 07083 RE: Y2-1040; GAB Robins N America Inc.; 22 Courtland Street

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
1-022	201101831-22	Yes	<1.%

Location: 25th Floor, Office, North West

Description: Grey, Heterogeneous, Debris
 Asbestos Types: Chrysotile Trace
 Other Material: Cellulose 20. %, Fibrous glass 35. %, Non-fibrous 45. %

1-023	201101831-23	Yes	<1.>% ^I
-------	--------------	-----	--------------------

Location: 25th Floor, Office, South West

Description: Grey, Heterogeneous, Debris
 Asbestos Types: Chrysotile Trace
 Other Material: Cellulose 15. %, Fibrous glass 30. %, Non-fibrous 55. %

1-025	201101831-24	No	NAD ^I
-------	--------------	----	------------------

Location: 24th Floor, Elevator, East

Description: Brown, Heterogeneous, Cementitious, Debris
 Asbestos Types:
 Other Material: Cellulose Trace, Non-fibrous 100. %

1-026	201101831-25	Yes	<1.>% ^I
-------	--------------	-----	--------------------

Location: 23rd Floor, Cafe, North West

Description: Grey, Heterogeneous, Debris
 Asbestos Types: Chrysotile Trace
 Other Material: Cellulose 15. %, Fibrous glass 35. %, Non-fibrous 50. %

1-027	201101831-26	Yes	<1.>% ^I
-------	--------------	-----	--------------------

Location: 22nd Floor, Elevator, East

Description: Grey, Heterogeneous, Debris
 Asbestos Types: Chrysotile <1. %
 Other Material: Cellulose 25 %, Fibrous glass 15. %, Non-fibrous >59. %

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10018

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

Hillmann Environmental Company, Inc. **Date Received** 10/09/2001 **SciLab Job No.** 201101831
Attn: Mike Nehlsen **Date Examined** 10/10/2001 **P.O. #** Y2-1040
 1600 Rt. 22 East **Page** 7 of 15
 Union, NJ 07083 **RE:** Y2-1040; GAB Robins N America Inc.; 22 Courtland Street

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
1-028	201101831-27	No	NAD

Location: 22nd Floor, Office, South West**Description:** Grey/White, Heterogeneous, Debris**Asbestos Types:****Other Material:** Cellulose 25. %, Fibrous glass 40. %, Non-fibrous 35. %

1-029A	201101831-28	No	NAD ¹
--------	--------------	----	------------------

Location: 21st Floor, Office, West**Description:** White, Heterogeneous, Debris**Asbestos Types:****Other Material:** Cellulose 7. %, Fibrous glass 60. %, Non-fibrous 33. %

1-029B	201101831-29	Yes	1.1 % ¹
--------	--------------	-----	--------------------

Location: 25th Floor, Hallway, North**Description:** Grey, Heterogeneous, Debris**Asbestos Types:** Amosite Trace, Chrysotile <1. %**Other Material:** Cellulose 10. %, Fibrous glass 25. %, Non-fibrous >64. %

1-030	201101831-30	No	NAD ¹
-------	--------------	----	------------------

Location: 20th Floor, Stairwell, North**Description:** White, Heterogeneous, Debris**Asbestos Types:****Other Material:** Cellulose 15. %, Fibrous glass 60. %, Non-fibrous 25. %

1-031	201101831-31	Yes	<1. % ¹
-------	--------------	-----	--------------------

Location: 19th Floor, Office, South West**Description:** Grey, Heterogeneous, Debris**Asbestos Types:** Chrysotile <1. %**Other Material:** Cellulose 15. %, Fibrous glass 45. %, Non-fibrous >39. %

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

Hillmann Environmental Company, Inc. Date Received 10/09/2001 SciLab Job No. 201101831
 Attn: Mike Nehlsen Date Examined 10/10/2001 P.O. # Y2-1040
 1600 Rt. 22 East Page 8 of 15
 Union, NJ 07083 RE: Y2-1040; GAB Robins N America Inc., 22 Courtland Street

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
1-032	201101831-32	No	NAD ¹
Location: 19th Floor, Center Office, West			
Description: Grey, Heterogeneous, Debris			
Asbestos Types:			
Other Material: Cellulose 5. %, Fibrous glass 60. %, Non-fibrous 35. %			
1-033	201101831-33	Yes	<1. % ¹
Location: 19th Floor, Office, Center Room			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile <1. %			
Other Material: Cellulose 15. %, Fibrous glass 40. %, Non-fibrous >44. %			
1-037	201101831-34	Yes	<1. % ¹
Location: 18th Floor, Office, Center West			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile <1. %			
Other Material: Cellulose 20. %, Fibrous glass 40. %, Non-fibrous >39. %			
1-038A	201101831-35	Yes	<1. % ¹
Location: 18th Floor, Office, South West			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile Trace			
Other Material: Cellulose 30. %, Fibrous glass 40. %, Non-fibrous 30. %			
1-038B	201101831-36	Yes	<1. % ¹
Location: 18th Floor, Office, South West			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile <1. %			
Other Material: Cellulose 25. %, Fibrous glass 40. %, Non-fibrous 34. %			

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

Hillmann Environmental Company, Inc. **Date Received** 10/09/2001 **SciLab Job No.** 201101831
Attn: Mike Nehlsen **Date Examined** 10/10/2001 **P.O. #** Y2-1040
 1600 Rt. 22 East **Page 9 of 15**
 Union, NJ 07083 **RE: Y2-1040; GAB Robins N America Inc.; 22 Courtland Street**

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
1-039	201101831-37	Yes	<1.% ¹
Location: 17th Floor, Office North West Description: Grey, Heterogeneous, Debris Asbestos Types: Chrysotile <1. % Other Material: Cellulose 15. %, Fibrous glass 35. %, Non-fibrous >49. %			
1-040	201101831-38	Yes	<1.% ¹
Location: 17th Floor, Office, North West Description: Grey, Heterogeneous, Debris Asbestos Types: Chrysotile <1. % Other Material: Cellulose 25. %, Fibrous glass 35. %, Non-fibrous >39. %			
1-041	201101831-39	No	NAD ¹
Location: 17th Floor, Office North East Description: White, Heterogeneous, Debris Asbestos Types: Other Material: Cellulose 15. %, Fibrous glass 60. %, Non-fibrous 25. %			
1-043	201101831-40	Yes	<1.% ¹
Location: 16th Floor, Room 1610 Description: Grey, Heterogeneous, Debris Asbestos Types: Chrysotile <1. % Other Material: Cellulose 15. %, Fibrous glass 50. %, Non-fibrous >34. %			
1-044	201101831-41	No	NAD ¹
Location: 16th Floor, Admin Area Description: Grey, Heterogeneous, Debris Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100. %			

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

Hillmann Environmental Company, Inc.

Attn: Mike Nehlsen

1600 Rt. 22 East

Union, NJ 07083

Date Received10/09/2001 **SciLab Job No.** 201101831**Date Examined**10/10/2001 **P.O. #** Y2-1040**Page 10 of 15****RE:** Y2-1040; GAB Robins N America Inc.; 22 Courtland Street

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
1-045	201101831-42	Yes	<1.% ¹
Location: 16th Floor, Office, West Center Description: Grey, Heterogeneous, Debris Asbestos Types: Chrysotile <1. % Other Material: Cellulose 5. %, Fibrous glass 30. %, Non-fibrous >64. %			
1-046	201101831-43	Yes	<1.% ¹
Location: 15th Floor, Office, South West Description: Grey, Heterogeneous, Debris Asbestos Types: Chrysotile <1. % Other Material: Cellulose 10. %, Fibrous glass 35. %, Non-fibrous >54. %			
1-047	201101831-44	Yes	<1.% ¹
Location: 15th Floor, Office, West Center Description: Grey, Heterogeneous, Debris Asbestos Types: Chrysotile <1. % Other Material: Cellulose 10. %, Fibrous glass 45. %, Non-fibrous >44. %			
1-048	201101831-45	Yes	<1.% ¹
Location: 15th Floor, Office, North West Description: Grey, Heterogeneous, Debris Asbestos Types: Chrysotile <1. % Other Material: Cellulose 20. %, Fibrous glass 40. %, Non-fibrous >39. %			
1-049	201101831-46	Yes	<1.% ¹
Location: 14th Floor, Office, South West Description: Grey, Heterogeneous, Debris Asbestos Types: Chrysotile <1. % Other Material: Cellulose 25. %, Fibrous glass 40. %, Non-fibrous >34. %			

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8800 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

Hillmann Environmental Company, Inc. **Date Received** 10/09/2001 **SciLab Job No.** 201101831
Attn: Mike Nehlsen **Date Examined** 10/10/2001 **P.O. #** Y2-1040
 1600 Rt. 22 East **Page 11 of 15**
 Union, NJ 07083 **RE: Y2-1040; GAB Robins N America Inc.; 22 Courtland Street**

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
1-050	201101831-47	Yes	<1.% ¹
Location: 14th Floor, Office, North West			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile <1. %			
Other Material: Cellulose 25. %, Fibrous glass 45. %, Non-fibrous >29. %			
1-051	201101831-48	Yes	<1.% ¹
Location: 14th Floor, Office, West Center			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile <1. %			
Other Material: Cellulose 20. %, Fibrous glass 45. %, Non-fibrous >34. %			
1-052	201101831-49	Yes	<1.% ¹
Location: 12th Floor, Office, South West			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile <1. %			
Other Material: Cellulose 15. %, Fibrous glass 40. %, Non-fibrous >44. %			
1-053	201101831-50	Yes	<1.% ¹
Location: 12th Floor, Office, South East			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile Trace			
Other Material: Cellulose 7. %, Fibrous glass 35. %, Non-fibrous 58. %			
1-054	201101831-51	Yes	<1.% ¹
Location: 12th Floor, Office, North West			
Description: Grey, Heterogeneous, Debris			
Asbestos Types: Chrysotile Trace			
Other Material: Cellulose 15. %, Fibrous glass 45. %, Non-fibrous 40. %			