

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

**AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)**

Client: Jack Resnick & Sons, Inc.
Address: 75 Park Place
Project ID: 211658

Field ID Number	Sample ID	Date	Time	FloorSample Location Description	Analytical Sensitivity	Asbestos Structures/
4061-01	11990	12/10/01	5:30 PM	9th Floor: Reception Area	LT ANYL SENS	< 0.0045
4061-02	11991	12/10/01	5:33 PM	9th Floor: Opposite Window North Side	LT ANYL SENS	< 0.0045
4061-03	11992	12/10/01	5:36 PM	9th Floor: Opposite Window North West Corner	LT ANYL SENS	< 0.0045
4061-04	11993	12/10/01	5:39 PM	9th Floor: Corridor Opposite Stairwell X	LT ANYL SENS	< 0.0045
4061-05	11994	12/10/01	5:42 PM	9th Floor: Opposite Window North East Corner	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

**AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)**

Client: Jack Resnick & Sons, Inc.
Address: 75 Park Place
Project ID: 211658

Field ID Number	Sample ID	Date	Time	Floor Sample Location Description	Analytical Sensitivity	Asbestos Structures/
4090-06	11995	12/10/01	5:45 PM	9th Floor: South East	LT ANYL SENS	< 0.0045
4090-07	11996	12/10/01	5:48 PM	9th Floor: S.W. Corner Inside Pantry	LT ANYL SENS	< 0.0045
4090-08	11997	12/10/01	8:40 PM	8th Floor: Reception Area	LT ANYL SENS	< 0.0045
4090-09	11998	12/10/01	8:43 PM	8th Floor: North Side Opposite Window	LT ANYL SENS	< 0.0045
4090-10	11999	12/10/01	8:46 PM	8th Floor: South East Opposite Computer Room	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

**AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)**

Client: Jack Resnick & Sons, Inc.

Address: 75 Park Place

Project ID: 211658

Field ID Number	Sample ID	Date	Time	Floor/Sample Location Description	Analytical Sensitivity	Asbestos Structures/
4091-11	12000	12/10/01	8:49 PM	8th Floor: S.W. Corner Opposite Window	LT ANYL SENS	< 0.0045
4091-12	12001	12/10/01	8:52 PM	8th Floor: N.E. Adj. To Window	LT ANYL SENS	< 0.0045
4091-13	12002	12/10/01	8:55 PM	8th Floor: Central Area	LT ANYL SENS	< 0.0045
4091-14	12003	12/10/01	8:58 PM	8th Floor: S.W. Near Pantry	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY