

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m ³)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels									300			
EPA Site Specific Trigger Levels									3000	Air Quality Levels	Site Specific Trigger Levels	
TotalHg ST1 3/6/06	06BR0333-01	Southwest Area (sidewalk bridge level)	3/6/06	0.59	Mercury	EPA 3241/631	BRL	3/8/06	< 25.0	No	No	
TotalHg ST2 3/6/06	06BR0333-02	Southeast Area (sidewalk bridge level)	3/6/06	0.59	Mercury	EPA 3241/631	BRL	3/8/06	< 25.0	No	No	
TotalHg ST4 3/6/06	06BR0333-03	Northwest Area (street level)	3/6/06	0.57	Mercury	EPA 3241/631	BRL	3/8/06	< 26.0	No	No	
TotalHg ST5 3/6/06	06BR0333-04	Firehouse #10 (roof level)	3/6/06	0.58	Mercury	EPA 3241/631	BRL	3/8/06	< 26.0	No	No	
TotalHg ST10 3/6/06	06BR0333-05	North Side Sidewalk Bridge	3/6/06	0.58	Mercury	EPA 3241/631	BRL	3/8/06	< 26.0	No	No	
TotalHg ST11 3/6/06	06BR0333-06	30 Trinity Place (roof level)	3/6/06	0.58	Mercury	EPA 3241/631	BRL	3/8/06	< 26.0	No	No	
TotalHg ST12 3/6/06	06BR0333-07	110 Greenwich Street (roof level)	3/6/06	0.58	Mercury	EPA 3241/631	BRL	3/8/06	< 26.0	No	No	
TotalHg ST13 3/6/06	06BR0333-08	Maniott Hotel, 38th Floor (roof level)	3/6/06	0.58	Mercury	EPA 3241/631	BRL	3/8/06	< 26.0	No	No	
TotalHg ST14 3/6/06	06BR0333-09	West Face - South end at corner (scaffolding level)	3/6/06	0.58	Mercury	EPA 3241/631	BRL	3/8/06	< 26.0	No	No	
TotalHg ST15 3/6/06	06BR0333-10	South Face - East end at corner (scaffolding level)	3/6/06	0.58	Mercury	EPA 3241/631	BRL	3/8/06	< 26.0	No	No	
TotalHg ST16 3/6/06	06BR0333-11	East Face - North end at corner (scaffolding level)	3/6/06	0.57	Mercury	EPA 3241/631	BRL	3/8/06	< 26.0	No	No	
TotalHg ST17 3/6/06	06BR0333-12	North Face - West end at corner (scaffolding level)	3/6/06	0.58	Mercury	EPA 3241/631	BRL	3/8/06	< 26.0	No	No	
TotalHg ST1 3/7/06	06BR0342-01	Southwest Area (sidewalk bridge level)	3/7/06	0.57	Mercury	EPA 3241/631	BRL	3/9/06	< 26.0	No	No	
TotalHg ST2 3/7/06	06BR0342-02	Southeast Area (sidewalk bridge level)	3/7/06	0.58	Mercury	EPA 3241/631	BRL	3/9/06	< 26.0	No	No	
TotalHg ST4 3/7/06	06BR0342-03	Northwest Area (street level)	3/7/06	0.57	Mercury	EPA 3241/631	BRL	3/9/06	< 26.0	No	No	
TotalHg ST5 3/7/06	06BR0342-04	Firehouse #10 (roof level)	3/7/06	0.57	Mercury	EPA 3241/631	BRL	3/9/06	< 26.0	No	No	
TotalHg ST11 3/7/06	06BR0342-05	30 Trinity Place (roof level)	3/7/06	0.57	Mercury	EPA 3241/631	BRL	3/9/06	< 26.0	No	No	
TotalHg ST12 3/7/06	06BR0342-06	110 Greenwich Street (roof level)	3/7/06	0.57	Mercury	EPA 3241/631	BRL	3/9/06	< 26.0	No	No	
TotalHg ST13 3/7/06	06BR0342-07	Maniott Hotel, 38th Floor (roof level)	3/7/06	0.57	Mercury	EPA 3241/631	BRL	3/9/06	< 26.0	No	No	
TotalHg ST14 3/7/06	06BR0342-08	West Face - South end at corner (scaffolding level)	3/7/06	0.57	Mercury	EPA 3241/631	BRL	3/9/06	< 26.0	No	No	
TotalHg ST15 3/7/06	06BR0342-09	South Face - East end at corner (scaffolding level)	3/7/06	0.57	Mercury	EPA 3241/631	BRL	3/9/06	< 26.0	No	No	
TotalHg ST16 3/7/06	06BR0342-10	East Face - North end at corner (scaffolding level)	3/7/06	0.57	Mercury	EPA 3241/631	BRL	3/9/06	< 26.0	No	No	
TotalHg ST17 3/7/06	06BR0342-11	North Face - West end at corner (scaffolding level)	3/7/06	0.57	Mercury	EPA 3241/631	BRL	3/9/06	< 26.0	No	No	
TotalHg ST1 3/8/06	06BR0349-01	Southwest Area (sidewalk bridge level)	3/8/06	0.56	Mercury	EPA 3241/631	BRL	3/10/06	< 27.0	No	No	
TotalHg ST2 3/8/06	06BR0349-02	Southeast Area (sidewalk bridge level)	3/8/06	0.56	Mercury	EPA 3241/631	BRL	3/10/06	< 27.0	No	No	
TotalHg ST4 3/8/06	06BR0349-03	Northwest Area (street level)	3/8/06	0.57	Mercury	EPA 3241/631	BRL	3/10/06	< 26.0	No	No	
TotalHg ST5 3/8/06	06BR0349-04	Firehouse #10 (roof level)	3/8/06	0.57	Mercury	EPA 3241/631	BRL	3/10/06	< 26.0	No	No	
TotalHg ST10 3/8/06	06BR0349-05	North Side Sidewalk Bridge	3/8/06	0.55	Mercury	EPA 3241/631	BRL	3/10/06	< 27.0	No	No	
TotalHg ST11 3/8/06	06BR0349-06	30 Trinity Place (roof level)	3/8/06	0.57	Mercury	EPA 3241/631	BRL	3/10/06	< 26.0	No	No	
TotalHg ST12 3/8/06	06BR0349-07	110 Greenwich Street (roof level)	3/8/06	0.57	Mercury	EPA 3241/631	BRL	3/10/06	< 26.0	No	No	
TotalHg ST13 3/8/06	06BR0349-08	Maniott Hotel, 38th Floor (roof level)	3/8/06	0.56	Mercury	EPA 3241/631	BRL	3/10/06	< 27.0	No	No	
TotalHg ST14 3/8/06	06BR0349-09	West Face - South end at corner (scaffolding level)	3/8/06	0.58	Mercury	EPA 3241/631	BRL	3/10/06	< 26.0	No	No	
TotalHg ST15 3/8/06	06BR0349-10	South Face - East end at corner (scaffolding level)	3/8/06	0.57	Mercury	EPA 3241/631	BRL	3/10/06	< 26.0	No	No	
TotalHg ST16 3/8/06	06BR0349-11	East Face - North end at corner (scaffolding level)	3/8/06	0.57	Mercury	EPA 3241/631	BRL	3/10/06	< 26.0	No	No	
TotalHg ST17 3/8/06	06BR0349-12	North Face - West end at corner (scaffolding level)	3/8/06	0.58	Mercury	EPA 3241/631	BRL	3/10/06	< 26.0	No	No	
TotalHg ST1 3/9/06	06BR0354-01	Southwest Area (sidewalk bridge level)	3/9/06	0.57	Mercury	EPA 3241/631	BRL	3/11/06	< 26.0	No	No	
TotalHg ST2 3/9/06	06BR0354-02	Southeast Area (sidewalk bridge level)	3/9/06	0.57	Mercury	EPA 3241/631	BRL	3/11/06	< 26.0	No	No	
TotalHg ST4 3/9/06	06BR0354-03	Northwest Area (street level)	3/9/06	0.57	Mercury	EPA 3241/631	BRL	3/11/06	< 26.0	No	No	
TotalHg ST5 3/9/06	06BR0354-04	Firehouse #10 (roof level)	3/9/06	0.57	Mercury	EPA 3241/631	BRL	3/11/06	< 26.0	No	No	
TotalHg ST10 3/9/06	06BR0354-05	North Side Sidewalk Bridge	3/9/06	0.57	Mercury	EPA 3241/631	BRL	3/11/06	< 26.0	No	No	
3/9/06FD	06BR0354-13	Station 10 Field Duplicate	3/9/06	0.57	Mercury	EPA 3241/631	BRL	3/11/06	< 26.0	No	No	
TotalHg ST11 3/9/06	06BR0354-06	30 Trinity Place (roof level)	3/9/06	0.57	Mercury	EPA 3241/631	BRL	3/11/06	< 26.0	No	No	
TotalHg ST12 3/9/06	06BR0354-07	110 Greenwich Street (roof level)	3/9/06	0.58	Mercury	EPA 3241/631	BRL	3/11/06	< 26.0	No	No	
TotalHg ST13 3/9/06	06BR0354-08	Maniott Hotel, 38th Floor (roof level)	3/9/06	0.57	Mercury	EPA 3241/631	BRL	3/11/06	< 26.0	No	No	
TotalHg ST14 3/9/06	06BR0354-09	West Face - South end at corner (scaffolding level)	3/9/06	0.57	Mercury	EPA 3241/631	BRL	3/11/06	< 26.0	No	No	
TotalHg ST15 3/9/06	06BR0354-10	South Face - East end at corner (scaffolding level)	3/9/06	0.57	Mercury	EPA 3241/631	BRL	3/11/06	< 26.0	No	No	
TotalHg ST16 3/9/06	06BR0354-11	East Face - North end at corner (scaffolding level)	3/9/06	0.57	Mercury	EPA 3241/631	BRL	3/11/06	< 26.0	No	No	
TotalHg ST17 3/9/06	06BR0354-12	North Face - West end at corner (scaffolding level)	3/9/06	0.57	Mercury	EPA 3241/631	BRL	3/11/06	< 26.0	No	No	
TotalHg ST1 3/10/06	06BR0362-01	Southwest Area (sidewalk bridge level)	3/10/06	0.58	Mercury	EPA 3241/631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST2 3/10/06	06BR0362-02	Southeast Area (sidewalk bridge level)	3/10/06	0.58	Mercury	EPA 3241/631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST4 3/10/06	06BR0362-03	Northwest Area (street level)	3/10/06	0.59	Mercury	EPA 3241/631	BRL	3/14/06	< 25.0	No	No	
TotalHg ST5 3/10/06	06BR0362-04	Firehouse #10 (roof level)	3/10/06	0.57	Mercury	EPA 3241/631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST10 3/10/06	06BR0362-05	North Side Sidewalk Bridge	3/10/06	0.59	Mercury	EPA 3241/631	BRL	3/14/06	< 25.0	No	No	
TotalHg ST11 3/10/06	06BR0362-06	30 Trinity Place (roof level)	3/10/06	0.59	Mercury	EPA 3241/631	BRL	3/14/06	< 25.0	No	No	
TotalHg ST12 3/10/06	06BR0362-07	110 Greenwich Street (roof level)	3/10/06	0.59	Mercury	EPA 3241/631	BRL	3/14/06	< 25.0	No	No	
TotalHg ST13 3/10/06	06BR0362-08	Maniott Hotel, 38th Floor (roof level)	3/10/06	0.59	Mercury	EPA 3241/631	BRL	3/14/06	< 25.0	No	No	
TotalHg ST14 3/10/06	06BR0362-09	West Face - South end at corner (scaffolding level)	3/10/06	0.55	Mercury	EPA 3241/631	BRL	3/14/06	< 27.0	No	No	
TotalHg ST15 3/10/06	06BR0362-10	South Face - East end at corner (scaffolding level)	3/10/06	0.53	Mercury	EPA 3241/631	BRL	3/14/06	< 28.0	No	No	
TotalHg ST16 3/10/06	06BR0362-11	East Face - North end at corner (scaffolding level)	3/10/06	0.54	Mercury	EPA 3241/631	BRL	3/14/06	< 28.0	No	No	
TotalHg ST17 3/10/06	06BR0362-12	North Face - West end at corner (scaffolding level)	3/10/06	0.55	Mercury	EPA 3241/631	BRL	3/14/06	< 27.0	No	No	
TotalHg ST1 3/11/06	06BR0363-01	Southwest Area (sidewalk bridge level)	3/11/06	0.57	Mercury	EPA 3241/631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST2 3/11/06	06BR0363-02	Southeast Area (sidewalk bridge level)	3/11/06	0.57	Mercury	EPA 3241/631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST4 3/11/06	06BR0363-03	Northwest Area (street level)	3/11/06	0.57	Mercury	EPA 3241/631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST5 3/11/06	06BR0363-04	Firehouse #10 (roof level)	3/11/06	0.57	Mercury	EPA 3241/631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST10 3/11/06	06BR0363-05	North Side Sidewalk Bridge	3/11/06	0.57	Mercury	EPA 3241/631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST11 3/11/06	06BR0363-06	30 Trinity Place (roof level)	3/11/06	0.57	Mercury	EPA 3241/631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST12 3/11/06	06BR0363-07	110 Greenwich Street (roof level)	3/11/06	0.55	Mercury	EPA 3241/631	BRL	3/14/06	< 27.0	No	No	

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels									300	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels									3000			
TotalHg ST13-3/11/06	06BR0363-06	Marriott Hotel, 38th Floor (roof level)	3/11/06	0.53	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST14-3/11/06	06BR0363-09	West Face - South end at corner (scaffolding level)	3/11/06	0.57	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST15-3/11/06	06BR0363-10	South Face - East end at corner (scaffolding level)	3/11/06	0.58	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST16-3/11/06	06BR0363-11	East Face - North end at corner (scaffolding level)	3/11/06	0.58	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST17-3/11/06	06BR0363-12	North Face - West end at corner (scaffolding level)	3/11/06	0.57	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST1-3/12/06	06BR0364-01	Southwest Area (sidewalk bridge level)	3/12/06	0.57	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST2-3/12/06	06BR0364-02	Southeast Area (sidewalk bridge level)	3/12/06	0.57	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST4-3/12/06	06BR0364-03	Northwest Area (street level)	3/12/06	0.55	Mercury	EPA 324/1631	BRL	3/14/06	< 27.0	No	No	
TotalHg ST5-3/12/06	06BR0364-04	Finhouse #10 (roof level)	3/12/06	0.57	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST10-3/12/06	06BR0364-05	North Side Sidewalk Bridge	3/12/06	0.55	Mercury	EPA 324/1631	BRL	3/14/06	< 27.0	No	No	
TotalHg ST11-3/12/06	06BR0364-06	90 Trinity Place (roof level)	3/12/06	0.56	Mercury	EPA 324/1631	BRL	3/14/06	< 27.0	No	No	
TotalHg ST12-3/12/06	06BR0364-07	110 Greenwich Street (roof level)	3/12/06	0.58	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg ST13-3/12/06	06BR0364-08	Marriott Hotel, 38th Floor (roof level)	3/12/06	0.59	Mercury	EPA 324/1631	BRL	3/14/06	< 25.0	No	No	
TotalHg ST14-3/12/06	06BR0364-09	West Face - South end at corner (scaffolding level)	3/12/06	0.60	Mercury	EPA 324/1631	BRL	3/14/06	< 25.0	No	No	
TotalHg ST15-3/12/06	06BR0364-10	South Face - East end at corner (scaffolding level)	3/12/06	0.60	Mercury	EPA 324/1631	BRL	3/14/06	< 25.0	No	No	
TotalHg ST16-3/12/06	06BR0364-11	East Face - North end at corner (scaffolding level)	3/12/06	0.59	Mercury	EPA 324/1631	BRL	3/14/06	< 25.0	No	No	
TotalHg ST17-3/12/06	06BR0364-12	North Face - West end at corner (scaffolding level)	3/12/06	0.60	Mercury	EPA 324/1631	BRL	3/14/06	< 25.0	No	No	

Note
1. Mercury sample was not available for analysis at Station 10 (North Side [sidewalk bridge level]) on March 7, 2006, on account of pump failure.

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (µg/m³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									10			
EPA Site Specific Trigger Levels									26			
SILICA-511-3/8/05	00C1	Southwest Area (sidewalk bridge level)	3/8/05	3.51	Silica	NIOSH 7500 XRD	EMSL	3/10/06	<1	No	Nc	
SILICA-512-3/8/05	00C2	Southwest Area (sidewalk bridge level)	3/8/05	3.51	Silica	NIOSH 7500 XRD	EMSL	3/10/06	<1	No	Nc	
SILICA-514-3/8/05	00C3	Northwest Area (dwell level)	3/8/05	3.56	Silica	NIOSH 7500 XRD	EMSL	3/10/06	<1	No	Nc	
SILICA-515-3/8/05	00C4	Firehouse #10 (roof level)	3/8/05	3.47	Silica	NIOSH 7500 XRD	EMSL	3/10/06	<1	No	Nc	
SILICA-511C-3/8/05	00C5	North Side Sidewalk Bridge	3/8/05	3.55	Silica	NIOSH 7500 XRD	EMSL	3/10/06	<1	No	Nc	
SILICA-511-3/8/05	00C6	90 Trinity Place (roof level)	3/8/05	3.56	Silica	NIOSH 7500 XRD	EMSL	3/10/06	<1	No	Nc	
SILICA-512-3/8/05	00C7	110 Greenwch Street (roof eval)	3/8/05	3.56	Silica	NIOSH 7500 XRD	EMSL	3/10/06	<1	No	Nc	
SILICA-515-3/8/05	00C8	Marriott hotel, 38th Floor (roof eval)	3/8/05	3.51	Silica	NIOSH 7500 XRD	EMSL	3/10/06	<1	No	Nc	
SILICA-514-3/8/05	00C9	West Face - South end at corner (scaffolding level)	3/8/05	3.4	Silica	NIOSH 7500 XRD	EMSL	3/10/06	<1	No	Nc	
SILICA-516-3/8/05	0010	South Face - East end at corner (scaffolding level)	3/8/05	3.69	Silica	NIOSH 7500 XRD	EMSL	3/10/06	<1	No	Nc	
SILICA-517-3/8/05	0011	East Face - North end at corner (scaffolding level)	3/8/05	3.56	Silica	NIOSH 7500 XRD	EMSL	3/10/06	<1	No	Nc	
SILICA-517-3/8/05	0012	North Face - West end at corner (scaffolding level)	3/8/05	3.4	Silica	NIOSH 7500 XRD	EMSL	3/10/06	<1	No	Nc	
SILICA-511-3/8/05	00C1	Southwest Area (sidewalk bridge level)	3/8/05	3.59	Silica	NIOSH 7500 XRD	EMSL	3/11/06	<1	No	Nc	
SILICA-512-3/8/05	00C2	Southwest Area (sidewalk bridge level)	3/8/05	3.56	Silica	NIOSH 7500 XRD	EMSL	3/11/06	<1	No	Nc	
SILICA-514-3/8/05	00C3	Northwest Area (dwell level)	3/8/05	3.57	Silica	NIOSH 7500 XRD	EMSL	3/11/06	<1	No	Nc	
SILICA-515-3/8/05	00C4	Firehouse #10 (roof level)	3/8/05	3.59	Silica	NIOSH 7500 XRD	EMSL	3/11/06	<1	No	Nc	
SILICA-511C-3/8/05	00C5	North Side Sidewalk Bridge	3/8/05	3.54	Silica	NIOSH 7500 XRD	EMSL	3/11/06	<1	No	Nc	
SILICA-511C-3/8/05	0013	Redden - N Field Tuffalana	3/8/05	3.53	Silica	NIOSH 7500 XRD	EMSL	3/11/06	<1	No	Nc	
SILICA-511-3/8/05	00C6	90 Trinity Place (roof level)	3/8/05	3.59	Silica	NIOSH 7500 XRD	EMSL	3/11/06	<1	No	Nc	
SILICA-512-3/8/05	00C7	110 Greenwch Street (roof eval)	3/8/05	3.6	Silica	NIOSH 7500 XRD	EMSL	3/11/06	<1	No	Nc	
SILICA-515-3/8/05	00C8	Marriott hotel, 38th Floor (roof eval)	3/8/05	3.55	Silica	NIOSH 7500 XRD	EMSL	3/11/06	<1	No	Nc	
SILICA-514-3/8/05	00C9	West Face - South end at corner (scaffolding level)	3/8/05	3.35	Silica	NIOSH 7500 XRD	EMSL	3/11/06	<1	No	Nc	
SILICA-516-3/8/05	0010	South Face - East end at corner (scaffolding level)	3/8/05	3.59	Silica	NIOSH 7500 XRD	EMSL	3/11/06	<1	No	Nc	
SILICA-517-3/8/05	0011	East Face - North end at corner (scaffolding level)	3/8/05	3.59	Silica	NIOSH 7500 XRD	EMSL	3/11/06	<1	No	Nc	
SILICA-517-3/8/05	0012	North Face - West end at corner (scaffolding level)	3/8/05	3.59	Silica	NIOSH 7500 XRD	EMSL	3/11/06	<1	No	Nc	
SILICA-511-3/8/05	00C1	Southwest Area (sidewalk bridge level)	3/10/06	3.61	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-512-3/8/05	00C3	Southwest Area (sidewalk bridge level)	3/10/06	3.67	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-515-3/8/05	00C4	Northwest Area (dwell level)	3/10/06	3.65	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-511C-3/8/05	00C5	North Side Sidewalk Bridge	3/10/06	3.66	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-511-3/8/05	00C6	90 Trinity Place (roof level)	3/10/06	3.66	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-512-3/8/05	00C7	110 Greenwch Street (roof eval)	3/10/06	3.4	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-515-3/8/05	00C8	Marriott hotel, 38th Floor (roof eval)	3/10/06	3.62	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-514-3/8/05	00C9	West Face - South end at corner (scaffolding level)	3/10/06	3.43	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-516-3/8/05	0010	South Face - East end at corner (scaffolding level)	3/10/06	3.34	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-517-3/8/05	0011	East Face - North end at corner (scaffolding level)	3/10/06	3.4	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-517-3/8/05	0012	North Face - West end at corner (scaffolding level)	3/10/06	3.43	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-511-3/11/05	00C1	Southwest Area (sidewalk bridge level)	3/11/06	3.56	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-512-3/11/05	00C2	Southwest Area (sidewalk bridge level)	3/11/06	3.55	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-514-3/11/05	00C3	Northwest Area (dwell level)	3/11/06	3.45	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-515-3/11/05	00C4	Firehouse #10 (roof level)	3/11/06	3.58	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-511C-3/11/05	00C5	North Side Sidewalk Bridge	3/11/06	3.55	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-511-3/11/05	00C6	90 Trinity Place (roof level)	3/11/06	3.57	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-512-3/11/05	00C7	110 Greenwch Street (roof eval)	3/11/06	3.43	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-515-3/11/05	00C8	Marriott hotel, 38th Floor (roof eval)	3/11/06	3.31	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-514-3/11/05	00C9	West Face - South end at corner (scaffolding level)	3/11/06	3.54	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-516-3/11/05	0010	South Face - East end at corner (scaffolding level)	3/11/06	3.63	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-516-3/11/05	0011	East Face - North end at corner (scaffolding level)	3/11/06	3.63	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-517-3/11/05	0012	North Face - West end at corner (scaffolding level)	3/11/06	3.54	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-512-3/12/05	00C1	Southwest Area (sidewalk bridge level)	3/12/06	3.55	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-515-3/12/05	00C2	Southwest Area (sidewalk bridge level)	3/12/06	3.54	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-514-3/12/05	00C3	Northwest Area (dwell level)	3/12/06	3.46	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-515-3/12/05	00C4	Firehouse #10 (roof level)	3/12/06	3.55	Silica	NIOSH 7500 XRD	EMSL	3/13/06	6	No	Nc	
SILICA-511C-3/12/05	00C5	North Side Sidewalk Bridge	3/12/06	3.46	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-511-3/12/05	00C6	90 Trinity Place (roof level)	3/12/06	3.51	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-512-3/12/05	00C7	110 Greenwch Street (roof eval)	3/12/06	3.61	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-515-3/12/05	00C8	Marriott hotel, 38th Floor (roof eval)	3/12/06	3.71	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-514-3/12/05	00C9	West Face - South end at corner (scaffolding level)	3/12/06	3.75	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-516-3/12/05	0010	South Face - East end at corner (scaffolding level)	3/12/06	3.75	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-516-3/12/05	0011	East Face - North end at corner (scaffolding level)	3/12/06	3.72	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-517-3/12/05	0012	North Face - West end at corner (scaffolding level)	3/12/06	3.75	Silica	NIOSH 7500 XRD	EMSL	3/13/06	<1	No	Nc	
SILICA-511-3/13/05	00C1	Southwest Area (sidewalk bridge level)	3/13/06	3.5	Silica	NIOSH 7500 XRD	EMSL	3/14/06	<1	No	Nc	
SILICA-512-3/13/05	00C2	Southwest Area (sidewalk bridge level)	3/13/06	3.5	Silica	NIOSH 7500 XRD	EMSL	3/14/06	<1	No	Nc	
SILICA-515-3/13/05	00C3	Northwest Area (dwell level)	3/13/06	3.53	Silica	NIOSH 7500 XRD	EMSL	3/14/06	<1	No	Nc	
SILICA-511C-3/13/05	00C4	North Side Sidewalk Bridge	3/13/06	3.53	Silica	NIOSH 7500 XRD	EMSL	3/14/06	<1	No	Nc	
SILICA-511-3/13/05	00C6	90 Trinity Place (roof level)	3/13/06	3.59	Silica	NIOSH 7500 XRD	EMSL	3/14/06	<1	No	Nc	
SILICA-512-3/13/05	00C7	110 Greenwch Street (roof eval)	3/13/06	3.59	Silica	NIOSH 7500 XRD	EMSL	3/14/06	<1	No	Nc	
SILICA-515-3/13/05	00C8	Marriott hotel, 38th Floor (roof eval)	3/13/06	3.71	Silica	NIOSH 7500 XRD	EMSL	3/14/06	<1	No	Nc	
SILICA-514-3/13/05	00C9	West Face - South end at corner (scaffolding level)	3/13/06	3.62	Silica	NIOSH 7500 XRD	EMSL	3/14/06	<1	No	Nc	
SILICA-516-3/13/05	0010	South Face - East end at corner (scaffolding level)	3/13/06	3.61	Silica	NIOSH 7500 XRD	EMSL	3/14/06	<1	No	Nc	
SILICA-516-3/13/05	0011	East Face - North end at corner (scaffolding level)	3/13/06	3.61	Silica	NIOSH 7500 XRD	EMSL	3/14/06	<1	No	Nc	
SILICA-517-3/13/05	0012	North Face - West end at corner (scaffolding level)	3/13/06	3.63	Silica	NIOSH 7500 XRD	EMSL	3/14/06	<1	No	Nc	
SILICA-511-3/14/05	00C1	Southwest Area (sidewalk bridge level)	3/14/06	3.5	Silica	NIOSH 7500 XRD	EMSL	3/15/06	<1	No	Nc	
SILICA-512-3/14/05	00C2	Southwest Area (sidewalk bridge level)	3/14/06	3.67	Silica	NIOSH 7500 XRD	EMSL	3/15/06	<1	No	Nc	
SILICA-514-3/14/05	00C3	Northwest Area (dwell level)	3/14/06	3.7	Silica	NIOSH 7500 XRD	EMSL	3/15/06	<1	No	Nc	
SILICA-515-3/14/05	00C4	Firehouse #10 (roof level)	3/14/06	3.63	Silica	NIOSH 7500 XRD	EMSL	3/15/06	2	No	Nc	
SILICA-511C-3/14/05	00C5	North Side Sidewalk Bridge	3/14/06	3.69	Silica	NIOSH 7500 XRD	EMSL	3/15/06	<1	No	Nc	
SILICA-511-3/14/05	00C6	90 Trinity Place (roof level)	3/14/06	3.69	Silica	NIOSH 7500 XRD	EMSL	3/15/06	<1	No	Nc	
SILICA-512-3/14/05	00C7	110 Greenwch Street (roof eval)	3/14/06	3.6	Silica	NIOSH 7500 XRD	EMSL	3/15/06	<1	No	Nc	
SILICA-515-3/14/05	00C8	Marriott hotel, 38th Floor (roof eval)	3/14/06	3.74	Silica	NIOSH 7500 XRD	EMSL	3/15/06	<1	No	Nc	
SILICA-514-3/14/05	00C9	West Face - South end at corner (scaffolding level)	3/14/06	3.44	Silica	NIOSH 7500 XRD	EMSL	3/15/06	5	No	Nc	
SILICA-516-3/14/05	0010	South Face - East end at corner (scaffolding level)	3/14/06	3.58	Silica	NIOSH 7500 XRD	EMSL	3/15/06	<1	No	Nc	
SILICA-516-3/14/05	0011	East Face - North end at corner (scaffolding level)	3/14/06	3.62	Silica	NIOSH 7500 XRD	EMSL	3/15/06	<1	No	Nc	
SILICA-517-3/14/05	0012	North Face - West end at corner (scaffolding level)	3/14/06	3.56	Silica	NIOSH 7500 XRD	EMSL	3/15/06	<1	No	Nc	

1. The asbestos sample at Station 13 (East Face - North end at corner (scaffold level)) on March 13, 2006 was not available for analysis on account of filter damage.

1501 Liberty Street Demolition Project

As before,

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels EPA Site Specific Trigger Levels											0.0005	0.0005	
ASBESTOS-ST1-3/1/06	0001	Southwest Area (sidewalk bridge level)	3/1/06	1	3,000	Asbestos	PCME	EMSL	3/1/06	<0.0002	No	No	
ASBESTOS-ST2-3/1/06	0002	Southwest Area (sidewalk bridge level)	3/1/06	1	3,000	Asbestos	PCME	EMSL	3/1/06	<0.0002	No	No	
ASBESTOS-ST3-3/1/06	0003	Northwest Area (stair level)	3/1/06	1	3,000	Asbestos	PCME	EMSL	3/1/06	<0.0002	No	No	
ASBESTOS-ST5-3/1/06	0004	Finchouse #10 (roof level)	3/1/06	1	3,000	Asbestos	PCME	EMSL	3/1/06	<0.0002	No	No	
ASBESTOS-ST10-3/1/06	0005	North Side Sidewalk Bridge	3/1/06	1	3,000	Asbestos	PCME	EMSL	3/1/06	<0.0002	No	No	
ASBESTOS-ST11-3/1/06	0006	80 "riny" Plaza (roof level)	3/1/06	1	3,000	Asbestos	PCME	EMSL	3/1/06	<0.0002	No	No	
ASBESTOS-ST18-3/1/06	0007	110 Greenwich Street (roof level)	3/1/06	1	3,000	Asbestos	PCME	EMSL	3/1/06	<0.0002	No	No	
ASBESTOS-ST19-3/1/06	0008	Marriot Hotel, 34th Floor (roof level)	3/1/06	1	3,000	Asbestos	PCME	EMSL	3/1/06	<0.0002	No	No	
ASBESTOS-ST14-3/1/06	0009	West Face - South end at corner (scaffolding level)	3/1/06	1	3,000	Asbestos	PCME	EMSL	3/1/06	<0.0002	No	No	
ASBESTOS-ST15-3/1/06	0010	South Face - East end at corner (scaffolding level)	3/1/06	1	3,000	Asbestos	PCME	EMSL	3/1/06	<0.0002	No	No	
ASBESTOS-ST16-3/1/06	0011	East Face - North end at corner (scaffolding level)	3/1/06	1	3,000	Asbestos	PCME	EMSL	3/1/06	<0.0002	No	No	
ASBESTOS-ST17-3/1/06	0012	North Face - West end at corner (scaffolding level)	3/1/06	1	3,000	Asbestos	PCME	EMSL	3/1/06	<0.0002	No	No	
ASBESTOS-ST1-3/2/06	0001	Southwest Area (sidewalk bridge level)	3/2/06	1	3,000	Asbestos	PCME	EMSL	3/2/06	<0.0002	No	No	
ASBESTOS-ST2-3/2/06	0002	Southwest Area (sidewalk bridge level)	3/2/06	1	3,000	Asbestos	PCME	EMSL	3/2/06	<0.0002	No	No	
ASBESTOS-ST3-3/2/06	0003	Northwest Area (stair level)	3/2/06	1	3,000	Asbestos	PCME	EMSL	3/2/06	<0.0002	No	No	
ASBESTOS-ST5-3/2/06	0004	Finchouse #10 (roof level)	3/2/06	1	3,000	Asbestos	PCME	EMSL	3/2/06	<0.0002	No	No	
ASBESTOS-ST10-3/2/06	0005	North Side Sidewalk Bridge	3/2/06	1	3,000	Asbestos	PCME	EMSL	3/2/06	<0.0002	No	No	
ASBESTOS-ST11-3/2/06	0006	80 "riny" Plaza (roof level)	3/2/06	1	3,000	Asbestos	PCME	EMSL	3/2/06	<0.0002	No	No	
ASBESTOS-ST18-3/2/06	0007	110 Greenwich Street (roof level)	3/2/06	1	3,000	Asbestos	PCME	EMSL	3/2/06	<0.0002	No	No	
ASBESTOS-ST14-3/2/06	0008	Marriot Hotel, 34th Floor (roof level)	3/2/06	1	3,000	Asbestos	PCME	EMSL	3/2/06	<0.0002	No	No	
ASBESTOS-ST15-3/2/06	0009	West Face - South end at corner (scaffolding level)	3/2/06	1	3,000	Asbestos	PCME	EMSL	3/2/06	<0.0002	No	No	
ASBESTOS-ST16-3/2/06	0010	South Face - East end at corner (scaffolding level)	3/2/06	1	3,000	Asbestos	PCME	EMSL	3/2/06	<0.0002	No	No	
ASBESTOS-ST17-3/2/06	0011	East Face - North end at corner (scaffolding level)	3/2/06	1	3,000	Asbestos	PCME	EMSL	3/2/06	<0.0002	No	No	
ASBESTOS-ST1-3/3/06	0001	Southwest Area (sidewalk bridge level)	3/3/06	1	3,000	Asbestos	PCME	EMSL	3/3/06	<0.0002	No	No	
ASBESTOS-ST2-3/3/06	0002	Southwest Area (sidewalk bridge level)	3/3/06	1	3,000	Asbestos	PCME	EMSL	3/3/06	<0.0002	No	No	
ASBESTOS-ST3-3/3/06	0003	Northwest Area (stair level)	3/3/06	1	3,000	Asbestos	PCME	EMSL	3/3/06	<0.0002	No	No	
ASBESTOS-ST5-3/3/06	0004	Finchouse #10 (roof level)	3/3/06	1	3,000	Asbestos	PCME	EMSL	3/3/06	<0.0002	No	No	
ASBESTOS-ST10-3/3/06	0005	North Side Sidewalk Bridge	3/3/06	1	3,000	Asbestos	PCME	EMSL	3/3/06	<0.0002	No	No	
ASBESTOS-ST11-3/3/06	0006	80 "riny" Plaza (roof level)	3/3/06	1	3,000	Asbestos	PCME	EMSL	3/3/06	<0.0002	No	No	
ASBESTOS-ST18-3/3/06	0007	110 Greenwich Street (roof level)	3/3/06	1	3,000	Asbestos	PCME	EMSL	3/3/06	<0.0002	No	No	
ASBESTOS-ST14-3/3/06	0008	Marriot Hotel, 34th Floor (roof level)	3/3/06	1	3,000	Asbestos	PCME	EMSL	3/3/06	<0.0002	No	No	
ASBESTOS-ST15-3/3/06	0009	West Face - South end at corner (scaffolding level)	3/3/06	1	3,000	Asbestos	PCME	EMSL	3/3/06	<0.0002	No	No	
ASBESTOS-ST16-3/3/06	0010	South Face - East end at corner (scaffolding level)	3/3/06	1	3,000	Asbestos	PCME	EMSL	3/3/06	<0.0002	No	No	
ASBESTOS-ST17-3/3/06	0011	East Face - North end at corner (scaffolding level)	3/3/06	1	3,000	Asbestos	PCME	EMSL	3/3/06	<0.0002	No	No	
ASBESTOS-ST1-3/4/06	0001	Southwest Area (sidewalk bridge level)	3/4/06	1	3,000	Asbestos	PCME	EMSL	3/4/06	<0.0002	No	No	
ASBESTOS-ST2-3/4/06	0002	Southwest Area (sidewalk bridge level)	3/4/06	1	3,000	Asbestos	PCME	EMSL	3/4/06	<0.0002	No	No	
ASBESTOS-ST3-3/4/06	0003	Northwest Area (stair level)	3/4/06	1	3,000	Asbestos	PCME	EMSL	3/4/06	<0.0002	No	No	
ASBESTOS-ST5-3/4/06	0004	Finchouse #10 (roof level)	3/4/06	1	3,000	Asbestos	PCME	EMSL	3/4/06	<0.0002	No	No	
ASBESTOS-ST10-3/4/06	0005	North Side Sidewalk Bridge	3/4/06	1	3,000	Asbestos	PCME	EMSL	3/4/06	<0.0002	No	No	
ASBESTOS-ST11-3/4/06	0006	80 "riny" Plaza (roof level)	3/4/06	1	3,000	Asbestos	PCME	EMSL	3/4/06	<0.0002	No	No	
ASBESTOS-ST18-3/4/06	0007	110 Greenwich Street (roof level)	3/4/06	1	3,000	Asbestos	PCME	EMSL	3/4/06	<0.0002	No	No	
ASBESTOS-ST14-3/4/06	0008	Marriot Hotel, 34th Floor (roof level)	3/4/06	1	3,000	Asbestos	PCME	EMSL	3/4/06	<0.0002	No	No	
ASBESTOS-ST15-3/4/06	0009	West Face - South end at corner (scaffolding level)	3/4/06	1	3,000	Asbestos	PCME	EMSL	3/4/06	<0.0002	No	No	
ASBESTOS-ST16-3/4/06	0010	South Face - East end at corner (scaffolding level)	3/4/06	1	3,000	Asbestos	PCME	EMSL	3/4/06	<0.0002	No	No	
ASBESTOS-ST17-3/4/06	0011	East Face - North end at corner (scaffolding level)	3/4/06	1	3,000	Asbestos	PCME	EMSL	3/4/06	<0.0002	No	No	
ASBESTOS-ST1-3/5/06	0001	Southwest Area (sidewalk bridge level)	3/5/06	1	3,000	Asbestos	PCME	EMSL	3/5/06	<0.0002	No	No	
ASBESTOS-ST2-3/5/06	0002	Southwest Area (sidewalk bridge level)	3/5/06	1	3,000	Asbestos	PCME	EMSL	3/5/06	<0.0002	No	No	
ASBESTOS-ST3-3/5/06	0003	Northwest Area (stair level)	3/5/06	1	3,000	Asbestos	PCME	EMSL	3/5/06	<0.0002	No	No	
ASBESTOS-ST5-3/5/06	0004	Finchouse #10 (roof level)	3/5/06	1	3,000	Asbestos	PCME	EMSL	3/5/06	<0.0002	No	No	
ASBESTOS-ST10-3/5/06	0005	North Side Sidewalk Bridge	3/5/06	1	3,000	Asbestos	PCME	EMSL	3/5/06	<0.0002	No	No	
ASBESTOS-ST11-3/5/06	0006	80 "riny" Plaza (roof level)	3/5/06	1	3,000	Asbestos	PCME	EMSL	3/5/06	<0.0002	No	No	
ASBESTOS-ST18-3/5/06	0007	110 Greenwich Street (roof level)	3/5/06	1	3,000	Asbestos	PCME	EMSL	3/5/06	<0.0002	No	No	
ASBESTOS-ST14-3/5/06	0008	Marriot Hotel, 34th Floor (roof level)	3/5/06	1	3,000	Asbestos	PCME	EMSL	3/5/06	<0.0002	No	No	
ASBESTOS-ST15-3/5/06	0009	West Face - South end at corner (scaffolding level)	3/5/06	1	3,000	Asbestos	PCME	EMSL	3/5/06	<0.0002	No	No	
ASBESTOS-ST16-3/5/06	0010	South Face - East end at corner (scaffolding level)	3/5/06	1	3,000	Asbestos	PCME	EMSL	3/5/06	<0.0002	No	No	
ASBESTOS-ST17-3/5/06	0011	East Face - North end at corner (scaffolding level)	3/5/06	1	3,000	Asbestos	PCME	EMSL	3/5/06	<0.0002	No	No	
ASBESTOS-ST1-3/6/06	0001	Southwest Area (sidewalk bridge level)	3/6/06	1	3,000	Asbestos	PCME	EMSL	3/6/06	<0.0002	No	No	
ASBESTOS-ST2-3/6/06	0002	Southwest Area (sidewalk bridge level)	3/6/06	1	3,000	Asbestos	PCME	EMSL	3/6/06	<0.0002	No	No	
ASBESTOS-ST3-3/6/06	0003	Northwest Area (stair level)	3/6/06	1	3,000	Asbestos	PCME	EMSL	3/6/06	<0.0002	No	No	
ASBESTOS-ST5-3/6/06	0004	Finchouse #10 (roof level)	3/6/06	1	3,000	Asbestos	PCME	EMSL	3/6/06	<0.0002	No	No	
ASBESTOS-ST10-3/6/06	0005	North Side Sidewalk Bridge	3/6/06	1	3,000	Asbestos	PCME	EMSL	3/6/06	<0.0002	No	No	
ASBESTOS-ST11-3/6/06	0006	80 "riny" Plaza (roof level)	3/6/06	1	3,000	Asbestos	PCME	EMSL	3/6/06	<0.0002	No	No	
ASBESTOS-ST18-3/6/06	0007	110 Greenwich Street (roof level)	3/6/06	1	3,000	Asbestos	PCME	EMSL	3/6/06	<0.0002	No	No	
ASBESTOS-ST14-3/6/06	0008	Marriot Hotel, 34th Floor (roof level)	3/6/06	1	3,000	Asbestos	PCME	EMSL	3/6/06	<0.0002	No	No	
ASBESTOS-ST15-3/6/06	0009	West Face - South end at corner (scaffolding level)	3/6/06	1	3,000	Asbestos	PCME	EMSL	3/6/06	<0.0002	No	No	
ASBESTOS-ST16-3/6/06	0010	South Face - East end at corner (scaffolding level)	3/6/06	1	3,000	Asbestos	PCME	EMSL	3/6/06	<0.0002	No	No	
ASBESTOS-ST17-3/6/06	0011	East Face - North end at corner (scaffolding level)	3/6/06	1	3,000	Asbestos	PCME	EMSL	3/6/06	<0.0002	No	No	
ASBESTOS-ST1-3/7/06	0012	Southwest Area (sidewalk bridge level)	3/7/06	1	3,000	Asbestos	PCME	EMSL	3/7/06	<0.0002	No	No	
ASBESTOS-ST2-3/7/06	0002	Southwest Area (sidewalk bridge level)	3/7/06	1	3,000	Asbestos	PCME	EMSL	3/7/06	<0.0002	No	No	
ASBESTOS-ST3-3/7/06	0003	Northwest Area (stair level)	3/7/06	1	3,000	Asbestos	PCME	EMSL	3/7/06	<0.0002	No	No	
ASBESTOS-ST5-3/7/06	0004	Finchouse #10 (roof level)	3/7/06	1	3,000	Asbestos	PCME	EMSL	3/7/06	<0.0002	No	No	
ASBESTOS-ST10-3/7/06	0005	North Side Sidewalk Bridge	3/7/06	1	3,000	Asbestos	PCME	EMSL	3/7/06	<0.0002	No	No	
ASBESTOS-ST11-3/7/06	0006	80 "riny" Plaza (roof level)	3/7/06	1	3,000	Asbestos	PCME	EMSL	3/7/06	<0.0002	No	No	
ASBESTOS-ST18-3/7/06	0007	110 Greenwich Street (roof level)	3/7/06	1	3,000	Asbestos	PCME	EMSL	3/7/06	<0.0002	No	No	
ASBESTOS-ST14-3/7/06	0008	Marriot Hotel, 34th Floor (roof level)	3/7/06	1	3,000	Asbestos	PCME	EMSL	3/7/06	<0.0002	No	No	
ASBESTOS-ST15-3/7/06	0009	West Face - South end at corner (scaffolding level)	3/7/06	1	3,000	Asbestos	PCME	EMSL	3/7/06	<0.0002	No	No	
ASBESTOS-ST16-3/7/06	0010	South Face - East end at corner (scaffolding level)	3/7/06	1	3,000	Asbestos	PCME	EMSL	3/7/06	<0.0002	No	No	
ASBESTOS-ST17-3/7/06	0011	East Face - North end at corner (scaffolding level)	3/7/06	1	3,000	Asbestos	PCME	EMSL	3/7/06	<0.0002	No	No	
ASBESTOS-ST1-3/8/06	0012	Southwest Area (sidewalk bridge level)	3/8/06	1	3,000	Asbestos	PCME	EMSL	3/8/06	<0.0002	No	No	

Note:
1. The asbestos sample at Station 15 (East Face - North end at corner (scaffolding level)) on March 13, 2006 was not available for analysis on account of filter damage.

1301 Liberty Street, New York, NY 10006

Asbestos

Page 1 of 1

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Dioxin TEQ Concentration (pg/m3)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels									0.25	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels									25			
Dioxins/Furans-ST2-3/7/06	3	Southeast Area (sidewalk bridge level)	3/7/06	336	Dioxin	TO-9A	AP	3/9/06	0.0398	No	No	
Dioxins/Furans-ST10-3/7/06	6	North Side Sidewalk Bridge	3/7/06	323	Dioxin	TO-9A	AP	3/9/06	0.0256	No	No	

Note:
1. The Dioxin sample analysis at Station 100 (Station 10 Field Duplicate) on March 7, 2006, was delayed due to miscommunication with the laboratory. The result will be included in the next weekly report.

CITY_DEP_WORBY_CANNATA_SUBP_000076068

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	PAHs (EAP-equivalent) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									34	No	No	
EPA Site Specific Trigger Levels									5.96			
PAHS-ST2-3/7/06	G6C090219002	Southeast Area (sidewalk bridge level)	3/7/06	361.03	PAHs	8270C SIM	STL-SAC	3/9/06	< 7.0	No	No	
PAHS-ST10-3/7/06	G6C090219005	North Side Sidewalk Bridge	3/7/06	341.27	PAHs	8270C SIM	STL-SAC	3/9/06	< 7.3	No	No	

CITY_DEP_WORBY_CANNATA_SUBP_000076069

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Total PCBs Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									0.12			
EPA Site Specific Trigger Levels									32			
PCBS-ST2-3/7/06	AJ01974	Southeast Area (sidewalk bridge level)	3/7/06	7.2	PCBs	EPA Method TO-10A/EPA 8082 Northeast		3/9/06	< 0.0974	No	No	
PCBS-ST10-3/7/06	AJ01975	North Side Sidewalk Bridge	3/7/06	7.2	PCBs	EPA Method TO-10A/EPA 8082 Northeast		3/9/06	< 0.0972	No	No	
PCBS-ST100-3/7/06	AJ01983	Station 10 Field Duplicate	3/7/06	7.2	PCBs	EPA Method TO-10A/EPA 8082 Northeast		3/9/06	< 0.0972	No	No	

CITY_DEP_WORBY_CANNATA_SUBP_000076070

150 Liberty Street Reconstruction Project

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							30			
9/11/06 10:00 AM - 11:00 AM Levels							30			
PM2.5 ST11-0/1/2006	Southwest Area (sidewalk bridge level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	18	No	No	
PM2.5 ST2-0/1/2006	Southeast Area (sidewalk bridge level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	35	No	No	
PM2.5 ST4-0/1/2006	Northwest Area (steel level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	35	No	No	
PM2.5 ST9-0/1/2006	Flint House #1C (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	35	No	No	
PM2.5 ST1003-0/1/2006	Station 10 Field Duplicate	3/1/2006	1110	Particulate	Direct Read	Nel One E-BAM	33	No	No	
PM2.5 ST11-0/1/2006	90 Trinity Place (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	29	No	No	
PM2.5 ST12-0/1/2006	110 Greenwich Street (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	28	No	No	
PM2.5 ST13-0/1/2006	Marriot Hotel, 36th Floor (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	17	No	No	
PM2.5 ST14-0/1/2006	West Face - South end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	14	No	No	
PM2.5 ST15-0/1/2006	South Face - East end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	34	No	No	
PM2.5 ST16-0/1/2006	East Face - North end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	32	No	No	
PM2.5 ST17-0/1/2006	North Face - West end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	29	No	No	
PM2.5 ST18-0/1/2006	Southwest Area (sidewalk bridge level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	39	Yes	No	Note 2
PM2.5 ST4-0/3/2006	Northwest Area (steel level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	46	Yes	No	Note 2
PM2.5 ST5-0/3/2006	Flint House #1C (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	41	Yes	No	Note 2
PM2.5 ST10-0/3/2006	North Side Sidewalk Bridge	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	33	No	No	
PM2.5 ST1003-0/3/2006	Station 10 Field Duplicate	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	37	No	No	
PM2.5 ST11-0/3/2006	90 Trinity Place (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	37	No	No	
PM2.5 ST12-0/3/2006	110 Greenwich Street (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	37	No	No	
PM2.5 ST13-0/3/2006	Marriot Hotel, 36th Floor (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	35	No	No	
PM2.5 ST14-0/3/2006	West Face - South end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	31	No	No	
PM2.5 ST15-0/3/2006	South Face - East end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	30	No	No	
PM2.5 ST16-0/3/2006	East Face - North end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	35	No	No	
PM2.5 ST17-0/3/2006	North Face - West end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	43	Yes	No	Note 2
PM2.5 ST11-0/14/2006	Southwest Area (sidewalk bridge level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	15	No	No	
PM2.5 ST2-0/14/2006	Southeast Area (sidewalk bridge level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	23	No	No	
PM2.5 ST4-0/14/2006	Northwest Area (steel level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	13	No	No	
PM2.5 ST9-0/14/2006	Flint House #1C (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	19	No	No	
PM2.5 ST10-0/14/2006	North Side Sidewalk Bridge	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	11	No	No	
PM2.5 ST1003-0/14/2006	Station 10 Field Duplicate	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	16	No	No	
PM2.5 ST11-0/14/2006	90 Trinity Place (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	14	No	No	
PM2.5 ST12-0/14/2006	110 Greenwich Street (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	15	No	No	
PM2.5 ST13-0/14/2006	Marriot Hotel, 36th Floor (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	12	No	No	
PM2.5 ST14-0/14/2006	West Face - South end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	12	No	No	
PM2.5 ST15-0/14/2006	South Face - East end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	12	No	No	
PM2.5 ST16-0/14/2006	East Face - North end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	16	No	No	
PM2.5 ST17-0/14/2006	North Face - West end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	14	No	No	
PM2.5 ST18-0/14/2006	Southeast Area (sidewalk bridge level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	10	No	No	
PM2.5 ST2-0/15/2006	Southeast Area (sidewalk bridge level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	12	No	No	
PM2.5 ST4-0/15/2006	Northwest Area (steel level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST9-0/15/2006	Flint House #1C (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	7	No	No	
PM2.5 ST10-0/15/2006	North Side Sidewalk Bridge	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	4	No	No	
PM2.5 ST1003-0/15/2006	Station 10 Field Duplicate	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	4	No	No	
PM2.5 ST11-0/15/2006	90 Trinity Place (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	4	No	No	
PM2.5 ST12-0/15/2006	110 Greenwich Street (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST13-0/15/2006	Marriot Hotel, 36th Floor (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	6	No	No	
PM2.5 ST14-0/15/2006	West Face - South end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST15-0/15/2006	South Face - East end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST16-0/15/2006	East Face - North end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST17-0/15/2006	North Face - West end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	7	No	No	
PM2.5 ST18-0/15/2006	Southeast Area (sidewalk bridge level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	11	No	No	
PM2.5 ST2-0/16/2006	Southeast Area (sidewalk bridge level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	12	No	No	
PM2.5 ST4-0/16/2006	Northwest Area (steel level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	4	No	No	
PM2.5 ST9-0/16/2006	Flint House #1C (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	8	No	No	
PM2.5 ST10-0/16/2006	North Side Sidewalk Bridge	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST1003-0/16/2006	Station 10 Field Duplicate	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	4	No	No	
PM2.5 ST11-0/16/2006	90 Trinity Place (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	4	No	No	
PM2.5 ST12-0/16/2006	110 Greenwich Street (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST13-0/16/2006	Marriot Hotel, 36th Floor (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST14-0/16/2006	West Face - South end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	4	No	No	
PM2.5 ST15-0/16/2006	South Face - East end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST16-0/16/2006	East Face - North end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	3	No	No	
PM2.5 ST17-0/16/2006	North Face - West end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST18-0/16/2006	Southeast Area (sidewalk bridge level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	13	No	No	
PM2.5 ST2-0/17/2006	Southeast Area (sidewalk bridge level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	12	No	No	
PM2.5 ST4-0/17/2006	Northwest Area (steel level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	16	No	No	
PM2.5 ST9-0/17/2006	Flint House #1C (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	7	No	No	
PM2.5 ST10-0/17/2006	North Side Sidewalk Bridge	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST1003-0/17/2006	Station 10 Field Duplicate	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	4	No	No	
PM2.5 ST11-0/17/2006	90 Trinity Place (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	4	No	No	
PM2.5 ST12-0/17/2006	110 Greenwich Street (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST13-0/17/2006	Marriot Hotel, 36th Floor (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST14-0/17/2006	West Face - South end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST15-0/17/2006	South Face - East end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST16-0/17/2006	East Face - North end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST17-0/17/2006	North Face - West end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST18-0/17/2006	Southeast Area (sidewalk bridge level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	10	No	No	
PM2.5 ST2-0/18/2006	Southeast Area (sidewalk bridge level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	10	No	No	
PM2.5 ST4-0/18/2006	Northwest Area (steel level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	4	No	No	
PM2.5 ST9-0/18/2006	Flint House #1C (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST10-0/18/2006	North Side Sidewalk Bridge	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST1003-0/18/2006	Station 10 Field Duplicate	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	4	No	No	
PM2.5 ST11-0/18/2006	90 Trinity Place (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	4	No	No	
PM2.5 ST12-0/18/2006	110 Greenwich Street (roof level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST13-0/18/2006	Marriot Hotel, 36th Floor (roof level)	3/1/2006	1110	Particulate	Direct Read	Nel One E-BAM	6	No	No	
PM2.5 ST14-0/18/2006	West Face - South end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST15-0/18/2006	South Face - East end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	4	No	No	
PM2.5 ST16-0/18/2006	East Face - North end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	4	No	No	
PM2.5 ST17-0/18/2006	North Face - West end at corner (scalloping level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	
PM2.5 ST18-0/18/2006	Southeast Area (sidewalk bridge level)	3/1/2006	1440	Particulate	Direct Read	Nel One E-BAM	5	No	No	

Notes:

- The PM 2.5 readings at Station 10 (North Side Sidewalk Bridge level) on March 12, and 15, 2006 were not available on account of instrument malfunction. However, it should be noted that at the PM 2.5 readings from the collected sample at this station (Station 100) were available.
- The elevated PM 2.5 concentrations measured at Station 2 (Southeast Area (sidewalk bridge level)), Station 1 (Northwest Area (steel level)), Station 5 (Flint House #1C roof level)), and Station 17 (North Face - West end at corner (scalloping level)) on March 15, 2006 were likely influenced by regional air quality conditions including haze, fog, and mist. The elevated PM2.5 concentrations measured network-wide on March 15, 2006 are not attributable to work activities at 130 Liberty.