

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m3)	Barium Concentration (ng/m3)	Beryllium Concentration (ng/m3)
Target Air Quality Levels									5,000	5,000	20
EPA Site Specific Trigger Levels									10,000	5,000	200
METALS-ST1-9/26/05	G5I280200001	Southwest Area (street-level)	9/26/05	1751.1	Metals	6020	STL-SAC	9/28/05	1.5	< 68.5	< 0.68
METALS-ST2-9/26/05	G5I280200002	Southeast Area (street-level)	9/26/05	1773.2	Metals	6020	STL-SAC	9/28/05	< 1.4	< 67.7	< 0.68
METALS-ST4-9/26/05	G5I280200003	Northwest Area (street-level)	9/26/05	1715.4	Metals	6020	STL-SAC	9/28/05	1.9	< 70.0	< 0.70
METALS-ST5-9/26/05	G5I280200004	Firehouse #10 (roof level)	9/26/05	1816.8	Metals	6020	STL-SAC	9/28/05	1.4	< 66.1	< 0.66
METALS-ST6-9/26/05	G5I280200005	Southwest Area (roof level)	9/26/05	1858.7	Metals	6020	STL-SAC	9/28/05	< 1.3	< 64.8	< 0.64
METALS-ST7-9/26/05	G5I280200006	Southeast Area (roof level)	9/26/05	1799.9	Metals	6020	STL-SAC	9/28/05	< 1.3	< 66.7	< 0.67
METALS-ST8-9/26/05	G5I280200007	Northeast Area (roof level)	9/26/05	1826.4	Metals	6020	STL-SAC	9/28/05	1.6	< 65.7	< 0.66
METALS-ST9-9/26/05	G5I280200008	Northwest Area (roof level)	9/26/05	1733.7	Metals	6020	STL-SAC	9/28/05	< 1.4	< 69.2	< 0.69
METALS-ST10-9/26/05	G5I280200009	North Side Sidewalk Bridge	9/26/05	1817.6	Metals	6020	STL-SAC	9/28/05	1.7	< 66.0	< 0.66
METALS-ST11-9/27/05	G5I290193001	Southwest Area (street-level)	9/27/05	1734.8	Metals	6020	STL-SAC	9/29/05	2.6	< 69.2	< 0.69
METALS-ST2-9/27/05	G5I290193002	Southeast Area (street-level)	9/27/05	1787.1	Metals	6020	STL-SAC	9/29/05	4.4	118	< 0.67
METALS-ST4-9/27/05	G5I290193003	Northwest Area (street-level)	9/27/05	1786	Metals	6020	STL-SAC	9/29/05	2.4	< 67.2	< 0.67
METALS-ST5-9/27/05	G5I290193004	Firehouse #10 (roof level)	9/27/05	1800.5	Metals	6020	STL-SAC	9/29/05	2.4	< 66.6	< 0.67
METALS-ST6-9/27/05	G5I290193005	Southwest Area (roof level)	9/27/05	1887.5	Metals	6020	STL-SAC	9/29/05	2.0	< 63.6	< 0.64
METALS-ST7-9/27/05	G5I290193006	Southeast Area (roof level)	9/27/05	1839.1	Metals	6020	STL-SAC	9/29/05	2.3	< 65.2	< 0.65
METALS-ST8-9/27/05	G5I290193007	Northeast Area (roof level)	9/27/05	1836	Metals	6020	STL-SAC	9/29/05	2.4	< 65.4	< 0.65
METALS-ST9-9/27/05	G5I290193008	Northwest Area (roof level)	9/27/05	1749.3	Metals	6020	STL-SAC	9/29/05	2.5	< 66.6	< 0.68
METALS-ST10-9/27/05	G5I290193009	North Side Sidewalk Bridge	9/27/05	1776.6	Metals	6020	STL-SAC	9/29/05	2.4	< 67.5	< 0.68
METALS-ST11-9/28/05	G5I300220001	Southwest Area (street-level)	9/28/05	1744.4	Metals	6020	STL-SAC	9/30/05	2.8	< 68.8	< 0.69
METALS-ST2-9/28/05	G5I300220002	Southeast Area (street-level)	9/28/05	1763.8	Metals	6020	STL-SAC	9/30/05	2.0	< 68.0	< 0.68
METALS-ST4-9/28/05	G5I300220003	Northwest Area (street-level)	9/28/05	1723.8	Metals	6020	STL-SAC	9/30/05	2.7	< 69.6	< 0.70
METALS-ST5-9/28/05	G5I300220004	Firehouse #10 (roof level)	9/28/05	1778.7	Metals	6020	STL-SAC	9/30/05	2.6	< 67.5	< 0.67
METALS-ST6-9/28/05	G5I300220005	Southwest Area (roof level)	9/28/05	1881.6	Metals	6020	STL-SAC	9/30/05	2.5	< 63.8	< 0.64
METALS-ST7-9/28/05	G5I300220006	Southeast Area (roof level)	9/28/05	1816.6	Metals	6020	STL-SAC	9/30/05	5.2	< 66.1	< 0.66
METALS-ST8-9/28/05	G5I300220007	Northeast Area (roof level)	9/28/05	1873.1	Metals	6020	STL-SAC	9/30/05	3.6	< 64.1	< 0.64
METALS-ST9-9/28/05	G5I300220008	Northwest Area (roof level)	9/28/05	1727.3	Metals	6020	STL-SAC	9/30/05	2.8	< 69.5	< 0.69
METALS-ST10-9/28/05	G5I300220009	North Side Sidewalk Bridge	9/28/05	1797.4	Metals	6020	STL-SAC	9/30/05	2.6	< 66.8	< 0.67
METALS-ST100-9/28/05	G5I300220010	Station 10 Field Duplicate	9/28/05	1731.4	Metals	6020	STL-SAC	9/30/05	2.6	< 69.3	< 0.69
METALS-ST11-9/29/05	G5J10216001	Southwest Area (street-level)	9/29/05	1782.1	Metals	6020	STL-SAC	10/1/05	2.3	< 67.3	< 0.67
METALS-ST2-9/29/05	G5J10216002	Southeast Area (street-level)	9/29/05	1729.8	Metals	6020	STL-SAC	10/1/05	2.2	< 69.4	< 0.69
METALS-ST4-9/29/05	G5J10216003	Northwest Area (street-level)	9/29/05	1835.9	Metals	6020	STL-SAC	10/1/05	2.2	< 65.4	< 0.65
METALS-ST5-9/29/05	G5J10216004	Firehouse #10 (roof level)	9/29/05	1800.9	Metals	6020	STL-SAC	10/1/05	1.8	< 66.6	< 0.67
METALS-ST10-9/29/05	G5J10216005	North Side Sidewalk Bridge	9/29/05	1863.2	Metals	6020	STL-SAC	10/1/05	2.0	< 64.4	< 0.64
METALS-ST11-9/30/05	G5J040193001	Southwest Area (street-level)	9/30/05	1845.9	Metals	6020	STL-SAC	10/4/05	3.4	< 65.0	< 0.65
METALS-ST2-9/30/05	G5J040193002	Southeast Area (street-level)	9/30/05	1856.8	Metals	6020	STL-SAC	10/4/05	3.5	< 64.6	< 0.65
METALS-ST4-9/30/05	G5J040193004	Northwest Area (street-level)	9/30/05	1803.8	Metals	6020	STL-SAC	10/4/05	3.6	< 66.5	< 0.67
METALS-ST5-9/30/05	G5J040193005	Firehouse #10 (roof level)	9/30/05	1820.4	Metals	6020	STL-SAC	10/4/05	3.0	< 65.9	< 0.66
METALS-ST10-9/30/05	G5J040193003	North Side Sidewalk Bridge	9/30/05	1808.4	Metals	6020	STL-SAC	10/4/05	3.8	< 66.4	< 0.66
METALS-ST11-10/1/05	G5J040193007	Southwest Area (street-level)	10/1/05	1733.5	Metals	6020	STL-SAC	10/4/05	3.3	< 69.2	< 0.69
METALS-ST2-10/1/05	G5J040193008	Southeast Area (street-level)	10/1/05	1755	Metals	6020	STL-SAC	10/4/05	3.3	< 68.4	< 0.68
METALS-ST4-10/1/05	G5J040193010	Northwest Area (street-level)	10/1/05	1739.4	Metals	6020	STL-SAC	10/4/05	3.3	< 69.0	< 0.69
METALS-ST5-10/1/05	G5J040193011	Firehouse #10 (roof level)	10/1/05	2021.2	Metals	6020	STL-SAC	10/4/05	4.0	< 59.4	< 0.59
METALS-ST10-10/1/05	G5J040193009	North Side Sidewalk Bridge	10/1/05	1773.5	Metals	6020	STL-SAC	10/4/05	3.6	< 67.7	< 0.68
METALS-ST11-10/2/05	G5J040193013	Southwest Area (street-level)	10/2/05	1613.8	Metals	6020	STL-SAC	10/4/05	4.1	< 74.4	< 0.74
METALS-ST2-10/2/05	G5J040193014	Southeast Area (street-level)	10/2/05	1653.6	Metals	6020	STL-SAC	10/4/05	5.0	< 72.6	< 0.73
METALS-ST4-10/2/05	G5J040193016	Northwest Area (street-level)	10/2/05	1642	Metals	6020	STL-SAC	10/4/05	3.9	< 73.1	< 0.73
METALS-ST5-10/2/05	G5J040193017	Firehouse #10 (roof level)	10/2/05	1543.3	Metals	6020	STL-SAC	10/4/05	5.1	< 77.8	< 0.78
METALS-ST10-10/2/05	G5J040193015	North Side Sidewalk Bridge	10/2/05	1659	Metals	6020	STL-SAC	10/4/05	4.7	< 71.9	< 0.72

Cadmium Concentration (ng/m3)	Chromium (Total) Concentration (ng/m3)	Copper Concentration (ng/m3)	Lead Concentration (ng/m3)	Manganese Concentration (ng/m3)	Nickel Concentration (ng/m3)	Zinc Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
40	600	10,000	1,500	500	600	16,000			
2,000	600	100,000	5,000	500	25,000	160,000			
< 0.68	< 6.8	119	18.7	17.9	4.6	65.0	No	No	
< 0.68	< 6.8	53.1	11.9	14.3	4.0	40.6	No	No	
< 0.70	< 7.0	105	60.4	17.0	4.1	72.9	No	No	
< 0.66	< 6.6	39.6	21.6	17.6	4.1	43.3	No	No	
< 0.64	< 6.5	42.9	4.2	5.4	< 3.2	26.2	No	No	
< 0.67	< 6.7	33.3	5.3	8.9	< 3.3	51.4	No	No	
0.74	7.2	30.7	16.9	46.4	6.5	321	No	No	
< 0.69	< 6.9	31.7	10	20.8	4.5	63.3	No	No	
< 0.66	< 6.6	34.2	19.8	22.1	4.6	59.3	No	No	
< 0.69	< 6.9	182	30.5	20.3	7.9	80.6	No	No	
< 0.67	11.4	173	31.1	61.4	10	93.9	No	No	
< 0.67	< 6.7	150	24.5	13.8	8.2	55.9	No	No	
< 0.67	< 6.7	31.9	7.8	12.2	6.6	42.2	No	No	
< 0.64	< 6.4	70.5	11.2	12.6	6.6	59.7	No	No	
< 0.65	< 6.5	70.0	14.0	27.1	8.1	79.8	No	No	
0.67	< 6.5	38.7	13.7	28.7	8.6	157	No	No	
1.1	< 6.9	69.8	20.8	30.6	9.1	182	No	No	
< 0.68	< 6.8	29.2	7.6	13.2	6.7	49.4	No	No	
< 0.69	< 6.9	91.3	38.4	26.7	6.5	270	No	No	
< 0.68	< 6.8	237	17.7	20.5	< 3.4	56.4	No	No	
< 0.70	< 7.0	242	60.6	25.4	6.7	93.6	No	No	
< 0.67	< 6.7	72.5	18.9	21.9	5.3	78.8	No	No	
0.64	< 6.4	93.9	29.9	33.9	6.1	165	No	No	
3.7	16.2	137	73.8	208	19.3	417	No	No	
1.6	11.3	65.9	43.1	97.5	12.2	369	No	No	
1.2	7.8	59.4	32.8	60.5	8.8	186	No	No	
< 0.67	< 6.7	89.5	20.8	21.7	5.2	74.1	No	No	
< 0.69	< 6.9	86.0	21.2	23.1	5.5	80.8	No	No	
< 0.67	< 6.7	44.4	34.0	20.6	3.5	92.2	No	No	
< 0.69	< 6.9	54.5	14.8	19.5	< 3.5	49.2	No	No	
< 0.65	< 6.5	118	68.4	15.2	< 3.3	67.0	No	No	
< 0.67	< 6.7	45.4	10	12.8	< 3.3	35.4	No	No	
< 0.64	< 6.4	32.5	13.6	15.5	< 3.2	43.1	No	No	
< 0.65	< 6.5	45.6	32.3	28.4	9.6	146	No	No	
< 0.65	< 6.5	51.9	26.8	35.9	9.6	91.6	No	No	
< 0.66	< 6.6	93.8	40.4	25.3	10	77.0	No	No	
< 0.66	< 6.6	47.2	15.4	24.3	8.9	54.3	No	No	
< 0.66	< 6.6	46.8	21.0	29.1	12.0	74.0	No	No	
< 0.69	< 6.9	34.1	13.3	13.5	7.4	44.8	No	No	
< 0.68	< 6.8	31.8	12.7	14.0	7.3	45.1	No	No	
< 0.69	< 6.9	59.1	23.1	13.2	6.9	45.3	No	No	
< 0.59	< 5.9	44.5	13.2	19.1	7.9	48.0	No	No	
< 0.68	< 6.8	45.9	14.7	17.1	7.8	46.0	No	No	
< 0.74	< 7.4	40.0	27.6	20.3	10	66.6	No	No	
< 0.72	< 7.2	40.5	23.2	29.5	11.0	68.9	No	No	
< 0.73	< 7.3	56.6	21.2	19.6	10.6	57.9	No	No	
< 0.78	< 7.8	53.8	17.8	27.7	12.6	75.2	No	No	
< 0.72	< 7.2	42.1	16.1	24.5	11.8	67.8	No	No	

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels									300	Air Quality Levels	Site Specific Trigger Levels	
EPA 806 Specific Trigger Levels									3,000			
TotalHg-ST1-3/26/05	05BR1433-01	Southwest Area (street level)	3/26/2005	0.57	Mercury	EPA 324/163	BRL	3/28/2005	< 26.3	No	No	
TotalHg-ST2-3/26/05	05BR1433-02	Southeast Area (street level)	3/26/2005	0.57	Mercury	EPA 324/163	BRL	3/28/2005	< 26.3	No	No	
TotalHg-ST4-3/26/05	05DR1433-03	Northwest Area (street level)	3/26/2005	0.55	Mercury	EPA 324/163	DL	3/28/2005	< 27.3	No	No	
TotalHg-ST5-3/26/05	05BR1433-04	Firehouse #10 (roof level)	3/26/2005	N/A	Mercury	EPA 324/163	BRL	3/28/2005	< 15	No	No	Actual volume collected is unknown due to pump failure, reported result in the units of ng.
TotalHg-ST6-3/26/05	05BR1433-05	Southwest Area (roof level)	3/26/2005	0.57	Mercury	EPA 324/163	BRL	3/28/2005	< 26.3	No	No	
TotalHg-ST7-3/26/05	05DR1433-06	Southeast Area (roof level)	3/26/2005	0.57	Mercury	EPA 324/163	DL	3/28/2005	< 26.3	No	No	
TotalHg-ST8-3/26/05	05BR1433-07	Northwest Area (roof level)	3/26/2005	0.28	Mercury	EPA 324/163	BRL	3/28/2005	< 53.6	No	No	Reduced volume, pump failure due to water intrusion
TotalHg-ST9-3/26/05	05BR1433-08	Northwest Area (roof level)	3/26/2005	0.58	Mercury	EPA 324/163	BRL	3/28/2005	< 25.9	No	No	
TotalHg-ST10-3/26/05	05BR1433-09	North Side Sidewalk Bridge	3/26/2005	0.58	Mercury	EPA 324/163	BRL	3/28/2005	< 25.9	No	No	
TotalHg-ST11-3/27/05	05BR1438-1	Southwest Area (street level)	3/27/2005	0.58	Mercury	EPA 324/163	BRL	3/29/2005	< 25.9	No	No	
TotalHg-ST12-3/27/05	05BR1438-2	Southwest Area (street level)	3/27/2005	0.58	Mercury	EPA 324/163	BRL	3/29/2005	< 25.9	No	No	
TotalHg-ST13-3/27/05	05BR1438-3	Northwest Area (street level)	3/27/2005	0.17	Mercury	EPA 324/163	BRL	3/29/2005	< 88.2	No	No	Reduced volume, pump failure due to water intrusion
TotalHg-ST14-3/27/05	05BR1438-4	Firehouse #10 (roof level)	3/27/2005	0.58	Mercury	EPA 324/163	BRL	3/29/2005	< 25.9	No	No	
TotalHg-ST15-3/27/05	05BR1438-5	Southwest Area (roof level)	3/27/2005	0.58	Mercury	EPA 324/163	BRL	3/29/2005	< 25.9	No	No	
TotalHg-ST16-3/27/05	05BR1438-6	Southeast Area (roof level)	3/27/2005	0.58	Mercury	EPA 324/163	BRL	3/29/2005	< 25.9	No	No	
TotalHg-ST17-3/27/05	05BR1438-7	Northwest Area (roof level)	3/27/2005	0.28	Mercury	EPA 324/163	BRL	3/29/2005	< 53.6	No	No	Reduced volume, pump failure due to water intrusion
TotalHg-ST18-3/27/05	05BR1438-8	Northwest Area (roof level)	3/27/2005	0.57	Mercury	EPA 324/163	BRL	3/29/2005	< 26.3	No	No	
TotalHg-ST19-3/27/05	05BR1438-9	North Side Sidewalk Bridge	3/27/2005	0.57	Mercury	EPA 324/163	BRL	3/29/2005	< 26.3	No	No	
TotalHg-ST20-3/28/05	05BR1467-1	Southwest Area (street level)	3/28/2005	0.57	Mercury	EPA 324/163	BRL	3/30/2005	< 26.3	No	No	
TotalHg-ST21-3/28/05	05BR1467-2	Southwest Area (street level)	3/28/2005	0.57	Mercury	EPA 324/163	BRL	3/30/2005	< 26.3	No	No	
TotalHg-ST22-3/28/05	05BR1467-3	Northwest Area (street level)	3/28/2005	0.56	Mercury	EPA 324/163	BRL	3/30/2005	< 26.8	No	No	
TotalHg-ST23-3/28/05	05BR1467-4	Firehouse #10 (roof level)	3/28/2005	0.57	Mercury	EPA 324/163	BRL	3/30/2005	< 26.3	No	No	
TotalHg-ST24-3/28/05	05BR1467-5	Southwest Area (roof level)	3/28/2005	0.57	Mercury	EPA 324/163	BRL	3/30/2005	< 26.3	No	No	
TotalHg-ST25-3/28/05	05BR1467-6	Southwest Area (roof level)	3/28/2005	0.57	Mercury	EPA 324/163	BRL	3/30/2005	< 26.3	No	No	
TotalHg-ST26-3/28/05	05BR1467-7	Northwest Area (roof level)	3/28/2005	0.58	Mercury	EPA 324/163	BRL	3/30/2005	< 25.9	No	No	
TotalHg-ST27-3/28/05	05BR1467-8	Northwest Area (roof level)	3/28/2005	0.58	Mercury	EPA 324/163	BRL	3/30/2005	< 25.9	No	No	
TotalHg-ST28-3/28/05	05BR1467-9	North Side Sidewalk Bridge	3/28/2005	0.58	Mercury	EPA 324/163	BRL	3/30/2005	< 25.9	No	No	
TotalHg-ST29-3/28/05	05BR1467-10	Station 10 Field Duplicate	3/28/2005	0.56	Mercury	EPA 324/163	BRL	3/30/2005	< 26.8	No	No	
TotalHg-ST30-3/29/05	05BR1478-1	Southwest Area (street level)	3/29/2005	0.59	Mercury	EPA 324/163	BRL	10/1/2005	< 25.4	No	No	
TotalHg-ST31-3/29/05	05BR1478-2	Southwest Area (street level)	3/29/2005	0.59	Mercury	EPA 324/163	BRL	10/1/2005	< 25.4	No	No	
TotalHg-ST32-3/29/05	05BR1478-3	Northwest Area (street level)	3/29/2005	0.60	Mercury	EPA 324/163	BRL	10/1/2005	< 25.0	No	No	
TotalHg-ST33-3/29/05	05BR1478-4	Firehouse #10 (roof level)	3/29/2005	0.58	Mercury	EPA 324/163	BRL	10/1/2005	< 25.9	No	No	
TotalHg-ST34-3/29/05	05BR1478-5	North Side Sidewalk Bridge	3/29/2005	0.58	Mercury	EPA 324/163	BRL	10/1/2005	< 25.9	No	No	
TotalHg-ST35-3/30/05	05BR1480-1	Southwest Area (street level)	3/30/2005	0.6	Mercury	EPA 324/163	BRL	10/4/2005	< 25.0	No	No	
TotalHg-ST36-3/30/05	05BR1480-2	Southeast Area (street level)	3/30/2005	0.6	Mercury	EPA 324/163	BRL	10/4/2005	< 25.0	No	No	
TotalHg-ST37-3/30/05	05BR1480-3	Northwest Area (street level)	3/30/2005	0.59	Mercury	EPA 324/163	BRL	10/4/2005	< 25.4	No	No	
TotalHg-ST38-3/30/05	05BR1480-4	Firehouse #10 (roof level)	3/30/2005	N/A	Mercury	EPA 324/163	BRL	10/4/2005	< 15.0	No	No	Actual volume collected is unknown due to pump failure, reported result in the units of ng.
TotalHg-ST39-3/30/05	05BR1480-5	North Side Sidewalk Bridge	3/30/2005	0.59	Mercury	EPA 324/163	BRL	10/4/2005	< 25.4	No	No	
TotalHg-ST40-3/30/05	05BR1480-6	Southwest Area (street level)	10/1/2005	0.57	Mercury	EPA 324/163	BRL	10/4/2005	< 26.3	No	No	
TotalHg-ST41-3/30/05	05DR1480-7	Southeast Area (street level)	10/1/2005	0.57	Mercury	EPA 324/163	DL	10/4/2005	< 26.3	No	No	
TotalHg-ST42-3/30/05	05BR1480-8	Northwest Area (street level)	10/1/2005	0.57	Mercury	EPA 324/163	BRL	10/4/2005	< 26.3	No	No	
TotalHg-ST43-3/30/05	05BR1480-9	Firehouse #10 (roof level)	10/1/2005	0.65	Mercury	EPA 324/163	BRL	10/4/2005	< 23.1	No	No	
TotalHg-ST44-3/30/05	05DR1480-10	North Side Sidewalk Bridge	10/1/2005	0.57	Mercury	EPA 324/163	DL	10/4/2005	< 26.3	No	No	
TotalHg-ST45-3/30/05	05BR1480-11	Southwest Area (street level)	10/2/2005	0.54	Mercury	EPA 324/163	BRL	10/4/2005	< 27.8	No	No	
TotalHg-ST46-3/30/05	05BR1480-12	Southeast Area (street level)	10/2/2005	0.54	Mercury	EPA 324/163	BRL	10/4/2005	< 27.8	No	No	
TotalHg-ST47-3/30/05	05BR1480-13	Northwest Area (street level)	10/2/2005	0.54	Mercury	EPA 324/163	BRL	10/4/2005	< 27.8	No	No	
TotalHg-ST48-3/30/05	05BR1480-14	Firehouse #10 (roof level)	10/2/2005	0.50	Mercury	EPA 324/163	BRL	10/4/2005	< 30.0	No	No	
TotalHg-ST49-3/30/05	05BR1480-15	North Side Sidewalk Bridge	10/2/2005	0.54	Mercury	EPA 324/163	BRL	10/4/2005	< 27.8	No	No	
TotalHg-ST50-3/30/05	05BR1488-1	Southwest Area (street level)	10/3/2005	0.57	Mercury	EPA 324/163	BRL	10/5/2005	< 26.3	No	No	
TotalHg-ST51-3/30/05	05BR1488-2	Southeast Area (street level)	10/3/2005	0.57	Mercury	EPA 324/163	BRL	10/5/2005	< 26.3	No	No	
TotalHg-ST52-3/30/05	05BR1488-3	Northwest Area (street level)	10/3/2005	0.56	Mercury	EPA 324/163	BRL	10/5/2005	< 26.8	No	No	
TotalHg-ST53-3/30/05	05BR1488-4	Firehouse #10 (roof level)	10/3/2005	0.56	Mercury	EPA 324/163	BRL	10/5/2005	< 26.8	No	No	
TotalHg-ST54-3/30/05	05BR1488-5	North Side Sidewalk Bridge	10/3/2005	0.56	Mercury	EPA 324/163	BRL	10/5/2005	< 26.8	No	No	

30 Liberty Street Reconstruction Project

Mercury

Page 1 of 4

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									10			
EPA Site Specific Trigger Levels									10			
SILICA-ST1-9/28/05	040518712-0001	Southwest Area (street-level)	9/28/2005	2.87	Silica	NIOSH 7500 XRD	EMSL	9/30/2005	< 2	No	No	
SILICA-ST2-9/28/05	040518712-0002	Southeast Area (street-level)	9/28/2005	2.84	Silica	NIOSH 7500 XRD	EMSL	9/30/2005	< 2	No	No	
SILICA-ST4-9/28/05	040518712-0003	Northwest Area (street-level)	9/28/2005	2.8	Silica	NIOSH 7500 XRD	EMSL	9/30/2005	< 2	No	No	
SILICA-ST5-9/28/05	040518712-0004	Firehouse #10 (roof level)	9/28/2005	2.84	Silica	NIOSH 7500 XRD	EMSL	9/30/2005	< 2	No	No	
SILICA-ST6-9/28/05	040518712-0005	Southwest Area (roof level)	9/28/2005	2.87	Silica	NIOSH 7500 XRD	EMSL	9/30/2005	< 2	No	No	
SILICA-ST7-9/28/05	040518712-0006	Southeast Area (roof level)	9/28/2005	2.87	Silica	NIOSH 7500 XRD	EMSL	9/30/2005	< 2	No	No	
SILICA-ST8-9/28/05	040518712-0007	Northwest Area (roof level)	9/28/2005	2.92	Silica	NIOSH 7500 XRD	EMSL	9/30/2005	< 2	No	No	See 9/28/05 Exceedance Report.
SILICA-ST9-9/28/05	040518712-0008	Northwest Area (roof level)	9/28/2005	2.88	Silica	NIOSH 7500 XRD	EMSL	9/30/2005	< 2	No	No	
SILICA-ST10-9/28/05	040518712-0009	North Side Sidewalk Bridge	9/28/2005	2.88	Silica	NIOSH 7500 XRD	EMSL	9/30/2005	< 2	No	No	
SILICA-ST100-9/28/05	040518712-0010	Station 10 Field Duplicate	9/28/2005	2.82	Silica	NIOSH 7500 XRD	EMSL	9/30/2005	< 2	No	No	
SILICA-ST1-9/29/05	040518800-0001	Southwest Area (street-level)	9/29/2005	2.94	Silica	NIOSH 7500 XRD	EMSL	9/29/2005	< 2	No	No	
SILICA-ST2-9/29/05	040518800-0002	Southeast Area (street-level)	9/29/2005	2.96	Silica	NIOSH 7500 XRD	EMSL	9/29/2005	< 2	No	No	
SILICA-ST4-9/29/05	040518800-0003	Northwest Area (street-level)	9/29/2005	2.99	Silica	NIOSH 7500 XRD	EMSL	9/29/2005	< 2	No	No	
SILICA-ST5-9/29/05	040518800-0004	Firehouse #10 (roof level)	9/29/2005	2.88	Silica	NIOSH 7500 XRD	EMSL	9/29/2005	< 2	No	No	
SILICA-ST10-9/29/05	040518800-0005	North Side Sidewalk Bridge	9/29/2005	2.88	Silica	NIOSH 7500 XRD	EMSL	9/29/2005	< 2	No	No	
SILICA-ST1-9/30/05	040518886-0001	Southwest Area (street-level)	9/30/2005	3	Silica	NIOSH 7500 XRD	EMSL	10/3/2005	< 2	No	No	
SILICA-ST2-9/30/05	040518886-0002	Southeast Area (street-level)	9/30/2005	2.98	Silica	NIOSH 7500 XRD	EMSL	10/3/2005	< 2	No	No	
SILICA-ST4-9/30/05	040518886-0004	Northwest Area (street-level)	9/30/2005	2.96	Silica	NIOSH 7500 XRD	EMSL	10/3/2005	< 2	No	No	
SILICA-ST5-9/30/05	040518886-0005	Firehouse #10 (roof level)	9/30/2005	2.91	Silica	NIOSH 7500 XRD	EMSL	10/3/2005	< 2	No	No	
SILICA-ST10-9/30/05	040518886-0003	North Side Sidewalk Bridge	9/30/2005	2.96	Silica	NIOSH 7500 XRD	EMSL	10/3/2005	< 2	No	No	
SILICA-ST1-10/1/05	040518886-0007	Southwest Area (street-level)	10/1/2005	2.86	Silica	NIOSH 7500 XRD	EMSL	10/3/2005	< 2	No	No	
SILICA-ST2-10/1/05	040518886-0008	Southeast Area (street-level)	10/1/2005	2.85	Silica	NIOSH 7500 XRD	EMSL	10/3/2005	< 2	No	No	
SILICA-ST4-10/1/05	040518886-0010	Northwest Area (street-level)	10/1/2005	2.85	Silica	NIOSH 7500 XRD	EMSL	10/3/2005	< 2	No	No	
SILICA-ST5-10/1/05	040518886-0011	Firehouse #10 (roof level)	10/1/2005	3.25	Silica	NIOSH 7500 XRD	EMSL	10/3/2005	< 2	No	No	
SILICA-ST10-10/1/05	040518886-0009	North Side Sidewalk Bridge	10/1/2005	2.86	Silica	NIOSH 7500 XRD	EMSL	10/3/2005	< 2	No	No	
SILICA-ST1-10/2/05	040518886-0013	Southwest Area (street-level)	10/2/2005	2.68	Silica	NIOSH 7500 XRD	EMSL	10/3/2005	< 2	No	No	
SILICA-ST2-10/2/05	040518886-0014	Southeast Area (street-level)	10/2/2005	2.7	Silica	NIOSH 7500 XRD	EMSL	10/3/2005	< 2	No	No	
SILICA-ST4-10/2/05	040518886-0016	Northwest Area (street-level)	10/2/2005	2.72	Silica	NIOSH 7500 XRD	EMSL	10/3/2005	< 2	No	No	
SILICA-ST5-10/2/05	040518886-0017	Firehouse #10 (roof level)	10/2/2005	2.48	Silica	NIOSH 7500 XRD	EMSL	10/3/2005	< 2	No	No	
SILICA-ST10-10/2/05	040518886-0015	North Side Sidewalk Bridge	10/2/2005	2.71	Silica	NIOSH 7500 XRD	EMSL	10/3/2005	< 2	No	No	
SILICA-ST1-10/3/05	040518939-0001	Southwest Area (street-level)	10/3/2005	2.86	Silica	NIOSH 7500 XRD	EMSL	10/4/2005	< 2	No	No	
SILICA-ST2-10/3/05	040518939-0002	Southeast Area (street-level)	10/3/2005	2.85	Silica	NIOSH 7500 XRD	EMSL	10/4/2005	< 2	No	No	
SILICA-ST4-10/3/05	040518939-0003	Northwest Area (street-level)	10/3/2005	2.78	Silica	NIOSH 7500 XRD	EMSL	10/4/2005	< 2	No	No	
SILICA-ST5-10/3/05	040518939-0004	Firehouse #10 (roof level)	10/3/2005	2.78	Silica	NIOSH 7500 XRD	EMSL	10/4/2005	< 2	No	No	
SILICA-ST10-10/3/05	040518939-0005	North Side Sidewalk Bridge	10/3/2005	2.8	Silica	NIOSH 7500 XRD	EMSL	10/4/2005	< 2	No	No	
SILICA-ST1-10/4/05	040519012-0001	Southwest Area (street-level)	10/4/2005	2.86	Silica	NIOSH 7500 XRD	EMSL	10/5/2005	< 2	No	No	
SILICA-ST2-10/4/05	040519012-0002	Southeast Area (street-level)	10/4/2005	2.86	Silica	NIOSH 7500 XRD	EMSL	10/5/2005	< 2	No	No	
SILICA-ST4-10/4/05	040519012-0003	Northwest Area (street-level)	10/4/2005	2.9	Silica	NIOSH 7500 XRD	EMSL	10/5/2005	< 2	No	No	
SILICA-ST5-10/4/05	040519012-0004	Firehouse #10 (roof level)	10/4/2005	2.93	Silica	NIOSH 7500 XRD	EMSL	10/5/2005	< 2	No	No	
SILICA-ST10-10/4/05	040519012-0005	North Side Sidewalk Bridge	10/4/2005	2.91	Silica	NIOSH 7500 XRD	EMSL	10/5/2005	< 2	No	No	
SILICA-ST1-10/5/05	040519115-0001	Southwest Area (street-level)	10/5/2005	2.87	Silica	NIOSH 7500 XRD	EMSL	10/6/2005	< 2	No	No	
SILICA-ST2-10/5/05	040519115-0002	Southeast Area (street-level)	10/5/2005	2.89	Silica	NIOSH 7500 XRD	EMSL	10/6/2005	< 2	No	No	
SILICA-ST4-10/5/05	040519115-0003	Northwest Area (street-level)	10/5/2005	2.83	Silica	NIOSH 7500 XRD	EMSL	10/6/2005	< 2	No	No	
SILICA-ST5-10/5/05	040519115-0004	Firehouse #10 (roof level)	10/5/2005	0.59	Silica	NIOSH 7500 XRD	EMSL	10/6/2005	< 8	No	No	Reduced sample volume due to pump failure.
SILICA-ST10-10/5/05	040519115-0005	North Side Sidewalk Bridge	10/5/2005	2.9	Silica	NIOSH 7500 XRD	EMSL	10/6/2005	< 2	No	No	
SILICA-ST11-10/5/05	040519115-0006	90 Trinity Place (roof level)	10/5/2005	2.78	Silica	NIOSH 7500 XRD	EMSL	10/6/2005	< 2	No	No	

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-9/30/05	030529623-0001	Southwest Area (street-level)	9/30/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No	
ASBESTOS-ST2-9/30/05	030529623-0002	Southeast Area (street-level)	9/30/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No	
ASBESTOS-ST4-9/30/05	030529623-0004	Northwest Area (street-level)	9/30/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No	
ASBESTOS-ST5-9/30/05	030529623-0005	Firehouse #10 (roof level)	9/30/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No	
ASBESTOS-ST10-9/30/05	030529623-0003	North Side Sidewalk Bridge	9/30/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No	
ASBESTOS-ST11-10/1/05	030529640-0001	Southwest Area (street-level)	10/1/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No	
ASBESTOS-ST2-10/1/05	030529640-0002	Southeast Area (street-level)	10/1/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No	
ASBESTOS-ST4-10/1/05	030529640-0004	Northwest Area (street-level)	10/1/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No	
ASBESTOS-ST5-10/1/05	030529640-0005	Firehouse #10 (roof level)	10/1/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No	
ASBESTOS-ST10-10/1/05	030529640-0003	North Side Sidewalk Bridge	10/1/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No	
ASBESTOS-ST11-10/2/05	030529641-0001	Southwest Area (street-level)	10/2/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No	
ASBESTOS-ST2-10/2/05	030529641-0002	Southeast Area (street-level)	10/2/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No	
ASBESTOS-ST4-10/2/05	030529641-0004	Northwest Area (street-level)	10/2/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No	
ASBESTOS-ST5-10/2/05	030529641-0005	Firehouse #10 (roof level)	10/2/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No	
ASBESTOS-ST10-10/2/05	030529641-0003	North Side Sidewalk Bridge	10/2/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No	
ASBESTOS-ST11-10/3/05	030529713-0001	Southwest Area (street-level)	10/3/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/2005	< 19.00	No	No	
ASBESTOS-ST2-10/3/05	030529713-0002	Southeast Area (street-level)	10/3/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/2005	< 19.00	No	No	
ASBESTOS-ST4-10/3/05	030529713-0003	Northwest Area (street-level)	10/3/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/2005	< 19.00	No	No	
ASBESTOS-ST5-10/3/05	030529713-0004	Firehouse #10 (roof level)	10/3/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/2005	< 19.00	No	No	
ASBESTOS-ST10-10/3/05	030529713-0005	North Side Sidewalk Bridge	10/3/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/2005	< 19.00	No	No	
ASBESTOS-ST11-10/4/05	03529858-0001	Southwest Area (street-level)	10/4/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/2005	< 19.00	No	No	
ASBESTOS-ST2-10/4/05	03529858-0002	Southeast Area (street-level)	10/4/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/2005	< 19.00	No	No	
ASBESTOS-ST4-10/4/05	03529858-0003	Northwest Area (street-level)	10/4/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/2005	< 19.00	No	No	
ASBESTOS-ST5-10/4/05	03529858-0004	Firehouse #10 (roof level)	10/4/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/2005	< 19.00	No	No	
ASBESTOS-ST10-10/4/05	03529858-0005	North Side Sidewalk Bridge	10/4/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/2005	< 19.00	No	No	
ASBESTOS-ST11-10/5/05	030529961-0001	Southwest Area (street-level)	10/5/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/2005	< 19.00	No	No	
ASBESTOS-ST2-10/5/05	030529961-0002	Southeast Area (street-level)	10/5/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/2005	< 19.00	No	No	
ASBESTOS-ST4-10/5/05	030529961-0003	Northwest Area (street-level)	10/5/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/2005	< 19.00	No	No	
ASBESTOS-ST5-10/5/05	030529961-0004	Firehouse #10 (roof level)	10/5/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/2005	< 19.00	No	No	
ASBESTOS-ST10-10/5/05	030529961-0005	North Side Sidewalk Bridge	10/5/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/2005	< 19.00	No	No	
ASBESTOS-ST11-10/5/05	030529961-0006	90 Trinity Place (roof level)	10/5/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/2005	< 19.00	No	No	
ASBESTOS-ST13-10/5/05	030529961-0007	Marriott Hotel, 38th Floor (roof)	10/5/2005	1	4,580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/2005	< 19.00	No	No	
ASBESTOS-ST1-10/6/05	030530065-0001	Southwest Area (street-level)	10/6/2005	1	2,990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	
ASBESTOS-ST2-10/6/05	030530065-0002	Southeast Area (street-level)	10/6/2005	1	2,990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	
ASBESTOS-ST4-10/6/05	030530065-0003	Northwest Area (street-level)	10/6/2005	1	2,990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	
ASBESTOS-ST5-10/6/05	030530065-0004	Firehouse #10 (roof level)	10/6/2005	1	2,990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	
ASBESTOS-ST10-10/6/05	030530065-0005	North Side Sidewalk Bridge	10/6/2005	1	2,990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	
ASBESTOS-ST100-10/6/05	030530065-0009	Station 10 Field Duplicate	10/6/2005	1	2,990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	
ASBESTOS-ST11-10/6/05	030530065-0006	90 Trinity Place (roof level)	10/6/2005	1	2,990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	
ASBESTOS-ST12-10/6/05	030530065-0007	110 Greenwich Street (roof lev	10/6/2005	1	2,990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	
ASBESTOS-ST13-10/6/05	030530065-0008	Marriott Hotel, 38th Floor (roof	10/6/2005	1	2,990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	

* 30 Liberty Street Decontamination Project

Asbestos/S

Page 1 of

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										0.0009	Air Quality	Site Specific	
EPA Site Specific Trigger Levels										NA	Levels	Trigger Levels	
ASBESTOS-ST1-9/30/05	030529623-0001	Southwest Area (street-level)	9/30/2005	1	4.680	Asbestos	PCME	EMSL	10/3/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/30/05	030529623-0002	Southeast Area (street-level)	9/30/2005	1	4.680	Asbestos	PCME	EMSL	10/3/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/30/05	030529623-0004	Northwest Area (street-level)	9/30/2005	1	4.680	Asbestos	PCME	EMSL	10/3/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/30/05	030529623-0005	Firehouse #10 (roof level)	9/30/2005	1	4.680	Asbestos	PCME	EMSL	10/3/2005	< 0.00079	No	No	
ASBESTOS-ST10-9/30/05	030529623-0003	North Side Sidewalk Bridge	9/30/2005	1	4.680	Asbestos	PCME	EMSL	10/3/2005	< 0.00079	No	No	
ASBESTOS-ST1-10/1/05	030529640-0001	Southwest Area (street-level)	10/1/2005	1	4.680	Asbestos	PCME	EMSL	10/3/2005	< 0.00079	No	No	
ASBESTOS-ST2-10/1/05	030529640-0002	Southeast Area (street-level)	10/1/2005	1	4.680	Asbestos	PCME	EMSL	10/3/2005	< 0.00079	No	No	
ASBESTOS-ST4-10/1/05	030529640-0004	Northwest Area (street-level)	10/1/2005	1	4.680	Asbestos	PCME	EMSL	10/3/2005	< 0.00079	No	No	
ASBESTOS-ST5-10/1/05	030529640-0005	Firehouse #10 (roof level)	10/1/2005	1	4.680	Asbestos	PCME	EMSL	10/3/2005	< 0.00079	No	No	
ASBESTOS-ST10-10/1/05	030529640-0003	North Side Sidewalk Bridge	10/1/2005	1	4.680	Asbestos	PCME	EMSL	10/3/2005	< 0.00079	No	No	
ASBESTOS-ST1-10/2/05	030529641-0001	Southwest Area (street-level)	10/2/2005	1	4.680	Asbestos	PCME	EMSL	10/3/2005	< 0.00079	No	No	
ASBESTOS-ST2-10/2/05	030529641-0002	Southeast Area (street-level)	10/2/2005	1	4.680	Asbestos	PCME	EMSL	10/3/2005	< 0.00079	No	No	
ASBESTOS-ST4-10/2/05	030529641-0004	Northwest Area (street-level)	10/2/2005	1	4.680	Asbestos	PCME	EMSL	10/3/2005	< 0.00079	No	No	
ASBESTOS-ST5-10/2/05	030529641-0005	Firehouse #10 (roof level)	10/2/2005	1	4.680	Asbestos	PCME	EMSL	10/3/2005	< 0.00079	No	No	
ASBESTOS-ST10-10/2/05	030529641-0003	North Side Sidewalk Bridge	10/2/2005	1	4.680	Asbestos	PCME	EMSL	10/3/2005	< 0.00079	No	No	
ASBESTOS-ST1-10/3/05	030529713-0001	Southwest Area (street-level)	10/3/2005	1	4.680	Asbestos	PCME	EMSL	10/4/2005	< 0.00079	No	No	
ASBESTOS-ST2-10/3/05	030529713-0002	Southeast Area (street-level)	10/3/2005	1	4.680	Asbestos	PCME	EMSL	10/4/2005	< 0.00079	No	No	
ASBESTOS-ST4-10/3/05	030529713-0003	Northwest Area (street-level)	10/3/2005	1	4.680	Asbestos	PCME	EMSL	10/4/2005	< 0.00079	No	No	
ASBESTOS-ST5-10/3/05	030529713-0004	Firehouse #10 (roof level)	10/3/2005	1	4.680	Asbestos	PCME	EMSL	10/4/2005	< 0.00079	No	No	
ASBESTOS-ST10-10/3/05	030529713-0005	North Side Sidewalk Bridge	10/3/2005	1	4.680	Asbestos	PCME	EMSL	10/4/2005	< 0.00079	No	No	
ASBESTOS-ST1-10/4/05	030529858-0001	Southwest Area (street-level)	10/4/2005	1	4.680	Asbestos	PCME	EMSL	10/5/2005	< 0.00079	No	No	
ASBESTOS-ST2-10/4/05	030529858-0002	Southeast Area (street-level)	10/4/2005	1	4.680	Asbestos	PCME	EMSL	10/5/2005	< 0.00079	No	No	
ASBESTOS-ST4-10/4/05	030529858-0003	Northwest Area (street-level)	10/4/2005	1	4.680	Asbestos	PCME	EMSL	10/5/2005	< 0.00079	No	No	
ASBESTOS-ST5-10/4/05	030529858-0004	Firehouse #10 (roof level)	10/4/2005	1	4.680	Asbestos	PCME	EMSL	10/5/2005	< 0.00079	No	No	
ASBESTOS-ST10-10/4/05	030529858-0005	North Side Sidewalk Bridge	10/4/2005	1	4.680	Asbestos	PCME	EMSL	10/5/2005	< 0.00079	No	No	
ASBESTOS-ST1-10/5/05	030529961-0001	Southwest Area (street-level)	10/5/2005	1	4.680	Asbestos	PCME	EMSL	10/6/2005	< 0.00079	No	No	
ASBESTOS-ST2-10/5/05	030529961-0002	Southeast Area (street-level)	10/5/2005	1	4.680	Asbestos	PCME	EMSL	10/6/2005	< 0.00079	No	No	
ASBESTOS-ST4-10/5/05	030529961-0003	Northwest Area (street-level)	10/5/2005	1	4.680	Asbestos	PCME	EMSL	10/6/2005	< 0.00079	No	No	
ASBESTOS-ST5-10/5/05	030529961-0004	Firehouse #10 (roof level)	10/5/2005	1	4.680	Asbestos	PCME	EMSL	10/6/2005	< 0.00079	No	No	
ASBESTOS-ST10-10/5/05	030529961-0005	North Side Sidewalk Bridge	10/5/2005	1	4.680	Asbestos	PCME	EMSL	10/6/2005	< 0.00079	No	No	
ASBESTOS-ST11-10/5/05	030529961-0006	90 Trinity Place (roof level)	10/5/2005	1	4.680	Asbestos	PCME	EMSL	10/6/2005	0.00079	No	No	
ASBESTOS-ST13-10/5/05	030529961-0007	Marriott Hotel, 38th Floor (roof	10/5/2005	1	4.680	Asbestos	PCME	EMSL	10/6/2005	< 0.00079	No	No	
ASBESTOS-ST1-10/6/05	030530065-0001	Southwest Area (street-level)	10/6/2005	1	2.890	Asbestos	PCME	EMSL	10/7/2005	< 0.00085	No	No	
ASBESTOS-ST2-10/6/05	030530065-0002	Southeast Area (street-level)	10/6/2005	1	2.890	Asbestos	PCME	EMSL	10/7/2005	< 0.00085	No	No	
ASBESTOS-ST4-10/6/05	030530065-0003	Northwest Area (street-level)	10/6/2005	1	2.890	Asbestos	PCME	EMSL	10/7/2005	< 0.00085	No	No	
ASBESTOS-ST5-10/6/05	030530065-0004	Firehouse #10 (roof level)	10/6/2005	1	2.890	Asbestos	PCME	EMSL	10/7/2005	< 0.00085	No	No	
ASBESTOS-ST10-10/6/05	030530065-0005	North Side Sidewalk Bridge	10/6/2005	1	2.890	Asbestos	PCME	EMSL	10/7/2005	< 0.00085	No	No	
ASBESTOS-ST100-10/6/05	030530065-0009	Station 10 Field Duplicate	10/6/2005	1	2.890	Asbestos	PCME	EMSL	10/7/2005	< 0.00085	No	No	
ASBESTOS-ST11-10/6/05	030530065-0006	90 Trinity Place (roof level)	10/6/2005	1	2.890	Asbestos	PCME	EMSL	10/7/2005	< 0.00085	No	No	
ASBESTOS-ST12-10/6/05	030530065-0007	110 Greenwich Street (roof lev	10/6/2005	1	2.890	Asbestos	PCME	EMSL	10/7/2005	< 0.00085	No	No	
ASBESTOS-ST13-10/6/05	030530065-0008	Marriott Hotel, 38th Floor (roof	10/6/2005	1	2.890	Asbestos	PCME	EMSL	10/7/2005	< 0.00085	No	No	

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Total PCBs Concentration (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels									0.12	No	No	Comments
EPA Site Specific Trigger Levels									12			
PCBS-ST2-9/28/05	AI11305	Southeast Area (street-level)	9/28/2005	7.105	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/30/2005	< 0.0985	No	No	
PCBS-ST10-9/28/05	AI11312	North Side Sidewalk Bridge	9/28/2005	7.2	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/30/2005	< 0.0972	No	No	
PCBS-ST100-9/28/05	AI11313	Station 10 Field Duplicate	9/28/2005	7.081	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/30/2005	< 0.0989	No	No	

CITY_21MC100_003244018

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Dioxin TEQ Concentration (pg/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									0.25			
EPA Site Specific Trigger Levels									25			
Dioxins/Furans-ST2-9/28/05	P5907_3518_003	Southeast Area (street-level)	9/28/2005	355	Dioxin	TO-9A	AP	9/30/2005	0.0657	No	No	
Dioxins/Furans-ST10-9/28/05	P5907_3518_010	North Side Sidewalk Bridge	9/28/2005	361	Dioxin	TO-9A	AP	9/30/2005	0.154	No	No	
Dioxins/Furans-ST100-9/28/05	P5907_3518_011	Station 10 Field Duplicate	9/28/2005	349	Dioxin	TO-9A	AP	9/30/2005	0.0672	No	No	

CITY_21MC100_003244019

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels							150	No	No	
EPA Site Specific Trigger Levels							150			
PM10-ST1-10/2/2005	Southwest Area (street-level)	10/2/2005	1440	Particulate	Direct Read	Met One E-BAM	35.1	No	No	
PM10-ST2-10/2/2005	Southeast Area (street-level)	10/2/2005	1440	Particulate	Direct Read	Met One E-BAM	44.2	No	No	
PM10-ST4-10/2/2005	Northwest Area (street-level)	10/2/2005	1440	Particulate	Direct Read	Met One E-BAM	35.1	No	No	
PM10-ST5-10/2/2005	Firehouse #10 (roof level)	10/2/2005	1440	Particulate	Direct Read	Met One E-BAM	37.7	No	No	
PM10-ST6-10/2/2005	Southwest Area (roof level)	10/2/2005	1440	Particulate	Direct Read	Met One E-BAM	28.6	No	No	
PM10-ST7-10/2/2005	Southeast Area (roof level)	10/2/2005	1440	Particulate	Direct Read	Met One E-BAM	28.6	No	No	
PM10-ST9-10/2/2005	Northwest Area (roof level)	10/2/2005	1440	Particulate	Direct Read	Met One E-BAM	28.6	No	No	
PM10-ST10-10/2/2005	North Side Sidewalk Bridge	10/2/2005	1440	Particulate	Direct Read	Met One E-BAM	36.4	No	No	
PM10-ST11-10/3/2005	Southwest Area (street-level)	10/3/2005	1440	Particulate	Direct Read	Met One E-BAM	48.1	No	No	
PM10-ST2-10/3/2005	Southeast Area (street-level)	10/3/2005	1440	Particulate	Direct Read	Met One E-BAM	58.5	No	No	
PM10-ST4-10/3/2005	Northwest Area (street-level)	10/3/2005	1440	Particulate	Direct Read	Met One E-BAM	37.7	No	No	
PM10-ST5-10/3/2005	Firehouse #10 (roof level)	10/3/2005	1440	Particulate	Direct Read	Met One E-BAM	41.6	No	No	
PM10-ST6-10/3/2005	Southwest Area (roof level)	10/3/2005	1440	Particulate	Direct Read	Met One E-BAM	27.3	No	No	
PM10-ST7-10/3/2005	Southeast Area (roof level)	10/3/2005	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM10-ST9-10/3/2005	Northwest Area (roof level)	10/3/2005	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM10-ST10-10/3/2005	North Side Sidewalk Bridge	10/3/2005	1440	Particulate	Direct Read	Met One E-BAM	40.3	No	No	
PM10-ST11-10/4/2005	Southwest Area (street-level)	10/4/2005	1440	Particulate	Direct Read	Met One E-BAM	37.7	No	No	
PM10-ST2-10/4/2005	Southeast Area (street-level)	10/4/2005	1440	Particulate	Direct Read	Met One E-BAM	42.9	No	No	
PM10-ST4-10/4/2005	Northwest Area (street-level)	10/4/2005	1440	Particulate	Direct Read	Met One E-BAM	29.9	No	No	
PM10-ST5-10/4/2005	Firehouse #10 (roof level)	10/4/2005	1440	Particulate	Direct Read	Met One E-BAM	36.4	No	No	
PM10-ST6-10/4/2005	Southwest Area (roof level)	10/4/2005	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM10-ST7-10/4/2005	Southeast Area (roof level)	10/4/2005	1440	Particulate	Direct Read	Met One E-BAM	20.8	No	No	
PM10-ST9-10/4/2005	Northwest Area (roof level)	10/4/2005	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM10-ST10-10/4/2005	North Side Sidewalk Bridge	10/4/2005	1440	Particulate	Direct Read	Met One E-BAM	32.5	No	No	
PM10-ST11-10/5/2005	Southwest Area (street-level)	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	57.2	No	No	
PM10-ST2-10/5/2005	Southeast Area (street-level)	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	79.3	No	No	
PM10-ST4-10/5/2005	Northwest Area (street-level)	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	55.9	No	No	
PM10-ST5-10/5/2005	Firehouse #10 (roof level)	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	58.5	No	No	
PM10-ST6-10/5/2005	Southwest Area (roof level)	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	42.9	No	No	
PM10-ST7-10/5/2005	Southeast Area (roof level)	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	36.4	No	No	
PM10-ST9-10/5/2005	Northwest Area (roof level)	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST10-10/5/2005	North Side Sidewalk Bridge	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	58.5	No	No	
PM10-ST11-10/5/2005	90 Trinity Place (roof level)	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	45.5	No	No	
PM10-ST1-10/6/2005	Southwest Area (street-level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	48.1	No	No	
PM10-ST2-10/6/2005	Southeast Area (street-level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	68.9	No	No	
PM10-ST4-10/6/2005	Northwest Area (street-level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	50.7	No	No	
PM10-ST5-10/6/2005	Firehouse #10 (roof level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	57.2	No	No	
PM10-ST6-10/6/2005	Southwest Area (roof level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	20.8	No	No	
PM10-ST7-10/6/2005	Southeast Area (roof level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM10-ST9-10/6/2005	Northwest Area (roof level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	20.8	No	No	
PM10-ST10-10/6/2005	North Side Sidewalk Bridge	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	42.9	No	No	
PM10-ST11-10/6/2005	90 Trinity Place (roof level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	24.7	No	No	
PM10-ST12-10/6/2005	110 Greenwich Street (roof level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	27.3	No	No	
PM10-ST13-10/6/2005	Marriott Hotel, 38th Floor (roof level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	50.7	No	No	
PM10-ST1-10/7/2005	Southwest Area (street-level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	27.3	No	No	
PM10-ST2-10/7/2005	Southeast Area (street-level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	54.6	No	No	
PM10-ST4-10/7/2005	Northwest Area (street-level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	37.7	No	No	
PM10-ST5-10/7/2005	Firehouse #10 (roof level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	33.8	No	No	
PM10-ST6-10/7/2005	Southwest Area (roof level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	18.2	No	No	
PM10-ST7-10/7/2005	Southeast Area (roof level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	15.6	No	No	

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality Levels	Site Specific Trigger Levels	Comments
EPA Site Specific Trigger Levels							150			
PM10-ST9-10/7/2005	Northwest Area (roof level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	16.9	No	No	
PM10-ST10-10/7/2005	North Side Sidewalk Bridge	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	33.8	No	No	
PM10-ST11-10/7/2005	90 Trinity Place (roof level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM10-ST12-10/7/2005	110 Greenwich Street (roof level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	32.5	No	No	
PM10-ST13-10/7/2005	Marriott Hotel, 38th Floor (roof level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	29.9	No	No	
PM10-ST1-10/8/2005	Southwest Area (street-level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	110.5	No	No	
PM10-ST2-10/8/2005	Southeast Area (street-level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	97.5	No	No	
PM10-ST4-10/8/2005	Northwest Area (street-level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	54.6	No	No	
PM10-ST5-10/8/2005	Firehouse #10 (roof level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	41.6	No	No	
PM10-ST6-10/8/2005	Southwest Area (roof level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	10.4	No	No	
PM10-ST7-10/8/2005	Southeast Area (roof level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	10.4	No	No	
PM10-ST9-10/8/2005	Northwest Area (roof level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	9.1	No	No	
PM10-ST10-10/8/2005	North Side Sidewalk Bridge	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	29.9	No	No	
PM10-ST11-10/8/2005	90 Trinity Place (roof level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST12-10/8/2005	110 Greenwich Street (roof level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	31.2	No	No	
PM10-ST13-10/8/2005	Marriott Hotel, 38th Floor (roof level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	11.7	No	No	

CITY_21MC100_003244021

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ugm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							43			
EPA Site Specific Trigger Levels							65			
PM2.5-ST1-10/2/2005	Southwest Area (street-level)	10/2/2005	1440	Particulate	Direct Read	Met One E-BAM	33.8	No	No	
PM2.5-ST2-10/2/2005	Southeast Area (street-level)	10/2/2005	1410	Particulate	Direct Read	Met One E-BAM	26.1	No	No	
PM2.5-ST4-10/2/2005	Northwest Area (street-level)	10/2/2005	1440	Particulate	Direct Read	Met One E-BAM	23.9	No	No	
PM2.5-ST5-10/2/2005	Firehouse #10 (roof level)	10/2/2005	1440	Particulate	Direct Read	Met One E-BAM	33.8	No	No	
PM2.5-ST3-10/2/2005	Southwest Area (roof level)	10/2/2005	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM2.5-ST7-10/2/2005	Southeast Area (roof level)	10/2/2005	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM2.5-ST9-10/2/2005	Northwest Area (roof level)	10/2/2005	1410	Particulate	Direct Read	Met One E-BAM	23.1	No	No	
PM2.5-ST3-10/2/2005	Northwest Area (roof level)	10/2/2005	1440	Particulate	Direct Read	Met One E-BAM	22.1	No	No	
PM2.5-ST10-10/2/2005	North Side Sidewalk Bridge	10/2/2005	1440	Particulate	Direct Read	Met One E-BAM	27.3	No	No	
PM2.5-ST1-10/3/2005	Southwest Area (street-level)	10/3/2005	1440	Particulate	Direct Read	Met One E-BAM	41.8	Yes	No	Regional Air Quality Influence; no corrective action required per 10/4/05 call with EPA.
PM2.5-ST2-10/3/2005	Southeast Area (street-level)	10/3/2005	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM2.5-ST4-10/3/2005	Northwest Area (street-level)	10/3/2005	1440	Particulate	Direct Read	Met One E-BAM	28.8	No	No	
PM2.5-ST5-10/3/2005	Firehouse #10 (roof level)	10/3/2005	1440	Particulate	Direct Read	Met One E-BAM	31.2	No	No	
PM2.5-ST3-10/3/2005	Southwest Area (roof level)	10/3/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM2.5-ST7-10/3/2005	Southeast Area (roof level)	10/3/2005	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM2.5-ST9-10/3/2005	Northwest Area (roof level)	10/3/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM2.5-ST3-10/3/2005	Northwest Area (roof level)	10/3/2005	1440	Particulate	Direct Read	Met One E-BAM	18.9	No	No	
PM2.5-ST10-10/3/2005	North Side Sidewalk Bridge	10/3/2005	1440	Particulate	Direct Read	Met One E-BAM	23.9	No	No	
PM2.5-ST1-10/4/2005	Southwest Area (street-level)	10/4/2005	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST2-10/4/2005	Southeast Area (street-level)	10/4/2005	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST4-10/4/2005	Northwest Area (street-level)	10/4/2005	1440	Particulate	Direct Read	Met One E-BAM	16.8	No	No	
PM2.5-ST5-10/4/2005	Firehouse #10 (roof level)	10/4/2005	1440	Particulate	Direct Read	Met One E-BAM	18.2	No	No	
PM2.5-ST3-10/4/2005	Southwest Area (roof level)	10/4/2005	1440	Particulate	Direct Read	Met One E-BAM	15.6	No	No	
PM2.5-ST7-10/4/2005	Southeast Area (roof level)	10/4/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM2.5-ST9-10/4/2005	Northwest Area (roof level)	10/4/2005	1440	Particulate	Direct Read	Met One E-BAM	14.1	No	No	
PM2.5-ST10-10/4/2005	North Side Sidewalk Bridge	10/4/2005	1440	Particulate	Direct Read	Met One E-BAM	20.8	No	No	
PM2.5-ST1-10/5/2005	Southwest Area (street-level)	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	44.2	Yes	No	Regional Air Quality Influence, exceedances communicated via telephone and e-mail to EPA on 10/6/05.
PM2.5-ST2-10/5/2005	Southeast Area (street-level)	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	48.9	Yes	No	
PM2.5-ST4-10/5/2005	Northwest Area (street-level)	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM2.5-ST5-10/5/2005	Firehouse #10 (roof level)	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM2.5-ST3-10/5/2005	Southwest Area (roof level)	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	32.5	No	No	
PM2.5-ST7-10/5/2005	Southeast Area (roof level)	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	35.1	No	No	
PM2.5-ST9-10/5/2005	Northwest Area (roof level)	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	23.9	No	No	Regional Air Quality Influence, exceedances communicated via telephone and e-mail to EPA on 10/6/05.
PM2.5-ST10-10/5/2005	North Side Sidewalk Bridge	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	44.2	Yes	No	
PM2.5-ST11-10/5/2005	30 Trinity Place (roof level)	10/5/2005	1440	Particulate	Direct Read	Met One E-BAM	33.8	No	No	
PM2.5-ST1-10/6/2005	Southwest Area (street-level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	28.8	No	No	
PM2.5-ST2-10/6/2005	Southeast Area (street-level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	36.4	No	No	
PM2.5-ST4-10/6/2005	Northwest Area (street-level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	22.1	No	No	
PM2.5-ST5-10/6/2005	Firehouse #10 (roof level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST3-10/6/2005	Southwest Area (roof level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	15.6	No	No	
PM2.5-ST7-10/6/2005	Southeast Area (roof level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM2.5-ST9-10/6/2005	Northwest Area (roof level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	14.3	No	No	
PM2.5-ST10-10/6/2005	North Side Sidewalk Bridge	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	23.9	No	No	
PM2.5-ST11-10/6/2005	30 Trinity Place (roof level)	10/6/2005	1410	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST12-10/6/2005	110 Greenwich Street (roof level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	27.3	No	No	
PM2.5-ST13-10/6/2005	Marriott Hotel, 38th Floor (roof level)	10/6/2005	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM2.5-ST1-10/7/2005	Southwest Area (street-level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	18.2	No	No	
PM2.5-ST2-10/7/2005	Southeast Area (street-level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	23.9	No	No	
PM2.5-ST4-10/7/2005	Northwest Area (street-level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	14.3	No	No	
PM2.5-ST5-10/7/2005	Firehouse #10 (roof level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	20.8	No	No	
PM2.5-ST3-10/7/2005	Southwest Area (roof level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	9.1	No	No	
PM2.5-ST7-10/7/2005	Southeast Area (roof level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	9.1	No	No	
PM2.5-ST9-10/7/2005	Northwest Area (roof level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	6.5	No	No	
PM2.5-ST10-10/7/2005	North Side Sidewalk Bridge	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	22.1	No	No	
PM2.5-ST11-10/7/2005	30 Trinity Place (roof level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	18.9	No	No	
PM2.5-ST12-10/7/2005	110 Greenwich Street (roof level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST13-10/7/2005	Marriott Hotel, 38th Floor (roof level)	10/7/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM2.5-ST1-10/8/2005	Southwest Area (street-level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	11.7	No	No	
PM2.5-ST2-10/8/2005	Southeast Area (street-level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM2.5-ST4-10/8/2005	Northwest Area (street-level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	36.4	No	No	
PM2.5-ST5-10/8/2005	Firehouse #10 (roof level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	54.6	Yes	No	Excessive rainfall and adverse weather conditions impacted instrument performance; results questionable (PM2.5 > PM10).
PM2.5-ST3-10/8/2005	Southwest Area (roof level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	2.6	No	No	
PM2.5-ST7-10/8/2005	Southeast Area (roof level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	5.2	No	No	
PM2.5-ST9-10/8/2005	Northwest Area (roof level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	3.9	No	No	
PM2.5-ST10-10/8/2005	North Side Sidewalk Bridge	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	45.5	Yes	No	Excessive rainfall and adverse weather conditions impacted instrument performance; results questionable (PM2.5 > PM10).
PM2.5-ST11-10/8/2005	Station 10 Field Duplicate	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	6.5	No	No	
PM2.5-ST11-10/8/2005	30 Trinity Place (roof level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	9.1	No	No	
PM2.5-ST12-10/8/2005	110 Greenwich Street (roof level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	9.1	No	No	
PM2.5-ST13-10/8/2005	Marriott Hotel, 38th Floor (roof level)	10/8/2005	1440	Particulate	Direct Read	Met One E-BAM	9.1	No	No	

Note: A correction factor of 1.3 was applied to the reported data. TRC does not believe a correction factor should be applied to this data; however, this has been performed as directed by the EPA.