NYC 9/11 Public Portal Document

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date (Eastern Air Quality Levels) (EDST/EST) | Sample Volume (m³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Antimony Concentration (ng/m3) | Barium Concentration (ng/m3) | Beryllium Concentration (ng/m3) | Cadmium Concentration (ng/m3) | Chromium (Total) Concentration (ng/m3) | Copper Concentration (ng/m3) | Lead Concentration (ng/m3) | Manganese Concentration (ng/m3) | Nickel Concentration (ng/m3) | Zinc Concentration (ng/m3) | Exceeds Target Air Quality Levels | Exceeds EPA Site-Specific Trigger Levels | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | 10,000 | 50,000 | 200 | 4,000 | 500 | 10,000 | 1,000 | 500 | 2,000 | 40,000 | | | |
| METALS-ST-11-112805 | QA20040000 | Southwest Area (sidewalk bridge level) | 11/1/2005 | 1696.4 | details | ocpp | STL-SAC | 11/28/05 | 5.4 | < 70.0 | < 0.71 | < 0.71 | < 7.1 | 127 | 69.0 | 7.5 | 10 | 64.0 | No | No | |
| METALS-ST2-11-112805 | QA20040003 | Southeast Area (sidewalk bridge level) | 11/1/2005 | 1648.5 | details | ocpp | STL-SAC | 11/28/05 | 3.9 | < 72.7 | < 0.73 | < 0.73 | < 7.3 | 94.4 | 53.7 | 10 | 10 | 61.5 | No | No | |
| METALS-ST4-11-112805 | QA20040005 | Northwest Area (street-level) | 11/1/2005 | 1655.7 | details | ocpp | STL-SAC | 11/28/05 | 4.5 | < 72.5 | < 0.72 | < 0.72 | < 7.2 | 87.4 | 29.4 | 1.9 | 6.9 | 116 | No | No | |
| METALS-ST-11-112805 | QA20040004 | Firehouse #10 (roof level) | 11/1/2005 | 1773.7 | details | ocpp | STL-SAC | 11/28/05 | 3.0 | < 67.6 | < 0.68 | < 0.68 | < 6.8 | 94.4 | 11.6 | 0.68 | 9.1 | 45.4 | No | No | |
| METALS-ST10-11-112805 | QA20040010 | North Side Sidewalk Bags | 11/1/2005 | 1744.6 | details | ocpp | STL-SAC | 11/28/05 | 5.5 | < 69.1 | < 0.69 | < 0.69 | < 6.9 | 110 | 41.1 | 1.9 | 9.0 | 83.0 | No | No | |
| METALS-ST1-11-112805 | QA20040006 | 90 Trinity Place (roof level) | 11/1/2005 | 1764.7 | details | ocpp | STL-SAC | 11/28/05 | 5.0 | < 68.0 | < 0.67 | < 0.67 | < 6.7 | 114 | 41.9 | 14.0 | 14.0 | 89.9 | No | No | |
| METALS-ST12-11-112805 | QA20040007 | 110 Greenwich Street (roof level) | 11/1/2005 | 1691.6 | details | ocpp | STL-SAC | 11/28/05 | 5.1 | < 73.7 | < 0.74 | < 0.74 | < 7.3 | 182 | 10.1 | 16 | 11.3 | 48.5 | No | No | |
| METALS-ST13-11-112805 | QA20040002 | Marriott Hotel, 5th Floor (roof level) | 11/1/2005 | 1679.4 | details | ocpp | STL-SAC | 11/28/05 | 3.9 | < 71.3 | < 0.71 | < 0.71 | < 7.1 | 9.3 | 5.5 | 0.71 | 10.9 | 57.0 | No | No | |
| METALS-ST14-11-112805 | QA20040009 | West Face - South end at corner (scaf/sidg lev-s) | 11/1/2005 | 1986.9 | details | ocpp | STL-SAC | 11/28/05 | 5.1 | < 62.0 | < 0.62 | < 0.62 | < 6.2 | 10 | 96.4 | 9.4 | 6.9 | 55.9 | No | No | |
| METALS-ST15-11-112805 | QA20040010 | South Face - East end at corner (scaf/sidg lev-s) | 11/1/2005 | 1979.5 | details | ocpp | STL-SAC | 11/28/05 | 5.0 | < 69.9 | < 0.64 | < 0.64 | < 6.4 | 79.9 | 13.5 | 11.6 | 13.5 | 10 | No | No | |
| METALS-ST16-11-112805 | QA20040401 | East Face - North end at corner (scaf/sidg lev-s) | 11/1/2005 | 1986.9 | details | ocpp | STL-SAC | 11/28/05 | 2.5 | < 62.0 | < 0.62 | < 0.62 | < 6.2 | 50.3 | 12.0 | 59.6 | 9.1 | 62.2 | No | No | |
| METALS-ST17-11-112805 | QA20040402 | North Face - West end at corner (scaf/sidg lev-s) | 11/1/2005 | 1788.5 | details | ocpp | STL-SAC | 11/28/05 | 5.3 | < 68.9 | < 0.67 | < 0.67 | < 6.7 | 1.7 | 29.2 | 13.1 | 14.7 | 9.5 | No | No | |
| METALS-ST-11-112805 | QA20040000 | Southwest Area (sidewalk bridge level) | 11/2/2005 | 1677.5 | details | ocpp | STL-SAC | 11/28/05 | 3.9 | < 71.5 | < 0.72 | < 0.72 | < 7.2 | 26.5 | 7.2 | 28.5 | 16.0 | 61.3 | No | No | |
| METALS-ST2-11-112805 | QA20040003 | Southeast Area (sidewalk bridge level) | 11/2/2005 | 1652.8 | details | ocpp | STL-SAC | 11/28/05 | 5.3 | < 75.9 | < 0.74 | < 0.74 | < 7.4 | 56.4 | 16.5 | 7.52 | 16.5 | 63.7 | No | No | |
| METALS-ST4-11-112805 | QA20040005 | Northwest Area (street-level) | 11/2/2005 | 1621.7 | details | ocpp | STL-SAC | 11/28/05 | 5.5 | < 74.0 | < 0.74 | < 0.74 | < 7.4 | 125 | 27.2 | 29.6 | 15.7 | 110 | No | No | |
| METALS-ST-11-112805 | QA20040004 | Firehouse #10 (roof level) | 11/2/2005 | 1794.7 | details | ocpp | STL-SAC | 11/28/05 | 5.3 | < 66.9 | < 0.67 | < 0.67 | < 6.7 | 55.5 | 21.0 | 26.8 | 15.0 | 70.4 | No | No | |
| METALS-ST10-11-112805 | QA20040010 | North Side Sidewalk Bags | 11/2/2005 | 1797 | details | ocpp | STL-SAC | 11/28/05 | 5.6 | < 69.1 | < 0.69 | < 0.69 | < 6.9 | 26.4 | 21.3 | 28.5 | 15.6 | 71.0 | No | No | |
| METALS-ST1-11-112805 | QA20040006 | 90 Trinity Place (roof level) | 11/2/2005 | 1707.5 | details | ocpp | STL-SAC | 11/28/05 | 5.9 | < 67.1 | < 0.67 | < 0.67 | < 6.7 | 15.3 | 33.8 | 15.1 | 15.7 | 59.5 | No | No | |
| METALS-ST12-11-112805 | QA20040007 | 110 Greenwich Street (roof level) | 11/2/2005 | 1755.1 | details | ocpp | STL-SAC | 11/28/05 | 5.1 | < 66.5 | < 0.66 | < 0.66 | < 6.6 | 142 | 16.5 | 16.5 | 15.5 | 63.3 | No | No | |
| METALS-ST13-11-112805 | QA20040002 | Marriott Hotel, 5th Floor (roof level) | 11/2/2005 | 1739.9 | details | ocpp | STL-SAC | 11/28/05 | 5.1 | < 69.5 | < 0.70 | < 0.70 | < 6.9 | 43.0 | 13.5 | 15.0 | 15.7 | 47.1 | No | No | |
| METALS-ST14-11-112805 | QA20040009 | West Face - South end at corner (scaf/sidg lev-s) | 11/2/2005 | 1986.9 | details | ocpp | STL-SAC | 11/28/05 | 5.1 | < 69.2 | < 0.69 | < 0.69 | < 6.9 | 15.3 | 19.5 | 13.5 | 12.5 | 46.5 | No | No | |
| METALS-ST15-11-112805 | QA20040010 | South Face - East end at corner (scaf/sidg lev-s) | 11/2/2005 | 1963.9 | details | ocpp | STL-SAC | 11/28/05 | 5.0 | < 64.4 | < 0.64 | < 0.64 | < 6.4 | 66.9 | 13.0 | 11.0 | 13.1 | 79.6 | No | No | |
| METALS-ST16-11-112805 | QA20040401 | East Face - North end at corner (scaf/sidg lev-s) | 11/2/2005 | 1983.3 | details | ocpp | STL-SAC | 11/28/05 | 2.4 | < 69.7 | 0.84 | < 0.64 | < 6.4 | 52.2 | 18.8 | 117 | 12.4 | 75.7 | No | No | |
| METALS-ST17-11-112805 | QA20040402 | North Face - West end at corner (scaf/sidg lev-s) | 11/2/2005 | 1793.0 | details | ocpp | STL-SAC | 11/28/05 | 5.0 | < 67.8 | < 0.68 | < 0.68 | < 6.8 | 146 | 21.6 | 24.8 | 14.0 | 69.0 | No | No | |
| METALS-ST-11-112905 | QA20040000 | Southwest Area (sidewalk bridge level) | 11/2/2005 | 1659.2 | details | ocpp | STL-SAC | 11/28/05 | 5.1 | < 72.5 | < 0.72 | < 0.72 | < 7.2 | 19.2 | 27.2 | 28.5 | 16.0 | 61.5 | No | No | |
| METALS-ST2-11-112905 | QA20040003 | Southeast Area (sidewalk bridge level) | 11/2/2005 | 1643.7 | details | ocpp | STL-SAC | 11/28/05 | 5.1 | < 76.9 | < 0.77 | < 0.77 | < 7.7 | 138 | 19.8 | 29.7 | 15.2 | 77.7 | No | No | |
| METALS-ST4-11-112905 | QA20040005 | Northwest Area (street-level) | 11/2/2005 | 1594.5 | details | ocpp | STL-SAC | 11/28/05 | 5.2 | < 75.7 | < 0.76 | < 0.76 | < 7.6 | 125 | 52.7 | 28.0 | 16.6 | 94.9 | No | No | |
| METALS-ST-11-112905 | QA20040004 | Firehouse #10 (roof level) | 11/2/2005 | 1751.0 | details | ocpp | STL-SAC | 11/28/05 | 5.2 | < 69.5 | < 0.69 | < 0.69 | < 6.9 | 57.4 | 38.6 | 29.8 | 16.0 | 100 | No | No | |
| METALS-ST10-11-112905 | QA20040010 | North Side Sidewalk Bags | 11/2/2005 | 1707.2 | details | ocpp | STL-SAC | 11/28/05 | 5.1 | < 67.6 | < 0.68 | < 0.68 | < 6.8 | 54.3 | 41.1 | 30.7 | 20.0 | 105 | No | No | |
| METALS-ST1-11-112905 | QA20040006 | 90 Trinity Place (roof level) | 11/2/2005 | 1769.1 | details | ocpp | STL-SAC | 11/28/05 | 5.3 | < 67.4 | < 0.67 | < 0.67 | < 6.7 | 40.8 | 30.5 | 27.1 | 16.8 | 96.8 | No | No | |
| METALS-ST12-11-112905 | QA20040007 | 110 Greenwich Street (roof level) | 11/2/2005 | 1785.5 | details | ocpp | STL-SAC | 11/28/05 | 5.1 | < 66.2 | < 0.66 | < 0.66 | < 6.6 | 134 | 20.6 | 28.6 | 23.0 | 65.1 | No | No | |
| METALS-ST13-11-112905 | QA20040002 | Marriott Hotel, 5th Floor (roof level) | 11/2/2005 | 1760.4 | details | ocpp | STL-SAC | 11/28/05 | 5.1 | < 68.2 | < 0.68 | < 0.68 | < 6.8 | 43.7 | 13.9 | 19.1 | 30.0 | 66.0 | No | No | |
| METALS-ST14-11-112905 | QA20040009 | West Face - South end at corner (scaf/sidg lev-s) | 11/2/2005 | 1974.4 | details | ocpp | STL-SAC | 11/28/05 | 5.0 | < 64.0 | < 0.64 | < 0.64 | < 6.4 | 18.6 | 27.1 | 23.0 | 11.4 | 50.0 | No | No | |
| METALS-ST15-11-112905 | QA20040010 | South Face - East end at corner (scaf/sidg lev-s) | 11/2/2005 | 1951.9 | details | ocpp | STL-SAC | 11/28/05 | 5.2 | < 66.9 | < 0.66 | < 0.66 | < 6.6 | 40.2 | 29.7 | 30.4 | 16.7 | 90.7 | No | No | |
| METALS-ST16-11-112905 | QA20040401 | East Face - North end at corner (scaf/sidg lev-s) | 11/2/2005 | 1949.7 | details | ocpp | STL-SAC | 11/28/05 | 5.1 | < 64.9 | < 0.65 | < 0.65 | < 6.5 | 34.4 | 30.7 | 29.0 | 16.4 | 94.4 | No | No | |
| METALS-ST17-11-112905 | QA20040402 | North Face - West end at corner (scaf/sidg lev-s) | 11/2/2005 | 1759.3 | details | ocpp | STL-SAC | 11/28/05 | 5.1 | < 66.7 | < 0.67 | 0.8 | < 6.7 | 69.0 | 37.7 | 1.92 | 16.7 | 94.4 | No | No | |
| METALS-ST-11-112905 | QA20040000 | Southwest Area (sidewalk bridge level) | 11/2/2005 | 1666.8 | details | ocpp | STL-SAC | 11/28/05 | < 1.4 | < 71.1 | < 0.71 | < 0.71 | < 7.1 | 41.7 | 6.8 | 3.5 | 4.9 | 34.5 | No | No | |
| METALS-ST2-11-112905 | QA20040003 | Southeast Area (sidewalk bridge level) | 11/2/2005 | 1641.7 | details | ocpp | STL-SAC | 11/28/05 | < 1.6 | < 79.1 | < 0.79 | < 0.79 | < 7.9 | 316 | 24.7 | 10.0 | 4.9 | 54.0 | No | No | |
| METALS-ST4-11-112905 | QA20040005 | Northwest Area (street-level) | 11/2/2005 | 1656 | details | ocpp | STL-SAC | 11/28/05 | < 1.6 | < 79.5 | < 0.79 | < 0.79 | < 7.9 | 320 | 40.4 | 19.0 | < 9.7 | 60.9 | No | No | |
| METALS-ST-11-112905 | QA20040004 | Firehouse #10 (roof level) | 11/2/2005 | 1802.7 | details | ocpp | STL-SAC | 11/28/05 | < 1.3 | < 66.6 | < 0.66 | < 0.66 | < 6.6 | 25.1 | 4.4 | 7.5 | < 9.3 | 31.2 | No | No | |
| METALS-ST10-11-112905 | QA20040010 | North Side Sidewalk Bags | 11/2/2005 | 1752 | details | ocpp | STL-SAC | 11/28/05 | < 1.4 | < 69.4 | < 0.69 | < 0.69 | < 6.9 | 7.7 | 5.0 | 7.0 | < 9.4 | 19.0 | No | No | |
| METALS-ST1-11-112905 | QA20040006 | 90 Trinity Place (roof level) | 11/2/2005 | 1808.6 | details | ocpp | STL-SAC | 11/28/05 | < 1.3 | < 66.3 | < 0.66 | < 0.66 | < 6.6 | 19.2 | 9.8 | 3.5 | 4.6 | 15.5 | No | No | |
| METALS-ST12-11-112905 | QA20040007 | 110 Greenwich Street (roof level) | 11/2/2005 | 1765.5 | details | ocpp | STL-SAC | 11/28/05 | < 1.4 | < 66.0 | < 0.66 | < 0.66 | < 6.6 | 58.3 | 5.5 | 4.5 | 4.1 | 15.0 | No | No | |
| METALS-ST13-11-112905 | QA20040002 | Marriott Hotel, 5th Floor (roof level) | 11/2/2005 | 1766.6 | details | ocpp | STL-SAC | 11/28/05 | < 1.4 | < 68.3 | < 0.68 | < 0.68 | < 6.8 | 59.4 | 2.9 | < 3.4 | < 3.4 | < 19.7 | No | No | |
| METALS-ST14-11-112905 | QA20040009 | West Face - South end at corner (scaf/sidg lev-s) | 11/2/2005 | 1975.8 | details | ocpp | STL-SAC | 11/28/05 | < 1.3 | < 63.8 | < 0.64 | < 0.64 | < 6.4 | 51.9 | 4.1 | 4.4 | < 3.2 | 28.2 | No | No | |
| METALS-ST15-11-112905 | QA20040010 | South Face - East end at corner (scaf/sidg lev-s) | 11/2/2005 | 1955.5 | details | ocpp | STL-SAC | 11/28/05 | 0.7 | < 66.8 | < 0.66 | < 0.66 | < 6.6 | 24.5 | 12.6 | 40.1 | < 9.3 | 29.6 | No | No | |
| METALS-ST16-11-112905 | QA20040401 | East Face - North end at corner (scaf/sidg lev-s) | 11/2/2005 | 1944.2 | details | ocpp | STL-SAC | 11/28/05 | < 1.3 | < 65.0 | < 0.65 | < 0.65 | < 6.5 | 111 | 10 | 19.0 | < 9.4 | 15.4 | No | No | |
| METALS-ST17-11-112905 | QA20040402 | North Face - West end at corner (scaf/sidg lev-s) | 11/2/2005 | 1751.5 | details | ocpp | STL-SAC | 11/28/05 | < 1.4 | < 69.1 | < 0.69 | 0.72 | < 6.9 | 9.3 | 5.2 | 26.9 | < 9.4 | 40.0 | No | No | |
| METALS-ST-11-112905 | QA20040000 | Southwest Area (sidewalk bridge level) | 11/2/2005 | 1677.5 | details | ocpp | STL-SAC | 11/28/05 | < 1.5 | < 74.2 | < 0.74 | < 0.74 | < 7.4 | 70.2 | 11.5 | 12.4 | 6.9 | 48.4 | No | No | |
| METALS-ST2-11-112905 | QA20040003 | Southeast Area (sidewalk bridge level) | 11/2/2005 | 1594.3 | details | ocpp | STL-SAC | 11/28/05 | < 1.6 | < 76.3 | < 0.76 | < 0.76 | < 7.5 | 1040 | 14.0 | 9.8 | 7.9 | 40.0 | No | No | |
| METALS-ST4-11-112905 | QA20040005 | Northwest Area (street-level) | 11/2/2005 | 1668.8 | details | ocpp | STL-SAC | 11/28/05 | < 1.5 | < 75.3 | < 0.75 | < 0.75 | < 7.5 | 563 | 17.5 | 19.5 | 6.2 | 57.5 | No | No | |
| METALS-ST-11-112905 | QA20040004 | Firehouse #10 (roof level) | 11/2/2005 | 1799.7 | details | ocpp | STL-SAC | 11/28/05 | < 1.5 | < 66.7 | < 0.67 | < 0.67 | < 6.7 | 42.3 | 5.9 | 11.5 | 5.9 | 29.4 | No | No | |
| METALS-ST10-11-112905 | QA20040010 | North Side Sidewalk Bags | 11/2/2005 | 1726.7 | details | ocpp | STL-SAC | 11/28/05 | < 1.4 | < 69.4 | < 0.69 | < 0.69 | < 6.9 | 15.2 | 7.6 | 12.2 | 7.5 | 31.5 | No | No | |
| METALS-ST1-11-112905 | QA20040006 | 90 Trinity Place (roof level) | 11/2/2005 | 1767.6 | details | ocpp | STL-SAC | 11/28/05 | < 1.4 | < 67.9 | < 0.68 | < 0.68 | < 6.8 | 52.4 | 5.8 | 10 | 5.5 | 29.1 | No | No | |
| METALS-ST12-11-112905 | QA20040007 | 110 Greenwich Street (roof level) | 11/2/2005 | 1734.8 | details | ocpp | STL-SAC | 11/28/05 | < 1.4 | < 69.2 | < 0.69 | < 0.69 | < 6.9 | 57.1 | 5.4 | 9.4 | 7.5 | 26.2 | No | No | |
| METALS-ST13-11-112905 | QA20040002 | Marriott Hotel, 5th Floor (roof level) | 11/2/2005 | 1696.4 | details | ocpp | STL-SAC | 11/28/05 | < 1.4 | < 70.5 | < 0.71 | < 0.71 | < 7.1 | 56.2 | 5.1 | 5.6 | 5.6 | 19.5 | No | No | |
| METALS-ST14-11-112905 | QA20040009 | West Face - South end at corner (scaf/sidg lev-s) | 11/2/2005 | 1950.5 | details | ocpp | STL-SAC | 11/28/05 | < 1.2 | < 61.5 | < 0.62 | < 0.62 | < 6.2 | 32.5 | 5.5 | 7.9 | 5.4 | 30.5 | No | No | |
| METALS-ST15-11-112905 | QA20040010 | South Face - East end at corner (scaf/sidg lev-s) | 11/2/2005 | 1936.9 | details | ocpp | STL-SAC | 11/28/05 | < 1.3 | < 66.7 | < 0.66 | < 0.66 | < 6.6 | 68.1 | 7.6 | 6.1 | 5.7 | 26.6 | No | No | |
| METALS-ST16-11-112905 | QA20040401 | East Face - North end at corner (scaf/sidg lev-s) | 11/2/2005 | 1876.9 | details | ocpp | STL-SAC | 11/28/05 | < 1.3 | < 63.9 | < 0.64 | 1.0 | < 6.4 | 23.0 | 6.3 | 10 | 5.8 | 30.2 | No | No | |
| METALS-ST17-11-112905 | QA20040402 | North Face - West end at corner (scaf/sidg lev-s) | 11/2/2005 | 1744.3 | details | ocpp | STL-SAC | 11/28/05 | < 1.3 | < 66.9 | < 0.67 | < 0.67 | < 6.7 | 226 | 6.8 | 1.1 | 6.1 | 52.6 | No | No | |
| METALS-ST-11-112905 | QA20040000 | Southwest Area (sidewalk bridge level) | 11/2/2005 | 1747.8 | details | ocpp | STL-SAC | 11/28/05 | 55.1 | < 66.6 | < 0.66 | < 0.66 | < 6.9 | 136 | 49.1 | 9.1 | 6.8 | 72.6 | No | No | |
| METALS-ST2-11-112905 | QA20040003 | Southeast Area (sidewalk bridge level) | 11/2/2005 | 1674.5 | details | ocpp | STL-SAC | 11/28/05 | 30.6 | < 71.0 | < 0.71 | < 0.71 | < 7.1 | 1160 | 19.5 | 7.5 | 7.9 | 47.1 | No | No | |
| METALS-ST4-11-112905 | QA20040005 | Northwest Area (street-level) | 11/2/2005 | 1662.8 | details | ocpp | STL-SAC | 11/28/05 | 29.9 | < 71.3 | < 0.71 | < 0.71 | < 7.1 | 145 | 58.7 | 9.5 | 7.3 | 71.4 | No | No | |
| METALS-ST-11-112905 | QA20040004 | Firehouse #10 (roof level) | 11/2/2005 | 1794.7 | details | ocpp | STL-SAC | 11/28/05 | 5.7 | < 67.7 | < 0.68 | < 0.68 | < 6.8 | 64.5 | 5.9 | 7.7 | 5.3 | < 19.7 | No | No | |
| METALS-ST10-11-112905 | QA20040010 | North Side Sidewalk Bags | 11/2/2005 | 1818.6 | details | ocpp | STL-SAC | 11/28/05 | 4.6 | < 66.0 | < 0.66 | < 0.66 | < 6.6 | 16.4 | 11.4 | 7.7 | 6.0 | 52.8 | No | No | |
| METALS-ST1-11-112905 | QA20040006 | 90 Trinity Place (roof level) | 11/2/2005 | 1884.1 | details | ocpp | STL-SAC | 11/28/05 | < 1.5 | < 64.2 | < 0.64 | < 0.64 | < 6.4 | 22.7 | 9.6 | 6.4 | 5.1 | 7.9 | No | No | |
| METALS-ST12-11-112905 | QA20040007 | 110 Greenwich Street (roof level) | 11/2/2005 | 1841.6 | details | ocpp | STL-SAC | 11/28/05 | < 1.3 | < 65.2 | < 0.65 | < 0.65 | < 6.5 | 74.0 | 5.0 | 6.4 | 5.7 | 25.6 | No | No | |
| METALS-ST13-11-112905 | QA20040002 | Marriott Hotel, 5th Floor (roof level) | 11/2/2005 | 1809.9 | details | ocpp | STL-SAC | 11/28/05 | < 1.3 | < 65.9 | < 0.65 | < 0.65 | < 6.5 | 56.4 | 5.6 | 5.6 | 7.0 | 16.0 | No | No | |
| METALS-ST14-11-112905 | QA20040009 | West Face - South end at corner (scaf/sidg lev-s) | 11/2/2005 | 1989.4 | details | ocpp | STL-SAC | 11/28/05 | 5.2 | < 60.3 | < 0.60 | < 0.60 | < 6.0 | 25.3 | 5.5 | 5.0 | 6.8 | 25.0 | No | No | |
| METALS-ST15-11-112905 | QA20040010 | South Face - East end at corner (scaf/sidg lev-s) | 11/2/2005 | 1977.7 | details | ocpp | STL-SAC | 11/28/05 | 5.9 | < 63.5 | < 0.63 | < 0.63 | < 6.3 | 29.2 | 5.6 | 5.6 | 7.0 | 35.1 | No | No | |
| METALS-ST16-11-112905 | QA20040401 | East Face - North end at corner (scaf/sidg lev-s) | 11/2/2005 | 1983.3 | details | ocpp | STL-SAC | 11/28/05 | 5.0 | < 62.1 | < 0.62 | < 0.62 | < 6.2 | 21.3 | 5.9 | 5.6 | 5.8 | 33.6 | No | No | |
| METALS-ST17-11-112905 | QA20040402 | North Face - West end at corner (scaf/sidg lev-s) | 11/2/2005 | 1956.8 | details | ocpp | STL-SAC | 11/28/05 | 5.4 | < 65.3 | < 0.65 | 0.97 | < 6.5 | 58.9 | 10 | 6.0 | 6.3 | 134 | No | No | |
| METALS-ST-11-112905 | QA20040000 | Southwest Area (sidewalk bridge level) | 11/2/2005 | 777.9 | details | ocpp | STL-SAC | 11/28/05 | < 3.1 | < 154 | < 1.5 | < 1.5 | < 15.4 | 112 | 16.1 | 11.7 | 11.4 | 62.5 | No | No | |
| METALS-ST2-11-112905 | QA20040003 | Southeast Area (sidewalk bridge level) | 11/2/2005 | 751.4 | details | ocpp | STL-SAC | 11/28/05 | < 3.4 | < 169 | < 1.7 | < 1.7 | < 16.9 | 121 | 19.0 | 16.1 | 11.2 | 44.9 | No | No | |
| METALS-ST4-11-112905 | QA20040005 | Northwest Area (street-level) | 11/2/2005 | 780 | details | ocpp | STL-SAC | 11/28/05 | < 3.2 | < 160 | < 1.6 | < 1.6 | < 16.0 | 100 | 19.5 | 19.5 | 15.4 | 49.3 | No | No | |
| METALS-ST-11-112905 | QA20040004 | Firehouse #10 (roof level) | 11/2/2005 | 912.5 | details | ocpp | STL-SAC | 11/28/05 | < 3.0 | < 146 | < 1.5 | < 1.5 | < 14.6 | 77.7 | 7.3 | 7.3 | 7.3 | 34.7 | No | No | |
| METALS-ST10-11-112905 | QA20040010 | North Side Sidewalk Bags | 11/2/2005 | 803.7 | details | ocpp | STL-SAC | 11/28/05 | < 3.0 | < 150 | < 1.5 | < 1.5 | < 15.0 | 52.1 | 7.5 | 10 | 13.4 | 45.4 | No | No | |
| METALS-ST1-11-112905 | QA20040006 | 90 Trinity Place (roof level) | 11/2/2005 | 1798.3 | details | ocpp | STL-SAC | 11/28/05 | 7.2 | < 66.6 | < 0.67 | < 0.67 | < 6.7 | 453 | 5.7 | 9.6 | 5.7 | 54.5 | No | No | |
| METALS-ST12-11-112905 | QA20040007 | 110 Greenwich Street (roof level) | 11/2/2005 | 1766.8 | details | ocpp | STL-SAC | 11/28/05 | 5.4 | < 66.0 | < 0.66 | < 0.66 | < 6.6 | 336 | 5.3 | 7.9 | 9.3 | 29.9 | No | No | |
| METALS-ST13-11-112905 | QA20040002 | Marriott Hotel, 5th Floor (roof level) | 11/2/2005 | 1894.2 | details | ocpp | STL-SAC | 11/28/05 | < 1.5 | < 75.7 | < 0.76 | < 0.76 | < 7.6 | 31.8 | 7.6 | 7.6 | 14.0 | 27.3 | No | No | |
| METALS-ST14-11-112905 | QA20040009 | West Face - South end at corner (scaf/sidg lev-s) | 11/2/2005 | 723.7 | details | ocpp | STL-SAC | 11/28/05 | < 3.3 | < 166 | < 1.7 | < 1.7 | < 16.6 | 30.0 | 5.4 | < 8.3 | 12.5 | < 39.3 | No | No | |
| METALS-ST15-11-112905 | QA20040010 | South Face - East end at corner (scaf/sidg lev-s) | 11/2/2005 | 791.5 | details | ocpp | STL-SAC | 11/28/05 | < 3.1 | < 154 | < 1.5 | < 1.5 | < 15.4 | 109 | 11.6 | 9.1 | 8.0 | 52.0 | No | No | |
| METALS-ST16-11-112905 | QA20040401 | East Face - North end at corner (scaf/sidg lev-s) | 11/2/2005 | 787 | details | ocpp | STL-SAC | 11/28/05 | < 3.1 | < 156 | < 1.5 | < 1.5 | < 15.6 | 261 | 7.0 | 15.6 | 12.4 | 56.4 | No | No | |
| METALS-ST17-11-112905 | QA20040402 | North Face - West end at corner (scaf/sidg lev-s) | 11/2/2005 | 689.2 | details | ocpp | STL-SAC | 11/28/05 | < 3.5 | < 174 | < 1.7 | < 1.7 | < 17.4 | 72.2 | 8.7 | 9.1 | 7.9 | 197 | No | No | |
| METALS-ST-11-112905 | QA20040000 | Southwest Area (sidewalk bridge level) | 11/2/2005 | 1651.7 | details | ocpp | STL-SAC | 11/28/05 | 2.8 | < 71.4 | < 0.71 | < 0.71 | < 7.1 | 69.0 | 5.9 | 8.6 | 10 | 58.9 | No | No | |
| METALS-ST2-11-112905 | QA20040003 | Southeast Area (sidewalk bridge level) | 11/2/2005 | 1632 | details | ocpp | STL-SAC | 11/28/05 | 3.4 | < 74.0 | < 0.74 | < 0.74 | < 7.4 | 1150 | 8.0 | 10.0 | 10.0 | 52.7 | No | No | |
| METALS-ST4-11-112905 | QA20040005 | Northwest Area (street-level) | 11/2/2005 | 1602 | details | ocpp | STL-SAC | 11/28/05 | 1.6 | < 74.9 | < 0.75 | < 0.75 | < 7.5 | 98.1 | 6.0 | 6.7 | 10.0 | 36.6 | No | No | |
| METALS-ST-11-112905 | QA20040004 | Firehouse #10 (roof level) | 11/2/2005 | 1767.8 | details | ocpp | STL-SAC | 11/28/05 | 2.1 | < 67.9 | < 0.68 | < 0.68 | < 6.8 | 130 | 5.7 | 13.4 | 13.1 | 50.1 | No | No | |
| METALS-ST10-11-112905 | QA20040010 | North Side Sidewalk Bags | 11/2/2005 | 1774.3 | details | ocpp | STL-SAC | 11/28/05 | 2.1 | < 69.5 | < 0.70 | < 0.70 | < 7.0 | 37.1 | 7.0 | 10.1 | 7.0 | 57.3 | No | No | |
| METALS-ST1-11-112905 | QA20040006 | 90 Trinity Place (roof level) | 11/2/2005 | 1791.5 | details | ocpp | STL-SAC | 11/28/05 | 1.6 | < 66.1 | < 0.66 | < 0.66 | < 6.6 | 49.0 | 5.7 | 9.5 | 10.0 | 29.5 | No | No | |
| METALS-ST12-11-112905 | QA20040007 | 110 Greenwich Street (roof level) | 11/2/2005 | 1749.4 | details | ocpp | STL-SAC | 11/28/05 | 1.6 | < 74.3 | < 0.74 | < 0.74 | < 7.4 | 97.4 | 5.9 | 7.4 | 13.1 | 51.0 | No | No | |
| METALS-ST13-11-112905 | QA20040002 | Marriott Hotel, 5th Floor (roof level) | 11/2/2005 | 1879.5 | details | ocpp | STL-SAC | 11/28/05 | < 1.4 | < 71.4 | < 0.71 | < 0.71 | < 7.1 | 59.2 | 5.4 | 7.1 | 14.2 | 36.2 | No | No | |
| METALS-ST14-11-112905 | QA20040009 | West Face - South end at corner (scaf/sidg lev-s) | 11/2/2005 | 1949.8 | details | ocpp | STL-SAC | 11/28/05 | 1.7 | < 61.4 | < 0.61 | < 0.61 | < 6.1 | 30.4 | 6.0 | 6.7 | 11.8 | 27.6 | No | No | |
| METALS-ST15-11-112905 | QA20040010 | South Face - East end at corner (scaf/sidg lev-s) | 11/2/2005 | 1811.1 | details | ocpp | STL-SAC | 11/28/05 | 1.6 | < 66.2 | < 0.66 | < 0.66 | < 6.6 | 146 | 5.6 | 6.6 | 12.2 | 28.3 | No | No | |
| METALS-ST16-11-112905 | QA20040401 | East Face - North end at corner (scaf/sidg lev-s) | 11/2/2005 | 1861 | details | ocpp | STL-SAC | 11/28/05 | 1.0 | < 64.5 | < 0.64 | < 0.64 | < 6.4 | 24.5 | 5.6 | 10 | 12.5 | 30.8 | No | No | |
| METALS-ST17-11-112905 | QA20040402 | North Face - West end at corner (scaf/sidg lev-s) | 11/2/2005 | 1797 | details | ocpp | STL-SAC | 11/28/05 | 2.2 | < 66.8 | < 0.67 | < 0.67 | < 6.7 | 50.1 | 5.6 | 10 | 11.2 | 39.6 | No | No | |
| METALS-ST-11-112905 | QA20040000 | Southwest Area (sidewalk bridge level) | 11/2/2005 | 1636.1 | details | ocpp | STL-SAC | 11/28/05 | 2.0 | < 70.8 | < 0.71 | < 0.71 | < 7.1 | 326 | 11.5 | 8.0 | 10 | 54.0 | No | No | |
| METALS-ST2-11-112905 | QA20040003 | Southeast Area (sidewalk bridge level) | 11/2/2005 | 1630.7 | details | ocpp | STL-SAC | 11/28/05 | 0.7 | < 72.7 | < 0.73 | < 0.73 | < 7.3 | 1010 | 9.6 | 10 | 10.0 | 54.6 | No | No | |
| METALS-ST4-11-112905 | QA20040005 | Northwest Area (street-level) | 11/2/2005 | 1589.4 | details | ocpp | STL-SAC | 11/28/05 | 2.0 | < 74.7 | < 0.75 | < 0.75 | < 7.5 | 1.23 | 9.9 | 11.2 | 17.4 | 58.6 | No | No | |
| METALS-ST-11-112905 | QA20040004 | Firehouse #10 (roof level) | 11/2/2005 | 1756.3 | details | ocpp | STL-SAC | 11/28/05 | 3.5 | < 70.3 | < 0.70 | < 0.70 | < 7.0 | 31.4 | 9.0 | 7.9 | 9.0 | 36.6 | No | No | |
| METALS-ST10-11-112905 | QA20040010 | North Side Sidewalk Bags | 11/2/2005 | 1744.9 | details | ocpp | STL-SAC | 11/28/05 | 3.0 | < 68.2 | < 0.68 | < 0.68 | < 6.8 | 37.3 | 9.4 | 14.7 | 10.4 | 39.4 | No | No | |
| METALS-ST1-11-112905 | QA20040006 | 90 Trinity Place (roof level) | 11/2/2005 | 1852.8 | details | ocpp | STL-SAC | 11/28/05 | 3.1 | < 65.5 | < 0.66 | < 0.66 | < 6.5 | 8.7 | 9.6 | 7.8 | 16.4 | 37.6 | No | No | |
| METALS-ST12-11-112905 | QA20040007 | 110 Greenwich Street (roof level) | 11/2/2005 | 1776.4 | details | ocpp | STL-SAC | 11/28/05 | 3.3 | < 67.5 | < 0.67 | 0.86 | < 6.7 | 51.3 | 7.5 | 8.7 | 15.4 | 36.5 | No | No | |
| METALS-ST13-11-112905 | QA20040002 | Marriott Hotel, 5th Floor (roof level) | 11/2/2005 | 1894.2 | details | ocpp | STL-SAC | 11/28/05 | 3.2 | < 65.8 | < 0.66 | < 0.66 | < 6.6 | 41.7 | 13.2 | 16.2 | 17.2 | 47.1 | No | No | |
| METALS-ST14-11-112905 | QA20040009 | West Face - South end at corner (scaf/sidg lev-s) | 11/2/2005 | 1808 | details | ocpp | STL-SAC | 11/28/05 | 2.5 | < 66.4 | < 0.66 | < 0.66 | < 6.6 | 376 | 19.6 | 7.70 | 16.3 | 56.3 | No | No | |
| METALS-ST15-11-112905 | QA20040010 | South Face - East end at corner (scaf/sidg lev-s) | 11/2/2005 | 1834.1 | details | ocpp | STL-SAC | 11/28/05 | 2.0 | < 65.8 | < 0.66 | < 0.66 

NYC 9/11 Public Portal Document

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Sample Volume ($m^3$) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Mercury (Total) Concentration (ng/m3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Target Air Quality Levels | | | | | | | | | 350 | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | 3,700 | | | |
| Total Hg-ST1-11/18/05 | 05BR1761-1 | Southwest Area (sidewalk bridge level) | 11/18/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST2-11/18/05 | 05BR1761-2 | Southeast Area (sidewalk bridge level) | 11/18/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST4-11/18/05 | 05BR1761-3 | Northwest Area (street-level) | 11/18/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST5-11/18/05 | 05BR1761-4 | Firehouse #10 (roof level) | 11/18/05 | 0.53 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST10-11/16/05 | 05BR1761-5 | North Side Sidewalk Bridge | 11/18/05 | 0.59 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 25.0 | No | No | |
| Total Hg-ST11-11/16/05 | 05BR1761-6 | 90 Trinity Place (roof level) | 11/18/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST12-11/16/05 | 05BR1761-7 | 110 Greenwich Street (roof level) | 11/18/05 | 0.54 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST13-11/16/05 | 05BR1761-8 | Marriott -Hotel, 38th Floor (roof level) | 11/18/05 | 0.55 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 27.0 | No | No | |
| Total Hg-ST14-11/16/05 | 05BR1761-9 | West Face - South end at corner (scaffolding level) | 11/18/05 | 0.59 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 25.0 | No | No | |
| Total Hg-ST15-11/16/05 | 05BR1761-10 | South Face - East end at corner (scaffolding level) | 11/18/05 | 0.59 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 25.0 | No | No | |
| Total Hg-ST16-11/16/05 | 05BR1761-11 | East Face - North end at corner (scaffolding level) | 11/18/05 | 0.60 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 25.0 | No | No | |
| Total Hg-ST17-11/16/05 | 05BR1761-12 | North Face - West end at corner (scaffolding level) | 11/18/05 | 0.59 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 25.0 | No | No | |
| Total Hg-ST1-11/19/05 | 05BR1762-1 | Southwest Area (sidewalk bridge level) | 11/19/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST2-11/19/05 | 05BR1762-2 | Southeast Area (sidewalk bridge level) | 11/19/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST4-11/19/05 | 05BR1762-3 | Northwest Area (street-level) | 11/19/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST5-11/19/05 | 05DU1762-4 | Firehouse #10 (roof level) | 11/19/05 | 0.57 | Mercury | EPA 324/1631 | DRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST10-11/16/05 | 05BR1762-5 | North Side Sidewalk Bridge | 11/19/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST11-11/15/05 | 05BR1762-6 | 90 Trinity Place (roof level) | 11/19/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST12-11/19/05 | 05BR1762-7 | 110 Greenwich Street (roof level) | 11/19/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST13-11/15/05 | 05BR1762-8 | Marriott -Hotel, 38th Floor (roof level) | 11/19/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST14-11/15/05 | 05BR1762-9 | West Face - South end at corner (scaffolding level) | 11/19/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST15-11/15/05 | 05BR1762-10 | South Face - East end at corner (scaffolding level) | 11/19/05 | 0.59 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST16-11/15/05 | 05DU1762-11 | East Face - North end at corner (scaffolding level) | 11/19/05 | 0.59 | Mercury | EPA 324/1631 | DRL | 1/22/05 | < 25.0 | No | No | |
| Total Hg-ST17-11/15/05 | 05BR1762-12 | North Face - West end at corner (scaffolding level) | 11/19/05 | 0.59 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 25.0 | No | No | |
| Total Hg-ST1-11/20/05 | 05BR1763-1 | Southwest Area (sidewalk bridge level) | 11/20/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST2-11/20/05 | 05BR1763-2 | Southeast Area (sidewalk bridge level) | 11/20/05 | 0.55 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 27.0 | No | No | |
| Total Hg-ST4-11/20/05 | 05BR1763-3 | Northwest Area (street-level) | 11/20/05 | 0.56 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 27.0 | No | No | |
| Total Hg-ST5-11/20/05 | 05BR1763-4 | Firehouse #10 (roof level) | 11/20/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST10-11/20/05 | 05BR1763-5 | North Side Sidewalk Bridge | 11/20/05 | 0.56 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 27.0 | No | No | |
| Total Hg-ST11-11/20/05 | 05DU1763-6 | 90 Trinity Place (roof level) | 11/20/05 | 0.56 | Mercury | EPA 324/1631 | DRL | 1/22/05 | < 27.0 | No | No | |
| Total Hg-ST13-11/20/05 | 05BR1763-7 | Marriott -Hotel, 38th Floor (roof level) | 11/20/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 26.0 | No | No | |
| Total Hg-ST14-11/20/05 | 05BR1763-8 | West Face - South end at corner (scaffolding level) | 11/20/05 | 0.53 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 28.0 | No | No | |
| Total Hg-ST15-11/20/05 | 05BR1763-9 | South Face - East end at corner (scaffolding level) | 11/20/05 | 0.56 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 27.0 | No | No | |
| Total Hg-ST16-11/20/05 | 05BR1763-10 | East Face - North end at corner (scaffolding level) | 11/20/05 | 0.55 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 27.0 | No | No | |
| Total Hg-ST17-11/20/05 | 05BR1763-11 | North Face - West end at corner (scaffolding level) | 11/20/05 | 0.53 | Mercury | EPA 324/1631 | BRL | 1/22/05 | < 28.0 | No | No | |
| Total Hg-ST1-11/21/05 | 05BR1764-1 | Southwest Area (sidewalk bridge level) | 11/21/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/23/05 | < 26.0 | No | No | |
| Total Hg-ST2-11/21/05 | 05BR1764-2 | Southeast Area (sidewalk bridge level) | 11/21/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/23/05 | < 26.0 | No | No | |
| Total Hg-ST4-11/21/05 | 05BR1764-3 | Northwest Area (street-level) | 11/21/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/23/05 | < 26.0 | No | No | |
| Total Hg-ST5-11/21/05 | 05BR1764-4 | Firehouse #10 (roof level) | 11/21/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/23/05 | < 26.0 | No | No | |
| Total Hg-ST10-11/21/05 | 05BR1764-5 | North Side Sidewalk Bridge | 11/21/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/23/05 | < 26.0 | No | No | |
| Total Hg-ST11-11/21/05 | 05BR1764-6 | 90 Trinity Place (roof level) | 11/21/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/23/05 | < 26.0 | No | No | |
| Total Hg-ST12-11/21/05 | 05BR1764-7 | 110 Greenwich Street (roof level) | 11/21/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/23/05 | < 26.0 | No | No | |
| Total Hg-ST13-11/21/05 | 05BR1764-8 | Marriott -Hotel, 38th Floor (roof level) | 11/21/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/23/05 | < 26.0 | No | No | |
| Total Hg-ST14-11/21/05 | 05BR1764-9 | West Face - South end at corner (scaffolding level) | 11/21/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/23/05 | < 26.0 | No | No | |
| Total Hg-ST15-11/21/05 | 05BR1764-10 | South Face - East end at corner (scaffolding level) | 11/21/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/23/05 | < 26.0 | No | No | |
| Total Hg-ST16-11/21/05 | 05BR1764-11 | East Face - North end at corner (scaffolding level) | 11/21/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/23/05 | < 26.0 | No | No | |
| Total Hg-ST17-11/21/05 | 05BR1764-12 | North Face - West end at corner (scaffolding level) | 11/21/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/23/05 | < 26.0 | No | No | |
| Total Hg-ST1-11/22/05 | 05BR1773-1 | Southwest Area (sidewalk bridge level) | 11/22/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 26.0 | No | No | |
| Total Hg-ST2-11/22/05 | 05BR1773-2 | Southeast Area (sidewalk bridge level) | 11/22/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 26.0 | No | No | |
| Total Hg-ST4-11/22/05 | 05BR1773-3 | Northwest Area (street-level) | 11/22/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 26.0 | No | No | |
| Total Hg-ST5-11/22/05 | 05BR1773-4 | Firehouse #10 (roof level) | 11/22/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 26.0 | No | No | |
| Total Hg-ST10-11/22/05 | 05BR1773-5 | North Side Sidewalk Bridge | 11/22/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 26.0 | No | No | |
| Total Hg-ST11-11/22/05 | 05BR1773-6 | 90 Trinity Place (roof level) | 11/22/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 26.0 | No | No | |
| Total Hg-ST12-11/22/05 | 05BR1773-7 | 110 Greenwich Street (roof level) | 11/22/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 26.0 | No | No | |
| Total Hg-ST13-11/22/05 | 05BR1773-8 | Marriott -Hotel, 38th Floor (roof level) | 11/22/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 26.0 | No | No | |
| Total Hg-ST14-11/22/05 | 05BR1773-9 | West Face - South end at corner (scaffolding level) | 11/22/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 26.0 | No | No | |
| Total Hg-ST15-11/22/05 | 05BR1773-10 | South Face - East end at corner (scaffolding level) | 11/22/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 26.0 | No | No | |
| Total Hg-ST16-11/22/05 | 05BR1773-11 | East Face - North end at corner (scaffolding level) | 11/22/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 26.0 | No | No | |
| Total Hg-ST17-11/22/05 | 05BR1773-12 | North Face - West end at corner (scaffolding level) | 11/22/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 26.0 | No | No | |
| Total Hg-ST1-11/23/05 | 05BR1774-1 | Southwest Area (sidewalk bridge level) | 11/23/05 | 0.55 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 27.0 | No | No | |
| Total Hg-ST2-11/23/05 | 05BR1774-2 | Southeast Area (sidewalk bridge level) | 11/23/05 | 0.56 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 27.0 | No | No | |
| Total Hg-ST4-11/23/05 | 05BR1774-3 | Northwest Area (street-level) | 11/23/05 | 0.56 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 26.0 | No | No | |
| Total Hg-ST5-11/23/05 | 05BR1774-4 | Firehouse #10 (roof level) | 11/23/05 | 0.57 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 27.0 | No | No | |
| Total Hg-ST10-11/23/05 | 05DU1774-5 | North Side Sidewalk Bridge | 11/23/05 | 0.56 | Mercury | EPA 324/1631 | DRL | 1/26/05 | < 27.0 | No | No | |
| Total Hg-ST11-11/23/05 | 05BR1774-6 | 90 Trinity Place (roof level) | 11/23/05 | 0.56 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 27.0 | No | No | |
| Total Hg-ST12-11/23/05 | 05BR1774-7 | 110 Greenwich Street (roof level) | 11/23/05 | 0.56 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 27.0 | No | No | |
| Total Hg-ST13-11/23/05 | 05BR1774-8 | Marriott -Hotel, 38th Floor (roof level) | 11/23/05 | 0.55 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 27.0 | No | No | |
| Total Hg-ST14-11/23/05 | 05BR1774-9 | West Face - South end at corner (scaffolding level) | 11/23/05 | 0.60 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 25.0 | No | No | |
| Total Hg-ST15-11/23/05 | 05BR1774-10 | South Face - East end at corner (scaffolding level) | 11/23/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 26.0 | No | No | |
| Total Hg-ST16-11/23/05 | 05BR1774-11 | East Face - North end at corner (scaffolding level) | 11/23/05 | 0.58 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 26.0 | No | No | |
| Total Hg-ST17-11/23/05 | 05DU1774-12 | North Face - West end at corner (scaffolding level) | 11/23/05 | 0.59 | Mercury | EPA 324/1631 | DRL | 1/26/05 | < 25.0 | No | No | |
| Total Hg-ST1-11/24/05 | 05BR1775-1 | Southwest Area (sidewalk bridge level) | 11/24/05 | 0.59 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 25.0 | No | No | |
| Total Hg-ST2-11/24/05 | 05BR1775-2 | Southeast Area (sidewalk bridge level) | 11/24/05 | 0.59 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 25.0 | No | No | |
| Total Hg-ST4-11/24/05 | 05BR1775-3 | Northwest Area (street-level) | 11/24/05 | 0.59 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 25.0 | No | No | |
| Total Hg-ST5-11/24/05 | 05BR1775-4 | Firehouse #10 (roof level) | 11/24/05 | 0.66 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 23.0 | No | No | |
| Total Hg-ST10-11/24/05 | 05BR1775-5 | North Side Sidewalk Bridge | 11/24/05 | 0.59 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 25.0 | No | No | |
| Total Hg-ST11-11/24/05 | 05BR1775-6 | 90 Trinity Place (roof level) | 11/24/05 | 0.60 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 25.0 | No | No | |
| Total Hg-ST12-11/24/05 | 05DU1775-7 | 110 Greenwich Street (roof level) | 11/24/05 | 0.60 | Mercury | EPA 324/1631 | DRL | 1/26/05 | < 25.0 | No | No | |
| Total Hg-ST14-11/24/05 | 05BR1775-8 | West Face - South end at corner (scaffolding level) | 11/24/05 | 0.61 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 25.0 | No | No | |
| Total Hg-ST15-11/24/05 | 05BR1775-10 | South Face - East end at corner (scaffolding level) | 11/24/05 | 0.60 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 25.0 | No | No | |
| Total Hg-ST16-11/24/05 | 05BR1775-11 | East Face - North end at corner (scaffolding level) | 11/24/05 | 0.61 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 25.0 | No | No | |
| Total Hg-ST17-11/24/05 | 05BR1775-12 | North Face - West end at corner (scaffolding level) | 11/24/05 | 0.61 | Mercury | EPA 324/1631 | BRL | 1/26/05 | < 25.0 | No | No | |

Notes:
1. Mercury sample at Station 12 on November 20, 2005 was not available for analysis or account of pump failure.
2. Mercury sample at Station 13 (Marriott Hotel, 38th Floor (roof level)) was deemed invalid on November 24, 2005 due to power interruption caused by utility and therefore was not submitted for analysis.



CITY_DEP_WORBY_CANNATA_SUBP_000076953

NYC-WTC_000424923

NYC 9/11 Public Portal Document

| TRZ Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Sample Volume (m³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Respirable Silica Concentration (µg/m3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Target Air Quality Levels | | | | | | 50 | | | |
| | | | EPA Site Specific Trigger Levels | | | | | | 100 | | | |
| SILICA-ST2-11/21/05 | 040322221-0003 | Southeast Area (sidewalk bridge level) | 11/21/05 | 2.93 | Silica | NIOSH 7500 XRD | EMSL | 11/22/05 | <3 | No | No | |
| SILICA-ST4-11/21/05 | 040322221-0005 | Northwest Area (street-level) | 11/21/05 | 2.91 | Silica | NIOSH 7500 XRD | EMSL | 11/22/05 | <2 | No | No | |
| SILICA-ST5-11/21/05 | 040322221-0004 | Firehouse #10 (roof level) | 11/21/05 | 2.88 | Silica | NIOSH 7500 XRD | EMSL | 11/22/05 | <3 | No | No | |
| SILICA-ST10-11/21/05 | 040322221-0005 | North Side Sidewalk Bridge | 11/21/05 | 2.91 | Silica | NIOSH 7500 XRD | EMSL | 11/22/05 | <2 | No | No | |
| SILICA-ST11-11/21/05 | 040322221-0006 | 90 Trinity Place (roof level) | 11/21/05 | 2.88 | Silica | NIOSH 7500 XRD | EMSL | 11/22/05 | <2 | No | No | |
| SILICA-ST12-11/21/05 | 040322221-0007 | 110 Greenwich Street (roof level) | 11/21/05 | 2.88 | Silica | NIOSH 7500 XRD | EMSL | 11/22/05 | <2 | No | No | |
| SILICA-ST13-11/21/05 | 040322221-0008 | Marriott Hotel, 38th Floor (roof level) | 11/21/05 | 2.97 | Silica | NIOSH 7500 XRD | EMSL | 11/22/05 | <2 | No | No | |
| SILICA-ST14-11/21/05 | 040322221-0009 | West Face - South end at corner (scaffolding level) | 11/21/05 | 2.88 | Silica | NIOSH 7500 XRD | EMSL | 11/22/05 | <2 | No | No | |
| SILICA-ST15-11/21/05 | 040322221-0010 | South Face - East end at corner (scaffolding level) | 11/21/05 | 2.9 | Silica | NIOSH 7500 XRD | EMSL | 11/22/05 | <2 | No | No | |
| SILICA-ST16-11/21/05 | 040322221-0011 | East Face - North end at corner (scaffolding level) | 11/21/05 | 2.99 | Silica | NIOSH 7500 XRD | EMSL | 11/22/05 | <2 | No | No | |
| SILICA-ST17-11/21/05 | 040322221-0012 | North Face - West end at corner (scaffolding level) | 11/21/05 | 2.97 | Silica | NIOSH 7500 XRD | EMSL | 11/22/05 | <2 | No | No | |
| SILICA-ST1-11/22/05 | 040322396-0001 | Southwest Area (sidewalk bridge level) | 11/22/05 | 2.88 | Silica | NIOSH 7500 XRD | EMSL | 11/23/05 | <2 | No | No | |
| SILICA-ST2-11/22/05 | 040322396-0002 | Southeast Area (sidewalk bridge level) | 11/22/05 | 2.88 | Silica | NIOSH 7500 XRD | EMSL | 11/23/05 | <2 | No | No | |
| SILICA-ST4-11/22/05 | 040322396-0003 | Northwest Area (street-level) | 11/22/05 | 2.85 | Silica | NIOSH 7500 XRD | EMSL | 11/23/05 | <2 | No | No | |
| SILICA-ST5-11/22/05 | 040322396-0004 | Firehouse #10 (roof level) | 11/22/05 | 2.87 | Silica | NIOSH 7500 XRD | EMSL | 11/23/05 | <2 | No | No | |
| SILICA-ST10-11/22/05 | 040322396-0005 | North Side Sidewalk Bridge | 11/22/05 | 2.88 | Silica | NIOSH 7500 XRD | EMSL | 11/23/05 | <2 | No | No | |
| SILICA-ST11-11/22/05 | 040322396-0006 | 90 Trinity Place (roof level) | 11/22/05 | 2.88 | Silica | NIOSH 7500 XRD | EMSL | 11/23/05 | <2 | No | No | |
| SILICA-ST12-11/22/05 | 040322396-0007 | 110 Greenwich Street (roof level) | 11/22/05 | 2.87 | Silica | NIOSH 7500 XRD | EMSL | 11/23/05 | <2 | No | No | |
| SILICA-ST14-11/22/05 | 040322396-0008 | West Face - South end at corner (scaffolding level) | 11/22/05 | 2.88 | Silica | NIOSH 7500 XRD | EMSL | 11/23/05 | <2 | No | No | |
| SILICA-ST15-11/22/05 | 040322396-0009 | South Face - East end at corner (scaffolding level) | 11/22/05 | 2.84 | Silica | NIOSH 7500 XRD | EMSL | 11/23/05 | <2 | No | No | |
| SILICA-ST16-11/22/05 | 040322396-0010 | East Face - North end at corner (scaffolding level) | 11/22/05 | 2.85 | Silica | NIOSH 7500 XRD | EMSL | 11/23/05 | <2 | No | No | |
| SILICA-ST17-11/22/05 | 040322396-0011 | North Face - West end at corner (scaffolding level) | 11/22/05 | 2.89 | Silica | NIOSH 7500 XRD | EMSL | 11/23/05 | <2 | No | No | |
| SILICA-ST1-11/23/05 | 040322425-0001 | Southwest Area (sidewalk bridge level) | 11/23/05 | 2.79 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST2-11/23/05 | 040322425-0002 | Southeast Area (sidewalk bridge level) | 11/23/05 | 2.88 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST4-11/23/05 | 040322425-0003 | Northwest Area (street-level) | 11/23/05 | 2.82 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST5-11/23/05 | 040322425-0004 | Firehouse #10 (roof level) | 11/23/05 | 2.87 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | 2 | No | No | |
| SILICA-ST10-11/23/05 | 040322425-0005 | North Side Sidewalk Bridge | 11/23/05 | 2.82 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST11-11/23/05 | 040322425-0006 | 90 Trinity Place (roof level) | 11/23/05 | 2.82 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST12-11/23/05 | 040322425-0007 | 110 Greenwich Street (roof level) | 11/23/05 | 2.82 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST13-11/23/05 | 040322425-0008 | Marriott Hotel, 38th Floor (roof level) | 11/23/05 | 2.77 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST14-11/23/05 | 040322425-0009 | West Face - South end at corner (scaffolding level) | 11/23/05 | 2.99 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <3 | No | No | |
| SILICA-ST15-11/23/05 | 040322425-0010 | South Face - East end at corner (scaffolding level) | 11/23/05 | 2.88 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST16-11/23/05 | 040322425-0011 | East Face - North end at corner (scaffolding level) | 11/23/05 | 2.92 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST17-11/23/05 | 040322425-0012 | North Face - West end at corner (scaffolding level) | 11/23/05 | 2.97 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST1-11/24/05 | 040322396-0001 | Southwest Area (sidewalk bridge level) | 11/24/05 | 2.96 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST2-11/24/05 | 040322396-0002 | Southeast Area (sidewalk bridge level) | 11/24/05 | 2.96 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST4-11/24/05 | 040322396-0003 | Northwest Area (street-level) | 11/24/05 | 2.95 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST5-11/24/05 | 040322396-0004 | Firehouse #10 (roof level) | 11/24/05 | 3.02 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST10-11/24/05 | 040322396-0005 | North Side Sidewalk Bridge | 11/24/05 | 2.97 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST11-11/24/05 | 040322396-0006 | 90 Trinity Place (roof level) | 11/24/05 | 2.96 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST12-11/24/05 | 040322396-0007 | 110 Greenwich Street (roof level) | 11/24/05 | 2.99 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST14-11/24/05 | 040322396-0008 | West Face - South end at corner (scaffolding level) | 11/24/05 | 3.04 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST15-11/24/05 | 040322396-0009 | South Face - East end at corner (scaffolding level) | 11/24/05 | 3.02 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST16-11/24/05 | 040322396-0010 | East Face - North end at corner (scaffolding level) | 11/24/05 | 3.05 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST17-11/24/05 | 040322396-0011 | North Face - West end at corner (scaffolding level) | 11/24/05 | 3.04 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | 2 | No | No | |
| SILICA-ST1-11/25/05 | 040322395-0001 | Southwest Area (sidewalk bridge level) | 11/25/05 | 1.65 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <3 | No | No | |
| SILICA-ST2-11/25/05 | 040322395-0002 | Southeast Area (sidewalk bridge level) | 11/25/05 | 1.67 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <3 | No | No | |
| SILICA-ST4-11/25/05 | 040322395-0003 | Northwest Area (street-level) | 11/25/05 | 1.65 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <3 | No | No | |
| SILICA-ST5-11/25/05 | 040322395-0004 | Firehouse #10 (roof level) | 11/25/05 | 1.22 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <4 | No | No | |
| SILICA-ST10-11/25/05 | 040322395-0005 | North Side Sidewalk Bridge | 11/25/05 | 1.64 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <3 | No | No | |
| SILICA-ST11-11/25/05 | 040322395-0006 | 90 Trinity Place (roof level) | 11/25/05 | 3.38 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST12-11/25/05 | 040322395-0007 | 110 Greenwich Street (roof level) | 11/25/05 | 2.89 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST13-11/25/05 | 040322395-0008 | Marriott Hotel, 38th Floor (roof level) | 11/25/05 | 2.99 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <2 | No | No | |
| SILICA-ST14-11/25/05 | 040322395-0009 | West Face - South end at corner (scaffolding level) | 11/25/05 | 1.38 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <4 | No | No | |
| SILICA-ST15-11/25/05 | 040322395-0010 | South Face - East end at corner (scaffolding level) | 11/25/05 | 1.66 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <3 | No | No | |
| SILICA-ST16-11/25/05 | 040322395-0011 | East Face - North end at corner (scaffolding level) | 11/25/05 | 1.49 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <3 | No | No | |
| SILICA-ST17-11/25/05 | 040322395-0012 | North Face - West end at corner (scaffolding level) | 11/25/05 | 1.45 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <3 | No | No | |
| SILICA-ST1-11/26/05 | 040322485-0001 | Southwest Area (sidewalk bridge level) | 11/26/05 | 3.53 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST2-11/26/05 | 040322485-0002 | Southeast Area (sidewalk bridge level) | 11/26/05 | 3.53 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST4-11/26/05 | 040322485-0003 | Northwest Area (street-level) | 11/26/05 | 3.69 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST5-11/26/05 | 040322485-0004 | Firehouse #10 (roof level) | 11/26/05 | 2.53 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | 2 | No | No | |
| SILICA-ST10-11/26/05 | 040322485-0005 | North Side Sidewalk Bridge | 11/26/05 | 3.52 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST11-11/26/05 | 040322485-0006 | 90 Trinity Place (roof level) | 11/26/05 | 3.54 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST12-11/26/05 | 040322485-0007 | 110 Greenwich Street (roof level) | 11/26/05 | 3.37 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST13-11/26/05 | 040322485-0008 | Marriott Hotel, 38th Floor (roof level) | 11/26/05 | 3.45 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST14-11/26/05 | 040322485-0009 | West Face - South end at corner (scaffolding level) | 11/26/05 | 3.77 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST15-11/26/05 | 040322485-0010 | South Face - East end at corner (scaffolding level) | 11/26/05 | 3.59 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST16-11/26/05 | 040322485-0011 | East Face - North end at corner (scaffolding level) | 11/26/05 | 3.61 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST17-11/26/05 | 040322485-0012 | North Face - West end at corner (scaffolding level) | 11/26/05 | 3.74 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST1-11/27/05 | 040322486-0001 | Southwest Area (sidewalk bridge level) | 11/27/05 | 3.97 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST2-11/27/05 | 040322486-0002 | Southeast Area (sidewalk bridge level) | 11/27/05 | 3.85 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST4-11/27/05 | 040322486-0003 | Northwest Area (street-level) | 11/27/05 | 3.64 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST5-11/27/05 | 040322486-0004 | Firehouse #10 (roof level) | 11/27/05 | 3.37 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST10-11/27/05 | 040322486-0005 | North Side Sidewalk Bridge | 11/27/05 | 3.51 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST11-11/27/05 | 040322486-0006 | 90 Trinity Place (roof level) | 11/27/05 | 3.72 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST12-11/27/05 | 040322486-0007 | 110 Greenwich Street (roof level) | 11/27/05 | 3.78 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST13-11/27/05 | 040322486-0008 | Marriott Hotel, 38th Floor (roof level) | 11/27/05 | 3.64 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST14-11/27/05 | 040322486-0009 | West Face - South end at corner (scaffolding level) | 11/27/05 | 3.83 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST15-11/27/05 | 040322486-0010 | South Face - East end at corner (scaffolding level) | 11/27/05 | 3.58 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST16-11/27/05 | 040322486-0011 | East Face - North end at corner (scaffolding level) | 11/27/05 | 3.67 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST17-11/27/05 | 040322486-0012 | North Face - West end at corner (scaffolding level) | 11/27/05 | 3.61 | Silica | NIOSH 7500 XRD | EMSL | 11/28/05 | <1 | No | No | |
| SILICA-ST1-11/28/05 | 040322537-0001 | Southwest Area (sidewalk bridge level) | 11/28/05 | 3.33 | Silica | NIOSH 7500 XRD | EMSL | 11/29/05 | <1 | No | No | |
| SILICA-ST2-11/28/05 | 040322537-0002 | Southeast Area (sidewalk bridge level) | 11/28/05 | 3.48 | Silica | NIOSH 7500 XRD | EMSL | 11/29/05 | <1 | No | No | |
| SILICA-ST4-11/28/05 | 040322537-0003 | Northwest Area (street-level) | 11/28/05 | 3.52 | Silica | NIOSH 7500 XRD | EMSL | 11/29/05 | 1 | No | No | |
| SILICA-ST5-11/28/05 | 040322537-0004 | Firehouse #10 (roof level) | 11/28/05 | 3.67 | Silica | NIOSH 7500 XRD | EMSL | 11/29/05 | <1 | No | No | |
| SILICA-ST10-11/28/05 | 040322537-0005 | North Side Sidewalk Bridge | 11/28/05 | 3.64 | Silica | NIOSH 7500 XRD | EMSL | 11/29/05 | <6 | No | No | |
| SILICA-ST105-11/28/05 | 040322537-0013 | Studio 10 Pier Duplicate | 11/28/05 | 3.61 | Silica | NIOSH 7500 XRD | EMSL | 11/29/05 | <1 | No | No | |
| SILICA-ST11-11/28/05 | 040322537-0006 | 90 Trinity Place (roof level) | 11/28/05 | 3.8 | Silica | NIOSH 7500 XRD | EMSL | 11/29/05 | <1 | No | No | |
| SILICA-ST12-11/28/05 | 040322537-0007 | 110 Greenwich Street (roof level) | 11/28/05 | 3.78 | Silica | NIOSH 7500 XRD | EMSL | 11/29/05 | <6 | No | No | |
| SILICA-ST13-11/28/05 | 040322537-0008 | Marriott Hotel, 38th Floor (roof level) | 11/28/05 | 3.68 | Silica | NIOSH 7500 XRD | EMSL | 11/29/05 | <1 | No | No | |
| SILICA-ST14-11/28/05 | 040322537-0009 | West Face - South end at corner (scaffolding level) | 11/28/05 | 3.56 | Silica | NIOSH 7500 XRD | EMSL | 11/29/05 | <1 | No | No | |
| SILICA-ST15-11/28/05 | 040322537-0010 | South Face - East end at corner (scaffolding level) | 11/28/05 | 3.59 | Silica | NIOSH 7500 XRD | EMSL | 11/29/05 | <1 | No | No | |
| SILICA-ST16-11/28/05 | 040322537-0011 | East Face - North end at corner (scaffolding level) | 11/28/05 | 3.78 | Silica | NIOSH 7500 XRD | EMSL | 11/29/05 | <1 | No | No | |
| SILICA-ST17-11/28/05 | 040322537-0012 | North Face - West end at corner (scaffolding level) | 11/28/05 | 3.83 | Silica | NIOSH 7500 XRD | EMSL | 11/29/05 | <1 | No | No | |
| SILICA-ST1-11/29/05 | 040322646-0001 | Southwest Area (sidewalk bridge level) | 11/29/05 | 3.57 | Silica | NIOSH 7500 XRD | EMSL | 11/30/05 | <1 | No | No | |
| SILICA-ST2-11/29/05 | 040322646-0002 | Southeast Area (sidewalk bridge level) | 11/29/05 | 3.51 | Silica | NIOSH 7500 XRD | EMSL | 11/30/05 | <1 | No | No | |
| SILICA-ST4-11/29/05 | 040322646-0003 | Northwest Area (street-level) | 11/29/05 | 3.77 | Silica | NIOSH 7500 XRD | EMSL | 11/30/05 | <5 | No | No | |
| SILICA-ST5-11/29/05 | 040322646-0004 | Firehouse #10 (roof level) | 11/29/05 | 3.65 | Silica | NIOSH 7500 XRD | EMSL | 11/30/05 | <1 | No | No | |
| SILICA-ST10-11/29/05 | 040322646-0005 | North Side Sidewalk Bridge | 11/29/05 | 3.52 | Silica | NIOSH 7500 XRD | EMSL | 11/30/05 | <1 | No | No | |
| SILICA-ST11-11/29/05 | 040322646-0006 | 90 Trinity Place (roof level) | 11/29/05 | 3.61 | Silica | NIOSH 7500 XRD | EMSL | 11/30/05 | <1 | No | No | |
| SILICA-ST12-11/29/05 | 040322646-0007 | 110 Greenwich Street (roof level) | 11/29/05 | 3.59 | Silica | NIOSH 7500 XRD | EMSL | 11/30/05 | <1 | No | No | |
| SILICA-ST13-11/29/05 | 040322646-0008 | Marriott Hotel, 38th Floor (roof level) | 11/29/05 | 3.76 | Silica | NIOSH 7500 XRD | EMSL | 11/30/05 | <1 | No | No | |
| SILICA-ST14-11/29/05 | 040322646-0009 | West Face - South end at corner (scaffolding level) | 11/29/05 | 3.61 | Silica | NIOSH 7500 XRD | EMSL | 11/30/05 | <1 | No | No | |
| SILICA-ST15-11/29/05 | 040322646-0010 | South Face - East end at corner (scaffolding level) | 11/29/05 | 3.67 | Silica | NIOSH 7500 XRD | EMSL | 11/30/05 | <1 | No | No | |
| SILICA-ST16-11/29/05 | 040322646-0011 | East Face - North end at corner (scaffolding level) | 11/29/05 | 3.66 | Silica | NIOSH 7500 XRD | EMSL | 11/30/05 | <1 | No | No | |
| SILICA-ST17-11/29/05 | 040322646-0012 | North Face - West end at corner (scaffolding level) | 11/29/05 | 3.83 | Silica | NIOSH 7500 XRD | EMSL | 11/30/05 | <1 | No | No | |
| SILICA-ST2-11/30/05 | 040322715-0002 | Southeast Area (sidewalk bridge level) | 11/30/05 | 3.69 | Silica | NIOSH 7500 XRD | EMSL | 12/1/05 | <1 | No | No | |
| SILICA-ST4-11/30/05 | 040322715-0003 | Northwest Area (street-level) | 11/30/05 | 3.64 | Silica | NIOSH 7500 XRD | EMSL | 12/1/05 | 1 | No | No | |
| SILICA-ST5-11/30/05 | 040322715-0004 | Firehouse #10 (roof level) | 11/30/05 | 3.53 | Silica | NIOSH 7500 XRD | EMSL | 12/1/05 | <2 | No | No | |
| SILICA-ST10-11/30/05 | 040322715-0004 | North Side Sidewalk Bridge | 11/30/05 | 3.62 | Silica | NIOSH 7500 XRD | EMSL | 12/1/05 | <1 | No | No | |
| SILICA-ST11-11/30/05 | 040322715-0005 | 90 Trinity Place (roof level) | 11/30/05 | 3.48 | Silica | NIOSH 7500 XRD | EMSL | 12/1/05 | <1 | No | No | |
| SILICA-ST12-11/30/05 | 040322715-0006 | 110 Greenwich Street (roof level) | 11/30/05 | 3.51 | Silica | NIOSH 7500 XRD | EMSL | 12/1/05 | <2 | No | No | |
| SILICA-ST13-11/30/05 | 040322715-0007 | Marriott Hotel, 38th Floor (roof level) | 11/30/05 | 3.3 | Silica | NIOSH 7500 XRD | EMSL | 12/1/05 | <2 | No | No | |
| SILICA-ST14-11/30/05 | 040322715-0008 | West Face - South end at corner (scaffolding level) | 11/30/05 | 3.6 | Silica | NIOSH 7500 XRD | EMSL | 12/1/05 | <1 | No | No | |
| SILICA-ST15-11/30/05 | 040322715-0009 | South Face - East end at corner (scaffolding level) | 11/30/05 | 3.59 | Silica | NIOSH 7500 XRD | EMSL | 12/1/05 | <1 | No | No | |
| SILICA-ST16-11/30/05 | 040322715-0010 | East Face - North end at corner (scaffolding level) | 11/30/05 | 3.56 | Silica | NIOSH 7500 XRD | EMSL | 12/1/05 | <1 | No | No | |
| SILICA-ST17-11/30/05 | 040322715-0011 | North Face - West end at corner (scaffolding level) | 11/30/05 | 3.66 | Silica | NIOSH 7500 XRD | EMSL | 12/1/05 | <1 | No | No | |

Notes:
1. Sample at Station 13 (Marriott Hotel, 38th Floor (roof level)) was damaged due to heavy rains on November 22, 2005 and could not be analyzed.
2. Sample at Station 13 (Marriott Hotel, 38th Floor (roof level)) was received invalid on November 24, 2005 due to interruption of power caused by utility and therefore was not submitted for analysis.
3. Silica sample at Station 1 (Southwest Area [sidewalk bridge level]) on November 30, 2005 was not available for analysis on account of pump failure.



CITY_DEP_WORBY_CANNATA_SUBP_000076954

NYC-WTC_000424924

NYC 9/11 Public Portal Document

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume ($m^3$) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Target Air Quality Levels | | | | | | | | NA | | | |
| | | EPA Site Specific Trigger Levels | | | | | | | | 70 | | | |
| ASBESTOS-ST1-11/26/05 | 030535578-0001 | Southwest Area (sidewalk bridge level) | 11/26/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST2-11/26/05 | 030535578-0002 | Southeast Area (sidewalk bridge level) | 11/26/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST4-11/26/05 | 030535578-0003 | Northwest Area (street-level) | 11/26/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST5-11/26/05 | 030535578-0004 | Firehouse #10 (roof level) | 11/26/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST10-11/26/05 | 030535578-0005 | North Side Sidewalk Bridge | 11/26/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST11-11/26/05 | 030535578-0006 | 90 Trinity Place (roof level) | 11/26/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST12-11/26/05 | 030535578-0007 | 110 Greenwich Street (roof level) | 11/26/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST13-11/26/05 | 030535578-0008 | Marriott Hotel, 38th Floor (roof level) | 11/26/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST14-11/26/05 | 030535578-0009 | West Face - South end at corner (scaffolding level) | 11/26/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST15-11/26/05 | 030535578-0010 | South Face - East end at corner (scaffolding level) | 11/26/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST16-11/26/05 | 030535578-0011 | East Face - North end at corner (scaffolding level) | 11/26/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST17-11/26/05 | 030535578-0012 | North Face - West end at corner (scaffolding level) | 11/26/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST1-11/27/05 | 030535573-0001 | Southwest Area (sidewalk bridge level) | 11/27/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST2-11/27/05 | 030535573-0002 | Southeast Area (sidewalk bridge level) | 11/27/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST4-11/27/05 | 030535573-0003 | Northwest Area (street-level) | 11/27/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST5-11/27/05 | 030535573-0004 | Firehouse #10 (roof level) | 11/27/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST10-11/27/05 | 030535573-0005 | North Side Sidewalk Bridge | 11/27/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST11-11/27/05 | 030535573-0006 | 90 Trinity Place (roof level) | 11/27/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST12-11/27/05 | 030535573-0007 | 110 Greenwich Street (roof level) | 11/27/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST13-11/27/05 | 030535573-0008 | Marriott Hotel, 38th Floor (roof level) | 11/27/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST14-11/27/05 | 030535573-0009 | West Face - South end at corner (scaffolding level) | 11/27/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST15-11/27/05 | 030535573-0010 | South Face - East end at corner (scaffolding level) | 11/27/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST16-11/27/05 | 030535573-0011 | East Face - North end at corner (scaffolding level) | 11/27/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST17-11/27/05 | 030535573-0012 | North Face - West end at corner (scaffolding level) | 11/27/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/28/05 | < 13.00 | No | No | |
| ASBESTOS-ST1-11/28/05 | 030535664-0001 | Southwest Area (sidewalk bridge level) | 11/28/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/29/05 | < 13.00 | No | No | |
| ASBESTOS-ST2-11/28/05 | 030535664-0002 | Southeast Area (sidewalk bridge level) | 11/28/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/29/05 | < 13.00 | No | No | |
| ASBESTOS-ST4-11/28/05 | 030535664-0003 | Northwest Area (street-level) | 11/28/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/29/05 | < 13.00 | No | No | |
| ASBESTOS-ST5-11/28/05 | 030535664-0004 | Firehouse #10 (roof level) | 11/28/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/29/05 | < 13.00 | No | No | |
| ASBESTOS-ST10-11/28/05 | 030535664-0005 | North Side Sidewalk Bridge | 11/28/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/29/05 | < 13.00 | No | No | |
| ASBESTOS-ST100-11/28/05 | 030535664-0013 | Station 10 Field Duplicate | 11/28/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/29/05 | < 13.00 | No | No | |
| ASBESTOS-ST11-11/28/05 | 030535664-0006 | 90 Trinity Place (roof level) | 11/28/05 | 1 | 3.670 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/29/05 | < 13.00 | No | No | |
| ASBESTOS-ST12-11/28/05 | 030535664-0007 | 110 Greenwich Street (roof level) | 11/28/05 | 1 | 3.510 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/29/05 | < 13.00 | No | No | |
| ASBESTOS-ST13-11/28/05 | 030535664-0008 | Marriott Hotel, 38th Floor (roof level) | 11/28/05 | 1 | 3.590 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/29/05 | < 13.00 | No | No | |
| ASBESTOS-ST14-11/28/05 | 030535664-0009 | West Face - South end at corner (scaffolding level) | 11/28/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/29/05 | < 13.00 | No | No | |
| ASBESTOS-ST15-11/28/05 | 030535664-0010 | South Face - East end at corner (scaffolding level) | 11/28/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/29/05 | < 13.00 | No | No | |
| ASBESTOS-ST16-11/28/05 | 030535664-0011 | East Face - North end at corner (scaffolding level) | 11/28/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/29/05 | < 13.00 | No | No | |
| ASBESTOS-ST17-11/28/05 | 030535664-0012 | North Face - West end at corner (scaffolding level) | 11/28/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/29/05 | < 13.00 | No | No | |
| ASBESTOS-ST1-11/29/05 | 030535810-0001 | Southwest Area (sidewalk bridge level) | 11/29/05 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/30/05 | < 13.00 | No | No | |
| ASBESTOS-ST2-11/29/05 | 030535810-0002 | Southeast Area (sidewalk bridge level) | 11/29/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/30/05 | < 13.00 | No | No | |
| ASBESTOS-ST4-11/29/05 | 030535810-0003 | Northwest Area (street-level) | 11/29/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/30/05 | < 13.00 | No | No | |
| ASBESTOS-ST5-11/29/05 | 030535810-0004 | Firehouse #10 (roof level) | 11/29/05 | 1 | 2.780 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/30/05 | < 13.00 | No | No | |
| ASBESTOS-ST10-11/29/05 | 030535810-0005 | North Side Sidewalk Bridge | 11/29/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/30/05 | < 13.00 | No | No | |
| ASBESTOS-ST11-11/29/05 | 030535810-0006 | 90 Trinity Place (roof level) | 11/29/05 | 1 | 2.920 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/30/05 | < 13.00 | No | No | |
| ASBESTOS-ST12-11/29/05 | 030535810-0007 | 110 Greenwich Street (roof level) | 11/29/05 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/30/05 | < 13.00 | No | No | |
| ASBESTOS-ST13-11/29/05 | 030535810-0008 | Marriott Hotel, 38th Floor (roof level) | 11/29/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/30/05 | < 13.00 | No | No | |
| ASBESTOS-ST14-11/29/05 | 030535810-0009 | West Face - South end at corner (scaffolding level) | 11/29/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/30/05 | < 13.00 | No | No | |
| ASBESTOS-ST15-11/29/05 | 030535810-0010 | South Face - East end at corner (scaffolding level) | 11/29/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/30/05 | < 13.00 | No | No | |
| ASBESTOS-ST16-11/29/05 | 030535810-0011 | East Face - North end at corner (scaffolding level) | 11/29/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/30/05 | < 13.00 | No | No | |
| ASBESTOS-ST17-11/29/05 | 030535810-0012 | North Face - West end at corner (scaffolding level) | 11/29/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/30/05 | < 13.00 | No | No | |
| ASBESTOS-ST1-11/30/05 | 030535971-0001 | Southwest Area (sidewalk bridge level) | 11/30/05 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/1/05 | < 13.00 | No | No | |
| ASBESTOS-ST2-11/30/05 | 030535971-0002 | Southeast Area (sidewalk bridge level) | 11/30/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/1/05 | < 13.00 | No | No | |
| ASBESTOS-ST4-11/30/05 | 030535971-0003 | Northwest Area (street-level) | 11/30/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/1/05 | < 13.00 | No | No | |
| ASBESTOS-ST5-11/30/05 | 030535971-0004 | Firehouse #10 (roof level) | 11/30/05 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/1/05 | < 13.00 | No | No | |
| ASBESTOS-ST10-11/30/05 | 030535971-0005 | North Side Sidewalk Bridge | 11/30/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/1/05 | < 13.00 | No | No | |
| ASBESTOS-ST11-11/30/05 | 030535971-0006 | 90 Trinity Place (roof level) | 11/30/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/1/05 | < 13.00 | No | No | |
| ASBESTOS-ST12-11/30/05 | 030535971-0007 | 110 Greenwich Street (roof level) | 11/30/05 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/1/05 | < 13.00 | No | No | |
| ASBESTOS-ST13-11/30/05 | 030535971-0008 | Marriott Hotel, 38th Floor (roof level) | 11/30/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/1/05 | < 13.00 | No | No | |
| ASBESTOS-ST14-11/30/05 | 030535971-0009 | West Face - South end at corner (scaffolding level) | 11/30/05 | 1 | 2.130 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/1/05 | < 9.60 | No | No | |
| ASBESTOS-ST15-11/30/05 | 030535971-0010 | South Face - East end at corner (scaffolding level) | 11/30/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/1/05 | < 13.00 | No | No | |
| ASBESTOS-ST16-11/30/05 | 030535971-0011 | East Face - North end at corner (scaffolding level) | 11/30/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/1/05 | < 13.00 | No | No | |
| ASBESTOS-ST17-11/30/05 | 030535971-0012 | North Face - West end at corner (scaffolding level) | 11/30/05 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/1/05 | < 13.00 | No | No | |
| ASBESTOS-ST1-12/1/05 | 030536064-0001 | Southwest Area (sidewalk bridge level) | 12/1/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/2/05 | < 13.00 | No | No | |
| ASBESTOS-ST2-12/1/05 | 030536064-0002 | Southeast Area (sidewalk bridge level) | 12/1/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/2/05 | < 13.00 | No | No | |
| ASBESTOS-ST4-12/1/05 | 030536064-0003 | Northwest Area (street-level) | 12/1/05 | 1 | 3.050 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/2/05 | < 13.00 | No | No | |
| ASBESTOS-ST5-12/1/05 | 030536064-0004 | Firehouse #10 (roof level) | 12/1/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/2/05 | < 13.00 | No | No | |
| ASBESTOS-ST10-12/1/05 | 030536064-0005 | North Side Sidewalk Bridge | 12/1/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/2/05 | < 13.00 | No | No | |
| ASBESTOS-ST11-12/1/05 | 030536064-0006 | 90 Trinity Place (roof level) | 12/1/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/2/05 | < 13.00 | No | No | |
| ASBESTOS-ST12-12/1/05 | 030536064-0007 | 110 Greenwich Street (roof level) | 12/1/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/2/05 | < 13.00 | No | No | |
| ASBESTOS-ST13-12/1/05 | 030536064-0008 | Marriott Hotel, 38th Floor (roof level) | 12/1/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/2/05 | < 13.00 | No | No | |
| ASBESTOS-ST14-12/1/05 | 030536064-0009 | West Face - South end at corner (scaffolding level) | 12/1/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/2/05 | < 13.00 | No | No | |
| ASBESTOS-ST15-12/1/05 | 030536064-0010 | South Face - East end at corner (scaffolding level) | 12/1/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/2/05 | < 13.00 | No | No | |
| ASBESTOS-ST16-12/1/05 | 030536064-0011 | East Face - North end at corner (scaffolding level) | 12/1/05 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/2/05 | < 13.00 | No | No | |
| ASBESTOS-ST17-12/1/05 | 030536064-0012 | North Face - West end at corner (scaffolding level) | 12/1/05 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/2/05 | < 13.00 | No | No | |



CITY_DEP_WORBY_CANNATA_SUBP_000076955

NYC-WTC_000424925

NYC 9/11 Public Portal Document

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume ($m^3$) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Target Air Quality Levels | | | | | | | | 0.0009 | | | |
| | | EPA Site Specific Trigger Levels | | | | | | | | NA | | | |
| ASBESTOS-ST1-11/26/05 | 030535578-0001 | Southwest Area (sidewalk bridge level) | 11/26/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST2-11/26/05 | 030535578-0002 | Southeast Area (sidewalk bridge level) | 11/26/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST4-11/26/05 | 030535578-0003 | Northwest Area (street-level) | 11/26/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST5-11/26/05 | 030535578-0004 | Firehouse #10 (roof level) | 11/26/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST10-11/26/05 | 030535578-0005 | North Side Sidewalk Bridge | 11/26/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST11-11/26/05 | 030535578-0006 | 90 Trinity Place (roof level) | 11/26/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST12-11/26/05 | 030535578-0007 | 110 Greenwich Street (roof level) | 11/26/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST13-11/26/05 | 030535578-0008 | Marriott Hotel, 38th Floor (roof level) | 11/26/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST14-11/26/05 | 030535578-0009 | West Face - South end at corner (scaffolding level) | 11/26/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST15-11/26/05 | 030535578-0010 | South Face - East end at corner (scaffolding level) | 11/26/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST16-11/26/05 | 030535578-0011 | East Face - North end at corner (scaffolding level) | 11/26/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST17-11/26/05 | 030535578-0012 | North Face - West end at corner (scaffolding level) | 11/26/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST1-11/27/05 | 030535573-0001 | Southwest Area (sidewalk bridge level) | 11/27/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST2-11/27/05 | 030535573-0002 | Southeast Area (sidewalk bridge level) | 11/27/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST4-11/27/05 | 030535573-0003 | Northwest Area (street-level) | 11/27/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST5-11/27/05 | 030535573-0004 | Firehouse #10 (roof level) | 11/27/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST10-11/27/05 | 030535573-0005 | North Side Sidewalk Bridge | 11/27/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST11-11/27/05 | 030535573-0006 | 90 Trinity Place (roof level) | 11/27/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST12-11/27/05 | 030535573-0007 | 110 Greenwich Street (roof level) | 11/27/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST13-11/27/05 | 030535573-0008 | Marriott Hotel, 38th Floor (roof level) | 11/27/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST14-11/27/05 | 030535573-0009 | West Face - South end at corner (scaffolding level) | 11/27/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST15-11/27/05 | 030535573-0010 | South Face - East end at corner (scaffolding level) | 11/27/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST16-11/27/05 | 030535573-0011 | East Face - North end at corner (scaffolding level) | 11/27/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST17-11/27/05 | 030535573-0012 | North Face - West end at corner (scaffolding level) | 11/27/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/25/05 | < 0.00083 | No | No | |
| ASBESTOS-ST1-11/28/05 | 030535664-0001 | Southwest Area (sidewalk bridge level) | 11/28/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/29/05 | < 0.00083 | No | No | |
| ASBESTOS-ST2-11/28/05 | 030535664-0002 | Southeast Area (sidewalk bridge level) | 11/28/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/29/05 | < 0.00083 | No | No | |
| ASBESTOS-ST4-11/28/05 | 030535664-0003 | Northwest Area (street-level) | 11/28/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/29/05 | < 0.00083 | No | No | |
| ASBESTOS-ST5-11/28/05 | 030535664-0004 | Firehouse #10 (roof level) | 11/28/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/29/05 | < 0.00083 | No | No | |
| ASBESTOS-ST10-11/28/05 | 030535664-0005 | North Side Sidewalk Bridge | 11/28/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/29/05 | < 0.00083 | No | No | |
| ASBESTOS-ST100-11/28/05 | 030535664-0013 | Station 10 Field Duplicate | 11/28/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/29/05 | < 0.00083 | No | No | |
| ASBESTOS-ST11-11/28/05 | 030535664-0006 | 90 Trinity Place (roof level) | 11/28/05 | 1 | 3.670 | Asbestos | PCME | EMSL | 11/29/05 | < 0.00067 | No | No | |
| ASBESTOS-ST12-11/28/05 | 030535664-0007 | 110 Greenwich Street (roof level) | 11/28/05 | 1 | 3.510 | Asbestos | PCME | EMSL | 11/29/05 | < 0.00070 | No | No | |
| ASBESTOS-ST13-11/28/05 | 030535664-0008 | Marriott Hotel, 38th Floor (roof level) | 11/28/05 | 1 | 3.590 | Asbestos | PCME | EMSL | 11/29/05 | < 0.00069 | No | No | |
| ASBESTOS-ST14-11/28/05 | 030535664-0009 | West Face - South end at corner (scaffolding level) | 11/28/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/29/05 | < 0.00083 | No | No | |
| ASBESTOS-ST15-11/28/05 | 030535664-0010 | South Face - East end at corner (scaffolding level) | 11/28/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/29/05 | < 0.00083 | No | No | |
| ASBESTOS-ST16-11/28/05 | 030535664-0011 | East Face - North end at corner (scaffolding level) | 11/28/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/29/05 | < 0.00083 | No | No | |
| ASBESTOS-ST17-11/28/05 | 030535664-0012 | North Face - West end at corner (scaffolding level) | 11/28/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/29/05 | < 0.00083 | No | No | |
| ASBESTOS-ST1-11/29/05 | 030535810-0001 | Southwest Area (sidewalk bridge level) | 11/29/05 | 1 | 3.010 | Asbestos | PCME | EMSL | 11/30/05 | < 0.00082 | No | No | |
| ASBESTOS-ST2-11/29/05 | 030535810-0002 | Southeast Area (sidewalk bridge level) | 11/29/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/30/05 | < 0.00083 | No | No | |
| ASBESTOS-ST4-11/29/05 | 030535810-0003 | Northwest Area (street-level) | 11/29/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/30/05 | < 0.00083 | No | No | |
| ASBESTOS-ST5-11/29/05 | 030535810-0004 | Firehouse #10 (roof level) | 11/29/05 | 1 | 2.780 | Asbestos | PCME | EMSL | 11/30/05 | < 0.00089 | No | No | |
| ASBESTOS-ST10-11/29/05 | 030535810-0005 | North Side Sidewalk Bridge | 11/29/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/30/05 | < 0.00083 | No | No | |
| ASBESTOS-ST11-11/29/05 | 030535810-0006 | 90 Trinity Place (roof level) | 11/29/05 | 1 | 2.920 | Asbestos | PCME | EMSL | 11/30/05 | < 0.00085 | No | No | |
| ASBESTOS-ST12-11/29/05 | 030535810-0007 | 110 Greenwich Street (roof level) | 11/29/05 | 1 | 2.940 | Asbestos | PCME | EMSL | 11/30/05 | < 0.00084 | No | No | |
| ASBESTOS-ST13-11/29/05 | 030535810-0008 | Marriott Hotel, 38th Floor (roof level) | 11/29/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/30/05 | < 0.00083 | No | No | |
| ASBESTOS-ST14-11/29/05 | 030535810-0009 | West Face - South end at corner (scaffolding level) | 11/29/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/30/05 | < 0.00083 | No | No | |
| ASBESTOS-ST15-11/29/05 | 030535810-0010 | South Face - East end at corner (scaffolding level) | 11/29/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/30/05 | < 0.00083 | No | No | |
| ASBESTOS-ST16-11/29/05 | 030535810-0011 | East Face - North end at corner (scaffolding level) | 11/29/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/30/05 | < 0.00083 | No | No | |
| ASBESTOS-ST17-11/29/05 | 030535810-0012 | North Face - West end at corner (scaffolding level) | 11/29/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 11/30/05 | < 0.00083 | No | No | |
| ASBESTOS-ST1-11/30/05 | 030535971-0001 | Southwest Area (sidewalk bridge level) | 11/30/05 | 1 | 3.010 | Asbestos | PCME | EMSL | 12/1/05 | < 0.00082 | No | No | |
| ASBESTOS-ST2-11/30/05 | 030535971-0002 | Southeast Area (sidewalk bridge level) | 11/30/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 12/1/05 | < 0.00083 | No | No | |
| ASBESTOS-ST4-11/30/05 | 030535971-0003 | Northwest Area (street-level) | 11/30/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 12/1/05 | < 0.00083 | No | No | |
| ASBESTOS-ST5-11/30/05 | 030535971-0004 | Firehouse #10 (roof level) | 11/30/05 | 1 | 3.000 | Asbestos | PCME | EMSL | 12/1/05 | < 0.00083 | No | No | |
| ASBESTOS-ST10-11/30/05 | 030535971-0005 | North Side Sidewalk Bridge | 11/30/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 12/1/05 | < 0.00083 | No | No | |
| ASBESTOS-ST11-11/30/05 | 030535971-0006 | 90 Trinity Place (roof level) | 11/30/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 12/1/05 | < 0.00083 | No | No | |
| ASBESTOS-ST12-11/30/05 | 030535971-0007 | 110 Greenwich Street (roof level) | 11/30/05 | 1 | 2.940 | Asbestos | PCME | EMSL | 12/1/05 | < 0.00084 | No | No | |
| ASBESTOS-ST13-11/30/05 | 030535971-0008 | Marriott Hotel, 38th Floor (roof level) | 11/30/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 12/1/05 | < 0.00083 | No | No | |
| ASBESTOS-ST14-11/30/05 | 030535971-0009 | West Face - South end at corner (scaffolding level) | 11/30/05 | 1 | 2.130 | Asbestos | PCME | EMSL | 12/1/05 | < 0.00087 | No | No | |
| ASBESTOS-ST15-11/30/05 | 030535971-0010 | South Face - East end at corner (scaffolding level) | 11/30/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 12/1/05 | < 0.00083 | No | No | |
| ASBESTOS-ST16-11/30/05 | 030535971-0011 | East Face - North end at corner (scaffolding level) | 11/30/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 12/1/05 | < 0.00083 | No | No | |
| ASBESTOS-ST17-11/30/05 | 030535971-0012 | North Face - West end at corner (scaffolding level) | 11/30/05 | 1 | 3.020 | Asbestos | PCME | EMSL | 12/1/05 | < 0.00082 | No | No | |
| ASBESTOS-ST1-12/1/05 | 030536064-0001 | Southwest Area (sidewalk bridge level) | 12/1/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 12/2/05 | < 0.00083 | No | No | |
| ASBESTOS-ST2-12/1/05 | 030536064-0002 | Southeast Area (sidewalk bridge level) | 12/1/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 12/2/05 | < 0.00083 | No | No | |
| ASBESTOS-ST4-12/1/05 | 030536064-0003 | Northwest Area (street-level) | 12/1/05 | 1 | 3.050 | Asbestos | PCME | EMSL | 12/2/05 | < 0.00080 | No | No | |
| ASBESTOS-ST5-12/1/05 | 030536064-0004 | Firehouse #10 (roof level) | 12/1/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 12/2/05 | < 0.00083 | No | No | |
| ASBESTOS-ST10-12/1/05 | 030536064-0005 | North Side Sidewalk Bridge | 12/1/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 12/2/05 | < 0.00083 | No | No | |
| ASBESTOS-ST11-12/1/05 | 030536064-0006 | 90 Trinity Place (roof level) | 12/1/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 12/2/05 | < 0.00083 | No | No | |
| ASBESTOS-ST12-12/1/05 | 030536064-0007 | 110 Greenwich Street (roof level) | 12/1/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 12/2/05 | < 0.00083 | No | No | |
| ASBESTOS-ST13-12/1/05 | 030536064-0008 | Marriott Hotel, 38th Floor (roof level) | 12/1/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 12/2/05 | < 0.00083 | No | No | |
| ASBESTOS-ST14-12/1/05 | 030536064-0009 | West Face - South end at corner (scaffolding level) | 12/1/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 12/2/05 | < 0.00083 | No | No | |
| ASBESTOS-ST15-12/1/05 | 030536064-0010 | South Face - East end at corner (scaffolding level) | 12/1/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 12/2/05 | < 0.00083 | No | No | |
| ASBESTOS-ST16-12/1/05 | 030536064-0011 | East Face - North end at corner (scaffolding level) | 12/1/05 | 1 | 2.970 | Asbestos | PCME | EMSL | 12/2/05 | < 0.00083 | No | No | |
| ASBESTOS-ST17-12/1/05 | 030536064-0012 | North Face - West end at corner (scaffolding level) | 12/1/05 | 1 | 2.940 | Asbestos | PCME | EMSL | 12/2/05 | < 0.00084 | No | No | |



CITY_DEP_WORBY_CANNATA_SUBP_000076956

NYC-WTC_000424926

NYC 9/11 Public Portal Document

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Sample Volume ($m^3$) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | PAHs (BAP-equivalent) Concentration (ng/m3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Target Air Quality Levels | | | | | | | | | 34 | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | 3,400 | | | |
| PAHS-ST2-11/17/05 | G5K190230002 | Southeast Area (sidewalk bridge level) | 11/17/05 | 337.4 | PAHs | 8270C SIM | STL-SAC | 11/19/05 | < 7.5 | No | No | |



CITY_DEP_WORBY_CANNATA_SUBP_000076957

NYC-WTC_000424927

NYC 9/11 Public Portal Document

| TRC Field Sample No. | Station Location | Collection Start Date | Collection Time (minutes) | Analyte | Analytical Method | Instrument | Particulate PM10 (ug/m3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Target Air Quality Levels | | | | | 150 | | | |
| | | EPA Site Specific Trigger Levels | | | | | 150 | | | |
| PM10-ST1-11/27/2005 | Southwest Area (sidewalk bridge level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 24 | No | No | |
| PM10-ST2-11/27/2005 | Southeast Area (sidewalk bridge level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 33 | No | No | |
| PM10-ST4-11/27/2005 | Northwest Area (street-level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 32 | No | No | |
| PM10-ST5-11/27/2005 | Firehouse #10 (roof level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 22 | No | No | |
| PM10-ST13-11/27/2005 | North Side Sidewalk Bridge | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 29 | No | No | |
| PM10-ST130-11/27/2005 | Station 10 Field Duplicate | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 19 | No | No | |
| PM10-ST11-11/27/2005 | 90 Trinity Place (roof level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 20 | No | No | |
| PM10-ST12-11/27/2005 | 110 Greenwich Street (roof level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 22 | No | No | |
| PM10-ST13-11/27/2005 | Marriott Hotel, 38th Floor (roof level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 19 | No | No | |
| PM10-ST14-11/27/2005 | West Face - South end at corner (scaffolding level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 22 | No | No | |
| PM10-ST15-11/27/2005 | South Face - East end at corner (scaffolding level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 19 | No | No | |
| PM10-ST19-11/27/2005 | East Face - North end at corner (scaffolding level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 14 | No | No | |
| PM10-ST17-11/27/2005 | North Face - West end at corner (scaffolding level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 19 | No | No | |
| PM10-ST1-11/28/2005 | Southwest Area (sidewalk bridge level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 32 | No | No | |
| PM10-ST2-11/28/2005 | Southeast Area (sidewalk bridge level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 39 | No | No | |
| PM10-ST4-11/28/2005 | Northwest Area (street-level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 59 | No | No | |
| PM10-ST5-11/28/2005 | Firehouse #10 (roof level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 30 | No | No | |
| PM10-ST13-11/28/2005 | North Side Sidewalk Bridge | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 36 | No | No | |
| PM10-ST130-11/28/2005 | Station 10 Field Duplicate | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 30 | No | No | |
| PM10-ST11-11/28/2005 | 90 Trinity Place (roof level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 21 | No | No | |
| PM10-ST12-11/28/2005 | 110 Greenwich Street (roof level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 29 | No | No | |
| PM10 ST13 11/28/2005 | Marriott Hotel, 38th Floor (roof level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 22 | No | No | |
| PM10-ST14-11/28/2005 | West Face - South end at corner (scaffolding level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 32 | No | No | |
| PM10-ST15-11/28/2005 | South Face - East end at corner (scaffolding level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 23 | No | No | |
| PM10-ST19-11/28/2005 | East Face - North end at corner (scaffolding level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 16 | No | No | |
| PM10-ST17-11/28/2005 | North Face - West end at corner (scaffolding level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 23 | No | No | |
| PM10-ST1-11/29/2005 | Southwest Area (sidewalk bridge level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 28 | No | No | |
| PM10-ST2-11/29/2005 | Southeast Area (sidewalk bridge level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 38 | No | No | |
| PM10-ST4-11/29/2005 | Northwest Area (street-level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 31 | No | No | |
| PM10-ST5-11/29/2005 | Firehouse #10 (roof level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 24 | No | No | |
| PM10-ST13-11/29/2005 | North Side Sidewalk Bridge | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 29 | No | No | |
| PM10-ST130-11/29/2005 | Station 10 Field Duplicate | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 23 | No | No | |
| PM10-ST11-11/29/2005 | 90 Trinity Place (roof level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 22 | No | No | |
| PM10-ST12-11/29/2005 | 110 Greenwich Street (roof level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 24 | No | No | |
| PM10-ST13-11/29/2005 | Marriott Hotel, 38th Floor (roof level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 22 | No | No | |
| PM10-ST14-11/29/2005 | West Face - South end at corner (scaffolding level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 28 | No | No | |
| PM10-ST15-11/29/2005 | South Face - East end at corner (scaffolding level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 29 | No | No | |
| PM10-ST19-11/29/2005 | East Face - North end at corner (scaffolding level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 17 | No | No | |
| PM10-ST17-11/29/2005 | North Face - West end at corner (scaffolding level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 24 | No | No | |
| PM10-ST1-11/30/2005 | Southwest Area (sidewalk bridge level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 18 | No | No | |
| PM10-ST2-11/30/2005 | Southeast Area (sidewalk bridge level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 29 | No | No | |
| PM10-ST4-11/30/2005 | Northwest Area (street-level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 24 | No | No | |
| PM10-ST5-11/30/2005 | Firehouse #10 (roof level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 22 | No | No | |
| PM10-ST13-11/30/2005 | North Side Sidewalk Bridge | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 12 | No | No | |
| PM10-ST130-11/30/2005 | Station 10 Field Duplicate | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 14 | No | No | |
| PM10-ST11-11/30/2005 | 90 Trinity Place (roof level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 13 | No | No | |
| PM10-ST12-11/30/2005 | 110 Greenwich Street (roof level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 12 | No | No | |
| PM10-ST13-11/30/2005 | Marriott Hotel, 38th Floor (roof level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 10 | No | No | |
| PM10-ST14-11/30/2005 | West Face - South end at corner (scaffolding level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 13 | No | No | |
| PM10-ST15-11/30/2005 | South Face - East end at corner (scaffolding level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 15 | No | No | |
| PM10-ST19-11/30/2005 | East Face - North end at corner (scaffolding level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 10 | No | No | |
| PM10-ST17-11/30/2005 | North Face - West end at corner (scaffolding level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 12 | No | No | |
| PM10-ST1-12/1/2005 | Southwest Area (sidewalk bridge level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 11 | No | No | |
| PM10-ST2-12/1/2005 | Southeast Area (sidewalk bridge level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 26 | No | No | |
| PM10-ST4-12/1/2005 | Northwest Area (street-level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 10 | No | No | |
| PM10-ST5-12/1/2005 | Firehouse #10 (roof level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 11 | No | No | |
| PM10-ST13-12/1/2005 | North Side Sidewalk Bridge | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 11 | No | No | |
| PM10-ST130-12/1/2005 | Station 10 Field Duplicate | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 10 | No | No | |
| PM10-ST11-12/1/2005 | 90 Trinity Place (roof level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 13 | No | No | |
| PM10-ST12-12/1/2005 | 110 Greenwich Street (roof level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 10 | No | No | |
| PM10-ST13-12/1/2005 | Marriott Hotel, 38th Floor (roof level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM10-ST14-12/1/2005 | West Face - South end at corner (scaffolding level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 12 | No | No | |
| PM10-ST15-12/1/2005 | South Face - East end at corner (scaffolding level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 13 | No | No | |
| PM10-ST19-12/1/2005 | East Face - North end at corner (scaffolding level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 8 | No | No | |
| PM10-ST17-12/1/2005 | North Face - West end at corner (scaffolding level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 12 | No | No | |
| PM10-ST1-12/2/2005 | Southwest Area (sidewalk bridge level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 14 | No | No | |
| PM10-ST2-12/2/2005 | Southeast Area (sidewalk bridge level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 20 | No | No | |
| PM10-ST4-12/2/2005 | Northwest Area (street-level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 13 | No | No | |
| PM10 ST5 12/2/2005 | Firehouse #10 (roof level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 11 | No | No | |
| PM10-ST13-12/2/2005 | North Side Sidewalk Bridge | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 20 | No | No | |
| PM10-ST130-12/2/2005 | Station 10 Field Duplicate | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 11 | No | No | |
| PM10-ST11-12/2/2005 | 90 Trinity Place (roof level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 14 | No | No | |
| PM10-ST12-12/2/2005 | 110 Greenwich Street (roof level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 11 | No | No | |
| PM10-ST13-12/2/2005 | Marriott Hotel, 38th Floor (roof level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 10 | No | No | |
| PM10-ST14-12/2/2005 | West Face - South end at corner (scaffolding level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 11 | No | No | |
| PM10-ST15-12/2/2005 | South Face - East end at corner (scaffolding level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 14 | No | No | |
| PM10-ST19-12/2/2005 | East Face - North end at corner (scaffolding level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 14 | No | No | |
| PM10-ST17-12/2/2005 | North Face - West end at corner (scaffolding level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 11 | No | No | |
| PM10-ST1-12/3/2005 | Southwest Area (sidewalk bridge level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM10-ST2-12/3/2005 | Southeast Area (sidewalk bridge level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 18 | No | No | |
| PM10-ST4-12/3/2005 | Northwest Area (street-level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM10-ST5-12/3/2005 | Firehouse #10 (roof level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 8 | No | No | |
| PM10-ST13-12/3/2005 | North Side Sidewalk Bridge | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 8 | No | No | |
| PM10-ST130-12/3/2005 | Station 10 Field Duplicate | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 7 | No | No | |
| PM10-ST11-12/3/2005 | 90 Trinity Place (roof level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 11 | No | No | |
| PM10-ST12-12/3/2005 | 110 Greenwich Street (roof level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 8 | No | No | |
| PM10-ST13-12/3/2005 | Marriott Hotel, 38th Floor (roof level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 8 | No | No | |
| PM10-ST14-12/3/2005 | West Face - South end at corner (scaffolding level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 8 | No | No | |
| PM10-ST15-12/3/2005 | South Face - East end at corner (scaffolding level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 10 | No | No | |
| PM10 ST19 12/3/2005 | East Face - North end at corner (scaffolding level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM10-ST17-12/3/2005 | North Face - West end at corner (scaffolding level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 7 | No | No | |



CITY_DEP_WORBY_CANNATA_SUBP_000076958

NYC-WTC_000424928

NYC 9/11 Public Portal Document

| TRC Field Sample No. | Station Location | Collection Start Date | Collection Time (minutes) | Analyte | Analytical Method | Instrument | Particulate PM2.5 (ug/m3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|---|---|---|---|---|---|---|---|---|---|
| Target Air Quality Levels | | | | | | | 40 | | | |
| EPA Site Specific Trigger Levels | | | | | | | 65 | | | |
| PM2.5-ST-11/27/2005 | Southwest Area (sidewalk bridge level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 20 | No | No | |
| PM2.5-ST2-11/27/2005 | Southeast Area (sidewalk bridge level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 22 | No | No | |
| PM2.5-ST4-11/27/2005 | Northwest Area (street-level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 17 | No | No | |
| PM2.5-ST5-11/27/2005 | Firehouse #10 (roof level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 19 | No | No | |
| PM2.5-ST-0-11/27/2005 | North Side Sidewalk Bridge | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 18 | No | No | |
| PM2.5-ST-00-11/27/2005 | Station 10 Field Duplicate | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 19 | No | No | |
| PM2.5-ST-1-11/27/2005 | 90 Trinity Place (roof level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 15 | No | No | |
| PM2.5-ST-2-11/27/2005 | 110 Greenwich Street (roof level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 17 | No | No | |
| PM2.5-ST-3-11/27/2005 | Marriott Hotel, 38th Floor (roof level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 14 | No | No | |
| PM2.5-ST-4-11/27/2005 | West Face - South end at corner (scaffolding level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 16 | No | No | |
| PM2.5-ST-5-11/27/2005 | South Face - East end at corner (scaffolding level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 15 | No | No | |
| PM2.5-ST-6-11/27/2005 | East Face - North end at corner (scaffolding level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 16 | No | No | |
| PM2.5-ST-7-11/27/2005 | North Face - West end at corner (scaffolding level) | 11/27/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 15 | No | No | |
| PM2.5-ST-11/28/2005 | Southwest Area (sidewalk bridge level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 25 | No | No | |
| PM2.5-ST2-11/28/2005 | Southeast Area (sidewalk bridge level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 20 | No | No | |
| PM2.5-ST4-11/28/2005 | Northwest Area (street-level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 15 | No | No | |
| PM2.5-ST5-11/28/2005 | Firehouse #10 (roof level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 18 | No | No | |
| PM2.5-ST-0-11/28/2005 | North Side Sidewalk Bridge | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 17 | No | No | |
| PM2.5-ST-00-11/28/2005 | Station 10 Field Duplicate | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 19 | No | No | |
| PM2.5-ST-1-11/28/2005 | 90 Trinity Place (roof level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 13 | No | No | |
| PM2.5-ST-2-11/28/2005 | 110 Greenwich Street (roof level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 16 | No | No | |
| PM2.5-ST-3-11/28/2005 | Marriott Hotel, 38th Floor (roof level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 12 | No | No | |
| PM2.5-ST-4-11/28/2005 | West Face - South end at corner (scaffolding level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 15 | No | No | |
| PM2.5-ST-5-11/28/2005 | South Face - East end at corner (scaffolding level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 14 | No | No | |
| PM2.5-ST-6-11/28/2005 | East Face - North end at corner (scaffolding level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 13 | No | No | |
| PM2.5-ST-7-11/28/2005 | North Face - West end at corner (scaffolding level) | 11/28/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 15 | No | No | |
| PM2.5-ST-11/29/2005 | Southwest Area (sidewalk bridge level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 28 | No | No | |
| PM2.5-ST2-11/29/2005 | Southeast Area (sidewalk bridge level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 18 | No | No | |
| PM2.5-ST4-11/29/2005 | Northwest Area (street-level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 16 | No | No | |
| PM2.5-ST5-11/29/2005 | Firehouse #10 (roof level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 17 | No | No | |
| PM2.5-ST-0-11/29/2005 | North Side Sidewalk Bridge | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 21 | No | No | |
| PM2.5-ST-00-11/29/2005 | Station 10 Field Duplicate | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 17 | No | No | |
| PM2.5-ST-1-11/29/2005 | 90 Trinity Place (roof level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 18 | No | No | |
| PM2.5-ST-2-11/29/2005 | 110 Greenwich Street (roof level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 27 | No | No | |
| PM2.5-ST-3-11/29/2005 | Marriott Hotel, 38th Floor (roof level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 3 | No | No | |
| PM2.5-ST-4-11/29/2005 | West Face - South end at corner (scaffolding level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 3 | No | No | |
| PM2.5-ST-5-11/29/2005 | South Face - East end at corner (scaffolding level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 12 | No | No | |
| PM2.5-ST-6-11/29/2005 | East Face - North end at corner (scaffolding level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-7-11/29/2005 | North Face - West end at corner (scaffolding level) | 11/29/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 12 | No | No | |
| PM2.5-ST-11/30/2005 | Southwest Area (sidewalk bridge level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 17 | No | No | |
| PM2.5-ST2-11/30/2005 | Southeast Area (sidewalk bridge level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 15 | No | No | |
| PM2.5-ST4-11/30/2005 | Northwest Area (street-level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 10 | No | No | |
| PM2.5-ST5-11/30/2005 | Firehouse #10 (roof level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 10 | No | No | |
| PM2.5-ST-0-11/30/2005 | North Side Sidewalk Bridge | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-00-11/30/2005 | Station 10 Field Duplicate | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-1-11/30/2005 | 90 Trinity Place (roof level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 11 | No | No | |
| PM2.5-ST-2-11/30/2005 | 110 Greenwich Street (roof level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-3-11/30/2005 | Marriott Hotel, 38th Floor (roof level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 10 | No | No | |
| PM2.5-ST-4-11/30/2005 | West Face - South end at corner (scaffolding level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-5-11/30/2005 | South Face - East end at corner (scaffolding level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 10 | No | No | |
| PM2.5-ST-6-11/30/2005 | East Face - North end at corner (scaffolding level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 10 | No | No | |
| PM2.5-ST-7-11/30/2005 | North Face - West end at corner (scaffolding level) | 11/30/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-12/1/2005 | Southwest Area (sidewalk bridge level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 15 | No | No | |
| PM2.5-ST2-12/1/2005 | Southeast Area (sidewalk bridge level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 15 | No | No | |
| PM2.5-ST4-12/1/2005 | Northwest Area (street-level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST5-12/1/2005 | Firehouse #10 (roof level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-0-12/1/2005 | North Side Sidewalk Bridge | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 7 | No | No | |
| PM2.5-ST-00-12/1/2005 | Station 10 Field Duplicate | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-1-12/1/2005 | 90 Trinity Place (roof level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-2-12/1/2005 | 110 Greenwich Street (roof level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 13 | No | No | |
| PM2.5-ST-3-12/1/2005 | Marriott Hotel, 38th Floor (roof level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-4-12/1/2005 | West Face - South end at corner (scaffolding level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 10 | No | No | |
| PM2.5-ST-5-12/1/2005 | South Face - East end at corner (scaffolding level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 11 | No | No | |
| PM2.5-ST-6-12/1/2005 | East Face - North end at corner (scaffolding level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 10 | No | No | |
| PM2.5-ST-7-12/1/2005 | North Face - West end at corner (scaffolding level) | 12/1/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-12/2/2005 | Southwest Area (sidewalk bridge level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 12 | No | No | |
| PM2.5-ST2-12/2/2005 | Southeast Area (sidewalk bridge level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 10 | No | No | |
| PM2.5-ST4-12/2/2005 | Northwest Area (street-level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 7 | No | No | |
| PM2.5-ST5-12/2/2005 | Firehouse #10 (roof level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-0-12/2/2005 | North Side Sidewalk Bridge | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-00-12/2/2005 | Station 10 Field Duplicate | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 7 | No | No | |
| PM2.5-ST-1-12/2/2005 | 90 Trinity Place (roof level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 7 | No | No | |
| PM2.5-ST-2-12/2/2005 | 110 Greenwich Street (roof level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-3-12/2/2005 | Marriott Hotel, 38th Floor (roof level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-4-12/2/2005 | West Face - South end at corner (scaffolding level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-5-12/2/2005 | South Face - East end at corner (scaffolding level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-6-12/2/2005 | East Face - North end at corner (scaffolding level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-7-12/2/2005 | North Face - West end at corner (scaffolding level) | 12/2/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 7 | No | No | |
| PM2.5-ST-12/3/2005 | Southwest Area (sidewalk bridge level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 12 | No | No | |
| PM2.5-ST2-12/3/2005 | Southeast Area (sidewalk bridge level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 11 | No | No | |
| PM2.5-ST4-12/3/2005 | Northwest Area (street-level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 7 | No | No | |
| PM2.5-ST5-12/3/2005 | Firehouse #10 (roof level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-0-12/3/2005 | North Side Sidewalk Bridge | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 7 | No | No | |
| PM2.5-ST-00-12/3/2005 | Station 10 Field Duplicate | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-1-12/3/2005 | 90 Trinity Place (roof level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-2-12/3/2005 | 110 Greenwich Street (roof level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-3-12/3/2005 | Marriott Hotel, 38th Floor (roof level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 7 | No | No | |
| PM2.5-ST-4-12/3/2005 | West Face - South end at corner (scaffolding level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-5-12/3/2005 | South Face - East end at corner (scaffolding level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 10 | No | No | |
| PM2.5-ST-6-12/3/2005 | East Face - North end at corner (scaffolding level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |
| PM2.5-ST-7-12/3/2005 | North Face - West end at corner (scaffolding level) | 12/3/05 | 1440 | Particulate | Direct Read | Met One E-BAM | 9 | No | No | |



CITY_DEP_WORBY_CANNATA_SUBP_000076959

NYC-WTC_000424929