NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: NYC SCA / Stuyvesant H.S., Chambers St., NY, NY / Tent #1- Aud Front (Row A-C Seats 1-15) / Tent #2 Aud Rear (Row M,N,P Var Seats) / Tent #3 : Balcony (Row A St 101-117)

Customer ID: TAYL50
Customer PO:
Received: 12/30/02 4:34 PM
EMSL Order: 030218928
EMSL Project ID:
Analysis Date: 12/30/02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Final Rule (AHERA)

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures ≥ 0.5µ < 5	# Structures ≥ 5µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm²)	Asbestos Concentration (S/cc)	Notes
T-1 030218928-0001	1350.00	0.0625	0	None Detected			0.0046	<16.00	<0.0046	
T-2 030218928-0002	1350.00	0.0625	4	None Detected			0.0046	<16.00	<0.0046	
T-3 030218928-0003	1387.50	0.0625	0	None Detected			0.0044	<16.00	<0.0044	
T-4 030218928-0004	1350.00	0.0625	0	None Detected			0.0046	<16.00	<0.0046	
T-5 030218928-0005	1350.00	0.0625	2	None Detected			0.0046	<16.00	<0.0046	
T-6 030218928-0006	1275.00	0.0625	0	None Detected			0.0048	<16.00	<0.0048	
T-7 030218928-0007	1275.00	0.0625	0	None Detected			0.0048	<16.00	<0.0048	
T-8 030218928-0008	1275.00	0.0625	0	None Detected			0.0048	<16.00	<0.0048	
T-9 030218928-0009	1275.00	0.0625	2	None Detected			0.0048	<16.00	<0.0048	
T-10 030218928-0010	1350.00	0.0625	0	None Detected			0.0046	<16.00	<0.0046	
T-11 030218928-0011	1350.00	0.0625	0	None Detected			0.0046	<16.00	<0.0046	

Analyst(s)
Ranay Pruitt (24)

Laboratory Manager
or other approved signatory

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by EMSL. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis accuracy and precision) is available upon request
Accredited for: NVLAP PLM/TEM #101048-0, NY State ELAP #11506

TEMAHERA-1

CITY_21MC100_010218101

NYC-WTC_000429985

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: NYC SCA / Stuyvesant H.S., Chambers St., NY, NY / Tent #1- Aud Front (Row A-C Seats 1-15) / Tent #2 Aud Rear (Row M,N,P Var Seats) / Tent #3 : Balcony (Row A St 101-117)

Customer ID: TAYL50
Customer PO:
Received: 12/30/02 4:34 PM
EMSL Order: 030218928
EMSL Project ID:
Analysis Date: 12/30/02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Final Rule (AHERA)

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures ≥ 0.5µ < 5	# Structures ≥ 5µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm²)	Asbestos Concentration (S/cc)	Notes
T-12 030218928-0012	1312.50	0.0625	1	None Detected			0.0047	<16.00	<0.0047	
T-13 030218928-0013	1275.00	0.0625	1	None Detected			0.0048	<16.00	<0.0048	
T-14 030218928-0014	1387.50	0.0625	0	None Detected			0.0044	<16.00	<0.0044	
T-15 030218928-0015	1312.50	0.0625	0	None Detected			0.0047	<16.00	<0.0047	
T-16 030218928-0016	1275.00	0.0625	0	None Detected			0.0048	<16.00	<0.0048	
T-17 030218928-0017	1350.00	0.0625	2	None Detected			0.0046	<16.00	<0.0046	
T-18 030218928-0018	1350.00	0.0625	0	None Detected			0.0046	<16.00	<0.0046	
T-19 030218928-0019	1275.00	0.0625	3	None Detected			0.0048	<16.00	<0.0048	
T-20 030218928-0020	1275.00	0.0625	2	None Detected			0.0048	<16.00	<0.0048	
T-21 030218928-0021	1275.00	0.0625	1	None Detected			0.0048	<16.00	<0.0048	
T-22 030218928-0022	1350.00	0.0625	0	None Detected			0.0046	<16.00	<0.0046	

Analyst(s)
Randy Pruitt (24)

Laboratory Manager
or other approved signatory

Disclaimers: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by EMSL. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis accuracy and precision) is available upon request.
Accredited for NVLAP PLM/TEM #101049-0, NY State ELAP #11608

TEMAHERA-1

2

NYC-WTC_000429986

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122800058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
120 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: **NYC SCA / Stuyvesant H.S., Chambers St., NY. NY / Tent #1- Aud Front (Row A-C Seats 1-15) / Tent #2 Aud Rear (Row M,N,P Var Seats) / Tent #3 : Balcony (Row A St 101-117)**

Customer ID: TAYLS0
Customer PO:
Received: 12/30/02 4:34 PM
EMSL Order: 030218928
EMSL Project ID:
Analysis Date: 12/30/02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Final Rule (AHERA)

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures ≥ 0.5μ < 5	# Structures ≥5μ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm²)	Asbestos Concentration (S/cc)	Notes
T-23 030218928-0023	1312.50	0.0625	0	None Detected			0.0047	<16.00	<0.0047	
T-24 030218928-0024	1312.50	0.0625	2	None Detected			0.0047	<16.00	<0.0047	

Analyst(s)
Randy Pruitt (24)

Laboratory Manager
or other approved signatory

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This laboratory is responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by EMSL. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysts' accuracy and precision) is available upon request.
Accredited for NVLAP PLM/TEM #101049-0, NY State ELAP #11608