

05/20/2002 14:41 FAX 7188974537

SAMSON MANAGEMENT CORP

05/15/2002 20:45 FAX 8457821872

000
007

05/15/2002 23:01 2126799392

SCILAB NYC

PAGE 17/19

**SCIENTIFIC LABORATORIES, INC.**

117 EAST 30TH STREET

NEW YORK, NY 10016

TEL: (212) 679-8800 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

AA Asbestos Services
 Attn: Jean Rensink
 36 Eagle Street
 Walton Lake Park
 Monroe, NY 10950

Date Received 05/15/2002 SciLab Job No. 202052557
 Date Examined 05/15/2002 P.O. # Rensink
 ELAP Number 11480 Page 1 of 2
 RE: 120 Liberty St. AKA 125 Cedar St. NY NY 3rd Floor/No
 Access 3N

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
1	202052557-01		NA

Location: 3S Awp Radiator Cover North West Side

Description: Bulk Material

Asbestos Types:

Other Material:

Comment: INSUFFICIENT SAMPLE SIZE

2	202052557-02		NA
---	--------------	--	----

Location: 3S Kitchen Stove Top

Description: Bulk Material

Asbestos Types:

Other Material:

Comment: INSUFFICIENT SAMPLE SIZE

3	202052557-03	No	NAD ¹
---	--------------	----	------------------

Location: 3S Kitchen Floor

Description: Grey, Heterogeneous, Bulk Material

Asbestos Types:

Other Material: Cellulose 20. %, Fibrous glass 30. %, Non-fibrous 50. %

4	202052557-04	Yes	<1.0% ¹
---	--------------	-----	--------------------

Location: 3S Inside Apt. Hallway Floor

Description: Grey, Heterogeneous, Bulk Material

Asbestos Types: Chrysotile Trace

 Other Material: Animal hair Trace, Cellulose 25. %, Fibrous glass 25. %,
 Synthetic fibers 5. %, Non-fibrous 45. %


SCILAB
SCIENTIFIC LABORATORIES, INC.

117 EAST 30TH STREET

NEW YORK, NY 10016

TEL: (212) 678-8800 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

AA Asbestos Services

Attn: Jean Rensink

36 Eagle Street

Walton Lake Park

Monroe, NY 10950

Date Received 05/15/2002 SciLab Job No. 202052557

Date Examined 05/15/2002 P.O. # Rensink

ELAP Number 11480 Page 2 of 2

RE: 120 Liberty St AKA 125 Cedar St NY NY 3rd Floor/No

Access 3N

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
8	202052557-05	Yes	<1. %

Location: 3rd Fl. Hallway Floor

Description: Grey, Heterogeneous, Bulk Material

Asbestos Types: Chrysotile Trace

Other Material: Cellulose 20. %, Fibrous glass 35. %, Synthetic fibers Trace.

Non-fibrous 45. %

9	202052557-06	NA
---	--------------	----

Location: 3rd Fl. Banister

Description: Bulk Material

Asbestos Types:

Other Material:

Comment: INSUFFICIENT SAMPLE SIZE

Reporting Notes:

(1) Composite analysis results for heterogeneous debris samples may be highly variable due to inhomogenities in materials present

Analyzed by: David Roderick

*NAD/NSD = no asbestos detected; NA = not analyzed; NA/PS = not analyzed / positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NYLAP Lab #200546-0) and ELAP PLM Analysis Protocol 198.1 for New York samples (NYSDOH ELAP Lab # 11480); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-fibrous organically bound materials. TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 3/1/94). National Institute of Standards and Technology Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested. AIHA# 102843; VT Cert# AL016055

Reviewed By: _____