

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 1 of 2

TIME 3:00 pm

LOCATION PS 89 M

DATE 12/16/01

PROJECT NO. _____

Location	Occup.	Wind Direction	Sulfur Dioxide	Hydrogen Sulfide	Nitric Oxide	Nitrogen Dioxide
Play ground		N → S	0.0	0.0	0.0	0.2
Hallway by cafeteria			0.0	0.0	0.0	0.2
Room 202			0.0	0.0	0.0	0.1
Roof by the intake		N → S	0.0	0.0	0.0	0.3

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.

Signature: _____ Date: _____

ATC ASSOCIATES, INC.

Page 2 of 2TIME 3:00 pm

INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 89MDATE 12/16/01 PROJECT NO. _____

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
Play ground		43.6	27.1	360	2	21	0.0
Hallway by cafeteria		66.4	25.5	375	0	20	0.0
Room 202		66.0	24.9	369	1	22	0.0
Roof by the intake		42.2	29.1	358	3	13	0.0
Guideline levels ASIRAE/AIHA/EPA		68 -75°F/winter 73 -79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.

Signature: _____ Date: _____

ATC ASSOCIATES, INC.

Page 2 of 2

TIME 3:00 pm

INDOOR AIR QUALITY FIELD REPORT

LOCATION PS 89M

DATE 12/16/01

PROJECT NO. _____

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates(ug/m ³)	TVOCs (ppm)
Play ground		43.6	27.1	360	2	21	0.0
Hallway by cafeteria		66.4	25.5	375	0	20	0.0
Room 202		66.0	24.9	369	1	22	0.0
Roof by the intake		42.2	29.1	358	3	13	0.0
Guideline levels ASIRAE/AIHA/EPA		68 -75°F/winter 73 -79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.

Signature: _____ Date: _____