

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT


Page 1 of 4

LOCATION 17th floor. 40 Recto DATE 10/1/01 PROJECT NO. 15-19855-0001-

Location	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
Outdoors	63.1	45.4	368	0.0	35	0.0
17th floor SE corner	76.9	42.0	411	0.0	22	0.0
SE corner	78.4	38.0	380	0.0	27	0.0
Hallway South	78.0	36.8	419	0.0	21	0.0
NE corner	77.9	33.9	378	0.0	21	0.0
office space middle	77.5	33.1	387	0.0	20	0.0
NW corner	78.3	33.4	381	0.0	21	0.0
Middle of office area	78.5	33.2	389	0.0	22	0.0
17th floor security office	78.2	32.1	363	0.0	20	0.0
Hallway 17th floor	78.5	34.1	325	0.0	20	0.0
Guideline levels ASHRAE/AIHA	69 - 76°F/winter 73-78.5°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	50 ug/m ³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature:  Date: 10/1/01

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 2 of 4

LOCATION 15th floor 40 Rector st. DATE 10/01/01 PROJECT NO. 15 - 19855-0001

Location	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates(ug/m ³)	TVOCs (ppm)
Suite 1510				0.0	19	0.0
Conference Room		AC not working		0.1	17	0.0
NW area offices				0.0	15	0.0
Middle of the suite				0.0	16	0.0
Suite 1504	No access					
1500 front deck				0.0	21	0.0
Hallway middle		AC not working		0.0	22	0.0
Library				2.0	23	0.0
Hallway 15th floor				1.0	20	0.0
15th floor lobby				1.0	20	0.0
Guideline levels ASHRAE/AIHA	69 - 76°F/winter 73-78.5°F/summer	30-60%	Indoor level + 750 ppm	9 ppm	50 ug/m ³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: _____ Date: 10/1/01

ATC ASSOCIATES, INC. **INDOOR AIR QUALITY FIELD REPORT**

Page 3 of 11

LOCATION 14th floor. DATE 10/1/01 PROJECT NO. 19855 - 0001


Location	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates(ug/m ³)	TVOCs (ppm)
Advest North				1.0	19	0.0
Middle				1.0	20	0.0
Hallway back				1.0	20	0.0
South front desk				1.0	19	0.0
West				1.0	19	0.0
EAST conference room				2.0	19	0.0
Suite 1403 west				2.0	23	0.0
EAST				2.0	25	0.0
Advest Inc 1406A				1.0	23	0.0
Guideline levels ASHRAE/AIHA	69 - 76°F/winter 73-78.5°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	50 ug/m ³	1 ppm

not working

AC

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature:  Date: 10/1/01

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 4 of 4

LOCATION 12th floor. DATE 10/1/01 PROJECT NO. 19855-0001

No access

Location	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
Guideline levels ASHRAE/AIHA	69 – 76°F/winter 73-78.5°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	50 ug/m ³	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.

Signature: _____ Date: 10/1/01

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 5 of 44

LOCATION 11th floor. DATE 10/01/01 PROJECT NO. 19855-0001

Location	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
U.S. clearing Corp. main entrance				2.0	12	0.0
West wing.				2.0	14	0.0
N West				2.0	13	0.0
N East wing				2.0	10	0.0
FCIA Management offices				2.0	21	0.0
middle of E. office area				1.0	22	0.0
West corner				1.0	22	0.0
N East				1.0	19	0.0
Hallway by bathroom				1.0	20	0.0
Elevator lobby.				1.0	16	0.0
Guideline levels ASHRAE/AIHA	69 - 76°F/winter 73-78.5°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	50 ug/m ³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 10/01/01

ATC ASSOCIATES, INC. INDOOR AIR QUALITY FIELD REPORT

Page 6 of 11

LOCATION 7th floor DATE 10/01/01 PROJECT NO. 19855-0001

Location	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
NYC EAP Room 745 Main Entrance				1.0	17	0.0
middle of offices				1.0	18	0.0
NE office area				1.0	16	0.0
middle of west office area				1.0	15	0.0
NYC EAP main Entrance				1.0	16	0.0
office of collective bargaining main Entrance				0.0	21	0.0
West wing middle				0.0	17	0.0
E side hallway				0.0	21	0.0
South middle office area				0.0	20	0.0
South East wing				0.0	21	0.0
Guideline levels ASHRAE/AIHA	69 - 76°F/winter 73-78.5°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	50 ug/m ³	1 ppm

AC Not Working

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 10/01/01

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 7 of 7

LOCATION 6th floor DATE 10/01/01 PROJECT NO. 19855-0001

Location	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
Heating Room F				0.0	18	0.0
Heating Room E				1.0	19	0.0
Interview Room 2				1.0	18	0.0
Waiting Room				1.0	16	0.0
Administrative ^{Ray} Low	Smoke odor detected.			1.0	25	0.0
Suzanne P. Christen	"	" "		1.0	26	0.0
West side Hallway	"	" "		1.0	26	0.0
South west side	"	" "		1.0	23	0.0
North East wing middle	"	" "		1.0	23	0.0
Library	"	" "		1.0	25	0.0
Guideline levels ASHRAE/AIHA	69 - 76°F/winter 73-78.5°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	50 ug/m ³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: _____

Date: 10/01/01

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT


Page 8 of 11

LOCATION 5th floor DATE 10/01/01 PROJECT NO. 19855-0001

Location	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
NEast wing	strong smoke odor detected			0.0	27	0.0
NEast office area				0.0	11	0.0
NWest office area	strong smoke odor detected			1.0	24	0.0
middle of office area NW	"	"	"	1.0	29	0.0
South East Hallway	"	"	"	1.0	28	0.0
TLC Main dest				1.0	34	0.0
South west wing Hallway				1.0	28	0.0
SW office area	"	"	"	1.0	28	0.0
Middle Hallway				1.0	29	0.0
North sides middle Entrance	"	"	"	1.0	32	0.0
Guideline levels ASHRAE/AIHA	69 - 76°F/winter 73-78.5°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	50 ug/m ³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature:  Date: 10/01/01

ATC ASSOCIATES, INC. **INDOOR AIR QUALITY FIELD REPORT**


Page 9 of 11

LOCATION 4th DATE 10/01/01 PROJECT NO. 19855-0001

Location	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
North wing conference room C				1.0	25	0.0
NE side corner				1.0	26	0.0
N side Hallway				1.0	26	0.0
Library				1.0	27	0.0
NW office area				1.0	27	0.0
NW corner	strong smoke odor detected			1.0	27	0.0
NW Hallway				1.0	25	0.0
SW area offices				1.0	28	0.0
SW corner				1.0	25	0.0
SE middle of office area	smoke odor detected.			1.0	26	0.0
Guideline levels ASHRAE/AIHA	69 - 76°F/winter 73-78.5°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	50 ug/m ³	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.

Signature:  Date: 10/01/01

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT


Page 2 of 4

LOCATION 3rd DATE 10/01/01 PROJECT NO. 19855-0001

Location	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
NE Corner ^{NE}				1.0	24	0.0
NE office area ^{NE}				1.0	24	0.0
NW office area				1.0	27	0.0
NW Hallway	Smoke odor detected			1.0	28	0.0
NW Corner	u	u u		1.0	28	0.0
SW Corner	u	u u		1.0	27	0.0
South main Entrance	u	u u		1.0	26	0.0
SE office area	u	u u		1.0	27	0.0
SE office area middle	u	u u		1.0	26	0.0
Hallway East	u	u u		1.0	26	0.0
Guideline levels ASHRAE/AIHA	69 - 76°F/winter 73-78.5°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	50 ug/m ³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature:  Date: 10/01/01

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT


Page 11 of 11

LOCATION 2nd DATE 10/01/01 PROJECT NO. 19855-0601

Location	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
NE Corner				1.0	27	0.0
NE office space middle	smoke odor detected			1.0	27	0.0
NW corner	~	~ ~		1.0	27	0.0
NW Hallway	~	~ ~		1.0	28	0.0
N Main Entrance				1.0	27	0.0
SW Corner				1.0	26	0.0
S main Entrance	~	~ ~		1.0	28	0.0
S Hallway	~	~ ~		1.0	26	0.0
SE Corner	~	~ ~	~	1.0	27	0.0
SE middle of office area				1.0	28	0.0
Guideline levels ASHRAE/AIHA	69 - 76°F/winter 73-78.5°F/summer	30-60%	Outdoor level + 100 ppm	9 ppm	50 ug/m ³	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature:  Date: 10/01/01