

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:

EMSL

Attn: U.S. EPA - Residential
HQ Financial Services Division
1200 Pennsylvania Ave. NW Maildrop 2734R
Washington, DC 20460

Fax: Phone:
Project: USPHS MISSION #12 Residential Sampling Bldg
12/333 Pearl St

Customer ID: USEPA44
Customer PO:
Received: 11/20/01 7:36 PM
EMSL Order: 030108402
EMSL Project ID:
Analysis Date: 11/21/01

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Treatment	Non-Asbestos		Asbestos
				% Fibrous	% Non-Fibrous	% Type
{R}VA-C-12 030108402-0001	COMMON AREA	Tan/Black Non-Fibrous Heterogeneous	Teased Dissolved	3.00% Cellulose	97.00% Non-fibrous (other)	None Detected
{R}VA-R1-12 030108402-0002	RESIDENCE 1	Gray Fibrous Heterogeneous	Teased Dissolved	5.00% Glass 40.00% Cellulose	55.00% Non-fibrous (other)	None Detected
{R}VA-R2-12 030108402-0003	RESIDENCE 2	Gray Fibrous Heterogeneous	Teased Dissolved	5.00% Glass 40.00% Cellulose	55.00% Non-fibrous (other)	None Detected

Dan Osborne

Analyst



Laboratory Manager
or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.

Analysis performed by EMSL Manhattan (NVLAP #101048-9), NY ELAP 11505

PLM Point Count-1

1

CONFIDENTIAL,

CITY_21MC100_003434120

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008