

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0061 Fax: 212-290-0058 Email:

EMSL

Attn: U.S. EPA - Residential
 HQ Financial Services Division
 1200 Pennsylvania Ave. NW Maildrop 2734R
 Washington, DC 20460

Customer ID: USEPA44
 Customer PO: 2W-1103-NNLX
 Received: 11/27/01 6:09 PM

Fax: Phone:
 Project: USPHS MISSION #12: RESIDENTIAL SAMPLING NEW
 YORK CITY / BLDG #18 / 36 NORTH MOORE STREET

EMSL Order: 030108712

EMSL Project ID:

Analysis Date: 11/29/01

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Treatment	Non-Asbestos		Asbestos
				% Fibrous	% Non-Fibrous	% Type
(R)A-O-19 030108712-0001	OUTDOORS	Black Fibrous Heterogeneous	Teased Dissolved	5.00% Synthetic 4.00% Cellulose	91.00% Non-fibrous (other)	None Detected
(R)VA-C-19 030108712-0002	COMMON AREA	Tan Fibrous Heterogeneous	Teased Dissolved	7.00% Synthetic 5.00% Cellulose	88.00% Non-fibrous (other)	None Detected
(R)VA-R1-19 030108712-0003	RESIDENCE 1	Gray Fibrous Heterogeneous	Teased Dissolved	30.00% Synthetic 15.00% Cellulose	55.00% Non-fibrous (other)	None Detected
(R)VA-R2-19 030108712-0004	RESIDENCE 2	Gray Fibrous Heterogeneous	Teased Dissolved	40.00% Synthetic 10.00% Cellulose	50.00% Non-fibrous (other)	None Detected

Dan Osborne

Analyst

Laboratory Manager
 or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.
 Analytical performed by EMSL Manhattan (NVLAP #101048-B), NY ELAP 11506

PLM Point Count-1

1

CONFIDENTIAL,

CITY_21MC100_003434178

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008