

FEB. 11. 2002 9:46AM IATL

NO. 711 P. 14

IATL International Asbestos
Testing Laboratories

16000 Horizon Way Unit 100 Mt. Laurel, NJ 08054

Telephone: 856-231-9449 Fax: 856-231-9818

CERTIFICATE OF ANALYSIS**Client:** TRC Engineers, Inc.
134 West 29th Street, 11th Flr
New York, NY 10001**Report Date:** 12/31/2001
Project: NYC Law 100 Church St; 12-18-01
Project No.: 834345**TEM AIR SAMPLE ANALYSIS SUMMARY**


<u>Lab No</u>	<u>Client No.</u>	<u>Location</u>	<u>Volume</u>	<u>Result</u>	<u>Asbestos Types</u>
1403460	ASB-1218-5th-A36	Cube WS 5-147a	1200 Liters	<9.6 Fibers/mm2 <0.0031 Fibers/cc	None Detected
1403461	ASB-1218-5th-A37	Cube WS 5-153a	1200 Liters	<9.6 Fibers/mm2 <0.0031 Fibers/cc	None Detected
1403462	ASB-1218-5th-A38	Cube WS 5-162a	1200 Liters	<9.6 Fibers/mm2 <0.0031 Fibers/cc	None Detected
1403463	ASB-1218-5th-A39	Halfway Adjacent To Rm 5-169	1200 Liters	9.6 Fibers/mm2 0.0031 Fibers/cc	Actinolite
1403464	ASB-1218-5th-A40	Halfway Adjacent To Rm 5-208	1200 Liters	<9.6 Fibers/mm2 <0.0031 Fibers/cc	None Detected

Member AIHA Analysts Registry AIHA Lab No. 444 NIST-NVLAP No. 1165 NYS-DOH No. 11021

Methodology: NIOSH 7402

This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP or any agency of the U.S. government.


Analysis Performed By:



Craig A. Uska, AIAA-AAR 4681

Date: DEC 27 2001

Approved By:

Frank E. Eurenfeld, III
Laboratory Director

1603

FEB. 11. 2002 9:46AM



IATL

NO. 711

P. 15

IATL International Asbestos
Testing Laboratories16000 Horizon Way Unit 100 Mt. Laurel, NJ 08054
Telephone: 856-231-9449 Fax: 856-231-9818**CERTIFICATE OF ANALYSIS****Client:** TRC Engineers, Inc.
134 West 29th Street, 11th Flr
New York, NY 10001**Report Date:** 12/31/2001
Project: NYC Law 100 Church St; 12-18-01
Project No.: 834345**TEM AIR SAMPLE ANALYSIS SUMMARY**

<u>Lab No</u>	<u>Client No.</u>	<u>Location</u>	<u>Volume</u>	<u>Result</u>	<u>Asbestos Types</u>
1403465	ASB-1218-6th-A41	SW Hallway Near Rm 6-100	1300 Liters	<9.6 Fibers/mm2 <0.0028 Fibers/cc	None Detected
1403466	ASB-1218-6th-A42	Cube WS-6-110a	1300 Liters	<9.6 Fibers/mm2 <0.0028 Fibers/cc	None Detected
1403467	ASB-1218-6th-A43	Office Rm 6-139	1300 Liters	<9.6 Fibers/mm2 <0.0028 Fibers/cc	None Detected
1403468	ASB-1218-6th-A44	Office Rm 6-151	1300 Liters	<9.6 Fibers/mm2 <0.0028 Fibers/cc	None Detected
1403469	ASB-1218-6th-A45	Office Rm 6-168	1300 Liters	<9.6 Fibers/mm2 <0.0028 Fibers/cc	None Detected

Member AIHA Analysts Registry AIHA Lab No. 444 NIST-NVLAP No. 1165 NYS-DOH No. 11021**Methodology: NIOSH 7402***This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP or any agency of the U.S. government.***Analysis Performed By:** **Date:** DEC 27 2001 **Graciela Manjarres N., AIHA-AAR 4029****Approved By:** **Frank E. Ehrenfeld, III**
Laboratory Director

1604

FEB. 11. 2002 9:47AM

IATL

NO. 711

P. 16

IATL International Asbestos
Testing Laboratories

16000 Horizon Way Unit 100 Mt. Laurel, NJ 08054

Telephone: 856-231-9449 Fax: 856-231-9818

CERTIFICATE OF ANALYSIS

Client: TRC Engineers, Inc.
134 West 29th Street, 11th Flr
New York, NY 10001

Report Date: 12/31/2001
Project: NYC Law 100 Church St; 12-18-01
Project No.: 834345

TEM AIR SAMPLE ANALYSIS SUMMARY

<u>Lab No</u>	<u>Client No.</u>	<u>Location</u>	<u>Volume</u>	<u>Result</u>	<u>Asbestos Types</u>
1403470	ASB-1218-6th-A46	Office Rm 6-177	1300 Liters	<9.6 Fibers/mm2 <0.0028 Fibers/cc	None Detected
1403471	ASB-1218-6th-A47	Cube WS 6-207a	1300 Liters	<9.6 Fibers/mm2 <0.0028 Fibers/cc	None Detected
1403472	ASB-1218-6th-A48	Sample Invalid	1300 Liters	<9.6 Fibers/mm2 <0.0028 Fibers/cc	None Detected
1403473	ASB-1218-6th-A49	Adjacent To Rm 6-238	1300 Liters	9.6 Fibers/mm2 0.0028 Fibers/cc	Chrysotile
1403474	ASB-1218-6th-A50	Rm 6-100a	1300 Liters	<9.6 Fibers/mm2 <0.0028 Fibers/cc	None Detected

Member AIHA Analysts Registry AIHA Lab No. 444 NIST-NVLAP No. 1165 NYS-DOH No. 11021

Methodology: NIOSH 7402

This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP or any agency of the U.S. government.

Analysis Performed By:

Graciela Manjarres M.

Graciela Manjarres M., AIHA-AAR 4029

Date: DEC 27 2001

Approved By:

Frank E. Ehrenfeld, III

Frank E. Ehrenfeld, III
Laboratory Director

1605

FEB. 11. 2002 9:47AM

IATL

NO. 711 P. 17

IATL International Asbestos
Testing Laboratories

16000 Horizon Way Unit 100 Mt. Laurel, NY 08054

Telephone: 856-231-9449 Fax: 856-231-9818

CERTIFICATE OF ANALYSIS**Client:** TRC Engineers, Inc.
134 West 29th Street, 11th Flr
New York, NY 10001**Report Date:** 12/31/2001
Project: NYC Law 100 Church St, 12-18-01
Project No.: 834345**TEM AIR SAMPLE ANALYSIS SUMMARY**

<u>Lab No</u>	<u>Client No.</u>	<u>Location</u>	<u>Volume</u>	<u>Result</u>	<u>Asbestos Types</u>
1403475	ASB-1218-20th-A51	NW Corner	1250 Liters	<9.6 Fibers/mm2 <0.0030 Fibers/cc	None Detected
1403476	ASB-1218-20th-A52	W Hallway Center	1250 Liters	19.2 Fibers/mm2 0.0060 Fibers/cc	Chrysotile
1403477	ASB-1218-20th-A53	SW Corner	1250 Liters	19.2 Fibers/mm2 0.0060 Fibers/cc	Amosite
1403478	ASB-1218-20th-A54	S-Wall	1250 Liters	<9.6 Fibers/mm2 <0.0030 Fibers/cc	None Detected
1403479	ASB-1218-20th-A55	S-Wall Linda Werbel	1250 Liters	<9.6 Fibers/mm2 <0.0030 Fibers/cc	None Detected

Member AIHA Analysts Registry AIHA Lab No. 444 NIST-NVLAP No. 1165 NYS-DOH No. 11021

Methodology: NIOSH 7402

This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP or any agency of the U.S. government.

Analysis Performed By:

Graciela Manjarres H.

Date: DEC 27 2001

Graciela Manjarres H., AIHA-AAR 4029

Approved By:

*Frank E. Ehrenfeld, III*Frank E. Ehrenfeld, III
Laboratory Director

1606

FEB. 11. 2002 9:47AM

IATL

NO. 711 P. 18

IATL International Asbestos
Testing Laboratories

16000 Horizon Way Unit 100 Mt. Laurel, NJ 08054

Telephone: 856-231-9449 Fax: 856-231-9818

CERTIFICATE OF ANALYSIS**Client:** TRC Engineers, Inc.
134 West 29th Street, 11th Flr
New York, NY 10001**Report Date:** 12/31/2001
Project: NYC Law 100 Church St, 12-18-01
Project No.: 834345**TEM AIR SAMPLE ANALYSIS SUMMARY**

<u>Lab No</u>	<u>Client No.</u>	<u>Location</u>	<u>Volume</u>	<u>Result</u>	<u>Asbestos Types</u>
1403480	ASB-1218-20th-A56	S-Wall Luis Torres	1250 Liters	<9.6 Fibers/mm2 <0.0030 Fibers/cc	None Detected
1403481	ASB-1218-20th-A57	SE-Corner	1250 Liters	<9.6 Fibers/mm2 <0.0031 Fibers/cc	None Detected
1403482	ASB-1218-20th-A58	E-Wall	1250 Liters	9.6 Fibers/mm2 0.0030 Fibers/cc	Chrysotile
1403483	ASB-1218-20th-A59	NE Corner Near H2O Fountain	1250 Liters	<9.6 Fibers/mm2 <0.0030 Fibers/cc	None Detected
1403484	ASB-1218-20th-A60	N Center Hall Near Elevator	1250 Liters	<9.6 Fibers/mm2 <0.0030 Fibers/cc	None Detected

Member AIHA Analysts Registry AIHA Lab No. 444 NIST-NVLAP No. 1165 NYS-DOH No. 11021

Methodology: NIOSH 7402

This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP or any agency of the U.S. government.


Analysis Performed By:



Craig A. Uska, AIHA-AAR 4881

Date: DEC 27 2001

Approved By:

Frank E. Shrenfeld, III
Laboratory Director


1607

FEB. 11. 2002 9:47AM IATL

NO. 711 P. 19

IATL International Asbestos
Testing Laboratories16000 Horizon Way Unit 100 Mt. Laurel, NJ 08054
Telephone: 856-231-9449 Fax: 856-231-9818**CERTIFICATE OF ANALYSIS****Client:** TRC Engineers, Inc.
134 West 29th Street, 11th Flr
New York, NY 10001**Report Date:** 12/31/2001
Project: NYC Law 100 Church St; 12-18-01
Project No.: 834345**TEM AIR SAMPLE ANALYSIS SUMMARY**

<u>Lab No</u>	<u>Client No.</u>	<u>Location</u>	<u>Volume</u>	<u>Result</u>	<u>Asbestos Types</u>
1403485	ASB-1218-FB-A61	Field Blank	Blank Liters	<9.6 Fibers/mm2 Blank Fibers/cc	None Detected
1403486	ASB-1218-FB-A62	Field Blank	Blank Liters	<9.6 Fibers/mm2 Blank Fibers/cc	None Detected
1403487	ASB-1218-FB-A63	Field Blank	Blank Liters	<9.6 Fibers/mm2 Blank Fibers/cc	None Detected
1403488	ASB-1218-FB-A64	Field Blank	Blank Liters	<9.6 Fibers/mm2 Blank Fibers/cc	None Detected
1403489	ASB-1218-FB-A65	Field Blank	Blank Liters	<9.6 Fibers/mm2 Blank Fibers/cc	None Detected

Member AIHA Analysts Registry AIHA Lab No. 444 NIST-NVLAP No. 1165 - NYS-DOH No. 11021**Methodology: NIOSH 7402***This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP or any agency of the U.S. government.***Analysis Performed By:**
Craig A. Liska, AIHA-AAR 4581**Approved By:**
Frank E. Ehrenfeld, III
Laboratory Director**Date:** DEC 27 2001

1608