

EMSL Analytical, Inc.

307 West 38th Street, New York, NY 10018

Phone: (212) 290-0051 Fax: (212) 290-0058 Email: manhattanlab@emsl.com**EMSL**

Attn: **TRC Environmental Consultants**
1430 Broadway, 10th Floor
New York, NY 10018

Fax: (212) 221-7840 Phone: (212) 221-7822

Project: **NEW YORK CITY LAW DEPARTMENT/ 100 CHURCH STREET, 6TH FLOOR RENOVATION**

Customer ID: **TRCE51**
 Customer PO:
 Received: **03/11/05 5:19 PM**
 EMSL Order: **030506590**
 EMSL Proj:
 Analysis Date: **3/13/2005**
 Report Date: **3/14/2005**

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
7 030506590-0010	DEBRIS BETWEEN WALLS 6TH FLOOR COPY ROOM	Brown/White Fibrous Heterogeneous	2.00% Glass 5.00% Cellulose	13.00% Non-fibrous (other) 80.00% Gypsum	None Detected
8 030506590-0011	DEBRIS BETWEEN WALLS 6TH FLOOR COPY ROOM	White Fibrous Heterogeneous	2.00% Glass 3.00% Cellulose	15.00% Non-fibrous (other) 80.00% Gypsum	None Detected
9 030506590-0012	DEBRIS BETWEEN WALLS 6TH FLOOR COPY ROOM	Brown/White Fibrous Heterogeneous	2.00% Glass 5.00% Cellulose	13.00% Non-fibrous (other) 80.00% Gypsum	None Detected
13 030506590-0013	DEBRIS BETWEEN WALLS 6TH FLOOR LIBRARY	Brown/White Fibrous Heterogeneous	1.00% Glass 20.00% Cellulose	19.00% Non-fibrous (other) 60.00% Gypsum	None Detected
14 030506590-0014	DEBRIS BETWEEN WALLS 6TH FLOOR LIBRARY	Brown/White Fibrous Heterogeneous	2.00% Glass 25.00% Cellulose	18.00% Non-fibrous (other) 55.00% Gypsum	None Detected
15 030506590-0015	DEBRIS BETWEEN WALLS 6TH FLOOR LIBRARY	Brown/Gray Fibrous Heterogeneous	2.00% Glass 10.00% Cellulose	23.00% Non-fibrous (other) 65.00% Gypsum	None Detected

Analyst(s)

Alex Chechelovski (6)



Jose Arriaga
 or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.

Analysis performed by EMSL Manhattan (NVLAP #101048-9), NY ELAP 11508

PLMPointCount-1

THIS IS THE LAST PAGE OF THE REPORT.

1

CITY_21MC100_014584978