

**EMSL Analytical, Inc.**

307 West 38th Street, New York, NY 10018

Phone: (212) 290-0051 Fax: (212) 290-0058 Email: manhattanlab@emsl.com

**EMSL**Attn: TRC Environmental Consultants  
1430 Broadway  
10th Floor  
New York, NY 10018

Fax: (212) 221-7840

Phone: (212) 221-7822

Project: 35052-0000-00020 / New York City Law Department / 100  
Church St. 4th Floor Server Room

Customer ID: TRCE51

Customer PO:

Received: 07/17/03 3:08 PM

EMSL Order: 030313033

EMSL Project ID:


Analysis Date: 7/18/03

**Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by  
EPA 40 CFR Part 763 Final Rule (AHERA)**

| Sample                                 | Volume<br>(Liters) | Area<br>Analyzed<br>(mm <sup>2</sup> ) | Non<br>Asb | Asbestos<br>Type(s) | # Structures  |          | Analytical<br>Sensitivity<br>(S/cc) | Asbestos<br>Concentration |         | Notes |
|----------------------------------------|--------------------|----------------------------------------|------------|---------------------|---------------|----------|-------------------------------------|---------------------------|---------|-------|
|                                        |                    |                                        |            |                     | $\geq 0.5\mu$ | $< 5\mu$ |                                     | (S/mm <sup>2</sup> )      | (S/cc)  |       |
| NA071703ASBAI<br>R01<br>030313033-0001 | 1350.00            | 0.0600                                 | 0          | None Detected       |               |          | 0.0048                              | <16.67                    | <0.0048 |       |
| NA071703ASBAI<br>R02<br>030313033-0002 | 1341.00            | 0.0600                                 | 0          | None Detected       |               |          | 0.0048                              | <16.67                    | <0.0048 |       |

Analyst(s)

Jose Arriaga (2)

Laboratory Manager  
or other approved signatory

Disclaimers: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm<sup>2</sup>. This report may not be reproduced, except in full, without written approval by EMSL. This report must not be used to claim product endorsement. As per 40 CFR 763, the initial screening test may not be applied to samples with collected volumes of <1200 liters.

Accredited for NVLAP PLM/TEM #101048-9, NY State ELAP #11506

TEMAHERA-1

**THIS IS THE LAST PAGE OF THE REPORT.**

1