

Asbestos Inspection Report

Premise No. 130 Liberty Street					Inspection Date: 07/31/08	
Floor Various	Zip 10006	Borough 1	Block 54	Lot 1	Squad # 1	Badge # AO61
Inspector H. Guirguis		Building Type A		Basis of Inspection TRU0086MN08		Photos Taken NO
Contractor's Name LVI Environmental				Sample Number -----		
Address City				Sample Number -----		
State Zip Phone				Sample Number -----		
Laboratory Name TRC Environmental Corp				Owner's Name The Lower Manhattan Development Corp.		
Address 1430 Broadway		City New York		Address One Liberty Plaza		City New York
State Zip NY 10018		Phone		State Zip NY 10006		Phone (212) 962-2300
Contact Person Arnel Javal, Sr. Proj. Mgr./TRC Environmental				Time of Inspection from: 5:00 pm – 6:00 pm		
<p>On arrival I met Victor, Supervisor for TRC Environmental at TRC field office, who informed me that a total of 1 Handler Supervisor and 18 Asbestos Handlers were on the 15th floor for the Second shift.</p> <p>The daily work schedule informed me of the following:</p> <ol style="list-style-type: none"> 1. 16th, 17th floors: 30 men (each) fine cleaning floors. 2. 14th & 15th floors: 18 men (each) loading out debris, scaffolds, etc. 3. 13th & 12th floors: 10 men (each) demo, boxing debris 4. Various floors: 12 men- Loading out boxes to ATC trailer <p>I went to the decontamination enclosure system on the 15th floor and after signing the log book, donned personal protection and accessed the work areas.</p> <ol style="list-style-type: none"> 1. The workers were found in the process of scraping and wrapping debris <ul style="list-style-type: none"> 8 workers on scaffolds, cleaning ceilings and beams 4 workers removing debris from ground 3 workers fine spraying amended water in the work area 3 workers preparing Gaylord boxes 5 Gaylord boxes on the floor ready to be taken out 2. Inspection was done on the Micro trap Machines and the Micro trap tents. 20 Micro trap Machines were powered on and 5 were on stand by 3. I observed that the primary filters for all micro trap machines were very dirty and needed to be replaced; the supervisor was advised and he replaced all the filters. 4. The negative Pressure was 0.071 <p>I exited the work area after decontaminating myself and signing the log book.</p>						
NOV #	Infraction	Infraction	Infraction	Infraction		
NOV #	Infraction	Infraction	Infraction	Infraction	Result Code 2	
NOV #	Infraction	Infraction	Infraction	Infraction	Supervisor's Initial 	

Borough 1=Manhattan 2=Bronx 3=Brooklyn 4=Queens 5=Richmond
 Building Type A ≥6 stories B <6 stories C single family D school E hospital F public owned
 Result Code 1 = Violation Issued 2=No Violation Issued 3=No access 4=Project not started (no NOV)
 5=Public Owned Property