

APPENDIX A
AIR SAMPLES ANALYZED BY
TRANSMISSION ELECTRON MICROSCOPY

Ambient Group, Inc.
10 Morris Avenue
Glen Cove 11542
(516) 609-0009

ELAP 10865

AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)

J. Resnick & Sons
Project Address: 75 Park Place
Project Number 211658

Field ID Number	Field Sheet	Lab Sample ID	Date	Time	Sample Location	Analytical Sensibility	Asbestos Structures/cm ³
2881-01	2881	AEM9900 11015	11/8/01	4:35 PM	10 th Floor\NE Side	<0.0045	LT ANYL SENS
2881-02	2881	AEM9900 11016	11/8/01	4:37 PM	10 th Floor\SE Side	<0.0045	LT ANYL SENS
2881-03	2881	AEM9900 11017	11/8/01	4:39 PM	10 th Floor\SW Side	<0.0045	LT ANYL SENS
2881-04	2881	AEM9900 11018	11/8/01	4:41 PM	10 th Floor\NW Side	<0.0045	LT ANYL SENS
2881-05	2881	AEM9900 11019	11/8/01	4:43 PM	10 th Floor\In Center	<0.0045	LT ANYL SENS
2880-01	2880	AEM9900 11000	11/8/01	11:02 AM	11 th Floor\NE Side	<0.0045	LT ANYL SENS
2880-02	2880	AEM9900 11001	11/8/01	11:04 AM	11 th Floor\SE Side	<0.0045	LT ANYL SENS
2880-03	2880	AEM9900 11002	11/8/01	11:06 AM	11 th Floor\SW Side	<0.0045	LT ANYL SENS
2880-04	2880	AEM9900 11003	11/8/01	11:08 AM	11 th Floor\NW Side	<0.0045	LT ANYL SENS

LT ANALY SENS = LESS THAN THE ANALYTICAL SENSITIVITY

CITY_21MC100_009894089

JAN-09-2002 12:39

A00

01311110111

05.51 0000 001101 P.04/25

Ambient Group, Inc.
10 Morris Avenue
Glen Cove 11542
(516) 609-0009

ELAP 10865

AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)

J. Resnick & Sons
Project Address: 75 Park Place
Project Number 211658

Field ID Number	Field Sheet	Lab Sample ID	Date	Time	Sample Location	Analytical Sensibility	Asbestos Structures/cm ³
2880-05	2880	AEM9900 11004	11/8/01	11:10 AM	11 th Floor/In Center	<0.0045	LT ANYL SENS

LT ANALY SENS = LESS THAN THE ANALYTICAL SENSITTIVITY

P.05/25

P.04

CITY_21MC100_009894090

98%

2129444618

JAN-09-2002 12:39

JAN-07-2002 16:00

Ambient Group, Inc.
10 Morris Avenue
Glen Cove 11542
(516) 609-0009

ELAP 10865

AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)

J. Resnick & Sons
Project Address: 75 Park Place
Project Number 211658

Field ID Number	Field Sheet	Lab Sample ID	Date	Time	Sample Location	Analytical Sensibility	Asbestos Structures/cm ³
81781-01	81781	AEM9900 11217	11/17/01	8:10 AM	Lobby entrance on top of scaffold	<0.0047	LT ANYL SENS
81781-02	81781	AEM9900 11218	11/17/01	8:14 AM	Lobby: adj. to passenger elevators	<0.0047	LT ANYL SENS
81781-03	81781	AEM9900 11219	11/17/01	8:20 AM	Loading dock: adj. to ramp	<0.0043	LT ANYL SENS
81781-04	81781	AEM9900 11220	11/17/01	8:25 AM	Loading dock: adj. to ramp	<0.0043	LT ANYL SENS

LT ANALY SENS = LESS THAN THE ANALYTICAL SENSITIVITY

P.05

97%

2129444618

JAN-07-2002 16:00

CITY_21MC100_009894091

P.06/25

JAN-09-2002 12:39

JAN-09-2002 12:39

P.07/25

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)

Client: Jack Resnick & Sons, Inc.

Address: 75 Park Place

Project ID: 211658

Field ID Number	Sample ID	Date	Time	FloorSample Location Description	Analytical Sensitivity	Asbestos Structures/c
5790-01	11918	12/5/01	11:30 AM	1st Floor: Lobby at Security Desk	LT ANYL SENS	< 0.0045
5790-02	11919	12/5/01	11:31 AM	1st Floor: Lobby Adj. to Passenger Elevators	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

JAN-07-2002 16:00

2129444618

98%

P.06

CITY_21MC100_009894092

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)

Client: Jack Resnick & Sons, Inc.

Address: 75 Park Place

Project ID: 211658

Field ID Number	Sample ID	Date	Time	Floor Sample Location Description	Analytical Sensitivity	Asbestos Structures/c
5788-01	11901	12/5/01	11:38 AM	2nd Floor: Corridor adj. to Electrical Closet	LT ANYL SENS	< 0.0045
5788-02	11902	12/5/01	11:40 AM	2nd Floor: Office Area Adj. to Sue Tidswell's Office	LT ANYL SENS	< 0.045
5788-03	11903	12/5/01	11:42 AM	2nd Floor: Office Area adj. to J. Cosgriff Office	LT ANYL SENS	< 0.0045
5788-04	11904	12/5/01	1:44 AM	2nd Floor: Donnelley, adj. to D. Morosky Office	LT ANYL SENS	< 0.0045
5788-05	11905	12/5/01	11:48 AM	2nd Floor: Donnelley Services Reception Area	LT ANYL SENS	< 0.0045
5784-06	11906	12/5/01	11:46 AM	2nd Floor: Vacant Office Space	LT ANYL SENS	< 0.0045
5784-07	11907	12/5/01	11:50 AM	2nd Floor: Donnelley Training Room	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

**AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)**

Client: Jack Resnick & Sons, Inc.

Address: 75 Park Place

Project ID: 211658

Field ID Number	Sample ID	Date	Time	Floor Sample Location Description	Analytical Sensitivity	Asbestos Structures/c
4043-01	11868	12/5/01	3:00 PM	3rd Floor: Reception Area	LT ANYL SENS	< 0.0045
4043-02	11869	12/5/01	3:02 PM	3rd Floor: Recreation Area Opposite Soda Machine	LT ANYL SENS	< 0.0045
4043-03	11870	12/5/01	3:04 PM	3rd Floor: Corridor Opposite Conf. Room "D"	LT ANYL SENS	< 0.0045
4043-04	11871	12/5/01	3:06 PM	3rd Floor: Kitchen Area	LT ANYL SENS	< 0.0045
4043-05	11872	12/5/01	3:08 PM	3rd Floor: Office Area Opposite Conference Room (N)	LT ANYL SENS	< 0.0045
4045-06	11873	12/5/01	3:10 PM	3rd Floor: Corridor Opposite Mail Room	LT ANYL SENS	< 0.0045
4045-07	11874	12/5/01	3:12 PM	3rd Floor: Corridor Opposite Conference Room (H)	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)

Client: Jack Resnick & Sons, Inc.
Address: 75 Park Place
Project ID: 211658

Field ID Number	Sample ID	Date	Time	FloorSample Location Description	Analytical Sensitivity	Asbestos Structures/c
5787-01	11939	12/6/01	2:00 PM	6th Floor: Reception Area	LT ANYL SENS	< 0.0045
5787-02	11940	12/6/01	2:02 PM	6th Floor: Storage Room	LT ANYL SENS	< 0.0045
5787-03	11941	12/6/01	2:04 PM	6th Floor: East Side	LT ANYL SENS	< 0.0045
5787-04	11942	12/6/01	2:06 PM	6th Floor: North East Office Area	LT ANYL SENS	< 0.0045
5787-05	11943	12/6/01	2:08 PM	6th Floor: Office Area Adj. to Conference Room	LT ANYL SENS	< 0.0045
5786-06	11944	12/6/01	2:10 PM	6th Floor: In Small Conference Room	LT ANYL SENS	< 0.0045
5786-07	11945	12/6/01	2:12 PM	6th Floor: West Side Opposite Pantry	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10855

AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)

Client: Jack Resnick & Sons, Inc.

Address: 75 Park Place

Project ID: 211658

Field ID Number	Sample ID	Date	Time	FloorSample Location Description	Analytical Sensitivity	Asbestos Structures/c
5785-01	11908	12/6/01	8:50 AM	14th Floor: Reception Area	LT ANYL SENS	< 0.0045
5785-02	11909	12/6/01	8:52 AM	14th Floor: North Side Opposite Middle Window	LT ANYL SENS	< 0.0045
5785-03	11910	12/6/01	8:54 AM	14th Floor: West End Adj. to Window	LT ANYL SENS	< 0.0045
5785-04	11911	12/6/01	9:45 AM	12th Floor: Large Office Area	LT ANYL SENS	< 0.0045
5785-05	11912	12/6/01	9:47 AM	12th Floor: Large Office Area	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

JAN-09-2002 12:40

P.12/25

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)

Client: Jack Resnick & Sons, Inc.

Address: 75 Park Place

Project ID: 211658

Field ID Number	Sample ID	Date	Time	Floor Sample Location Description	Analytical Sensitivity	Asbestos Structures/c
4073-01	11913	12/6/01	9:49 AM	12th Floor: Large Office Space	LT ANYL SENS	< 0.0045
4073-02	11914	12/6/01	9:51 AM	12th Floor: East Office Suite	LT ANYL SENS	< 0.0045
4073-03	11915	12/6/01	9:53 AM	12th Floor: West Office Suite	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

JAN-07-2002 16:01

2129444618

98%

P.11

CITY_21MC100_009894097

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)

Client: Jack Resnick & Sons, Inc.
Address: 75 Park Place
Project ID: 211658

Field ID Number	Sample ID	Date	Time	Floor Sample Location Description	Analytical Sensitivity	Asbestos Structures/
4083-01	11889	12/7/01	1:14 PM	4th Floor: N.W. Office Area	LT ANYL SENS	< 0.0045
4083-02	11970	12/7/01	1:16 PM	4th Floor: Inside Computer Room	LT ANYL SENS	< 0.0045
4083-03	11971	12/7/01	1:18 PM	4th Floor: Computer Room	LT ANYL SENS	< 0.0045
4083-04	11972	12/7/01	1:20 PM	4th Floor: Entrance of Accountant Office	LT ANYL SENS	< 0.0045
4084-01	11973	12/7/01	10:14 AM	5th Floor: Opposite Computer Room	LT ANYL SENS	< 0.0045
4084-02	11974	12/7/01	10:16 AM	5th Floor: N.W. Corner Opposite Window	LT ANYL SENS	< 0.0045
4084-03	11975	12/7/01	1:08 PM	4th Floor: Reception Area	LT ANYL SENS	< 0.0045
4084-04	11976	12/7/01	1:10 PM	4th Floor North Tracing Floor	LT ANYL SENS	< 0.0045
4084-05	11977	12/7/01	1:12 PM	4th Floor Corridor	LT ANYL SENS	< 0.0045
4085-01	11978	12/7/01	10:04 AM	5th Floor: Reception Area City Council	LT ANYL SENS	< 0.0045
4085-02	11979	12/7/01	10:06 AM	5th Floor: Southside Multex Com.	LT ANYL SENS	< 0.0045
4085-03	11980	12/7/01	10:08 AM	5th Floor: South East Corner	LT ANYL SENS	< 0.0045
4085-04	11981	12/7/01	10:10 AM	5th Floor: City C Storage Room	LT ANYL SENS	< 0.0045
4085-05	11982	12/7/01	10:12 AM	5th Floor: N.W. Corner Opposite R. Weinberg Office	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

JAN-09-2002 12:40

P.14/25

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)

Client: Jack Resnick & Sons, Inc.

Address: 75 Park Place

Project ID: 211658

Field ID Number	Sample ID	Date	Time	Floor/ Sample Location Description	Analytical Sensitivity	Asbestos Structures/
4055-01	11976	12/10/01	10:47 AM	11th Floor: South Side	LT ANYL SENS	< 0.0045
4055-02	11977	12/10/01	10:48 AM	11th Floor: North Side	LT ANYL SENS	< 0.0045
4055-03	11978	12/10/01	10:49 AM	11th Floor: Central Area	LT ANYL SENS	< 0.0045
4055-04	11979	12/10/01	10:50 AM	11th Floor: East Side	LT ANYL SENS	< 0.0045
4055-05	11980	12/10/01	10:51 AM	11th Floor: West Side	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

JAN-07-2002 16:01

2129444618

96%

P.13

CITY_21MC100_009894099

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

**AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)**

Client: Jack Resnick & Sons, Inc.

Address: 75 Park Place

Project ID: 211658

Field ID Number	Sample ID	Date	Time	FloorSample Location Description	Analytical Sensitivity	Asbestos Structures/
4056-01	11981	12/10/01	10:52 AM	11th Floor: Elevator Lobby	LT ANYL SENS	< 0.0045
4056-02	11982	12/10/01	10:53 AM	11th Floor: South West Section	LT ANYL SENS	< 0.0045
4056-03	11983	12/10/01	1:20 PM	10th Floor: Central Area	LT ANYL SENS	< 0.0045
4056-04	11984	12/10/01	1:22 PM	10th Floor: West End	LT ANYL SENS	< 0.0045
4056-05	11985	12/10/01	1:24 PM	10th Floor: Central Area	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

**AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)**

Client: Jack Resnick & Sons, Inc.

Address: 75 Park Place

Project ID: 211658

Field ID Number	Sample ID	Date	Time	Floor	Sample Location Description	Analytical Sensitivity	Asbestos Structures/
4057-01	11986	12/10/01	1:26 PM	10th Floor	South East Corner	LT ANYL SENS	< 0.0045
4057-02	11987	12/10/01	1:28 PM	10th Floor	North East Corner	LT ANYL SENS	< 0.0045
4057-03	11988	12/10/01	1:30 PM	10th Floor	South West Corner	LT ANYL SENS	< 0.0045
4057-04	11989	12/10/01	1:32 PM	10th Floor	North West Corner	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

JAN-09-2002 12:41

P.17/25

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)

Client: Jack Resnick & Sons, Inc.**Address:** 75 Park Place**Project ID:** 211658

Field ID Number	Sample ID	Date	Time	Floor/Sample Location Description	Analytical Sensitivity	Asbestos Structures/
4061-01	11990	12/10/01	5:30 PM	9th Floor: Reception Area	LT ANYL SENS	< 0.0045
4061-02	11991	12/10/01	5:33 PM	9th Floor: Opposite Window North Side	LT ANYL SENS	< 0.0045
4061-03	11992	12/10/01	5:36 PM	9th Floor: Opposite Window North West Corner	LT ANYL SENS	< 0.0045
4061-04	11993	12/10/01	5:39 PM	9th Floor: Corridor Opposite Stairwell X	LT ANYL SENS	< 0.0045
4061-05	11994	12/10/01	5:42 PM	9th Floor: Opposite Window North East Corner	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

JAN-07-2002 16:02

2129444618

98%

P.16

CITY_21MC100_009894102

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 608-0009

ELAP 10865

**AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)**

Client: Jack Resnick & Sons, Inc.

Address: 75 Park Place

Project ID: 211658

Field ID Number	Sample ID	Date	Time	Floor Sample Location Description	Analytical Sensitivity	Asbestos Structures/
4090-06	11995	12/10/01	5:45 PM	9th Floor: South East	LT ANYL SENS	< 0.0045
4090-07	11996	12/10/01	5:48 PM	9th Floor: S.V.I. Corner Inside Pantry	LT ANYL SENS	< 0.0045
4090-08	11997	12/10/01	8:40 PM	8th Floor: Reception Area	LT ANYL SENS	< 0.0045
4090-09	11998	12/10/01	8:43 PM	8th Floor: North Side Opposite Window	LT ANYL SENS	< 0.0045
4090-10	11999	12/10/01	8:46 PM	8th Floor: South East Opposite Computer Room	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)

Client: Jack Resnick & Sons, Inc.

Address: 75 Park Place

Project ID: 211658

Field ID Number	Sample ID	Date	Time	FloorSample Location Description	Analytical Sensitivity	Asbestos Structures/
4091-11	12000	12/10/01	8:49 PM	8th Floor: S.W. Corner Opposite Window	LT ANYL SENS	< 0.0045
4091-12	12001	12/10/01	8:52 PM	8th Floor: N.E. Adj. To Window	LT ANYL SENS	< 0.0045
4091-13	12002	12/10/01	8:55 PM	8th Floor: Central Area	LT ANYL SENS	< 0.0045
4091-14	12003	12/10/01	8:58 PM	8th Floor: S.W. Near Pantry	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)

Client: Jack Resnick & Sons, Inc.

Address: 75 Park Place

Project ID: 211658

Field ID Number	Sample ID	Date	Time	Floor/Sample Location Description	Analytical Sensitivity	Asbestos Structures/
4095-01	11969	12/11/01	8:50 AM	7th Floor Reception Area	LT ANYL SENS	<0.0045
4095-02	11970	12/11/01	8:52 AM	7th Floor: Opposite Exit Stairwell X	LT ANYL SENS	<0.0045
4095-03	11971	12/11/01	8:54 AM	7th Floor: Northside Adj. To Window	LT ANYL SENS	<0.0045
4095-04	11972	12/11/01	8:56 AM	7th Floor: South Side, Near Copy Area	LT ANYL SENS	<0.0045
4095-05	11973	12/11/01	8:58 AM	7th Floor: Near Pantry	LT ANYL SENS	<0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

**AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)**

Client: Jack Resnick & Sons, Inc.

Address: 75 Park Place

Project ID: 211658

Field ID Number	Sample ID	Date	Time	Floor Sample Location Description	Analytical Sensitivity	Asbestos Structures/
2174-06	11974	12/11/01	9:00 AM	7th Floor: South East Corner, Opposite Computer Room	LT ANYL SENS	< 0.0045
2174-07	11975	12/11/01	9:02 AM	7th Floor: North East Section	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

JAN-09-2002 12:42

P. 22/25

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)

Client: Jack Resnick & Sons, Inc.

Address: 75 Park Place

Project ID: 211658

Field ID Number	Sample ID	Date	Time	Floor/Sample Location Description	Analytical Sensitivity	Asbestos Structures/
84425-01	12158	12/13/01	9:05 AM	Southside, Basement Donnelley Print Shop	LT ANYL SENS	< 0.0045
84425-02	12159	12/13/01	9:52 AM	Basement Donnelley Print Shop	LT ANYL SENS	< 0.0045
84425-03	12160	12/13/01	9:54 AM	Basement Donnelley Print Shop	LT ANYL SENS	< 0.0045
84425-04	12161	12/13/01	9:56 AM	Basement Corridor	LT ANYL SENS	< 0.0045
84425-05	12162	12/13/01	9:58 AM	Basement Pump Room	LT ANYL SENS	< 0.0045
84425-06	12163	12/13/01	10:00 AM	Basement Steam Meter Room	LT ANYL SENS	< 0.0045
84425-07	12164	12/13/01	10:02 AM	Basement Gas Meter Room	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

JAN-07-2002 16:03

2129444618

98%

P. 21

CITY_21MC100_009894107

Ambient Group, Inc.
10 Morris Avenue
Glen Cove, NY 11542
(516) 609-0009

ELAP 10865

**AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)**

Client: Jack Resnick & Sons, Inc.
Address: 75 Park Place
Project ID: 211858

Field ID Number	Date	Time	Floor/Sample Location Description	Analytical Sensitivity	Asbestos Structures/c
1056-01	12/20/01	10:12 AM	Loading Dock Adjacent to Booth	LT ANYL SENS	< 0.0045
1056-02	12/20/01	10:15 AM	Loading Dock at Entrance to Street	LT ANYL SENS	< 0.0045
1056-03	12/20/01	10:28 AM	Parking Garage Near Back Exit Upper Level	LT ANYL SENS	< 0.0045
1056-04	12/20/01	10:30 AM	Parking Garage Adjacent to Soda Machine Upper Level	LT ANYL SENS	< 0.0045
1056-05	12/20/01	10:35 AM	Parking Garage Southend Lower Level	LT ANYL SENS	< 0.0045
1057-06	12/20/01	10:37 AM	Parking Garage Northend Lower Level	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

Ambient Group, Inc.
10 Morris Avenue,
Glen Cove 11542
(516) 609-0009

ELAP 10865

**AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)**

**J. RESNICK & SONS
75 PARK PLACE
PROJECT ID: 211658
DATE COLLECTED:**

SAMPLE NUMBER	LAB SAMPLE ID	SAMPLE LOCATION	ASBESTOS STRUCTURES cm ³
211358-01 FIELD SHT 6063	AEM990 12397	12/27/01 - 11:03 AM 10 th Floor: IWA/Northside Opposite Window LT ANYL SENS	<0.0045
211358-02 FIELD SHT 6063	AEM990 12398	12/27/01 - 11:04 AM 10 th Floor: IWA/Southside Opposite Window LT ANYL SENS	<0.0045
211358-03 FIELD SHT 6063	AEM990 12399	12/27/01 - 11:06 AM 10 th Floor: IWA/Westside Opposite Window LT ANYL SENS	<0.0045
211358-04 FIELD SHT 6063	AEM990 12400	12/27/01 - 11:08 AM 10 th Floor: IWA/Eastside Opposite Window LT ANYL SENS	<0.0045
211358-05 FIELD SHT 6063	AEM990 12401	12/27/01 - 11:10 AM 10 th Floor: IWA/Middle Area LT ANYL SENS	<0.0045
211358-06 FIELD SHT 6058	AEM990 12402	12/27/01 - 11:12 AM 10 th Floor: IWA/Southwest Corner, Opposite Window LT ANYL SENS	<0.0045
211358-07 FIELD SHT 6058	AEM990 12403	12/27/01 - 11:14 AM 10 th Floor: IWA/Northwest, Opposite Window/Corner LT ANYL SENS	<0.0045

LT ANAL SENS=LESS THAN ANALYTICAL SENSITIVITY
ANALYTICAL SENSITIVITY=0.0049

APPENDIX B
SURFACED METAL SAMPLE RESULTS