NYC 9/11 Public Portal Document



| Sample ID<br>Lab Sample Number<br>Sampling Date<br>Matrix<br>Dilution Factor<br>Units | New York TAGM<br>Rec. Soil<br>Cleanup Objective<br>Criteria (ug/l) | DischWells33-36<br>334555<br>02/25/02<br>WATER<br>1.0<br>ug/L | B-6_30HP-Pump<br>334556<br>02/25/02<br>WATER<br>1.0<br>ug/L |
|---|---|---|---|
| SEMIVOLATILE COMPOUNDS (GC/MS) | | | |
| Naphthalene | 13000 | 0.7 U | 6.7 |
| Total Confident Conc. BNAs (s) | | 0 | 6.7 |
| Total Estimated Conc. BNA TICs (s) | | NA | NA |

003
MORETRENCH AMERICAN
03/06/2002 17:55 FAX 973 627 3950
CITY_21MC100_00469621

Checked By: _____
__ OK
___ Make Corrections



NYC-WTC_000186473

NYC 9/11 Public Portal Document



| Sample ID<br>Lab Sample Number<br>Sampling Date<br>Matrix<br>Dilution Factor<br>Units | New York TAGM<br>Rec. Soil<br>Cleanup Objective<br>Criteria (ug/l) | DischWells33-36<br>334555<br>02/25/02<br>WATER<br>1.0<br>ug/L | B-6_30HP-Pump<br>334556<br>02/25/02<br>WATER<br>1.0<br>ug/L |
|---|---|---|---|
| PESTICIDES/PCBs | | | |
| (1) Aroclor-1016 | NA | 0.20 U | 0.20 U |
| (1) Aroclor-1221 | NA | 0.20 U | 0.20 U |
| (1) Aroclor-1232 | NA | 0.30 U | 0.30 U |
| (1) Aroclor-1242 | NA | 0.20 U | 0.20 U |
| (1) Aroclor-1248 | NA | 0.20 U | 0.20 U |
| (1) Aroclor-1254 | NA | 0.40 U | 0.40 U |
| (1) Aroclor-1260 | NA | 0.50 U | 0.50 U |
| (1) Aroclor-1262 | NA | 0.20 U | 0.20 U |
| (1) Aroclor-1268 | NA | 0.20 U | 0.20 U |

(1) Values listed reflect the combined standards for "Total PCBs"
(2) Soil Cleanup criteria is provided for "Endosulfan" without specification if it is for Endosulfan I or Endosulfan II.

Qualifiers

U - The compound was not detected at the indicated concentration
J - Data indicates the presence of a compound that meets the identification criteria The result is less than the quantitation limit but greater than zero The concentration given is an approximate value.
B - The analyte was found in the laboratory blank as well as the sample This indicates possible laboratory contamination of the environmental sample
P - For dual column analysis, the percent difference between the quantitated concentrations on the two columns is greater than 40%
* - For dual column analysis, the lowest quantitated concentration is being reported due to resulting interference
NR - Not analyzed

Checked By: _____
___ OK
___ Make Corrections



03/06/2002 17:55 FAX 973 627 3950 MUKE KENCH AMERICAN 004

CITY_21MC100_00469213

NYC-WTC_000186474

NYC 9/11 Public Portal Document



005

03/06/2002 17:55 FAX 973 627 3950 MORETRENCH AMERICAN

CITY_21MC100_0046962 14

| Sample ID<br>Lab Sample Number<br>Sampling Date<br>Matrix<br>Dilution Factor<br>Units | New York TAGM<br>Rec. Soil<br>Cleanup Objective<br>Criteria (mg/l) | DischWells33-36<br>334555<br>02/25/02<br>WATER<br>NA<br>ug/l | B-6_30HP-Pump<br>334556<br>02/25/02<br>WATER<br>NA<br>ug/l |
|---|---|---|---|
| METALS | | | |
| Cadmium | NA | 0.40 U | 3.2 |
| Chromium | NA | 2.8 U | 24.7 |
| Copper | NA | 2.1 U | 121 |
| Lead | NA | 8.6 U | 186 |
| Mercury | NA | 0.10 U | 0.10 U |
| Nickel | NA | 8.3 | 15.4 |
| Zinc | NA | 5.8 U | 752 |

Qualifiers

U - The compound was not detected at the indicated concentration.
B - Reported value is less than the Method Detection Limit but greater than or equal to the Instrument Detection Limit.
N - The spiked sample recovery is not within control limits.
NR - Not analyzed.

Checked By: _____
___ OK
___ Make Corrections



NYC-WTC_000186475

NYC 9/11 Public Portal Document



| mple ID<br>Lab Sample Number<br>Sampling Date<br>Matrix<br>Dilution Factor - NA<br>Units - See Parameter | New York TAGM<br>Rec. Soil<br>Cleanup Objective<br>Criteria (ug/l) | DischWells33-36<br>334555<br>02/25/02<br>WATER | B-6_30HP-Pump<br>334556<br>02/25/02<br>WATER |
|---|---|---|---|
| WET CHEMISTRY | | | |
| Ignitability - deg F | NA | >160 | >160 |
| pH - std unit | NA | 7.35 | 8.42 |
| TotalPetroleumHydrocarbons(418.1) | NA | 1.0 U | 2.6 |
| TotalSuspendedSolids - mg/l | NA | 10.0 U | 10.0 U |

Qualifiers
U - The compound was not detected at the indicated concentration
NR - Not analyzed.

Checked By: _____
__ OK
__ Make Corrections



03/06/2002 17:55 FAX 973 627 3950 MORETRENCH AMERICAN 006
CITY_21MC100_0046962 15
NYC-WTC_000186476