

01/17/1994 02:30 5162933152

S. MALL LABS/IRI/UN



26 NORTH MALL • PLAINVIEW, NY 11803
 (516) 293-2191 • FAX (516) 293-3152
 E-Mail: info@SouthMallLabs.com
 Website: www.SouthMallLabs.com

February 16, 2002

Miller Environmental Group
 538 Edwards Avenue
 Calverton, NY 11933

Attn: Mr. Bill Fisher


Sample Description:	Soil
Sample Collected By:	Miller Environmental Group
Purchase Order Number:	Murray & West
Date Samples Received:	2/6/02
Analysis Number:	126459

<u>Analyte</u>	<u>Results</u>	<u>Method</u>
Arsenic, mg/kg	<0.187	6010 ¹
Barium, mg/kg	32.6	6010 ¹
Cadmium, mg/kg	0.749	6010 ¹
Chromium, mg/kg	7.71	6010 ¹
Lead, mg/kg	55.7	8010 ¹
Mercury, mg/kg	0.069	7470 ¹
Selenium, mg/kg	<0.234	6010 ¹
Silver, mg/kg	<0.047	6010 ¹
Aroclor-1016 (PCB), µg/kg	<3.33	8082 ¹
Aroclor-1221 (PCB), µg/kg	<3.33	8082 ¹
Aroclor-1232 (PCB), µg/kg	<3.33	8082 ¹
Aroclor-1242 (PCB), µg/kg	<3.33	8082 ¹
Aroclor-1248 (PCB), µg/kg	<3.33	8082 ¹
Aroclor-1254 (PCB), µg/kg	<3.33	8082 ¹
Aroclor-1260 (PCB), µg/kg	<3.33	8082 ¹

¹ Federal Register, Vol. 49, No. 209

New York State ELAP Laboratory Identification #10950/EPA Laboratory Identification #NY01292

Laboratory Director:


 Joseph P. Shaulys

JPS:po

THE ANALYSIS HAS BEEN CARVED OUT UNDER CONTROLLED LABORATORY CONDITIONS AND ANY SUGGESTIONS ARE MADE SOLELY ON THAT BASIS.

CITY_21MC100_002941070