NYC 9/11 Public Portal Document

# ASBESTOS ANALYTICAL REPORT

**DEP**

ASBESTOS CONTROL PROGRAM LABORATORY
96-05 HORACE HARDING EXPRESSWAY
CORONA, NEW YORK 11368
(718) 595-6309 FAX# (718) 595-6307

ELAP # 11045

**TEST METHODS : 1) 40 CFR Part 763, Subpart F, App. A**
**2) Polarized Light Microscopy plus Stratified Point-Counting Method**
**3) EPA/600/R-93/116**

Incident #: TRU0273MN03
Inspector : P. THEODORELLYS
Premise : 114 LIBERTY STREET
Boro : Manhattan
Analyst : G. ANAKHU

Date Collected: 03/17/03
Received: 03/17/03
Analyzed: 03/17/03

---

| | | |
|---|---|---|
| Client #: | | |
| DEP Sample #: | 30317/A019010 | 30317/A019011 |
| Laboratory #: | 30317/342 | 30317/343 |
| Location Sampled: | 7TH FL BEAM | 9TH FL BEAM |
| Color: | GREY | GREY |
| Homogenous: | Yes | Yes |
| Asbestos Present: | No | No |

Results (%)

| | | | |
|---|---|---|---|
| Cellulose | 2 | Cellulose | 4 |
| Fibrous glass | 45 | Fibrous glass | 42 |
| Matrix | 52 | Matrix | 54 |
| Silicates | 1 | | |

Comments:

Reviewed by: A. Athalone
Laboratory Director

**This test report may not be reproduced except with the written approval of this laboratory. The test report relates only to the item(s) listed and does not represent a product endorsement by NVLAP or any other U.S. Government agency.**



NYC-WTC_000186824