

SciLab Job #: 203031539

Client Name: JLC Environmental Consultants


Table I
Summary of Transmission Electron Microscopy (TEM) Results for Asbestos (air)
 03-2744; NYCDEP; 114 Liberty St.

SciLab Sample #	Client Sample #	Dilution Factor	Air Filtered (liters)	Area Analyzed (sq. mm.)	* Analytical Sensitivity (struc/cc air)	Asbestos Structures Detected (Microns)			Structure Density (struc/sq. mm.)		Structure Concentration (struc/cc air)		Type of Asbestos
						0.5-5.0	>5.0	Total	>5.0	Total	>5.0	Total	
01	01/006779		4200	.1	0.0009	1.0	0.0	1.0	<10	10.0	<0.0009	0.0009	chrysotile
	Adjacent To The 1st Front Entrance To Bldg #114 Liberty St.												
02	02/006780		4200	.1	0.0009	0.0	0.0	0.0	<10	<10	<0.0009	<0.0009	NSD
	At The Center In Front Of Bldg #114 Liberty St.												
03	03/006781		4200	.1	0.0009	0.0	0.0	0.0	<10	<10	<0.0009	<0.0009	NSD
	Adjacent To The 2nd Entrance At The Front Bldg #114 Liberty St.												
04	04/006782		4200	.1	0.0009	0.0	1.0	1.0	10.0	10.0	0.0009	0.0009	chrysotile
	To The Far Right Of The Back Entrance Of Bldg #114 On Cedar St.												
05	05/006783		4200	.1	0.0009	0.0	0.0	0.0	<10	<10	<0.0009	<0.0009	NSD
	Adjacent To The Back Entrance Of Bldg #114 On Cedar St.												

* concentration represented by the detection of 1 structure

* * not analyzed

NSD: No Asbestos Structures Detected

Reviewed By: _____; Analyzed By:  Date: 3/7/03

Mark Peysakhov

NVLAP#: 200546-0

CITY_DEP_WORBY_CANNATA_SUBP_000006363